

NATIONAL Assessment Centre Services

(wef 1 Jan 2005)

MAA40117664

Date In: 11/09/2018 10:52	Job description: SAS e-filing	Date & Time Completed:	Done by:
Ref No: N8A1/MC/8016524/Y			
Veh No: YM 3753X	E-mail (within 8hrs, AIC 2hrs)		
D.O.A: 10/09/2018 06:55	i-Motor Claim Form	mt/1010967-001	11/09/2018
☒ OD TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		12.18
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: JRG 5176	INC () / Non-INC ()
Owner / Driver: (	Tel:	)
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79% F: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury : _____

Date/Time	Actions

Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments :- Cat. 1: Cat. 2 / 3:	Invoice Preparation Checklist		Amt (\$)	Amt (\$)
	1) AR : Accident Reporting (\$30);		1st Bill	Add Bill
	2) DA : Damage Assessment (\$100); INC (\$80)			
	3) TF : Towing Fee \$40/\$45			
	4) FT : Follow-Through Survey \$120			
	5) FT : Follow-Through Survey (Resurvey) \$30			
	For claiming against INC Only (wef 10 Jan 2005)			
	6) TR : Re-inspection \$75			
	7) N1 : Idac DA + SMRT Survey \$160			
	8) NTUC Additional Services:-			
OT*				
*N5: Courtesy Car / Tpt Allowance \$5				
*N6: Repair Co-ordination \$10				
*N7: Post Repair Inspection \$25				
*N8: DV / Collect Excess Coordination \$5				
TP (N11) : TP (Non INC) against INC \$20				
9) N12: Idac Mobile 30				
Invoice dated		Fee Charged		
Invoice dated		Fee Charged		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2018 10:52
Date Of Accident	10/09/2018 06:55
Exact Location Of Accident	X-JUNCTION OF TUAS CRESCENT/TUAS SOUTH AVENUE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3753X
Insured/Policyholder	
Name Of Registered Owner	BESTEC ENGINEERING PTE LTD
Co Reg No	201201288E
Email Address	ELUMALAI@BESTECENGG.COM.SG
Mobile Phone No	(LOCAL) +65-81386915
Alternative Phone No	OFFICE-83492920

Vehicle Particulars

Manufacturer	ISUZU
Model	NNR85UH4A-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	TAKING WORKERS TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5060562008-05
Cover Note Number	

Driver

Name of Driver	SEMBAIYAN MANIVASAKAN
Passport No/FIN	G2795906M
Date Of Birth	20/07/1992
Occupation	OUTDOOR
Date Of Driving Pass	20/07/2018
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81386915
Fax Number	
Contact Number	OTHERS-83492920
EMail Address	ELUMALAI@BESTECENGG.COM.SG

Address	NO 12 BENOI PLACE
Postcode	629932
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JRG5176 (MOTORCYCLE)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	19
Passenger 1	NAME: : WORKER GENDER: : MALE
Passenger 2	NAME: : WORKER GENDER: : MALE
Passenger 3	NAME: : WORKER GENDER: : MALE
Passenger 4	NAME: : WORKER GENDER: : MALE
Passenger 5	NAME: : WORKER GENDER: : MALE
Passenger 6	NAME: : WORKER GENDER: : MALE
Passenger 7	NAME: : WORKER GENDER: : MALE
Passenger 8	NAME: : WORKER GENDER: : MALE
Passenger 9	NAME: : WORKER GENDER: : MALE

Passenger 10	NAME: : WORKER
	GENDER: : MALE
Passenger 11	NAME: : WORKER
	GENDER: : MALE
Passenger 12	NAME: : WORKER
	GENDER: : MALE
Passenger 13	NAME: : WORKER
	GENDER: : MALE
Passenger 14	NAME: : WORKER
	GENDER: : MALE
Passenger 15	NAME: : WORKER
	GENDER: : MALE
Passenger 16	NAME: : WORKER
	GENDER: : MALE
Passenger 17	NAME: : WORKER
	GENDER: : MALE
Passenger 18	NAME: : WORKER
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180910/2012

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JRG5176
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PS REFER TO POLICE REPORT.
1/20180910/2012

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

S M
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

1/2018
 Reporting Centre Personnel's Signature
 Name: *Pauli Santos*
 NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180910/2012

1 of 3

Report No. T/20180910/2012

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/09/2018 09:21		Vide Report No.: J/20180910/0078		Station Diary No.: 13	
Informant's Particulars					
Name of Informant: SEMBAIYAN MANIVASAKAN			Address:		
ID Type / ID No.: FIN NO / G2795906M			Contact No.: Home/Office: Mobile: 83492920		
Nationality: INDIAN			Email:		
Sex: Male	Age: 26	Date of Birth: 20/07/1992	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: MARINE TRADES WORKER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/09/2018 06:50	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TUAS SOUTH AVENUE 5 TUAS CRESCENT X-JUNCTION				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRG5176	Motorcycle	YAMAHA		Red	No Damage	0
YN3753X	Lorry	ISUZU		White	Slightly Damaged	18

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180910/2012

2 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180910/2012

CONTINUATION OF REPORT

Driver			
Name	SEMBAIYAN MANIVASAKAN	ID No.	G2795906M
Related Vehicle	YN3753X (Lorry)	Contact No.	83492920
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10.09.2018 at about 0650hrs, I was driving my company lorry; YN3753X along Tuas South Avenue 5 towards Tuas Crescent. As I was approaching the X-junction of said 2 roads, I executed a turn but before doing so saw there was no oncoming traffic. When making the right turn, suddenly a motorcycle; JRG5176 collided onto the front side of my lorry.

Neither my passenger of 18 men nor myself were injured. However the motorcyclist sustained injuries and the ambulance and traffic police attended to my scene. The motorcyclist was then conveyed to hospital.



**SINGAPORE
POLICE FORCE**



T/20180910/2012

3 of 3

Report No. T/20180910/2012

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
J /
Staff Sgt MOHAMMED AMIRULHAFIZ BIN
RAMLAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Insp TAN CHIN YONG
Contact No.: 65476178

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
10/09/2018 09:21

Classification Of Case:

SN 120

Claim Handling

Accident HT/1010967

Policy No.	5060562008-05	Vehicle No.	YN3753X	GST Registration No.	
Certificate No.					
Policyholder Name	BESTEC ENGINEERING PTE LTD	Policyholder NRIC	2012012888		
Product Code	COMMERCIAL VEHICLE INSURANCE	Cover Type	Comprehensive	Leading	0
Contact No.(Mobile)	81386915	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KPK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No
Accident Details					
Report Date	11/09/2018 12:13	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head on collision
Date of Accident	10/09/2018	Time of Accident (Hr:Min)	06:55	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	X-JUNCTION OF TUAS CRESCENT/TUAS SOUTH AVENUE 5				
Excess					
Own Damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Date		GST Status Verified	No
GST Registration No.					
Modification History					
Policyholder Mailing Address					
Address 1	12 BENOI PLACE	Address 2	SINGAPORE 629932	Address 3	
Address 4		Address Type	Singapore address	Post Code	629932
Unit No.	02-01	Related Policy Number	5102202803		
Q1 Driver Info					
Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	SERBAYAN MANIVASAGAN	Driver NRIC	G2796906H	Driver DOB	29/07/1992
Register Date of Driver License	20/07/2018	Driver Age	26	Driving Experience	0
Contact No.(Mobile)	83492920	Contact No.(Office)		Contact No.(Home)	
Address 1	12 #02-01 BENOI PLACE	Address 2	SINGAPORE 629932	Address 3	
Address 4		Address Type	Foreign address	Post Code	629932
Unit No.	02-01				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	YN3753X	Driver Insurer Company	NTUC
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes ☐ No ☒		

Modification History

Claim 001

New

Claim Type *	OD-MD	Insured Name	BESTEC ENGINEERING PTE LTD	Insured NRIC	2012012888
Contact No.(Mobile)		Contact No.(Office)		Contact No.(Home)	81386915
Email Address		Vehicle No.	YN3753X	Vehicle Number	485176
Claim Description	YN3753X / 485176 On 10 Sept 2018				
Preferred Workshop		Insured Liability	Partially at Fault	GIA report	Received
Workshop No. Finalisation	Yes	Registered Repair Option	Income to assign workshop		
Date Registered	11/09/2018 12:13	Claim Close Date		Date Received	11/09/2018
Report Taken By	ROSLI WAHAB				
☒ Print AK letter					
Save Submit					

Attachment

Accident No.	HT/1010967	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	11/09/2018 12:18
Path *			
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read			
Attachment List			
Attachment	Uploaded By/Date	Category	Urgency
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:18		Photos	Normal
Description Photos 2018-9-11			

	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:18	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800678(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800678(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800678(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	Photos	Normal	Photos 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-9-11
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 11 Sep 2018 12:17	SAS	Normal	SAS 2018-9-11

Video List

ASSIGNMENT (ID-001)

By CSO- Notice of Accident:

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit ? ☐
- a) Motorist ☐ b) Pedestrian ☐
- b) Motorcycle ☐ c) Animal ☐
- c) Bicycle ☐
- 3) Vehicle hit Road Side Objects: ☐
- a) Govt Property ☐ b) Road Work Object ☐
- (Eg: signboard, barrier, tree etc)
- c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God: ☐
- a) Fallen Object ☐ b) Flood ☐
- c) Other: ☐
- 6) Parked & Found Damaged: ☐
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case ☐
- a) Stolen ☐ b) Damage found ☐
- when recovered.
- 8) Fire ☐
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

By Assessor- 1) Vehicle Information

Vehicle: YH3753X No Reg: X100 / 2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / ☐

/ Truck / Trailer or ☐

Make & Model: ISUZU NMR85UHYA c.c. 2999

Colour: WHITE Transmission Type: Auto / Manual ☐

Eng/No: 48J1715874 Sp. Reading: 408333

C/No: JAGNN

Gen. Cond: Good / Fair / Poor / Burnt ☐

Steering: Inorder / Jammed / Leaked / Burnt ☐

Brake: Inorder / Jammed / Leaked / Burnt ☐

Modi: W/P / S/Rim / STD A/Rim or ☐

Tyre Size: F: 195/85R16

R: 185/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ☐

Front

R/Bal. 6 mm

L/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

Parallel Import: Yes / No

Towed-In: Yes / No

Repair Type: LS / I.B.I

Towing Required: Yes / No

No of Repair Days: 5

Vehicle in Idac: Yes / No

D.O.I. 11/09/2008

Time: 11:30

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

a. Vehicle ☐ b. Motorcycle ☐ c. Bicycle ☐ d. Pedestrian ☐

e. Animal ☐ f. Govt Object ☐ g. Road Work Object ☐

h. Private Property ☐ i. Drain ☐ j. Road Kerb/Grass Verge ☐

3) Vehicle does not seem damaged as a result of:

a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐

e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Time Started

Time completed

1) CSO

2) ABS

3) Entire Operation Completed Time:

Vehicle No:

YM 3753X

From Portion

Front Portion			CON	AC	Qty
NAC	INC	Item			
1001	991886	Frt Number Plate	B7	✓	
1002	991887	Frt Number Plate Base	B7	✓	
1004	991300	Frt Bumper			
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	MS	✓	
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel	PRICE		
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem	NAC	✓	
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel	AT	2	
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen	ORD	✓	
1115	992097	Frt Windscreen Rubber	MS	✓	
1117	992098	Frt Windscreen Sealant	MS	✓	
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket	NAC	✓	
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

original copy

Claim Handling

Task Transfer Exit

Accident MT/1010967

LOG SAVE SUB

Policy No.	5060562008-05	Vehicle No.	YN3753X	GST Registration No.	
Certificate No.					
Policyholder Name	BESTEC ENGINEERING PTE LTD			Policyholder NRIC	201201288E
Product Code	COMMERCIAL VEHICLE INSURAT	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	81386915	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No *
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No

Accident Details

Report Date	11/09/2018 12:13	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head on collision
Date of Accident	10/09/2018	Time of Accident hh:mm	06:55	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Grange Force	No	ICM No.	
Accident Location	X-JUNCTION OF TUAS CRESCENT/TUAS SOUTH AVENUE 5				

Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	No
Modification History			

Policyholder Mailing Address

Address 1	12 BENOI PLACE	Address 2	SINGAPORE 629932	Address 3	
Address 4		Address Type	Singapore address	Post Code	629932
Unit No.	02-01	Related Policy Number	S102202803		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	20/07/1992
Unnamed driver Name	SEMBAYAN MANIVASAKAN	Driver NRIC	G2796906M	Driving Experience	0
Register Date of Driver License	20/07/2018	Driver Age	26	Contact No.(Home)	
Contact No.(Mobile)	83492920	Contact No.(Office)		Address 3	
Address 1	12 #02-01 BENOI PLACE	Address 2	SINGAPORE 629932	Post Code	629932
Address 4		Address Type	Foreign address		
Unit No.	02-01				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	YN3753X	Driver Insurer Company	RTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History			

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Chou

LOG SAVE SUB

Claim Type	OD-MD	Insured Name	BESTEC ENGINEERING PTE LTD	Insured NRIC	201201288E
Contact No (Mobile)		Contact No. (Home)		Contact No. (Office)	68633090
Email Address		OT Vehicle Number	YN3753X	TP Vehicle Number	JRG5176
Claim Description	YN3753X / JRG5176 ON 10 Sept 2018				Name of Preferred Workshop
Preferred Workshop Selection	Yes	Preferred Repair Option	Income to assign workshop	Insured Liability Accepted	Partially Accepted
Date Registered	11/09/2018 12:18	Claim Close Date		Date Received	11/09/2018 00:00
Report Taken By	RCISL1 WAHAB	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment

Attachment

Vehicle Info

Vehicle Make	ISUZU	Vehicle Model	NNR B5	Engine Capacity	2.52
Date of Registration	14/11/2008	Classis No.	JAANW8BSHB7100566		
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender		Assessor Name *		Survey Current Status	

9/11/2018

Claim Handling (damage assessment Claim Task MT/1010967 / Claim 001 OD-MD)

* IDAC/Workshop Name Windscreen Parts & Labour Cost Market Value(\$)	Own Damage *	IDAC/Workshop Location Total Loss * Scrap Value(\$)	ROSLI WAHAB 51 URI AVENUE 1 #01-35 PAYA ☐ Yes ☒ No	Economical Repair Value(\$)
Remark				

Remark for
Supplementary

Damage Listing

ER	No.	Part No.	Description	Qty *	Repair Code *	
CROWN HANDLE (MC)	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
CYLINDER	2	16000101	BUMPER (FRONT)	1	Replace	X
DASHBOARD	3	16005201	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
DECK	4	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
DIESEL FILTER	5	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
DIFFERENTIAL	6	27100101	GRILLE (FRONT)	1	Replace	X
OISC	7	33000101	PANEL (FRONT)	1	Replace	X
DISC (MC)	8	33000301	PANEL EMBLEM (FRONT)	1	Replace	X
DISTRIBUTOR	9	33000401	PANEL GARNISH (FRONT)	1	Unconfirm	X
DOOR	10	12900301	APRON PANEL (FRONT)	1	Replace	X
DOOR (BUS)	11	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
DOOR (EMERGENCY)	12	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	X
DRIVE SHAFT	13	45100401	WINDSCREEN GLASS (FRONT)	1	Replace	X
DRIVER CAB MOUNTING	14	45100601	WINDSCREEN GLASS RUBBER (FRONT)	1	Replace	X
DRIVER CABIN COMPARTMENT	15	451008	WINDSCREEN GLASS SEALANT	1	Replace	X
DROP DOOR	16	245001	ERP: BRACKET	1	Replace	X
ELECTRONIC CONTROL UNIT (ECU)						
ELECTRONIC IGNITION COIL						
EMBLEM						
ENGINE						
ENGINE (MC)						
ERP						
ERP BRACKET						
ERP UNIT						
EVAPORATOR						
EXHAUST						
EXPANSION TANK						
EXPANSION VALVE						
EXTENSION MEMBER						
EXTERIOR LAMP						
FAIRING						
FAN						
FENDER						
FIREWALL PANEL						
FLOOR						
FOG LAMP						
FOOT BRAKE (MC)						
FOOT GEAR SHIFTER (MC)						
FOOT PEDAL (MC)						

Save Submit

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Wednesday, 12 September, 2018 1:28 PM
To: NAC-Bukit Merah
Subject: YN3753X, OD claim no : MT/1010967

Importance: High

Dear IdAC,

As COR is below OD excess of \$1,600/- (std : \$600/-. Further excess : \$1K), hence OD claim does not response.

Owner Mr Elumalai (tel : 81386915) had been informed accordingly to ask his driver to sign addendum at your centre to change to Reporting Only.

I had given the contact nos of Auto Glass Venture to him to liaise with directly as he wants to activate Windscreen claim.

Pls assist to follow up accordingly.

Regards,

Tan Siew Choo
Senior Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

ACCIDENT STATEMENT

ACCIDENT DATE: 10/09/2018 (DD/MM/YYYY), TIME: 06:55 (HH:MM)

LOCATION: TUAS CRESCENT JUNCTION

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: YN 3753 X
 b) INSURANCE COMPANY: NTUC INCOME
 c) POLICY NUMBER: 5060562008-05
 d) POLICY TYPE: COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
 e) MAKE & MODEL: _____
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
 h) PURPOSE OF USING AT ACCIDENT TIME: TAKING WORKERS To work
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- a) NAME: BESTEC ENGINEERING PTE LTD (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 20201288E CONTACT: 8138 6915
 c) ADDRESS: No. 12 BENOT PLACE (ELUMMALAI)
SINGAPORE - 629932

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: SEMBAYAN MANIVASAKAN (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: G2795906M CONTACT: 83492920
 c) ADDRESS: No. 12 BENOT PLACE
SINGAPORE - 629932

* d) DATE OF BIRTH: 20/07/1992 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS: 11 OCT 2017

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: TURONG WEST N.P.C

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: JRG 5176 MODEL: YAMAHA
 b) DRIVER'S NAME: _____
 c) NRIC/FIN/PASSPORT: _____ CONTACT: _____

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
 e) DRIVER'S NAME: _____
 f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

EMAIL: elumalai@bestecengg.com.sg

VIDEO =

Employee
BESTEC ENGINEERING PTE. LTD.

91A)

Name
SEMBAIYAN MANIVASAKAN

Work Permit No.
O 37138557

Sector
MARINE

K0171801

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number
G2795906M

Name
SEMBAIYAN MANIVASAKAN

Birth Date: 20 Jul 1992

Issue Date: 11 Oct 2017

Valid Till: 10/10/2022

K002732975K

VISIT PASS
Immigration Regulations

07-03-2019

Name
SEMBAIYAN MANIVASAKAN

FIN
G2795906M

Date of Birth
20-07-1992

Sex
M

Nationality
INDIAN

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download SGWorkPass App to check status

Q0171801

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE
11 Oct 2017
20 Jul 2019

Class 15
Class 3

Motorcycles <= 250 CC
Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg

S / No. 9000317568

G2795906M

NP 428A

License No: G2795906M

Hello, NAC_BUKIT_MERAH_800676

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	10/09/2018 10:34
Vehicle No.(For Motor)	YN3753X	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5060562008-05		BESTEC ENGINEERING PTE LTD	201201288E	GCV	Comprehensive	YN3753X	YN3753X	14/05/2018	13/05/2019

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S685500200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MNA418117664 Vehicle Registration No: YN3753X
Name (as shown in NRIC) : SEMBAYAN MANIVASAKAN NRIC/FIN/Passport No : G2795906M
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : NO. 12 GENOI PLACE Singapore (629932)
Contact (Tel) : - Mobile No.: 81386915
Email Address : elumalai@bestecangy.com.sg
Date of Accident : 10/09/2018 Time of Accident: 06:55
Place of Accident : X-JUNCTION OF TUAS CRESCENT / TUAS SOUTH AVENUE 5
Insurance Company: NTUC Income Insurance Co-operative Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend from CD to Reporting only.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: