

ASS. REC. BY:

REF:

CS3 / AIG 18016529 / Gcd34

Special Instruction:

Surveyor:

Menthen

Suo Qiang

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

11/9/18 @ 9.43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SMA 7700H

Insured:

SLC 7860E

at Workshop m/s

Tecum Auto pro

Tel:

9092 7279

of

8 Kaki Bkt Ave 4 # 06-21

Policy No.:

2100467734

Claim No.:

4299474930SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/09/18

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9.58am 11.9.18

Person Contacted:

Alan

Vehicle:

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SMA 7700H - X
	SLC 7860E - X
	After repair: 20/9/2018
	Dismantle: 12/9/2018

MS
xcl

REF: A161

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Team Auto pro
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMAT700H Yr Regn: Jun / 18
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Merce G220 c.c. 1950
 Colour: Black A/C: Insured / Std / NI / NA
 Sp.Reading: 18741 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 213 00 42A 3929 05
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD/A/Rim or _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Tyre Size: F: 225/55 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : **Yes** or No
 GIA / PR Seen: _____ Consistent? : **Yes** or No
 Est. Repairs: 4 days Res.: **Yes** or No
 Lum Sum: 20 % 3 Val.: **Yes** or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11-09-18
 Survey held at w/s 3:35pm
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
FR O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$4000 - \$5000
<u>1/10</u>	<u>Submit DAR report.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: 4
 Resurvey No. of Trip: 2
 Survey Fee: 180
 Transportation: _____
 Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))
 Report Format : DAR
 Lump Sum / I.B.I: (\$ _____)
 Photos _____
 Others 20
 TOTAL 200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 11/9/2018 9:43:19 AM
Attachments:  [10092018110507.pdf](#)

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: William Lee [mailto:william@roypartners.com.sg]
Sent: Monday, September 10, 2018 11:06 AM
To: Gan, Angiegeokling; Fong, Andy-SY; Ng, Hai-Chuan; Lim, Sheng Yang
Cc: 'Ashley'; 'Team AutoPro East'; 'Roy'
Subject: Our Ref: MKR/404/8230/2018/as.wl; Your Ref: Your insured vehicle no. SLC 7860E; TA Ref: SMA 7700H;
Importance: High

Our Ref: MKR/404/8230/2018/as.wl;
Your Ref: Your insured vehicle no. SLC 78960E;

Dear Sirs,

✱

Attn: Motor claims department

**CLAIMANT: E CAPITAL ASIA PTE LTD (OWNER OF SMA 7700H)
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NO. SMA 7700H AND SLC 7860E ALONG CHANGI
AIRPORT T3 CARPARK BASEMENT 1 ON 06.09.2018 AT ABOUT 2150 HOURS.**

We refer to the above matter.

We act for E Capital Asia Pte Ltd, the owner of motor car No. **SMA 7700H**.

We are instructed by our client to notify you of a road traffic accident on 06.09.2018 at about 9.50 pm along Changi Airport T3 Carpark Basement 1 involving our client's motor car registration number **SMA 7700H** and motor car registration number **SLC 7860E** driven by

your insured at the material time. A copy of the Singapore Accident Statement and traffic police report is attached.

As a result of the accident, our client's motor car **SMA 7700H** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SMA 7700H** at our client's repairer workshop, M/s Team AutoPro Pte Ltd at No. 8 Kaki Bukit Avenue 4 #06-21 Premier @ Kaki Bukit (Gate 2) Singapore 415875, Your said surveyor may contact Mr. Alan at 9092 7279. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

William Lee

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : william@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9078M
Vehicle Details	
Vehicle No.:	SMA7700H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220D AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	65492080186324
Chassis No.:	WDD2130042A392905
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$46,820.00
Original Registration Date:	20 Jun 2018
First Registration Date:	20 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$57,548.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2028
PARF Rebate Amount:	\$43,161.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,389.00
COE Rebate Amount:	\$36,342.00
Total Rebate Amount:	\$79,503.00

The information contained herein is correct as at 25 Sep 2018

OK

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 06/09/2018 (dd/mm/yy) Time of Accident: 21:50 (24-HR-FORMAT)
Vehicle No.: SMA 7700 H Vehicle Make & Model: Mercedes E220D
Exact location of Accident: Changi Airport T3 Carpark Basement 1
Policyholder's Name / IC No.: E Capital Asia Pte Ltd 200919078M
Driver's Name / IC No.: Neo Chern Hui S7722379G (As Above)
Driver's Contact No.: 9337 3928 Company Contact No: _____
Driver's Address: Blk 413 Choa Chu Kang Ave 3 #06-403 S(680413)
Insurance Company: NTUC Income Email address (if any): _____

Relationship between Owner & Driver: Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

Own Insurance / Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Private use / Work purpose

Occupation (nature of job) Indoor / Outdoor

No. of Passengers (Including Driver): 01

Passenger Name : _____
Passenger Name : _____

Gender : _____
Gender : _____

Weather condition & Road conditions? (On the day of accident)

Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? Yes / No

Any Injuries: Yes / No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: Yes / No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SLC 7860 E

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: _____

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A reversed into a parking lot. There is a unknown vehicle overtake me hence I stopped. Suddenly I saw vehicle B coming towards my direction at a high speed. I honked him but vehicle B could not react in time and hit onto my stationary vehicle right portion.

I would like to state that my vehicle is stationary at that point of impact.

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180907/7005

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180907/7005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/09/2018 15:12	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: NEO CHERN HUI		Address: APT BLK 413 CHOA CHU KANG AVENUE 3 #06-403 SINGAPORE 680413	
ID Type / ID No.: NRIC NO / S7722379G		Contact No.: Home/Office: Mobile: 93373938	
Nationality: SINGAPORE CITIZEN		Email: nchedmund@gmail.com	
Sex: Male	Age: 41	Date of Birth: 16/07/1977	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Chauffeur		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/09/2018 21:50	Type of Location: Car Park
Location: UNNAMED ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLC7860E	Car	SUZUKI		Silver	Seriously Damaged	1
SMA7700H	Car	MERCEDES BENZ	E220D	Black	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180907/7005

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180907/7005

CONTINUATION OF REPORT

Driver			
Name	NEO CHERN HUI	ID No.	S7722379G
Related Vehicle	SMA7700H (Car)	Contact No.	93373938
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	07/09/2018	Date Discharge	07/09/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the stated date and time, I vehicle A was reversing into my lot in Changi Airport Terminal 3 Basement 1 carpark 3A lot number 173. As i was reversing into my lot i noticed an oncoming vehicle overtake me. After which i then realized that vehicle B wasn't looking and did not noticed that i was reversing into my lot. I horned him to alert him of my presence as he was coming at a fast speed, but to no avail he crashed into my front right portion. As the impact was huge i injured my hand and was awarded 5 days MC. I would also like to state that there were 2 security camera present at B1 section 3 near lot 168 and the other at the carpark gantry. That is all.



**SINGAPORE
POLICE FORCE**



T/20180907/7005

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180907/7005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/09/2018 15:12

Classification Of Case:

(05)Stilled (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Tom
 (14)Unfinished (15)Not Working

MOTOR CAR (Frt)

(1)Replace (✓) (2)Repair (S) (3)Check (T)
 (4)Not Conditional (N/C)

Vehicle No: **SMA 7700 H**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	DD	✓	
1006	991325	Frt Bumper Bracket	NEC	✓	
1007	991462	Frt Bumper Side Retainer	RH	DIS	✓
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	RH	?	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	MIS	✓	
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRA	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Flinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracker			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BAC	✓	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sucker			

[Signature]
 26/9/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018 Edit Reg		11 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Qua Choon Ling Yvonne , ID: S1763854H								
Main Claimant:	-								
Vehicle Reg. No.:	SMA7700H	Date of Loss:	06/09/2018 00:00 - :59 [2 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4299474930SG	Policy/Cover Note No.:	2100467734 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC7860E	Policy No. (Claimant):							
		Excess:							
Repairer:	Team Autopro Pte Ltd (HQ) 8 KAKI BUKIT AVE 4, #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/09/2018]								
Claimant's Solicitor:	ROY & PARTNERS - Tel: 65368466								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (12/09/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA7700H (4299474930SG)
[SLC7860E]**

TP

-

**Sep 6 2018 12:00AM
[Qua Choon Ling Yvonne]
Team Autopro Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	12/09/18 13:52	Accident Statement From: SC - Reg. No: SLC7860E, Claimant: YVONNE QUA CHOON LING						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
2	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
3	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
4	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
5	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
6	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
7	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
8	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
9	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
10	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
11	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
12	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
13	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
14	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
15	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
16	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
17	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
18	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
19	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
20	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
21	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
22	25/09/18 09:20	General View						Load JPG	<input checked="" type="checkbox"/>		
23	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
24	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
25	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
26	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
27	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
28	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
29	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
30	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
31	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
32	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
33	27/09/18 12:45	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	27/09/18 12:45	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
50	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	27/09/18 12:45	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016529/GCD3E2

Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100467734
Claimant Vehicle No : SMA7700H	Insured Vehicle No :	SLC7860E
Date of Loss: 06/09/2018	Nature of Claim:	TP
		Claim No: 4299474930SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7700H	Engine No:	65492080186324
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)	Chassis No:	WDD2130042A392905
Reg. Date:	20/06/2018 (Man. Year: 2017)	Odometer:	18741 km
Colour:	Black		
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/09/2018		
Date Inspected:	11/09/2018	Inspected At:	8 KAKI BUKIT AVE 4#06-21
			Repairer : Team Autopro Pte Ltd (HQ)
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
4	1		*FRT BUMPER GRILLE RH	* Check	0.00 F	*- F
5	1		*FRT BUMPER SENSOR	Missing	0.00 F	*- F
6	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
7	1		*FRT RH FENDER	Buckled	0.00 F	*- F
8	1		*FRT RH FENDER INNER SHIELD	* Check	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >