

22/03/2002

ASS. REC. BY:

REF:

CS3/AIG18016532/Acd3/

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Chin Lee King

of

AIG

Date/Time:

11/9/18 @ 10:52am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 1083K

Insured:

SKM8108Y

at Workshop m/s

A- Tec Automotive

Tel:

6384 5206

of

8 Kalki Bkt Ave 4 # 05-27

Policy No:

2100354924

Claim No:

101307018186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/9/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:47am @ 11/9/18

Person Contacted:

peggye

Vehicle

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SJR 1033K - CC6 / Ax A 17063970 / Ueb3q2

DOA: 21/02/17

SKM 8108Y - CC3 / AIG 18001727 / Kwb3q2

DOA: 25/01/2018

Dismantle: 12/9/2018

After repair: 20/9/2018

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJR1033K Yr Regn: 2009 JneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591Colour: Black A/C: Insured / Std / NI / NASp. Reading: 177960 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH 2441BR 94771678Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/09/18Survey held at A-TecDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TPALG PRS.MV : 11.51c.
PV : 6.51c
Nett : 51c.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 180

Transportation: _____

S + RS. \$ _____

Photos _____

Others 20

TOTAL

207Report Format: DAR

Lump Sum / L.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016532/Acd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-09-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKM 8108Y	Veh. Inspected	SJR 1033K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	11/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/09/2018	Inspection Date	11/09/2018
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 11/9/2018 10:52:18 AM
Attachments:  [20180910152110175.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJR 1033K (wk)

Your Ref : To be advised

10 September 2018

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : DREAM CARZ LEASING P/L
ACCIDENT INVOLVING SJR 1033K & SKM 8108Y ALONG EU TONG SEN
STREET ON 9 SEPTEMBER 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Dream Carz Leasing P/L, the owner of motor vehicle no. SJR 1033K which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKM 8108Y for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	A-TEC Automotive Pte Ltd
Address	8 Kaki Bukit Avenue 4 #05 - 27 Premier Singapore 415875
Contact Person	Ms. Peggie (6384 5206)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

M/s Chia S Arul LLC
Page 2

Our Ref : SJR 1033K (wk)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

Enquire Vehicle & Owner Information (Vehicle No. SKM8108Y As At 09 Sep 2018 / 15:35:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SJR1033K

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S1812813F
Owner Name: CHAN SIEW HIANG
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 15
Registered Street Name: WEST COAST WALK
Registered Unit No.: # 21 - 28
Registered Building Name: -
Registered Postal Code: 127162

Current Vehicle Details

Vehicle No.: SKM8108Y
Make Description/Model: JAGUAR / XF 2.0L GTDI
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3037R
Vehicle Details	
Vehicle No.:	SJR1033K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U661943
Chassis No.:	KMH DU41BR9U771678
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,263.00
Original Registration Date:	09 Jun 2009
First Registration Date:	09 Jun 2009
Transfer Count:	3
Actual ARF Paid:	\$11,263.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2019
PARF Rebate Amount:	\$5,631.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$11,690.00
COE Rebate Amount:	\$868.00
Total Rebate Amount:	\$6,499.00

The information contained herein is correct as at 11 Sep 2018

OK

- Hyundai i30N
- Cannot invest CPF SA anymore ?
- Camry Tailgate for free parking



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad
  Advertiser Login
  Ways of Selling



Mercedes Benz S350L (COE till 02/2027). WelKept

Full Maintenance By Cycle & Carriage. Low Mileage Done. New Road Tax Till Feb 2019



Shine Connect StarAd











Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SVTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category 
 Save Search
  Print
 « Back (1 2) Next »
 Sort by Date Posted 
 20 results/page 

40 vehicles
 Search
 Advanced Search  Search 

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status 

Search Selection	Avante	Any	Any	2009	Any	Any	Any	Available
------------------	--------	-----	-----	------	-----	-----	-----	-----------



☐ **Hyundai Avante 1.6M (New 5-yr COE)**
\$27,800
\$5,560 /yr
30-Apr-2009
1,591 cc
-
Sedan
Available

New 5 Years COE, Engine In Tip Top Conditions, Test Drive To Believe, Accident Free, Low Down Payment, Hurry, Call Now To Arrange For A Viewing.

 Posted: 08-Aug-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ **Hyundai Avante 1.6A**
\$11,800
\$9,110 /yr
13-May-2009
1,591 cc
170,000 km
Sedan
Available

2 Owner Car. Best Buy For Short Term Drive! New Car Paintwork, 6 Months Engine Gearbox Warranty, Excellent Condition, Low Fuel Consumption, Low Insurance Premium, Low Maintenance, Bank And In-House Lo...

 Posted: 01-Sep-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ **Hyundai Avante 1.6A S**
\$10,800
\$7,610 /yr
13-May-2009
1,591 cc
153,000 km
Sedan
Available

1 Owner Very Well Kept. Road Tax 11/2018, Monthly Only \$460 Depreciation, Guarantee Buy Back At \$6500 Upon Expire, Economical Car Great For Daily Usage, Car Still Look Presentable Despite Its Age, Pri...

 Posted: 11-Aug-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ **Hyundai Avante 1.6A S**
\$11,380
\$8,410 /yr
15-May-2009
1,591 cc
-
Sedan
Available

AA Trust Certified Quality Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner! Low Maintenance, Low Fuel Consumption! Good For Short Term Drive! Smooth, Responsive Engine And Gearbox Perfo...

AA Trust Automotive

 Posted: 31-Aug-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Car Buying ▶



Car Selling ▶



Car Ownership ▶



Car Aftermarket ▶



On The Move ▶




Lifestyle ▶



☐ **Hyundai Avante 1.6A RS Sunroof**
\$11,000
\$6,890 /yr
12-Jun-2009
1,591 cc
198,313 km
Sedan
Available

Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

Carro

 Posted: 10-Sep-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ **Hyundai Avante 1.6A S**
\$12,822
\$9,310 /yr
20-Jun-2009
1,591 cc
86,000 km
Sedan
Available

 Posted: 07-Sep-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ **Hyundai Avante 1.6A S**
\$13,151
\$9,670 /yr
22-Jun-2009
1,591 cc
146,000 km
Sedan
Available

Superb Condition Inside/Out. Best Value For Money Sedan, Cheaper Den Car Rental, Easy To Handle And Low Maintenance. Most Suitable For Your Daily Usage, Great For Short Term Use And Ideally For Future...

Dosh Car

 Posted: 18-Jul-2018
 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

SHORTLISTED  HISTORY
 Compare 

☐ **Hyundai Avante 1.6A**
\$12,000
\$8,160 /yr
23-Jun-2009
1,591 cc
123,800 km
Sedan
Available



Nice Paintwork. See To Believe, Spacious Sedan, Low Maintenance Cost, Very Well Maintained. Newly Fitted Enkel Rims With 3 Months Old Full Set Of XM2 Tyres. New Rear Coil Overs And Alrcon Compressor. ...

DIRECT OWNER

☆ Posted: 26-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A \$11,600 \$8,280 /yr 23-Jun-2009 1,591 cc 150,000 km Sedan Available

Very Good Running Condition. Fuel Efficient And Reliable 1.6L DOHC VVT Engine. Smooth And Responsive. Ideal For Short Term Or COE Extension. Near Flawless Body/Paintwork With Nice Shine. Value For Mon...

☆ Posted: 11-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A S \$12,900 \$8,780 /yr 13-Jul-2009 1,591 cc - Sedan Available

Consignment Unit! Flexible Repayment With In House Financing! A Stylish Sedan Yet It Is Very Reliable And Responsive Plus Good Fuel Consumption, Promise To Give You An Enjoyable Ride, Low Depre And Ch...

Quality Motor Trading Enterprise

☆ Posted: 06-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Lease a car for peace of mind

No worries over hefty repair costs and depreciation with leasing. Find the list of recommended car leasing companies now.

Find out more!



☐ Hyundai Avante 1.6A \$13,800 \$9,420 /yr 24-Jul-2009 1,591 cc 260,000 km Sedan Available

VICOM Inspection Passed On 23 July. Road Tax Renewed Till Jan 2019. PARF \$5667.

DIRECT OWNER

☆ Posted: 27-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A Sunroof \$13,800 \$9,110 /yr 28-Jul-2009 1,591 cc 118,000 km Sedan Available

Nice&Cheap Lady Driver Owner, Very Good Condition, You Can Know How Good Is It When Test Drive! Well Maintain Interior&Exterior, 1.99% Bank Loan Available For This Mth Purchase, No Initial Advance Ins...

DIRECT OWNER

☆ Posted: 06-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A \$14,998 \$10,640 /yr 29-Jul-2009 1,591 cc - Sedan Available

1 Careful Owner, Beautiful Silver. 100% Accident Free. Very Spacious And Big Boot Space. Ideal For Those Who Fancy Spacious And Comfort Interior Yet Powerful Drive! View To Believe! Down Payment \$2,99...

☆ Posted: 01-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A S (OPC) \$27,800 \$5,560 /yr 13-Aug-2009 1,591 cc 119,000 km Sedan Available

New Arrival, Only 1 Owner, Very Well Maintained, Clean Interiors, Original Paint With Black Leather Interiors, High Loans Available With \$3k Down Payment Trade In Are Welcome, Call Us Now.

☆ Posted: 10-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A S \$12,300 \$7,320 /yr 13-Aug-2009 1,591 cc 138,608 km Sedan Available

\$2777 Down Payment Available, Low Mileage, Powerful Engine, Smooth Auto Transmission, Flexible Loans With Low Interest Rates, Trade In Welcome.

☆ Posted: 05-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A (OPC) \$11,800 \$6,880 /yr 29-Sep-2009 1,591 cc 72,327 km Sedan Available

(New 5 Years COE At \$29800) 1 Owner Only. Good For COE Renewal.

☆ Posted: 09-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A S (OPC) \$12,800 \$6,730 /yr 20-Oct-2009 1,591 cc 98,000 km Sedan Available

Best Buy For Short Term Drive! Original Condition. Excellent Exterior And Interior Condition. Trade In All Available, Low Fuel Consumption,, Please Call To Make An Appointment To View The Vehicle.

☆ Posted: 09-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



☐ Hyundai Avante 1.6A S \$14,500 \$7,820 /yr 27-Oct-2009 1,591 cc 23,400 km Sedan Available

1 Owner Lady Owner, Paintwork Since Day 1, And Yes Mileage Just 23,000Km. Where To Find Such Low Mileage, Good For COE Renewal. Accident Free. Very Well Maintained, Service Promptly, Healthy Engine, S...

☆ Posted: 25-Aug-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

SHORTLISTED HISTORY

Compare

☐ Hyundai Avante 1.6M \$13,800 \$8,090 /yr 27-Oct-2009 1,591 cc 130,000 km Sedan Available

CONSIGNMENT

Low Mileage! Beautiful Silver Sedan! Selling Due To Upgrading! Good Condition, Well Taken Care And Maintained By Owner, Road Tax Until November. Good For COE Renewal/Short Term Usage! Consignment Unit...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 15:55
Date Of Accident	09/09/2018 15:35
Exact Location Of Accident	EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR1033K
Insured/Policyholder	
Name Of Registered Owner	DREAM CARZ LEASING PTE LTD
Co Reg No	20143303R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63845206

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098642708
Cover Note Number	

Driver

Name of Driver	LOH JUN LYNN
NRIC No	S8370462D
Date Of Birth	19/12/1983
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98509051
Fax Number	
Contact Number	
EEmail Address	NOEMAIL



Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJR1033K

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN

En Tung Sen Street



① SJR/033K

② SKM808Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along En Tung Sen Street. While vehicle in front stop, I also stopped in time and stationary. Suddenly vehicle B came from behind and hit into the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

10 SEP 2018

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)

23 KAKI BUKIT AVE 4

Reporting Centre Singapore 5933

Name: Tel: 67416697

NRIC/FIN No.: Fax: 67492305

Email: vackb@singnet.com.sg

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRA ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC ✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	BT ✓		
1150	992970	Rear Bumper Beam	BR ✓		
1151	993077	Rear Bumper Sponge	BR ✓		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT ✓		
1159	993327	Rear End Panel	DD ✓		
1160	993339	Rear End Panel Top Garnish	DE ✓		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR ✓		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD ✓		
1166	995116	Rear RH Taillamp	CRA ✓		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD ✓		
1171	991328	Bootlid Emblem	NEC ✓	3	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	BR ✓		
1176	992899	Bootlid Lamp RH	BR ✓		
1177	995243	Bootlid Lock	BT ✓		
1178	990377	Bootlid Rubber	CUT ✓		
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJR 1033K

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	DD	R	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 16

Assessor: _____

TGLim

25/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018 Edit Reg		11 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Chan Siew Hiang, ID: S1812813F

Main Claimant:

-

Vehicle Reg. No.:

SJR1033K

Date of Loss:

09/09/2018 15:00 - :59
[111 Months From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1013070181SG

Policy/Cover Note No.:

2100354924 (Comprehensive)

Vehicle Reg. No. (Insured):

SKM8108Y

Policy No. (Claimant):

Excess:

Repairer:

A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/09/2018]

Claimant's Solicitor:

CHIA S ARUL & LLC - Tel: 67334647

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (12/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR1033K (1013070181SG)**
[SKM8108Y]












































TP

-
Sep 9 2018 3:00PM

[Chan Siew Hiang]

A-Tec Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			<div></div>
Assessment Reports															1 per page			<div></div>	<div></div>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print			
1	12/09/18 13:46		Accident Statement From:OD - Reg. No: SKM8108Y, Claimant: CHAN SIEW HIANG												<div></div> Load HTM						
Photos/Images															3 per page			<div></div>	<div></div>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
2	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
3	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
4	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
5	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
6	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
7	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
8	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
9	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
10	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
11	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
12	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
13	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
14	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
15	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
16	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
17	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
18	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
19	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
20	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
21	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
22	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
23	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
24	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
25	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
26	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
27	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
28	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
29	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
30	24/09/18 19:14		General View												<div></div> Load JPG			<div></div>			
31	24/09/18 19:15		Photographs of Damaged Parts												<div></div> Load JPG			<div></div>			
32	24/09/18 19:15		Photographs of Damaged Parts												<div></div> Load JPG			<div></div>			
33	24/09/18 19:15		Photographs of Damaged Parts												<div></div> Load JPG			<div></div>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/18 19:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	24/09/18 19:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
86	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
87	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
88	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
89	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
90	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
91	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
92	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
93	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
94	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
95	24/09/18 19:15	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016532/ACD3E2

Date: 27/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100354924

Claimant Vehicle No : SJR1033K

Insured Vehicle No : SKM8108Y

Date of Loss: 09/09/2018

Nature of Claim:

TP

Claim No: 1013070181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR1033K**

Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)

Engine No: G4FC9U661943

Reg. Date: 09/06/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U771678

Colour: Black

Odometer: 177960 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/09/2018

Date Inspected: 11/09/2018 Inspected At:

A-Tec Automotive Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4 # 05-27 Premier
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*REAR BUMPER BEAM	Broken	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Dented	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
10	1		*REAR LH TAILLAMP PANEL	Dented	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*BOOTLID	Dented	0.00 F	*- F
13	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID LAMP LH	Broken	0.00 F	*- F
15	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

 10 SEP 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Report to the Police
Name: Singapore 415933
NRIC/FIN No: 67416697
Tel: 67492305
Fax: 67492305
Email: vackb@singnet.com.sg

Address	8 KAKI BUKIT AVENUE 4 #05-27 PREMIER @ KAKI BUKIT
Postcode	415875
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM8108Y
Vehicle Make/Model/Colour	JAGUAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE ENG SENG
NRIC/Passport Number	S1732888C
Contact Number	93865468
Address	15 WEST COAST WALK #2128
Postcode	127162
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LOH JUN LYNN
------	--------------