

ASS. REC. BY:

REF: CS/FCI18016545/KV d3/n2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

AWS

From (Person): Kelvin Tan of FCI Date/Time: 11/9/18 @ 2:28pm

Estimated Cost: Bill to:

OD (IP) WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No: SLG 19381 Insured: SHC 1926L

at Workshop m/s Cheng Hoe Motor Tel: 6755 6142

of BIK 1019, Yishun Ind. Park A # 01-374

Policy No: Claim No: D18065108MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 28/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement:

Date/Time: 3:07pm @ 11/9/18 Person Contacted: Elfeeda Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLG 19381 - CC4/III 18016303/pa3	DOA: 3/9/2018
	SHC 1926L - CS/FCI 13023780/M14m3u2	DOA: 13/12/2013
17/9/18	Email preli revised to FCI	
18/12	8827.28 Confirm Tune. (Red 20, 21)	

ASS. REC. BY:

REF:

F07/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

19 File pass to Catherine

Veh No:

SLG 1938J

Yr Regn:

09, 16

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Loy A1.5

c.c

1598

Colour:

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

92933

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH10455668

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Mxer 205/55R16

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

25/6/18

D.O.I.

12/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

1st window mirror.

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 DEC 2018

19/12/2018

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 19/12 - typist

Days Of Repair:

1

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

90

50

50

12

202

Report Format :

CWS

Lump Sum / I.B.I. (\$

957.28



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005108MFSH

Our ref: CS/FCI18016545/Kvd3

Date : 17/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 1938J


We thank for your instruction on 11/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/9/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$947.28
Revised Estimate Amount	: S\$927.28
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s door mirror.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-06-2018	Our Ref No. D18005108MFSH
Accident Date	25-06-2018	Claim Type. Third Party
Insured Vehicle	SHC1926L	Third Party Vehicle. SLG1938J
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 17 September 2018 2:24 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005108MFSH/1, SLG 1938J
Attachments: SLG 1938J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLG 1938J
Date of survey: 12/9/2018
Number of days : 1 day

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 11 September 2018 3:09 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005108MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 11 September 2018 2:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005108MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4358B
Vehicle Details	
Vehicle No.:	SLG1938J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	1ZRY328339
Chassis No.:	MR053REH104556696
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	23 Sep 2016
First Registration Date:	23 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2026
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$41,476.00
Total Rebate Amount:	\$54,962.00

The information contained herein is correct as at 03 Sep 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLG1938J

TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1891052/YISHUN

Date: 12 Sep 2018

Policy No: 5094394014

Veh Reg No: SLG1938J

Make/Model: TOYOTA TOYOTA
COROLLA ALTIS
CLASSIC 1.6CVT

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 25/06/2018

TP Veh Reg No: SHC1926L

Chassis No: MR053REH104556696

Engine No: 1ZRY328339

Reg. Date: 23/09/2016

Estimate Repair Cost to Vehicle No :SLG1938J

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 RH SIDE MIRROR	1,089.70	1 PC CM	1,089.70	✓
			1,089.70	
		Less 25%	272.43	817.28
Labour				
2 REMOE & REFIX FRT RH SIDE MIRROR & CHECK SYSTEM	50.00	1 LA	50.00	✓
3 PUTTY & RESPRAY ON FRT RH SIDE MIRROR	80.00	1 LA	80.00	6d
			130.00	130.00
Total				S\$ 947.28
Add GST @ 7%				66.31
Total Amount Payable				S\$ 1,013.59

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016545/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1926L	Veh. Inspected	SLG 1938J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005108MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	11/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104556696	Colour	METALLIC RED	
Odometer	92933	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	5 mm	
L/H Front Tyre	205/55 R16	NEXEN	5 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2018	Inspection Date	12/09/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 1938J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	CRACKED		
	RH SIDE MIRROR		1,089.70	1,089.70
	LESS 25% DISCOUNT		-272.42	-272.42
			817.28	817.28
	LABOUR			
	REMOVE & REFIX FRT RH SIDE MIRROR & CHECK FUNCTION.		50.00	50.00
	PUTTY & RESPRAY ON FRT RH SIDE MIRROR.		80.00	60.00
			130.00	110.00
GRAND TOTAL			947.28	927.28
RECOMMENDED COST OF REPAIRS				927.28

Report Ref No. CS/FCI18016545/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.