

Surveyor

Xarl

REF: LPC

16546 / 61407 - 04331

ASSIGNMENT

From: Date: 04.10.2018

Estimated Cost:

OD ☒ TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJE 1852G

at Workshop m/s

of

Kong Auto
160 Sin Ming Drive #02-16

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJE1852G

Yr Regn: 27 Feb 2015

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 6

C.C

1998

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

94892

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6GJ107 / F-0144465

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

04-10-18

Survey held at

w/s

2:40pm

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Total \$1850

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

___ \$ + RS. ___ SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / t.B.I.: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2133I
Vehicle Details	
Vehicle No.:	SJE1852G
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	PE20565780
Chassis No.:	JM6GJ1071F0144465
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$18,190.00
Original Registration Date:	27 Feb 2015
First Registration Date:	27 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$8,190.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2025
PARF Rebate Amount:	\$6,142.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$42,692.00
Total Rebate Amount:	\$48,834.00

The information contained herein is correct as at 05 Oct 2018

OK