

Sponsor:

XGQ

DOI:

ASSIGNMENT

04/10/18

Date / Time:

10/9/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II : S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

17/10/18/UP 05/020815

21XVP05015490

Suzuki

BLK 320 Juvy Curt ST 31

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJE 18526



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kang Auto.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

n/a

SJE 18526 - CA/AG/1001408/r ; OGA: 21/1/11
SJE 163954 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

03/10/18

- PUB REVIEWED. OIMOUED OUT WHEN HIT TP.

- BUILT LIABILITY CLIMATE

- FINANCIAL

- ORIGINAL TP LOD IN

04/12/18

- TYPE REPORT FOR WANDPES APPROVAL

- REPORT DONE

22/12/18

- GIVE WANDPES APPROVAL TO UPC BY BUILT

26/12/18

- LPC APPROVED WANDPES

18/01/19

- SEND 1ST OFFER TO TP.

28/01/19

- OKIS. BY M. TP ACCEPTED OFFER.

- ALL DOC IN ORDER.

- TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

03/10/18

Sent By:

AS

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L6

S\$

1,800.00

4 days

Reduction:

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

28/01/19

Confirm with:

Confirm by:

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

1,800.00

(OI NOVED OPT)

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

400.00

(\$100 x 4 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.15

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4480.00

Total:

S\$

2,257.15

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Email ☐ Call ☐

Payee 1:

S\$

2,257.15

Name 1:

KANG

AUTO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

Signature

Xarl

REF: LPC

16546 / 61407 - @2433i

ASSIGNMENT

From: _____ Date: **04-10-2018**
 Estimated Cost: _____
 QD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJE 1852G**
 at Workshop m/s: **Kong Auto**
 of: **160 Sin Ming Drive #02-16**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

☒ N/S	☐ O/S
☐	☐

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **4** days Res: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SJE1852G** Yr Regn: **27 Feb 2015**
 Type: ☒ M / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mazda 6** C.C: **1998**
 Colour: **Blue** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **94892** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **JM6GJ1071F-0144465**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: **Nil / S/Rim / STD A/Rim or**
 Tyre Size: F: **225 / 55 R17**
 R: **"**
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIS / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: _____ D.O.I: **04-10-18**
 Survey held at: **w/s** **2:40pm**
 Des. of Damages: **Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or**
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Total \$1850
	CRP: \$3,257.28 (63%)

Date/Time: File Pass to?	☐ : Preli. Report	Days Of Repair:	Survey Fee:
1)	☐ : Final Report	Resurvey No. of Trip:	Transportation:
Date/Time: File Return to?			) \$ + R\$ \$
2)			) Photos
Report Format:	Add Fee: ☐ : Site Insp. (\$		) Others
Lump Sum / t.B.I: (\$	☐ : Interview (\$		)
	☐ : Tech. Invs (\$		
	☐ : Weekend (\$		
		TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2133I

Vehicle Details

Vehicle No.:	SJE1852G
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	PE20565780
Chassis No.:	JM6GJ1071F0144465
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$18,190.00
Original Registration Date:	27 Feb 2015
First Registration Date:	27 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$8,190.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2025
PARF Rebate Amount:	\$6,142.00

Intended COE Rebate Details

COE Expiry Date:	26 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$42,692.00
Total Rebate Amount:	\$48,834.00

The information contained herein is correct as at 05 Oct 2018

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020815
Our ref: CC4/LPC18016546/Gha3

Date: 05/10/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJE 1852G

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.10.2018 at the premises of M/s Kang Auto Engineering Pte Ltd - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	5,107.28
Revised Estimate Amount	: S\$	2,319.20
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,319.20

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg



M/S ONG CHIN SHENG
BLK319 JURONG EAST
STREET.31, #12-52
SINGAPORE 600319

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/09/1121
VEHICLE NO : SJE1852G
MAKE/MODEL : MADAZ 6
DATE OF ACCIDENT : 04.08.18

1 PC	REAR BUMPER	X Repair	607.55	X
1 SET	REAR BUMPER CLIPS	/ REC	13.50	/
1 PC	REAR BUMPER LH RETAINER	X NN	16.05	X
1 PC	REAR R/H FENDER	X Repair	661.20	X
1 PC	REAR R/H FENDER INNER SHIELD	X NN	64.80	X
1 PC	PETROL COVER	X NN	89.00	X
1 PC	REAR LH DOOR	/ BUC	1210.50	/
1 PC	REAR LH DOOR REGULATOR	X	569.00	X
1 PC	REAR LH DOOR COVER	X NN	205.00	X
1 SET	REAR LH DOOR HINGES	X	85.00	X
1 SET	REAR DOOR STONE GUARD	/ SCR	50.00	/
			S\$ 3571.60	1274
			LESS 20%	714.32
			S\$ 2857.28	1019.2
TO CHECK WIRING			S\$ 50.00	X NN
TO TRANSFER NEW DOOR			120.00	60
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL			80.00	40
TO PUTTY & SPRAY PAINT ON DAMAGE PARTS			1200.00	800
LABOUR CHARGE			800.00	400
			S\$ 5107.28	1340

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

YOURS FAITHFULLY

Acknowledged by Repairer
Signature: _____
Date: _____

KANG AUTO ENGINEERING PTE LTD

SGD FIVE THOUSAND ONE HUNDRED SEVEN AND CENTS TWENTY-EIGHTY ONLY.

Chang.
Unpaid repair
After repair photos.
Gue Qiang - 82880282
04/10/18.

2319.2
20%: 1850

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

ONG LI LI

From: ONG LI LI
Sent: Monday, 10 September, 2018 9:59 AM
To: JOSELINE CHIA; MT_Claim_SG; assignments@lkkauto.com; catherine
Cc: kangauto@singnet.com.sg
Subject: RE: Accident involving SJE1852G & SJT6395Y Our Ref: 17/18/18/VP05/020815
Attachments: Photo 4-8-18, 2 10 22 PM.JPG

2:44pm @ 10/09/18
vehicle not in
possession @ Brene

Without Prejudice

Dear May

Please liaise with LKK Auto Consultants Pte Ltd for quantum(survey) & liability.

Dear Catherine/Nivitha

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555 Tel : (65) 6250 7388 Ext. 254
Fax: (65) 6296 2706

-----Original Message-----

From: JOSELINE CHIA
Sent: Monday, 10 September, 2018 9:43 AM
To: MT_Claim_SG
Cc: kangauto@singnet.com.sg
Subject: Accident involving SJE1852G & SJT6395Y

Dear Li Li and Gerald

For your action.

Claims Status

☒ Yes - Completed
☐ No - Reason/s:

Officer:

Date:

Best Regards
Joseline Chia
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext. 257 | Fax: (65) 6296 2706

-----Original Message-----

From: kangauto [<mailto:kangauto@singnet.com.sg>]
Sent: Tuesday, 4 September, 2018 11:59 AM
To: JOSELINE CHIA
Cc: JOSELINE CHIA
Subject: Accident involving SJE1852G & SJT6395Y

>Motor Claims Dept

>

>Your Insured : SJT6395Y

>Our Insured : SJE1852G

GERALD POH WEE BIN

From: ONG LI LI
Sent: Monday, 10 September, 2018 10:00 AM
To: assignments@lkkauto.com; catherine
Cc: MT_Claim_SG
Subject: FW: 2nd -Accident involving SJE1852G & SJT6395Y Our Ref: 17/18/18/VP05/020815
Attachments: Accident Report.pdf; Accident Report Final.pdf

Dear Nivitha/Catherine

Part 2 of earlier email for your action.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 Tel : (65) 6250 7388 Ext. 254

Fax: (65) 6296 2706

-----Original Message-----

From: JOSELINE CHIA
Sent: Monday, 10 September, 2018 9:44 AM
To: MT_Claim_SG
Cc: kangauto@singnet.com.sg
Subject: FW: 2nd -Accident involving SJE1852G & SJT6395Y

Dear Li Li and Gerald

For your action.

Best Regards

Joseline Chia

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext. 257 | Fax: (65) 6296 2706

-----Original Message-----

From: kangauto [mailto:kangauto@singnet.com.sg]
Sent: Tuesday, 4 September, 2018 12:00 PM
To: JOSELINE CHIA
Cc: JOSELINE CHIA; JOSELINE CHIA
Subject: 2nd -Accident involving SJE1852G & SJT6395Y

>-----Original Message-----

>From : kangauto@singnet.com.sg
>Date : 04/09/2018 - 11:59 GMT+8
>To : JOSELINECHIA@lonpac.com
>Cc : JOSELINECHIA@lonpac.com
>Subject : Accident involving SJE1852G & SJT6395Y
>
>>Motor Claims Dept
>>
>>Your Insured : SJT6395Y
>>Our Insured : SJE1852G
>>
>>Date of Accident : 04/8/2018

GERALD POH WEE BIN

From: ONG LI LI
Sent: Monday, 10 September, 2018 9:59 AM
To: JOSELINE CHIA; MT_Claim_SG; assignments@lkkauto.com; catherine
Cc: kangauto@singnet.com.sg
Subject: RE: Accident involving SJE1852G & SJT6395Y Our Ref: 17/18/VP05/020815
Attachments: Photo 4-8-18, 2 10 22 PM.JPG

Without Prejudice

Dear May

Please liaise with LKK Auto Consultants Pte Ltd for quantum(survey) & liability.

Dear Catherine/Nivitha

fya

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555 Tel : (65) 6250 7388 Ext. 254
Fax: (65) 6296 2706

-----Original Message-----

From: JOSELINE CHIA
Sent: Monday, 10 September, 2018 9:43 AM
To: MT_Claim_SG
Cc: kangauto@singnet.com.sg
Subject: Accident involving SJE1852G & SJT6395Y

Dear Li Li and Gerald

For your action.

Best Regards

Josephine Chia

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext. 257 | Fax: (65) 6296 2706

-----Original Message-----

From: kangauto [mailto:kangauto@singnet.com.sg]
Sent: Tuesday, 4 September, 2018 11:59 AM
To: JOSELINE CHIA
Cc: JOSELINE CHIA
Subject: Accident involving SJE1852G & SJT6395Y

>Motor Claims Dept

>

>Your Insured : SJT6395Y

>Our Insured : SJE1852G

>

>Date of Accident : 04/8/2018

>Location : Carpark roundabout of B/320 Jurong East St.31

>

>Please find attached report, scene photos for your reference.

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 11 September, 2018 4:19 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: 2nd -Accident involving SJE1852G & SJE6395Y Our Ref: 17/18/18/VP05/020815
Attachments: 11092018161511.pdf

Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

-----Original Message-----

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 11 September, 2018 3:39 PM
To: ONG LI LI
Cc: MT_Claim_SG; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: 2nd -Accident involving SJE1852G & SJE6395Y Our Ref: 17/18/18/VP05/020815

LPC ref: 17/18/18/VP05/020815
LKK REF: CC4/LPC18016546/ha3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)

To: JOSELINE CHIA
Cc: JOSELINE CHIA; JOSELINE CHIA
Subject: 2nd -Accident involving SJE1852G & SJT6395Y

>----Original Message----

>From : kangauto@singnet.com.sg
>Date : 04/09/2018 - 11:59 GMT+8
>To : JOSELINECHIA@lonpac.com
>Cc : JOSELINECHIA@lonpac.com
>Subject : Accident involving SJE1852G & SJT6395Y

>

>>Motor Claims Dept

>>

>>Your Insured : SJT6395Y

>>Our Insured : SJE1852G

>>

>>Date of Accident : 04/8/2018

>>Location : Carpark roundabout of B/320 Jurong East St.31

>>

>>Please find attached report, scene photos for your reference.

>>

>>Please assist reply on claim officer in-charge.

>>Please revert liability on this claim.

>>

>>Car not in.

>>

>>Yours Sincerely,

>>May Ang

>

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 10 September, 2018 9:59 AM
To: JOSELINE CHIA; MT_Claim_SG; assignments@lkkauto.com; catherine
Cc: kangauto@singnet.com.sg
Subject: RE: Accident involving SJE1852G & SJT6395Y Our Ref: 17/18/18/VP05/020815
Attachments: Photo 4-8-18, 2 10 22 PM.JPG

Without Prejudice

Dear May

Please liaise with LKK Auto Consultants Pte Ltd for quantum(survey) & liability.

Dear Catherine/Nivitha

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555 Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: JOSELINE CHIA
Sent: Monday, 10 September, 2018 9:43 AM
To: MT_Claim_SG
Cc: kangauto@singnet.com.sg
Subject: Accident involving SJE1852G & SJT6395Y

Dear Li Li and Gerald

For your action.

Best Regards
Joseline Chia
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext. 257 | Fax: (65) 6296 2706

-----Original Message-----

From: kangauto [mailto:kangauto@singnet.com.sg]
Sent: Tuesday, 4 September, 2018 11:59 AM
To: JOSELINE CHIA
Cc: JOSELINE CHIA
Subject: Accident involving SJE1852G & SJT6395Y

>Motor Claims Dept

>

>Your Insured : SJT6395Y

>Our Insured : SJE1852G

>

may Any (check liability)
6556 0103
11.09.2018 @ 9:27am
ven not in.

>Date of Accident : 04/8/2018
>Location : Carpark roundabout of B/320 Jurong East St.31
>
>Please find attached report, scene photos for your reference.
>
>Please assist reply on claim officer in-charge.
>Please revert liability on this claim.
>
>Car not in.
>
>Yours Sincerely,
>May Ang



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18016546/Gha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 30-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6395Y	Veh. Inspected	SJE 1852G
Policy No.	Z17VP05015490	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020815	Excess (\$)	0.00
Assign From	GERALD	Assign Date	10/09/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6GJ1071F0144465	Colour	BLUE
Odometer	94892	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	MICHELIN	6 mm
L/H Front Tyre	225/55 R17	MICHELIN	6 mm
R/H Rear Tyre	225/55 R17	MICHELIN	6 mm
L/H Rear Tyre	225/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2018	Inspection Date	04/10/2018
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 1852G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	607.55	-
1	SET REAR BUMPER CLIPS	NECESSARY	13.50	13.50
1	REAR BUMPER LH RETAINER	NOT NECESSARY	16.05	-
1	REAR R/H FENDER	TO REPAIR SEE LABOUR	661.20	-
1	REAR R/H FENDER INNER SHIELD	NOT NECESSARY	64.80	-
1	PETROL COVER	NOT NECESSARY	89.00	-
1	REAR LH DOOR	BUCKLED	1,210.50	1,210.50
1	REAR LH DOOR REGULATOR	NOT NECESSARY	569.00	-
1	REAR LH DOOR COVER	NOT NECESSARY	205.00	-
1	SET REAR LH DOOR HINGES	NOT NECESSARY	85.00	-
1	SET REAR DOOR STONE GUARD	SCRATCHED	50.00	50.00
	LESS 20% DISCOUNT		-714.32	-254.80
			2,857.28	1,019.20
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO TRANSFER NEW DOOR .		120.00	60.00
	TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL.		80.00	40.00
	TO PUTTY & SPRAY PAINT ON DAMAGE PARTS.		1,200.00	800.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR R/H FENDER .		800.00	400.00
			2,250.00	1,300.00
	GRAND TOTAL		5,107.28	2,319.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CC4/LPC18016546/Gha3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.