

15/5/2019

INS. CASE OWNER:

CCP/1801

LKK:

IDAC:

Surveyor:

DOE:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

( YES / NO )

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

15622.29

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

1800.00 (\$180 x 10 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

120.00

(e.g. 10w Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

Total:

SS

17549.74

Global Sum SS:

17,500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

17,500.00

Name 1:

Chew Goon Motor

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Chew Goon  
@ singtel.com  
(Att: MNC/Chew)

COPY SENT  
27/4/19

27/4/19

ASS. REC. BY:

REF:

AIG/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Chen Guan

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

1/2

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLZ 2201U

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Alphard

c.c.

Wagon 2493

Colour:

N. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

12286

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AGH 30.0117554

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

7/9/18

D.O.I.

11/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/9

File pass to Carhenge

B 14510.78 email

Confirm 2.B. &gt; B 14600.08 with 7 working days

\* 7 repair days + 1 Sunday + 2 PRS = 10 days.

(Ref: \$ 11295.22  
44.7.)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixt/OS

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR18016557/Kwb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 11-09-2018		
		Code : LCR		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLD 3673A	Veh. Inspected	SLZ 2201U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	07/09/2018	Inspection Date	11/09/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date : 07.09.2018

Not Notified  
Pursuing by 1-B-1  
Pain

7 days  
14574.28 14600.28  
Third Party

Policy No: \_\_\_\_\_

Date: 10.09.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A			
1pc	Headlamp Assy RH		3,090.00 X
1pc	Front Bumper 1655.10		1,856.00 ✓
13pcs	Front Bumper Clips	3.80	49.40 ✓
1pc	Front Fender RH 819.10		1,086.00 ✓
1pc	Front Fender Shield		281.00 ✓
10pcs	Front Fender Shield Clips	3.80	38.00 ✓
1pc	Front Fender Lower Protector		216.00 ✓
4pcs	Front Fender Lower Protector Clips	4.80	19.20 ✓
1pc	Front Fender Lower Protector Core		245.00 ✓
1pc	Front Wheel Rim 800 SN		1,835.60 ✓
1pc	Front Shock Absorber		426.00 ✓
1pc	Front Knuckle Arm		522.00 ✓
1pc	Front Knuckle Arm Bearing		514.00 ✓
1pc	Front Knuckle Arm Bearing Hub		495.00 ✓
1pc	Front Lower Arm		513.00 ✓
1pc	Front Lower Arm Ball Joint		205.00 ✓
1pc	Front Door RH		1,723.00 ✓
1pc	Front Door Sticker (Top)		95.30 ✓
1pc	Front Door Sticker (Side)		119.00 ✓
1pc	Front Door Lower Protector 822.60		1,086.00 ✓
10pcs	Front Door Lower Protector Clips	4.80	48.00 ✓
1pc	Front Door Lower Hinge		91.00 X
1pc	Front Door Rubber Seal (1)		112.00 X
1pc	Front Door Rubber Seal (2)		136.00 X
1pc	Front Door Weatherstrip		362.00 X
1pc	Front Door Trim Board		1,510.00 X
1pc	Front Door Lower Inner Trim		265.00 X
1pc	Rear Door RH		1,650.00 ✓
1pc	Rear Door Lower Protector 822.60		1,160.00 ✓
10pcs	Rear Door Lower Protector Clips	4.80	48.00 ✓
1pc	Rear Door Sticker		207.00 ✓
1pc	Rear Door Vertical Sensor Rubber Seal		1,107.00 ✓
1pc	Rear Door Protector Core		315.00 X
1pc	Rear Door Lower Rubber Seal		147.00 X
1pc	Rear Door Side Rubber Seal		98.00 X
1pc	Rear Door Reflector (Red) Inner		56.00 ✓
1pc	Rear Door Warning Sticker		51.00 ✓
1pc	Rear Fender Lower Protector		240.00 ✓
5pcs	Rear Fender Lower Protector Clips	4.80	24.00 ✓
		C/F	22,041.50

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **10.09.2018**

Accident Date : 07.09.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A			
		B/F	22,041.50
1pc	Rear Bumper <i>1380-40</i>		<i>CM</i> 1,636.00 <i>✓</i>
10pcs	Rear Bumper Clips	3.80	<i>~</i> 38.00 <i>✓</i>
1pc	Rear Bumper Top Retainer RH		<i>BIT</i> 101.00 <i>✓</i>
1pc	Rear Bumper Corner Holder RH		<i>CM</i> 123.00 <i>✓</i>
1pc	Rear Wheel Rim RH		<i>R</i> 1,835.60 <i>X</i>
1pc	Rear Wheel Bearing		<i>~</i> 912.00 <i>✓</i>
1pc	Rear Upper Arm		<i>SL</i> 329.00 <i>✓</i>
1pc	Rear Knuckle Arm		<i>SL</i> 842.00 <i>✓</i>
1pc	Rear Trailing Arm		<i>SL</i> 285.90 <i>✓</i>
1pc	Rear Lower Arm		<i>SL</i> 611.00 <i>✓</i>
1pc	Rear Lower Arm (2)		<i>SL</i> 439.00 <i>✓</i>
			29,194.00
	Less 25%		7,298.50
			21,895.50
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc / Reprogram Headlamp LED		<i>~</i> 250.00 <i>X</i>
	To Dismantle / Transfer 2 x Door Fittings / Ancillary Accessories		300.00 <i>1601</i>
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		250.00 <i>780</i>
	To Dismantle / Replace Rear Wheel Bearing		<i>~</i> 100.00 <i>X</i>
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		<i>~</i> 250.00 <i>X</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 <i>901</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>601</i>
	To Provide Transportation (Towing)		(Bill) 120.00 <i>301</i>
		G/F	23,445.50



# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 10.09.2018

Accident Date : 07.09.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A		
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Door "B" Pillar, O/S Rocker Panel, Rear Fender and Parts Replacement	B/F	23,445.50 950.00
	To Respray Affected Areas		1,500.00
		Total :	<u>25,895.50</u>

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### THIRD PARTY'S DISCHARGE AGREEMENT

Claim ref. : \_\_\_\_\_

To M/s : AIG ASIA PACIFIC INSURANCE PTE LTD

In consideration of your paying at my request to M/S CHEW GOON MOTOR of Blk 10  
Ang Mo Kio Ind. Park 2A, #01-15, 16 & 17, Ave 5, Singapore 568047 the sum of Dollars  
: NINETEEN THOUSAND NINE HUNDRED FORTY NINE AND CENTS SEVENTY FIVE ONLY

(\$ 19,949.75 ) being cost of repair carried out to my/our motor vehicle no :

SLZ2201U All actions, claims and damages arising out of and, in  
consequence of an accident occurring on 07.09.2018

at COLLER QUAY

between SLZ2201U & SLD3673A

I/We furthermore agree that the foregoing sum is voluntarily accepted as full and final  
compromise and settlement of all claims, that the payment of the said amount shall never  
be construed as an admission of liability by the parties hereby reached.

Signature : 



Witness : \_\_\_\_\_



Name : KEVIN BURKE

Name : \_\_\_\_\_

NRIC No. : S27723468

Date : \_\_\_\_\_

Address : 31 St Thomas Walk  
(S) 238141

Date : 25.09.2018

WITHOUT PREJUDICE to:

(a) Insurers' Subrogated Claim and/or

(b) Any Personal Injury Claims

[Note: This Notice supersedes any inconsistencies  
found in this Discharge Voucher]

**TO WHOM IT MAY CONCERN**  
**LETTER OF AUTHORITY**

ACCIDENT ON 07.09.2018 AT COLLYER QUAY  
INVOLVING SLZ2201U & SLD3673A

I, BURKE KEVIN GERARD NRIC No. S2772346B  
OF BLK 353A ADMIRALTY DRIVE #02-294 S751353  
Owner of motor vehicle registration No. SLZ2201U  
insured by MSIG INSURANCE (S) PTE LTD  
under policy no. A80456654QMX do hereby authorise **M/S CHEW GOON MOTOR** of  
**Blk 10 Ang Mo Kio Ind. Park 2A, Ave 5, #01-15, 16 & 17 AMK Autopoint Singapore**  
**568047** as my authorised representative to write, negotiate & settle claim on my behalf in my  
claim against the owner and/or driver of motor vehicle registration no. SLD3673A  
in respect of the above mentioned accident.

I also hereby authorise that the agreed settlement sum be made in favour of my  
representative **M/S CHEW GOON MOTOR** and that the said payment be forwarded to them  
as full and final discharge of my claim. I hereby exonerate the  
AIG ASIA PACIFIC INSURANCE PTE LTD and/or their insured and/or driver of vehicle  
no. SLD3673A from any liability after payment of any claim to my authorised  
representative **M/S CHEW GOON MOTOR**.

Signature :    
(Company's stamp if necessary)

Dated : 25.09.2018

**WITHOUT PREJUDICE to:**  
(a) Insurers' Subrogated Claim and/or  
(b) Any Personal Injury Claims  
[Note: This Notice supersedes any inconsistencies  
found in this Discharge Voucher]



C/O BLK 10 ANG MO KIO IND. PARK 2A  
AVE 5, #01-15, 16 & 17 AMK AUTOPOINT  
SINGAPORE 568047

DATE : 22.12.2018

THE MOTOR CLAIMS DEPARTMENT  
AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120

DEAR SIRs,

ACCIDENT ON : 07.09.2018  
ALONG/AT : COLLYER QUAY  
INVOLVING : SLZ2201U & SLD3673A

---

I/ We /am /are the registered owner of vehicle no. SLZ2201U which was involved  
in the above mentioned accident with your insured vehicle no. SLD3673A.

As the accident was caused due to the gross negligence on the part of your insured driver of  
vehicle no. SLD3673A . I/we have no alternative but to look to you for  
compensation for the losses sustained as a result of the above accident.

Presently, my/ our vehicle is lying at **M/S CHEW GOON MOTOR** of Blk 10, Ang Mo Kio  
Industrial Park 2A, Ave 5, #01-15, 16 & 17 AMK Autopoint, Singapore 568047. Telephone  
6484 1626. Kindly arrange to have it surveyed by your assessor, failing which I / we shall  
authorised my/ our repairer to proceed on with the repairs and the final bills will be  
forwarded to you for settlement.

Thank you.

Yours faithfully

  
\_\_\_\_\_



- Pre repair inspection request - SLZ2201U VS SLD3673A (OI) DOA: 07/09/2018

From: Mithoosingh, Aashweenjeetkaur  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Chan, Yoke Shi, Azlan, Syazairdina  
Sent: 11/9/2018 9:58:56 AM

Hi,

Please refer to the enclosed request from **Chew Goon Motor**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

1.04pm @ 11/9/18  
vehicle in  
person @ Gmlee  
sur @ kemefh.

**From:** Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]

**Sent:** Monday, September 10, 2018 4:39 PM

**To:** Chan, Yoke Shi

**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; chewgoon@singnet.com.sg; Eric

**Subject:** SLZ2201U Claiming Against Your Insured Vehicle No.SLD3673A Acc Date: 07.09.2018

Dear Sir/ Mdm,

Vehicle SLZ2201U is lying at our workshop.

According to your list, we will prefer **LKK Auto Consultants Pte Ltd** to survey the vehicle.

Kindly arrange for survey.

Thanks & Regards,  
Grace

**Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,

Ave 5 #01-15, 16 & 17,

Ang Mo Kio Autopoint

Singapore 568047

Tel : 6484 1626

Fax : 6484 0465

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## View Received Message

This mail is associated with :

**\*SLZ2201U (3327239015SG)**  
**[SLD3673A]**

TP  
BURKE KEVIN GERARD  
Sep 7 2018 12:00AM  
[LCRF Pte Ltd]  
Chew Goon Motor

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 12/09/2018 12:32 PM.  
**To** LKK\_HQ  
**Subject** No OI GIA Report

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

OI name : LCRF Pte Ltd

Address :  
29 Paya Lebar Road  
#01-03 Paya Lebar Office Centre  
Singapore 409005

Thank you.

Regards,  
chan yoke shi

### DOCUMENTS SUMMARY

There are no documents.

## Cecilia Chong (LKK Auto)

---

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Tuesday, 2 April 2019 6:07 PM  
**To:** 'Ivy-VA.Yong@aig.com'  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** Your ref: 3327239015SG (Our ref: CC4/LCR18016557/Kwb3s2) \*\*\* ACCIDENT INVOLVING SLD 3673A & SLZ 2201U ON 07/09/2018

AIG Ref: **3327239015SG**  
LKK Ref: CC4/LCR18016557/Kwbs2

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLD 3673A(OI) AND SLZ 2201U(TP) ON 07/09/2018**

We refer to the above matter.

It is a side swipe collision. Liability is not in our driver's favour.

We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "**Chew Goon Motor**" is as follows: -

	<b>Claimed Amount</b>	<b>Revised Amount</b>
1. Cost of Repair (w/GST)	\$ 25,895.50	\$ 15,622.29
2. Loss of Use (18days x \$240.00)	\$ 4,320.00	\$ 1,200.00 (10days x \$120.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
<b>Total</b>	<b>\$ 30,222.95</b>	<b>\$ 16,829.74</b>

\*\*07days recommendation for repair + 1Sunday + 2PRS = 10days

All the relevant documents had been uploaded in Merimen.

**Kindly let us have your mandate in Merimen.**

Best Regards,

Cecilia Chong | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [CeciliaChong@lkkauto.com](mailto:CeciliaChong@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Cecilia Chong (LKK Auto)

---

**From:** Eric <eric@chewgoonmotor.com.sg>  
**Sent:** Friday, 26 April 2019 11:33 AM  
**To:** Cecilia Chong (LKK Auto)  
**Cc:** Hsiao Tong (LKKAuto); Chew Goon Motor(ad3)  
**Subject:** RE: Your ref: SLZ 2201U (Our ref: CC4/LCR18016557/Kwb3s2) \*\*\* ACCIDENT INVOLVING SLD 3673A & SLZ 2201U ON 07/09/2018 \*\*\*

Dear Cecilia,

We regret to inform that your offer is too low.  
We propose 13 days LOU.

Vehicle is a brand New luxurious Alphard (OMV above 35k, Benchmark rate is \$240/day)  
Our Breakdown of days 13 days

2 days = Weekends (DOA on Friday 07 Sept 18)  
1 day = PRI  
7 days = Repair  
2 days = Weekends (Non working 15/09 and 16/09)  
1 day = Resurvey (19 Sept)

13 days = Total

COR = \$15,622.30 (Including GST)  
LTA = \$ 7.45 (with invoice)  
LOU = \$ 3,120.00 (13 days x \$240)

**Total = \$18,749.75**

Regards  
Eric Chew  
64841626  
Chew Goon Motor

-----Original Message-----

**From:** Cecilia Chong (LKK Auto)  
**Date:** 4/26/2019 10:32:10 AM  
**To:** [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)  
**Cc:** [Hsiao Tong \(LKKAuto\)](#); [Admin A](#)

**Subject:** Your ref: SLZ 2201U (Our ref: CC4/LCR18016557/Kwb3s2) \*\*\* ACCIDENT INVOLVING SLD 3673A & SLZ 2201U ON 07/09/2018 \*\*\*

Your Ref: **SLZ 2201U**

Without Prejudice

Our Ref: CC4/LCR18016557/Kwb3s2

Dear Sirs/Mdm,

**ACCIDENT INVOLVING SLD 3673A & SLZ 2201U ON 07/09/2018**

We refer to the above matter.

We propose settlement at a global sum of **\$16,800.00(all-in)**.

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.


Best Regards,

Cecilia Chong | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [CeciliaChong@lkkauto.com](mailto:CeciliaChong@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*



**FREE Animations for your email - by IncrediMail!**

**Click Here!**





Virus-free. [www.avast.com](http://www.avast.com)

**Vivian Lau (LKKAUTO)**

---

**From:** Vivian Lau (LKKAUTO)  
**Sent:** Wednesday, 19 September, 2018 5:51 PM  
**To:** 'insurance@lioncityrentals.com.sg'  
**Cc:** Hsiao Tong (LKKAUTO); 'Tan, Wilson-KL'  
**Subject:** ACCIDENT INVOLVING SLD 3673A AND SLZ 2201U ON 07/09/2018 (18:20 Hrs)  
ALONG COLLYER QUAY

Our Ref: CC4/LCR18016557/Kwb3

19 September 2018

Dear Sirs,

**ACCIDENT INVOLVING SLD 3673A AND SLZ 2201U ON 07/09/2018 (18:20 Hrs) ALONG COLLYER QUAY**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AIG. Failure to report the accident may affect the standing of your insurance policy.

Kindly proceed to lodge your accident report **immediately**, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

Should you have any clarifications, please contact the undersigned within 7 days from the date of this letter.

Yours faithfully,

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	21/09/2018 12:49
Date Of Accident	07/09/2018 18:20
Exact Location Of Accident	ALONG COLLYER QUAY ROAD
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SLD3673A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE HIRE

**Insurance Company**

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	

**Driver**

Name of Driver	TAN CHOON PHENG
NRIC No	S0161054F
Date Of Birth	19/01/1953
Occupation	OUTDOOR
Date Of Driving Pass	10/03/2005
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Participant's Signature  
Name:  
NRIC/FIN No.:

趙 源 摩 哆  
**Chew Goon Motor**

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)  
Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint  
Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

Date : 22.12.2018

Your Reference : SLD3673A

THE MOTOR CLAIM DEPARTMENT  
AIG ASIA PACIFIC INSURANCE PTE. LTD  
78 Shenton Way  
#07-16  
Singapore 079120

Dear Sir,

ACCIDENT ON : 07.09.2018  
ALONG / AT : Collyer Quay  
INVOLVING : SLZ2201U & SLD3673A

We wish to have a "Direct Settle" to the above matter.

We enclose herewith the following documents for your perusal and attention.

1. Final repair bill for \$15,622.29 (Include GST)
2. Letter of Authority
3. Third Party Discharge Voucher
4. Motor Accident Report made by SLZ2201U
5. Certificate of Insurance
6. Vehicle of Registration Log Card
7. Third Party Insure Enquiry Charges @\$7.45 (SLD3673A)
8. Loss Of Use (18days X \$240/-) @\$4320.00 ( Surveyor Recommend 7D Working + Loss Of Use for 2D Pre-repair Inspec + 6D Weekend) (OMV above \$35K)  
(In 08.09.2018 Out 25.09.2018)

Thank you.  
Yours faithfully

*chew*  
.....

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018 <a href="#">Edit Reg</a>		11 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$14,600.27</b> <a href="#">Edit Estimates</a>	<b>\$14,600.27</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	BURKE KEVIN GERARD, ID: S2772346B		
Vehicle Reg. No.:	SLZ2201U	Date of Loss:	07/09/2018 00:00 - :59 [4 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3327239015SG	Policy/Cover Note No.:	0999994768
Vehicle Reg. No. (Insured):	SLD3673A	Policy No. (Claimant):	A80456654QMX
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Yong, Ivy-AV</b> ] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 20/09/2018]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (09/04/2019): Alert - Adj Mandate Approved (\$16829.74) - SLZ2201U - Claim Handler: Yong, Ivy-...
- AIG\_SG (12/09/2018): Request To Upload TP GIA Report
- AIG\_SG (12/09/2018): No OI GIA Report

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.





## Claim Documents

\*SLZ2201U (3327239015SG)

[SLD3673A]

TP

























BURKE KEVIN GERARD

Sep 7 2018 12:00AM

[LCRF Pte Ltd]

Chew Goon Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Letters/Correspondences															1 per page ▾			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
															3 per page ▾			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
2	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
3	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
4	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
5	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
6	05/04/19 18:14		General View													Load JPG		<input checked="" type="checkbox"/>		
7	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
8	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
9	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
10	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
11	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
12	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
13	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
14	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
15	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
16	05/04/19 18:15		General View													Load JPG		<input checked="" type="checkbox"/>		
17	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
18	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
19	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
20	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
21	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
22	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
23	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
24	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
25	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
26	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
27	05/04/19 18:16		General View													Load JPG		<input checked="" type="checkbox"/>		
28	05/04/19 18:17		Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>		
29	05/04/19 18:17		Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>		
30	05/04/19 18:17		Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>		
31	05/04/19 18:17		Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>		
32	05/04/19 18:17		Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
34	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
35	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
36	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
37	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
38	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
39	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
40	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
41	05/04/19 18:17	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:35	EMAIL FROM AIG DD 11092018	 Load PDF	
2	12/09/18 16:33	TP ESTIMATE- MARKED	 Load PDF	
3	12/09/18 16:33	TP GIA REPORT	 Load PDF	
4	19/09/18 17:51	Email non reporting letter ACCIDENT INVOLVING SLD 3673A AND SLZ 2201U ON 07.09.2018 1820 Hrs ALONG C	 Load PDF	
5	22/01/19 13:59	LETTER TO OI	 Load PDF	
6	22/01/19 13:59	LTA SEARCH	 Load PDF	
7	22/01/19 13:59	TOWING FEE	 Load PDF	
8	29/03/19 16:03	INSPECTION REPORT	 Load PDF	
9	29/03/19 16:03	LOD AND OTHER DOCUMENTS	 Load PDF	
10	22/05/19 09:31	Email letter to oIACCIDENT INVOLVING SLD 3673A and SLZ 2201U on 07.09.2018	 Load PDF	
11	24/05/19 14:25	EMAIL	 Load PDF	
12	24/05/19 14:25	AUTHORISATION TO ACT	 Load PDF	
13	24/05/19 14:25	RELEASE VOUCHER	 Load PDF	
14	24/05/19 14:25	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/09/18 15:27	E-filed GIA report OI GIA	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLD3673A (Insd veh)	Model:	TOYOTA ALPHARD 2.5 S CVT
	SLZ2201U (TP veh)		ABS D/AIRBAG 2WD 5DR (A)
Date of Accident:	07/09/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	27,708.19
Final Repair Cost	:	\$	17,500.00
Loss of Use	:	\$	10.00 days at \$180.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	17,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Chew Goon Motor	:	\$ 17,500.00
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

24 May  
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18016557/KWB3S2  
Date: 24/05/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994768  
Claimant Vehicle No: SLZ2201U Insured Vehicle No: SLD3673A  
Date of Loss: 07/09/2018 Nature of Claim: TP Claim No: 3327239015SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLZ2201U  
Make & Model: TOYOTA ALPHARD, 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: 2ARH898164  
Reg. Date: 24/04/2018 (Man. Year: 2017) Chassis No: AGH300117554  
Colour: Metallic Black Odometer: 12266 km  
Engine Capacity: 2493 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18  
Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm  
Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,895.50	11,790.27	10,105.23	46.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,810.00	1,190.00	29.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,895.50</b>	<b>14,600.27</b>	<b>11,295.23</b>	<b>43.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,812.69</b>	<b>1,022.02</b>	<b>790.67</b>	<b>43.62</b>
<b>Nett Amount (S\$)</b>	<b>27,708.19</b>	<b>15,622.29</b>	<b>12,085.90</b>	<b>43.62</b>
<b>+ Loss of Use (10.0 x S\$180.00/day) (S\$)</b>		1,800.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		120.00		
<b>Nett Liability (S\$)</b>		<b>17,549.74</b>		
<b>Global Sum Settlement (S\$)</b>		<b>17,500.00</b>		

## INSPECTION

Date of Assignment: 11/09/2018  
Date Inspected: 11/09/2018 Inspected At: Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17,  
AMK Autopoint  
Singapore 568047  
Estimated Period of Repair: 7.0 days

---

**Adjuster:** KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$14,600.28

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Serviceable	3,090.00 FL	*-FL
2	1		*FRONT BUMPER	Cracked	1,856.00 FL	*1,655.10 FL
3	13		*FRONT BUMPER CLIPS	Necessary	49.40 FL	*49.40 FL
4	1		*FRONT FENDER RH	Bent	1,086.00 FL	*819.10 FL
5	1		*FRONT FENDER SHIELD	Distorted	281.00 FL	*281.00 FL
6	10		*FRONT FENDER SHIELD CLIPS	Necessary	38.00 FL	*38.00 FL
7	1		*FRONT FENDER LOWER PROTECTOR	Cracked	216.00 FL	*216.00 FL
8	4		*FRONT FENDER LOWER PROTECTOR CLIPS	Necessary	19.20 FL	*19.20 FL
9	1		*FRONT FENDER LOWER PROTECTOR CORE	Dented	245.00 FL	*245.00 FL
10	1		*FRONT SHOCK ABSORBER	Bent	426.00 FL	*426.00 FL
11	1		*FRONT KNUCKLE ARM	Bent	522.00 FL	*522.00 FL
12	1		*FRONT KNUCKLE BEARING	Necessary	514.00 FL	*514.00 FL
13	1		*FRONT KNUCKLE ARM BEARING HUB	Bent	495.00 FL	*495.00 FL
14	1		*FRONT LOWER ARM	Distorted	513.00 FL	*513.00 FL
15	1		*FRONT LOWER ARM BALL JOINT	Bent	205.00 FL	*205.00 FL
16	1		*FRONT DOOR RH	Bent	1,723.00 FL	*1,723.00 FL
17	1		*FRONT DOOR STICKER (TOP)	Necessary	95.30 FL	*95.30 FL
18	1		*FRONT DOOR STICKER (SIDE)	Necessary	119.00 FL	*119.00 FL
19	1		*FRONT DOOR LOWER PROTECTOR	Distorted / Cracked	1,086.00 FL	*822.60 FL
20	10		*FRONT DOOR LOWER PROTECTOR CLIPS	Necessary	48.00 FL	*48.00 FL
21	1		*FRONT DOOR LOWER HINGE	Repair	91.00 FL	*-FL
22	1		*FRONT DOOR RUBBER SEAL (1)	Serviceable	112.00 FL	*-FL
23	1		*FRONT DOOR RUBBER SEAL (2)	Serviceable	136.00 FL	*-FL
24	1		*FRONT DOOR WEATHERSTRIP	Serviceable	362.00 FL	*-FL
25	1		*FRONT DOOR TRIM BOARD	Serviceable	1,510.00 FL	*-FL
26	1		*FRONT DOOR LOWER INNER TRIM	Serviceable	265.00 FL	*-FL
27	1		*REAR DOOR RH	Bent	1,650.00 FL	*1,650.00 FL
28	1		*REAR DOOR LOWER PROTECTOR	Distorted	1,160.00 FL	*822.60 FL
29	10		*REAR DOOR LOWER PROTECTOR CLIPS	Necessary	48.00 FL	*48.00 FL
30	1		*REAR DOOR STICKER	Necessary	207.00 FL	*207.00 FL
31	1		*REAR DOOR VERTICAL SENSOR RUBBER SEAL	Cut	1,107.00 FL	*1,107.00 FL
32	1		*REAR DOOR PROTECTOR CORE	Serviceable	315.00 FL	*-FL
33	1		*REAR DOOR LOWER RUBBER SEAL	Serviceable	147.00 FL	*-FL
34	1		*REAR DOOR SIDE RUBBER SEAL	Serviceable	98.00 FL	*-FL
35	1		*REAR DOOR REFLECTOR (RED) INNER	Necessary	56.00 FL	*56.00 FL
36	1		*REAR DOOR WARNING STICKER	Necessary	51.00 FL	*51.00 FL
37	1		*REAR FENDER LOWER PROTECTOR	Distorted	240.00 FL	*240.00 FL
38	5		*REAR FENDER LOWER PROTECTOR CLIPS	Necessary	24.00 FL	*24.00 FL
39	1		*REAR BUMPER	Cracked	1,636.00 FL	*1,380.40 FL
40	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
41	1		*REAR BUMPER TOP RETAINER RH	Distorted	101.00 FL	*101.00 FL
42	1		*REAR BUMPER CORNER HOLDER RH	Cracked	123.00 FL	*123.00 FL
43	1		*REAR WHEEL RIM RH	Repair	1,835.60 FL	*-FL
44	1		*REAR WHEEL BEARING	Not Necessary	912.00 FL	*-FL
45	1		*REAR UPPER ARM	Serviceable	329.00 FL	*-FL
46	1		*REAR KNUCKLE ARM	Serviceable	842.00 FL	*-FL
47	1		*REAR TRAILING ARM	Serviceable	285.90 FL	*-FL
48	1		*REAR LOWER ARM	Serviceable	611.00 FL	*-FL
49	1		*REAR LOWER ARM (2)	Serviceable	439.00 FL	*-FL
50	1		*FRONT WHEEL RIM	Dented	1,376.70 FS	*800.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	28,735.10	15,453.70
			- List Item Discount on L Items 25.00/25.00% (S\$)		6,839.60	3,663.43
				Total Parts (S\$)	21,895.50	11,790.27

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT FRONT ELECTRICAL CHECK LIGHTING SYSTEM, ADJUST, FOCUS HEADLAMP ETC / REPROGRAM HEADLAMP LED.	New	250.00	0.00
2	TO DISMANTLE / TRANSFER 2 X DOOR FITTINGS / ANCILLARY ACCESSORIES.	New	300.00	160.00
3	TO DISMANTLE / REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR.	New	250.00	180.00
4	TO DISMANTLE / REPLACE REAR WHEEL BEARING.	New	100.00	0.00
5	TO DISMANTLE / REPLACE REAR UNDER CARRIAGE TO FACILITATE REPAIR.	New	250.00	0.00
6	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.	New	200.00	90.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT TEST.	New	80.00	60.00
8	TO PROVIDE TRANSPORTATION (TOWING)	New	120.00	120.00
9	LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT FENDER INNER PANEL, DOOR B PILLAR, O/S ROCKER PANEL, REAR FENDER AND PARTS REPLACEMENT.	New	950.00	800.00
10	TO RESPRAY AFFECTED AREAS.	New	1,500.00	1,400.00
<b>Gross Labour Cost (S\$)</b>			<b>4,000.00</b>	<b>2,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >