



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM18016564/R1es3q2 Date: 17/05/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJF 631D	Veh. Inspected	FU 603D
	Policy No.	GA352842/1	Coverage (\$)	0.00
	Claim No.	S8M00UGM	Excess (\$)	0.00
	Assign From		Assign Date	11/09/2018
2. Vehicle Particulars & Condition				
	Make & Model	KAWASAKI KRR-ZX150	c.c	148
	Engine No.	HIDDEN	Year of Reg.	2001
	Chassis No.	KR150KA54126	Colour	RED
	Odometer	89799 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90 -17	MAXXIS	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	70/90 -17	MAXXIS	3 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/09/2018	Inspection Date	11/09/2018
	Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	