

ASS. REC. BY:

REF: CS/GAI18016577/Rlsd3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kelvyna Ngian of GAI Date/Time: 11/9/18 @ 4:40pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHD 3693P Insured: SJX7787Xat Workshop in/s Comfort Delgro Tel: 6214 8398of 59 Loyang Drive

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh:
(Client's Record)D.O.A. 07/09/1812/09/2018 @ Before 12pm -

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5:07pm @ 11/9/18Person Contacted: Mr. LimVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 3693P - CC3/LCR18009728/Kljg 3y2 DOA: 26/5/18
	SJX 7787X - CS/GAI18001048/Urd 3n2 DOA: 13/02/18
14/09/18	@ 14:32 p.m. revised PN to Kelvyna via email.
20/09/18	Confirmed r/p \$ 300/- @ 2 days with Rasul.
	(\$ 839.04 Red - 74%)

Surveyor

REF:

3821R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 3693Pat Workshop m/s COMFORT BELARUof SS, COYAN DR

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

LM

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 3693P Yr Regn: 2015 / PGB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI 140 1-7L c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 4119.6 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLD41UMF4064570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 1-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WISSTAKEFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 07/09/18 D.O.I. 12/09/18Survey held at COMFORT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 SEP 2018

Date/Time, File Pass to?

1) 22/09/18
Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS. _____ SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____) -

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 300/- P/P)

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 14 September 2018

Our Ref: CS/GAI18016577/R1sd3

The Motor Claims Department
Great American Insurance Company

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 3693P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/09/2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,139.04</u>
Revised Estimate Amount	: S\$ <u>317.60</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 20 September 2018 10:57 AM
To: Lim Tien Siong
Cc: Admin-D (LKKAuto); Admin A
Subject: RE: SHD3693P - Finalize

Hi Lim,

Finalised amount of \$300.00 /2 days part by part confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Lim Tien Siong [mailto:limts@cdge.com.sg]
Sent: Tuesday, 18 September, 2018 12:17 PM
To: Rasul (LKKAuto)
Cc: Admin-D (LKKAuto); Admin A
Subject: Fw: SHD3693P - Finalize

Hi Rasul,

Please expedite. Low amount.
Thanks.

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

From: Lim Tien Siong
Sent: Thursday, 13 September 2018 3:32 PM
To: rasul@lkkauto.com
Cc:
Subject: SHD3693P - Finalize

Hi Rasul,

Finalize at PP \$ 300.00 and 02 repair days.
Rear Bumper Clips - Not Taken.

After paint

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 September 2018 2:32 PM
To: 'Ngian, Kelvyna'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@lkkauto.com
Subject: RE: RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18
Attachments: SHD 3693P - Preli Advise.pdf

Dear Kelvyna,

Enclosed herewith preliminary advice of SHD 3693P.

Kindly provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Tuesday, 11 September 2018 5:15 PM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>; ASSIGNMENTS@lkkauto.com
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18
Importance: High

Hi Nivitha,

Please touch base with Cdge first on survey as they just send another email to us

Thanks
Kelvyna

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, September 11, 2018 5:09 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; ASSIGNMENTS@lkkauto.com
Cc: 'SUR' <sur@lkkauto.com>
Subject: [External] RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Tuesday, 11 September 2018 4:40 PM
To: Nivitha (LKK Auto); 'Admin A'; "SUR"
Subject: RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18
Attachments: img-910081501-0001.pdf

Hi team

TP survey

Thanks
Kelvyna

From: Lim Tien Siong <limts@cde.com.sg>
Sent: Tuesday, September 11, 2018 3:56 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Kelvyna,

LKK Auto Consultants.
Thanks.

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Tuesday, 11 September 2018 2:54:04 PM
To: Lim Tien Siong
Subject: RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

WITHOUT PREJUDICE

Dear Mr Lim

We append the following list of our panel surveyors for survey without prejudice:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Please advise

Thanks
Kelvyna

From: Lim Tien Siong
Sent: Monday, 10 September 2018 8:22 AM
To: kelvyna.ngian@sg.gaig.com
Cc: generalClaims@sg.gaig.com
Subject: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Kelvyna,

Fyna.
Thanks.

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents

therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Reply | v

Delete

Junk | v

...

RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

N

Nivitha (LKK Auto) <admin-d@lkkauto.com>

Reply | v

Tue 11/9/2018 5:31 PM

To: ✓ Lim Tien Siong; 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>;

'LKK Assignments' <assignments@lkkauto.com>

Cc: ✓ Roger How Keen Meng; ✓ Tan Pei Wei ✉

Inbox

To help protect your privacy, some content in this message has been blocked. To re-enable the blocked features, click [here](#).

To always show content from this sender, click [here](#).

Dear Mr.Lim,

Thank you for the email.

We will arrange for the survey on 12/09/2018 before 12pm.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Tien Siong [mailto:limts@cdge.com.sg]

Sent: Tuesday, 11 September 2018 5:28 PM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; LKK Assignments <assignments@lkkauto.com>

Cc: Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>

Subject: Re: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Nivitha,

Urgent !

Just answered your call.

GAIC assigned the survey to LKK

Please advise on your surveyor the timing for tomorrow.

Refer to below email.

Thanks.

Best Regards,

Lim Tien Siong

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156

Reply | Delete | Junk | ...

Sent: Tuesday, 11 September 2018 3:55 PM

To: Ngian, Kelvyna

Cc: Roger How Keen Meng; Tan Pei Wei

Subject: Re: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Kelvyna,

Fyi - 48 hrs guide line ends tomorrow, 12/9 morning 08:30 hrs

Please advise your surveyor arrangement.

Without further delay, if we don't hear from you by 12/9 @ 09:30 hrs
we shall engage an independent surveyor for this claim.

Thanks.

Best Regards,

Lim Tien Siong

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156

From: Lim Tien Siong

Sent: Tuesday, 11 September 2018 3:55 PM

To: Ngian, Kelvyna

Subject: Re: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Kelvyna,

LKK Auto Consultants.

Thanks.

Best Regards,

Lim Tien Siong

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Sent: Tuesday, 11 September 2018 2:54:04 PM

To: Lim Tien Siong

Subject: RE: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

WITHOUT PREJUDICE

Dear Mr Lim

We append the following list of our panel surveyors for survey without prejudice:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Reply | Delete | Junk | ...

Please advise

Thanks
Kelvyna

From: Lim Tien Siong
Sent: Monday, 10 September 2018 8:22 AM
To: kelvyna.ngian@sg.gaig.com
Cc: generalClaims@sg.gaig.com
Subject: Accident involving SHD3693P and your insured SJX7787Y dated 07.09.18

Hi Kelvyna,

Fyna.
Thanks.

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the

Reply | ▾ Delete Junk | ▾ ...

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305210105

OMER
S
COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


UNIT CARD NO.

REGN NO.: SHD3693P	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.09.2018 17:05
YR OF MANUF 05.02.2015	TARGET DATE
CHASSIS CODE KMHLB41UMFU064570	COMPLETION DATE/TIME:

Accident Date: 07.09.2018
NATURE: 3P 07.09.18

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHD3693P LIMITS

Vehicle No.: SHD3693P

Service Advisor Signature/Date

Name of Service Advisor Date

med to Service Reception upon collection

To be kept by Security Guard

GAIC-4S

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305210105
 REGN NO : SHD3693P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.02.2015
 DATE/TIME IN : 07.09.2018 17:05
 ACCIDENT DATE : 07.09.2018

0830

LKK-

JOB / PARTS DESCRIPTION

Emails attached

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	repair
0002 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	X M
0003 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	35.60	20.00	28.48	X sue
0004 04-01-0103-0658-G	REAR WHEEL CAP LH	1	150.70	20.00	120.56	X sue

SUB-TOTAL : 609.04

JOB NATURE

0000 L PANEL BEATING
 0001 23-502 SPRAYPAINT ON AFFECTED AREA

~~280.00~~ 100~~250.00~~ 100 200

SUB-TOTAL : 530.00

TOTAL : 1,139.04

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
 Hp 90010068
 2 days
 4/3
 12/09/18 @ 1140

14/9/18

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 12.09.2018
Time: 17:26:21
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305210105
REGN NO : SHD3693P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.02.2015
DATE/TIME IN : 07.09.2018 17:05
ACCIDENT DATE : 07.09.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L PANEL BEATING


100.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA

200.00

SUB-TOTAL : 300.00

TOTAL : 300.00


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Shirley

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305210105
Date : 13/09/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : RASUL
Vehicle Reg No. : SHD3693P

Fax :


Date of Accident : 07-Sep-18


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: Great American Ins Co --- SJX7787Y
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>NIL</u>
(b) Labour Charges	<u>\$300.00</u>
Total for Part-By-Part Repair Cost	<u>\$300.00</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u> </u>
Final Lumpsum Repair cost	<u> </u>
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : RASUL
Date : 20/09/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18016577/R1sd3n2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 26-09-2018		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJX 7787Y	Veh. Inspected	SHD 3693P	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJX7787Y	Excess (\$)	0.00	
Assign From	KELVYNA NGIAN	Assign Date	11/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40 1.7L	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMFU064570	Colour	BLUE	
Odometer	411916	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2018	Inspection Date	12/09/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3693P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER SIDE BRKT LH	SERVICEABLE	35.60	-
1	REAR WHEEL CAP LH	SERVICEABLE	150.70	-
	LESS 20% DISCOUNT		-152.26	-
			609.04	-
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		280.00	100.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
			530.00	300.00
GRAND TOTAL			1,139.04	300.00
RECOMMENDED COST OF REPAIRS				300.00

Report Ref No. CS/GAI18016577/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.