

ASS. REC. BY:

REP CS/MSG18016579/TIRD3

Special Instruction:

Supervisor
MUMMEN

ASSIGNMENT (Office)

From (Person): VUNE JUN

of MSIG

Date/Time: 11/9/18 @ 4:09pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 6754K

Insured: FU 912L

at Workshop n/s: Ding Auto

Tel: 9733 5832

of 219 Julien Boon ley

Policy No: MSD/VM1118-381907

Claim No: MSC/v/18-001213

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 08/09/2018

CA / REV / REP. / REV 24 HRS

1up

12/09/18

H.O.D. Endorsement:

Date/Time: 5:46pm @ 11/9/18

Person Contacted: jin tong

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 6754K - NBA/MSG16011502/4 @A:20/6/18
	FU 912L-x
	Revert the reminder
	Confirm L/S \$850.00 @ 2 days (Red: \$ 8731.49, 91%.)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Est Auth'd	Status
Main	10 Sep 2018		11 Sep 2018 16:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ISHAM BIN MOHAMAD YUSOF, ID: S1733867F		
Main Claimant:	LCRF PTE LTD, Co, Reg, No.: 201624597K		
Vehicle Reg. No.:	SLC6754K	Date of Loss:	08/09/2018 20:00 - :59 [27 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001213	Policy/Cover Note No.:	MSD/VMT/18-381907 Coverage: 01/05/2018 - 30/04/2019
Vehicle Reg. No. (Insured):	FU912L	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523, 619523 Boon Lay - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK OI NOT REPORTED. CONTACT:YOU JING FENG 9733 5832/ 9239 4128		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 22 Oct 2018

Preliminary Advice

Insured Vehicle No	: FU912L	Accident Date	: 08/09/2018
TP Vehicle No	: SLC6754K	Assignment Date	: 11/09/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 2.00
Date of Inspection	: 12/09/2018		
Inspection At	: DING AUTO PTE LTD - BOON LAY (HQ) 249 JALAN BOON LAY SINGAPORE 619523 SINGAPORE 619523		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,581.49
Revised Amount	:S\$	1,065.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,065.68
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 10:42
Date Of Accident	08/09/2018 20:45
Exact Location Of Accident	ALONG DUNEARN ROAD NEAR SWISSCLUB ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6754K
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	GOH CHUNG SIEW
NRIC No	S1509844I
Date Of Birth	08/08/1961
Occupation	OUTDOOR
Date Of Driving Pass	17/02/1982
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FU912L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:





 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/RN No.:



SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]*
Date & Time: _____

Driver's Signature: *[Signature]*
(If driver is not the policyholder)
Date & Time: _____



Reporting Centre Personnel's Signature: *[Signature]*
Name: _____
NRIC/PIN No.: _____





**SINGAPORE
POLICE FORCE**



T/20180909/2060

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 3

Report No. T/20180909/2060

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2018 18:20	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: GOH CHUNG SIEW		Address: APT BLK 286 TAMPINES STREET 22 #08-171 SINGAPORE 520286	
ID Type / ID No.: NRIC NO / S15098441		Contact No.: Home/Office: Mobile: 96451194	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 07/08/1961	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/09/2018 20:45	Type of Location: Straight Road
Location: Along Road 1 DUNEARN ROAD Along dunearn road near swissclub road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved:

Vehicle No.	Type	Make	Model	Color	Registration No.
FU912L	Motorcycle				1
SLC6754K	Car				1

**SINGAPORE
POLICE FORCE**

T/20180909/2060

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20180909/2060

CONTINUATION OF REPORT**Brief Details.**

On 08/08/2018 at about 2045hrs, I was driving my vehicle (SLC6754K) on the extreme left when suddenly a taxi filtered from the middle lane and went in front of me to picked up a passenger. As such, I jammed brake and a motorcycle (FU912L) hit my vehicle from the rear.

Upon collision, both of us came out of our vehicle to make a check. We then exchanged particulars. I then called for Police assistance and also the ambulance. Traffic Police and ambulance came down subsequently. The rider's wife was also conveyed to the hospital afterwards.

On 09/09/2018 at about 1000hrs, I felt pain on my back and also suffering from a minor headache. As such, I went over to Mount Alvernia Hospital to make a check and was given 3 days of Medical Certificate by Dr Ong Swee Seng, Raymond.

I wish to state that my car had installed a CCTV. However, I had already passed the footage over to TP vide incident number: E/201809/08/0245.

The motorcyclist's particulars:
Isham Bin Mohamad Yusof
S1733867F
97402376



**SINGAPORE
POLICE FORCE**



T/20180909/2060

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 3

Report No. T/20180909/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 HO BOON KIAT, DARON	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/09/2018 18:20
Officer In Charge Of Case: TP / GIT / Sgt 3 MOHAMED RIZWAN BIN IBRAHIM Contact No.: 93265045	Classification Of Case: SN 070
Authentication Stamp NP168	

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/09/2018 11:31

JOB-NO: 85008608

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
 ADDRESS: 60 ANSON ROAD 0
 #11-01 MAPLETREE NIL
 ANSON
 SINGAPORE 079914

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLC6754K TRANS: AUTO CHASSIS: MHFBT9F3406064677
 MAKE / MODEL: TOYOTA / Vios 1.5 E (A) ENGINE: 1NZZ321219
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00		Y	200
2 R&R REVERSE SENSOR AND CHECK WIRING	1.00	100.00	0.00	100.00		Y	30
3 R&R SPARE TYRE BOARD, CARPET, TRIM AND ETC	1.00	150.00	0.00	150.00		Y	X
4 MOUNT ON WORKBENCH - ALIGNMENTS REAR CHASSIS	1.00	250.00	0.00	250.00		Y	X
5 SPRAY PAINTING ON REAR BUMPER, REAR REINF, REAR REINF ARM LH./RH, REAR FENDER LH, REAR FENDER RHS, BOOTLID, REAR END PANEL	1.00	1,500.00	0.00	1,500.00		Y	200
6 RUSH PROOFING	1.00	80.00	0.00	80.00		Y	X
TOTAL:		3,580.00	0.00	3,580.00			
MATERIALS							
1 REAR BUMPER	1.00	497.10	0.00	497.10	L	Y	del
2 REAR BUMPER REINFORCEMENT	1.00	375.80	0.00	375.80	L	Y	?
3 REAR BUMPER REINF ARM LH	1.00	134.70	0.00	134.70	L	Y	?
4 REAR BUMPER REINF ARM RH	1.00	134.70	0.00	134.70	L	Y	?
5 REAR BUMPER RETAINER LH	1.00	115.90	0.00	115.90	L	Y	X
6 REAR BUMPER RETAINER RH	1.00	115.90	0.00	115.90	L	Y	X
7 REAR BUMPER REAR BUMPER LH RETAINER SHORT	1.00	41.90	0.00	41.90	L	Y	del
8 REAR BUMPER RH RETAINER SHORT	1.00	41.90	0.00	41.90	L	Y	del
9 BOOTLID	1.00	830.80	0.00	830.80	L	Y	X
10 BOOTLID EMBLEM LOGO	1.00	56.75	0.00	56.75	L	Y	X
11 BOOTLID EMBLEM VIOS	1.00	49.97	0.00	49.97	L	Y	X
12 BOOTLID EMBLEM E	1.00	39.47	0.00	39.47	L	Y	X
13 TAIL LAMP LH	1.00	321.80	0.00	321.80	L	Y	X
14 TAIL LAMP RH	1.00	321.80	0.00	321.80	L	Y	X
15 END PANEL REAR	1.00	721.60	0.00	721.60	L	Y	X
16 REAR FENDER RHS	1.00	910.70	0.00	910.70	L	Y	X
17 REAR FENDER LHS	1.00	910.70	0.00	910.70	L	Y	X
18 REVERSE SENSOR	1.00	380.00	0.00	380.00	S	Y	200 dis
TOTAL:		8,001.49	0.00	8,001.49			
TOTAL PARTS & LABOUR :		9,581.49	0.00	9,581.49			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:SS 0.00

No. Of Day: 2

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS _____

DATE OF SURVEY: 12/9/18

SURVEYED BY: Tanfer

CONTACT NO: 97495749

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

wp
540 @ lkkauto.com

[Signature]
22/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Veron Chen (LKKAuto)

From: JingFeng <jingfeng@dingauto.sg>
Sent: Friday, 19 October 2018 8:59 AM
To: Taufikh (LKKAuto); SUR; CS A Team
Cc: kenneth.ding@dingauto.sg; ACCOUNTS@DINGAUTO.SG; Dd hashim; duan.hongbo@dingauto.sg
Subject: Re: 85008608/SLC6754K- FINALIZE AMOUNT AND AFTER PAINT PHOTO
Attachments: CCI18092018_0001.jpg; CCI18092018.jpg; DSC06670.JPG; DSC06665.JPG; DSC06666.JPG; DSC06667.JPG; DSC06668.JPG; DSC06669.JPG

Dear Officer

Please help us finalize this case asap

Thanks

BEST REGARDS

DING AUTO PTE LTD

YOU JING FENG
HP : 97335832
TEL Office : 92394128
FAX :62652690

ALL MAIL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 575645 -

On 18/09/2018 09:47, JingFeng wrote:

> HI ALL
>
> Please see attach file for the finalize according to our conversion to
> finalize for SLC6754K
>
> Total Repair - 02 Days
> L/S REPAIR
>
> Labour - \$430.00
> Special Netts - \$200.00
> Parts - \$580.90
> Parts after 25% Discount - \$435.68
> Total (Labour + S.N + Part) :\$1065.68
>
> Final Amount After -20% : \$852.54
>
> Thanks You And Please Help To Close The File
>
>
> Best Regards
> Ding Auto Pte Ltd
> You Jing Feng
> Hp : 9733 5832

>

>

>

> This email has been checked for viruses by Avast antivirus software.

> <https://www.avast.com/antivirus>

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/09/2018 11:31

OWNER'S PARTICULARS

JOB-NO: 85008608

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
 ADDRESS: 60 ANSON ROAD 0
 #11-01 MAPLETREE NIL
 ANSON
 SINGAPORE 079914

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLC6754K TRANS: AUTO CHASSIS: MHFBT9F3406064677
 MAKE / MODEL: TOYOTA / Vios 1.5 E (A) ENGINE: 1NZZ321219
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00		Y	<u>200</u>
2 R&R REVERSE SENSOR AND CHECK WIRING	1.00	100.00	0.00	100.00		Y	<u>30</u>
3 R&R SPARE TYRE ,BOARD , CARPET,TRIM AND ETC	1.00	150.00	0.00	150.00		Y	<u>X</u>
4 MOUNT ON WORKBENCH - ALIGNMENTS REAR CHASSIS	1.00	250.00	0.00	250.00		Y	<u>X</u>
5 SPRAY PAINTING ON REAR BUMPER ,REAR REINF ,REAR REINF ARM LH/RH , REAR FENDER LH, REAR FENDER RHS ,BOOTLID , REAR END PANEL	1.00	1,500.00	0.00	1,500.00		Y	<u>200</u>
6 RUSH PROOFING	1.00	80.00	0.00	80.00		Y	<u>X</u>
TOTAL:		3,580.00	0.00	3,580.00			
MATERIALS							
1 REAR BUMPER	1.00	497.10	0.00	497.10	L	Y	<u>del</u>
2 REAR BUMPER REINFORCEMENT	1.00	375.80	0.00	375.80	L	Y	<u>?</u>
3 REAR BUMPER REINF ARM LH	1.00	134.70	0.00	134.70	L	Y	<u>?</u>
4 REAR BUMPER REINF ARM RH	1.00	134.70	0.00	134.70	L	Y	<u>?</u>
5 REAR BUMPER RETAINER LH	1.00	115.90	0.00	115.90	L	Y	<u>X</u>
6 REAR BUMPER RETAINER RH	1.00	115.90	0.00	115.90	L	Y	<u>X</u>
7 REAR BUMPER REAR BUMPER LH RETAINER SHORT	1.00	41.90	0.00	41.90	L	Y	<u>del</u>
8 REAR BUMPER RH RETAINER SHORT	1.00	41.90	0.00	41.90	L	Y	<u>del</u>
9 BOOTLID	1.00	830.80	0.00	830.80	L	Y	<u>X</u>
10 BOOTLID EMBLEM LOGO	1.00	56.75	0.00	56.75	L	Y	<u>X</u>
11 BOOTLID EMBLEM VIOS	1.00	49.97	0.00	49.97	L	Y	<u>X</u>
12 BOOTLID EMBLEM E	1.00	39.47	0.00	39.47	L	Y	<u>X</u>
13 TAIL LAMP LH	1.00	321.80	0.00	321.80	L	Y	<u>X</u>
14 TAIL LAMP RH	1.00	321.80	0.00	321.80	L	Y	<u>X</u>
15 END PANEL REAR	1.00	721.60	0.00	721.60	L	Y	<u>X</u>
16 REAR FENDER RHS	1.00	910.70	0.00	910.70	L	Y	<u>X</u>
17 REAR FENDER LHS	1.00	910.70	0.00	910.70	L	Y	<u>X</u>
18 REVERSE SENSOR	1.00	380.00	0.00	380.00	S	Y	<u>200 dis</u>
TOTAL:		6,001.49	0.00	6,001.49			
TOTAL PARTS & LABOUR :		9,581.49	0.00	9,581.49			

430

Parts \$ 580.90 - 25% = 435.68
 s/n 200
 Labour 430
 Total \$ 1065.68 - 20%
 = 852.54

DESCRIPTION QTY QUOTED DISCOUNT DISC PRICE IND SUR.DISP REV PRICE
COSTS

EXCESS/LOADING:SS 0.00

No. Of Day: 2

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 12 / 9 / 18

SURVEYED BY: Tanfer

CONTACT NO: 97495749

FAX NO: _____

'wp'
S40 @ (kmanAuto.com)

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018		11 Sep 2018 16:09 Edit Adj Rpt	\$850.00 Edit Estimates	\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ISHAM BIN MOHAMAD YUSOF , ID: S1733867F								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLC6754K	Date of Loss:	08/09/2018 20:00 - :59 [27 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001213	Policy/Cover Note No.:	MSD/VMT/18-381907 Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured):	FU912L	Policy No. (Claimant):							
		Excess:							
Repairer:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523, 619523 Boon Lay - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/10/2018]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK OI NOT REPORTED. CONTACT:YOU JING FENG 9733 5832/ 9239 4128								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS [View All] [Search Tasks] [Create New Task] [Complete]									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC6754K (MSC/V/18-001213)
 [FU912L]
 TP
 LCRF PTE LTD
 Sep 8 2018 8:00PM
 [ISHAM BIN MOHAMAD YUSOF]
 Ding Auto Pte Ltd - Boon Lay

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Assessment Reports			1 per page <input type="button" value="✓"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	22/10/18 12:10	Adjuster Immediate Advice	<input type="button" value="1"/> Load HTM
Photos/Images			3 per page <input type="button" value="✓"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
2	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
3	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
4	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
5	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
6	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
7	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
8	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
9	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
10	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
11	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
12	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
13	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
14	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
15	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
16	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
17	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
18	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
19	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
20	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
21	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
22	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
23	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
24	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
25	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
26	22/10/18 12:11	General View	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
27	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
28	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
29	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
30	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
31	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
32	22/10/18 12:12	Reinspection Photo	<input type="button" value="1"/> Load JPG <input type="button" value="✓"/>
Documentation			1 per page <input type="button" value="✓"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	11/09/18 10:31	SLC6754K TP E-FILE REPORT	1	Load PDF
2	11/09/18 10:32	EMAIL FROM TP TO ASSIGN SURVEY	1	Load PDF
3	11/09/18 10:32	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK.	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016579/T1RD3Q2
Date: 26/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-381907
Claimant Vehicle No :	SLC6754K	Insured Vehicle No :	FU912L
Date of Loss:	08/09/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-001213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6754K	Engine No:	1NZZ321219
Make & Model:	TOYOTA VIOS, 1.5 E GRADE (A)	Chassis No:	MHFBT9F3406064677
Reg. Date:	23/05/2016 (Man. Year: 2015)	Odometer:	218230 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,001.49	635.67	5,365.82	89.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	430.00	3,150.00	87.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,581.49	1,065.67	8,515.82	88.88
Approved Total (Overridden) (S\$)		850.00		
	(S\$)	9,581.49	850.00	8,731.49
	+ GST 7.00/7.00% (S\$)	670.70	59.50	611.20
	Nett Amount (S\$)	10,252.19	909.50	9,342.69

INSPECTION

Date of Assignment:	11/09/2018	
Date Inspected:	12/09/2018 Inspected At:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523 Singapore 619523

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts: 143	TOYOTA VIOS 1.5 E GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC6754K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	497.10 F	*497.10 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	375.80 F	*- FL
3	1		*REAR BUMPER REINF ARM LH	Not Necessary	134.70 F	*- FL
4	1		*REAR BUMPER REINF ARM RH	Not Necessary	134.70 F	*- FL
5	1		*REAR BUMPER RETAINER LH	Not Necessary	115.90 F	*- FL
6	1		*REAR BUMPER RETAINER RH	Not Necessary	115.90 F	*- FL
7	1		*REAR BUMPER LH RETAINER SHORT	Necessary	41.90 F	*41.90 FL
8	1		*REAR BUMPER RH RETAINER SHORT	Necessary	41.90 F	*41.90 FL
9	1		*BOOTLID	Not Necessary	830.80 F	*- FL
10	1		*BOOTLID EMBLEM LOGO	Not Necessary	56.75 F	*- FL
11	1		*BOOTLID EMBLEM VIOS	Not Necessary	49.97 F	*- FL
12	1		*BOOTLID EMBLEM E	Not Necessary	39.47 F	*- FL
13	1		*TAIL LAMP LH	Not Necessary	321.80 F	*- FL
14	1		*TAIL LAMP RH	Not Necessary	321.80 F	*- FL
15	1		*END PANEL REAR	Not Necessary	721.60 F	*- FL
16	1		*REAR FENDER RHS	Not Necessary	910.70 F	*- FL
17	1		*REAR FENDER LHS	Not Necessary	910.70 F	*- FL
18	1		*REVERSE SENSOR	Distorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,001.49	780.90
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	145.23
Total Parts (S\$)	6,001.49	635.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,500.00	200.00
2	R&R REVERSE SENSOR AND CHECK WIRING	New	100.00	30.00
3	R&R SPARE TYRE BOARD ,CARPET ,TRIM AND ETC	New	150.00	0.00
4	MOUNT ON WORKBENCH-ALIGNMENTS REAR CHASSIS	New	250.00	0.00
5	SPRAY PAINTING ON REAR BUMPER,REAR REINF,REAR REINF ARM LH/RH ,REAR FENDER LH ,REAR FENDER RHS ,BOOTLID,REAR END PANEL	New	1,500.00	200.00
6	RUST PROOFING	New	80.00	0.00
Gross Labour Cost (S\$)			3,580.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >