

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18016618/R/cd302 Special Instruction:

Surveyor:

Mennen

ASSIGNMENT (Office)

From (Person): Irene Tan of MSG Date/Time: 11/9/18 @ 4:07pm.

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJH 3433D Insured: 8KE 6532K

at Workshop m/s Green Star Spray Painting Tel: 6546 3092

of Blk 3011, Bedok North Ave 4 # 01-2004

Policy No: 27472538QMX Claim No: 569795

Sum Insured: Excess:

Make of Veh: D.O.A. 08/09/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS Cup

H.O.D. Endorsement:

Date/Time: 9:24am @ 12/9/18 Person Contacted: Jane Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SJH 3433D-X
	8KE 6532K-X.
	Dismantle: 13/9/2018.
	After repair: 17/9/2018.

(08/11/13)

Surveyor: PASU

REF:

7954R

COT XPRY: 2023/July

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJH 34330at Workshop m/s GREEN STAR SPARKof BLK 3011, BEOOK NORTH BUK 4 # A-2004Insured: MS16

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJH 34330 Yr Regn: 2008 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA MISH 1.8 A c.c. 1794Colour: GR69 A/C: Insured / Std / NI / NASp. Reading: 186428 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W803000572

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/55R16R: A-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 08/09/12 D.O.I. 12/09/18Survey held at GREEN STARDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$2,500 - \$3,30024/9/2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: 2Survey Fee: 120

Transportation: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL

Report Format : PRE.

Lump Sum / I.B.I.: (\$ _____)

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Sep 2018		11 Sep 2018 16:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM ZHI WEI, MELVIN (LIN ZHIWEI), ID: S8230704D, Tel: +6596681890, Email: NOEMAIL		
Main Claimant:	ALPHA EXCELLENCE PTE. LTD., Co. Reg. No.: 201127954R		
Vehicle Reg. No.:	SJH3433D	Date of Loss:	08/09/2018 12:00 - :59 [121 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569795	Policy/Cover Note No.:	27472533QMX (Comprehensive) Coverage: 22/03/2018 - 21/03/2019
Vehicle Reg. No. (Insured):	SKE6532K	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]		
Driver/Custodian (Insured):	LIM ZHI WEI, MELVIN (LIN ZHIWEI) (35 / Male), NRIC: S8230704D, Tel: +6596681890		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: JANE 6546 3092		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7954R
Vehicle Details	
Vehicle No.:	SJH3433D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1ZZ3126971
Chassis No.:	JTDER12W803000572
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	31 Jul 2008
First Registration Date:	31 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$18,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,444.00
COE Rebate Amount:	\$17,888.00
Total Rebate Amount:	\$17,888.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 10:53
Date Of Accident	08/09/2018 12:30
Exact Location Of Accident	ALONG TAI SENG AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH3433D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	ALPHA EXCELLENCE PTE. LTD.
Co Reg No	201127954R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97730025
Alternative Phone No	OFFICE-64436625

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096280335
Cover Note Number	02/01/2018 - 01/01/2019

Driver

Name of Driver	SYED ABDUL KADER SHAIK ABDUR RAHMAN
NRIC No	S8170889D
Date Of Birth	03/02/1981
Occupation	OUTDOOR
Date Of Driving Pass	20/04/2001
Driving Experience	17 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81815342
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	682 RACE COURSE ROAD #03-323
Postcode	210682
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	7
Passenger 1	NAME: : SYEDA GENDER: : FEMALE
Passenger 2	NAME: : ROKAYAMA GENDER: : FEMALE
Passenger 3	NAME: : ABDULLAAH GENDER: : MALE
Passenger 4	NAME: : NAFISA GENDER: : FEMALE
Passenger 5	NAME: : ABDUL INAHHAAB GENDER: : MALE
Passenger 6	NAME: : SAFIYYAH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, MY VEHICLE WAS PARKED AT TAI SENG AVENUE ALONG THE PARALLEL PARKING LOT. I ALIGHTED AND MY WIFE CALLED ME MENTIONING THAT MY VEHICLE WAS BEING HIT A FEW TIMES FROM VEHICLE B (SKE6532K) WHICH IS TRYING TO PARK INTO THE LOT BEHIND MY VEHICLE. I WENT TO MY CAR AND CHECKED, MY VEHICLE WAS DAMAGED CAUSED BY VEHICLE B.

Attachment(s)

Are accident photos available for attachment?	YES
---	-----

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKE6532K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LIM ZHI WEI, MELVIN (LIM ZHIWEI)

NRIC/Passport Number S8230704D

Contact Number 96681890

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature _____
Date & Time: _____

Bahman

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

[Signature]

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



































...CLAIM SUBFOLDER...(Pending for Survey Report)

























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Sep 2018		11 Sep 2018 16:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIM ZHI WEI, MELVIN (LIN ZHIWEI) , ID: S8230704D, Tel: +6596681890, Email: NOEMAIL									
Main Claimant: ALPHA EXCELLENCE PTE. LTD. , Co. Reg. No.: 201127954R									
Vehicle Reg. No.:	SJH3433D	Date of Loss:	08/09/2018 12:00 - :59 [121 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569795	Policy/Cover Note No.:	27472533QMX (Comprehensive) Coverage: 22/03/2018 - 21/03/2019						
Vehicle Reg. No. (Insured):	SKE6532K	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 12/09/2018]								
Driver/Custodian (Insured):	LIM ZHI WEI, MELVIN (LIN ZHIWEI) (35 / Male), NRIC: S8230704D, Tel: +6596681890								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: JANE 6546 3092								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJH3433D (569795)**
[SKE6532K]
TP
ALPHA EXCELLENCE PTE. LTD.
Sep 8 2018 12:00PM
[LIM ZHI WEI, MELVIN (LIN ZHIWEI)]
GREEN STAR SPRAY PAINTING

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/09/18 09:56	Accident Statement From: SC - Reg. No: SKE6532K, Claimant: LIM ZHI WEI, MELVIN (LIN ZHIWEI)	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 14:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/09/18 09:56	SJH3433D TP E-FILE REPORT From: SC - Reg. No: SKE6532K, Claimant: LIM ZHI WEI, MELVIN (LIN ZHIWEI)	 Load PDF	
2	11/09/18 09:57	EMAIL FROM TP TO ASSIGN SURVEY	 Load PDF	
3	11/09/18 12:56	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016618/R1CD3E2

Date: 25/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27472533QMX

Claimant Vehicle No : SJH3433D

Insured Vehicle No : SKE6532K

Date of Loss: 08/09/2018

Nature of Claim: TP

Claim No: 569795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJH3433D

Make & Model: TOYOTA WISH, 1.8 (A)

Reg. Date: 31/07/2008 (Man. Year: 2008)

Colour: Grey

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 1ZZ3126971

Chassis No: JTDER12W803000572

Odometer: 188428 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Rear Tyre Size: 195/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/09/2018

Date Inspected: 12/09/2018 Inspected At:

GREEN STAR SPRAY PAINTING (HQ)
BLK 3011 BEDOK NORTH AVENUE 4
#01-2004 BEDOK INDUSTRIAL PARK E
Singapore 489977

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,300.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH3433D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >