

22/03/2002

ASS. REC. BY:

REF:

CS31AIG18016620/Rld3/27

Special Instruction:

Surveyor:

Maimen

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AIG

Date/Time:

12/9/18 @ 10:58am

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 8857M

Insured:

SDG 8992A

at Workshop m/s

H.S. Automotive

Tel:

65381368

of

2 Kalci Bkt Ave 2 # 02-25

Policy No:

2100311647

Claim No:

19978656458G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/09/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:20am @ 12/9/18

Person Contacted:

Alex

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction ( x ) Estimate
	GBA 8857M - NA/CTI/18016531/r3 DOA: 11/9/18
	SDG 8992A - NA/CTI/18016531/r3 DOA: 11/9/18
	Dismantle: 13/9/2018
	After repair: 17/9/2018

001-11  
BIRYMUS

Pam

REF:

ALG

# ASSIGNMENT

From:

Date:

12/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBA 8857 M

at Workshop m/s

H.S. Automotive

of

2 kaki Bkt Ave 2 # 02-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Alex @ 6538 1368

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. 1-24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBA 8857 M

Yr Regn:

Mar / 08

Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA

C.C

2900

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

153139

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KN C 5E 01428 7295045

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15C

R:

155 R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROVELO

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

11/09/18

D.O.I.

12/09/18

Survey held at

HS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/10

Submit DAR report.

- Repair days 4

TGIM

11/10/18

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

180

Transportation:

\$ + RS. SI

) Photos

) Others

TOTAL


200

Report Format :

DAR

Lump Sum / I.B.I: (\$

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 12/9/2018 10:58:48 AM  
Attachments:  [tmpD633.tif](#)

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** juseq@singnet.com.sg [mailto:juseq@singnet.com.sg]  
**Sent:** Tuesday, September 11, 2018 5:29 PM  
**To:** Mithoosingh, Aashweenjeetkaur  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Azlan, Syazairdina  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDG8992A AND GBA8857M ON 11/09/2018

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) SK Auto Consultants,
- 3) Chartered Auto Assessors,
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,

8) CM Automotive Consultancy,

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**H S Automotive Services**

Blk 2 Kaki Bukit Avenue 2 #02-25

Kaki Bukit AutoHub,

Singapore 417921

Person In-Charge: Mr. Alex. Tel: 6538 1368. Fax: 6538 1367

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

JusEquity Law Corporation.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



# JusEquity Law Corporation

## ADVOCATES & SOLICITORS - COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, GES Centre, Singapore 169877  
 Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327  
 Fax : (65) 6253 0120 (Conveyancing) . (65) 6536 5368 (Litigation)  
 Email : [jusseq@singnet.com.sg](mailto:jusseq@singnet.com.sg) website: [www.jusseq.com.sg](http://www.jusseq.com.sg)

Our Ref: JEQ/180718/0918/ HS A

Your Ref: SDG8992A

11 September 2018

**YAM WHO LEI**  
 700 LORONG 1 TOA PAYOH #09-14  
 SINGAPORE 319773

By Post Only

**AIG Asia Pacific Insurance Pte Ltd**  
 Singapore

By Fax: 6835 7416 Only

Dear Sir

**ACCIDENT INVOLVING GBA8857M & SDG8992A ON 11-9-2018**

We act for the owner of vehicle no. GBA8857M.

We hereby notify you of a road traffic accident on **11 September 2018** at about **1005 hrs**, at Kaki Bukit AutoHub involving our client's vehicle and vehicle registration no. **SDG8992A** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

### CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

## &gt; Back to OneMotoring

## Enquire Transfer Fee

## Vehicle Details

Vehicle No. :	GBA8857M
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	KIA
Vehicle Model :	KIA 2900L 5 M/T
Chassis No. :	KNCSE014287295045
Propellant :	Diesel
Engine No. :	J37257510
Engine Capacity :	2902 cc
Maximum Power Output :	-
Maximum Laden Weight :	3240 kg
Unladen Weight :	1740 kg
Year Of Manufacture :	2007
Original Registration Date :	14 Mar 2008
Lifespan Expiry Date :	13 Mar 2028
COE Category :	C - Goods Vehicle & Bus
PQP Paid :	\$20,115.00
COE Expiry Date :	13 Mar 2023
Road Tax Expiry Date :	26 Nov 2018
Inspection Due Date :	26 Nov 2018
Intended Transfer Date :	25 Sep 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 26 Nov 2018. You may renew the road tax from 27 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable (From 27 Nov 2018 to 26 May 2019)**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	62.00	-	62.00
<b>Total Amount Payable :</b>			<b>87.00</b>

**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

You may print this page for reference.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5357R
<b>Vehicle Details</b>	
Vehicle No.:	GBA8857M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	KIA
Vehicle Model:	KIA 2900L 5 M/T
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	J37257510
Chassis No.:	KNCSE014287295045
Maximum Power Output:	-
Open Market Value:	\$16,020.00
Original Registration Date:	14 Mar 2008
First Registration Date:	14 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$801.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Mar 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,115.00
COE Rebate Amount:	\$18,690.00
<b>Total Rebate Amount:</b>	<b>\$18,690.00</b>
<b>Message</b>	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 25 Sep 2018

OK

MNA110117079 / National Assessment Centre Services - Ubi  
 ENTRY DATE & TIME: 11/09/2018 11:13  
 SUBMITTED BY: Roslinda Binte Abdul Wahab

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

#### ACCIDENT STATEMENT

Date Of Report 11/09/2018 11:13  
 Date Of Accident 11/09/2018 10:05  
 Exact Location Of Accident KAKI BUKIT AUTOHUB  
 Country/State Of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA8857M  
**Insured/Policyholder**  
 Name Of Registered Owner TOTALLY TRANSPORTATION & SUPPLY PTE LTD  
 Co Reg No 201815357R  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-91182780

#### Vehicle Particulars

Manufacturer KIA  
 Model K2900  
 Exact Purpose for which vehicle was being used at time of accident MAINTENANCE OF LORRY  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy NO  
 Policy Number DMCVSN1817061800

#### Cover Note Number

#### Driver

Name of Driver TAN CHEE WEE  
 NRIC No S7723498E  
 Date Of Birth 09/09/1977  
 Occupation OUTDOOR  
 Date Of Driving Pass 09/06/2012  
 Driving Experience 6 YEARS AND 3 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-91182780  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL



Address BLK 802C KEAT HONG CLOSE  
#11-63  
Postcode 883802  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLIDED INTO PARKED VEHICLE  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SDG8992A  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)


## Accident Sketch Plan


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders


  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

 11/09/18  
Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.

## Individual Statement

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS PARKED IN FRONT OF MY CAR WORK SHOP  
 SUDDENLY VEHICLE B REVERSED AND HIT ONTO MY FRONT RIGHT  
 HAND SIDE

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

*[Signature]* 11/09/18  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No

## VAN/ LORRY (Frt)

Vehicle No: **GBA 8857M**

## Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	CRA	✓	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket	BT	✓	
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door	SCR	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board	BR	✓	
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		Frt Bumper retainer RH	NEC	✓	
		Frt Bumper clips	NEC	✓	

No of Items: **7**

Assessor: \_\_\_\_\_

TGLim

lin

1/10/18

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018 <a href="#">Edit Reg</a>		12 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>YAM WOH LEI</b> , ID: S1307956J								
Main Claimant:	<b>TOTALLY TRANSPORTATION &amp; SUPPLY PTE LTD</b> , Co. Reg. No.: 201815357R								
Vehicle Reg. No.:	<b>GBA8857M</b>	Date of Loss:	11/09/2018 00:00 - :59 <b>[125 Months and 28 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 1997865645SG</b>	Policy/Cover Note No.:	2100311647 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SDG8992A</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Hs Automotive Services (HQ)</b> Blk 2 Kaki Bukit Avenue 2 #02-25, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 21/09/2018]</b>								
Claimant's Solicitor:	<b>JusEquity Law Corporation</b> - Tel: 65369339								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (13/09/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBA8857M (1997865645SG)

[SDG8992A]

TP











TOTALLY TRANSPORTATION & SUPPLY PTE LTD

Sep 11 2018 12:00AM

[YAM WOH LEI]

Hs Automotive Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print					
1	25/09/18 09:59	General View																Load JPG			<input checked="" type="checkbox"/>		
2	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
3	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
4	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
5	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
6	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
7	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
8	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
9	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
10	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
11	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
12	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
13	25/09/18 10:01	General View																Load JPG			<input checked="" type="checkbox"/>		
14	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
15	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
16	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
17	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
18	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
19	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
20	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
21	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
22	25/09/18 10:02	General View																Load JPG			<input checked="" type="checkbox"/>		
23	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
24	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
25	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
26	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
27	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
28	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
29	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
30	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
31	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
32	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
33	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
34	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
35	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
36	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		
37	25/09/18 10:03	Photographs of Damaged Parts																Load JPG			<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/18 10:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/09/18 13:34	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016620/R1CD3E2

Date: 04/10/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100311647

**Claimant Vehicle No :** GBA8857M

**Insured Vehicle No :** SDG8992A

Date of Loss: 11/09/2018

Nature of Claim: TP

Claim No: 1997865645SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA8857M**

Make &amp; Model: KIA 2900L, 2.9 D (M)

Engine No: J37257510

Reg. Date: 14/03/2008 (Man. Year: 2007)

Chassis No: KNCSE014287295045

Colour: White

Odometer: 193139 km

Engine Capacity: 2902 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: Rovel 7 mm

Rear Left Side: Rovel 5 mm

Front Right Side: Rovel 7 mm

Rear Right Side: Rovel 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/09/2018

Date Inspected: 12/09/2018 Inspected At:

 Hs Automotive Services (HQ)  
 Blk 2 Kaki Bukit Avenue 2 #02-25, Kaki  
 Bukit AutoHub  
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
3	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
4	1		*FRT RH DOOR	Repair	0.00 F	*- F
5	1		*FRT RH DOOR INNER TRIM BOARD	Broken	0.00 F	*- F
6	1		*STICKER	Necessary	0.00 F	*- F
7	1		*FRT BUMPER RETAINER RH	Necessary	0.00 F	*- F
8	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >