

ASS. REC. BY:

REF: CS3/AIG18016623/Rld3<sup>SV</sup>

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Mammen

Chin Lee Ying

of AIG

Date/Time: 12/9/18 @ 9:38am

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 29164

Insured:

SLP 42C

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 Keki Blt Ave 2 # 01-17

Policy No:

1700017351

Claim No:

297455879836

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

11/09/18

CA / REV / REP. / REV 24 HRS cup

H.O.D. Endorsement:

Date/Time:

10:09am @ 12/9/18

Person Contacted:

Melody

Vehicle

IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJY 29164-x</u>
	<u>SLP 42C-x</u>
	<u>Dismantle: 13/9/2018</u>
	<u>After repair: 17/9/2018</u>
<u>1/10</u>	<u>Submit DAR report.</u>



- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 12/9/2018 9:38:19 AM

Attachments:  [11092018153526.pdf](#)  [11092018155717.pdf](#)  
 [11092018113124-0001.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

*10:09 am  
M/body  
V/h  
LKK*

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,  
2 Kaki Bukit Ave 2, #01-18  
Singapore 417921  
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

Our Ref:                    **SJY 2916 U**  
Your ref:                   **SLP 42 C**

11 September 2018

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**  
NO: 78 SHENTON WAY  
#07-16 CHARTIS BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Department

**BY FAX 6835-7416 & EMAIL :**  
**AIGSGP\_ClaimsSurvey@aig.com**

Dear Sir/Madam,

**DATE OF ACCIDENT : 11 Sept 2018**  
**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS**  
**PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We are instructed by **VISION ONE PTE LTD** to notify you of a road traffic accident on **11 Sept 2018** at about **07:15 HOURS** At **PI E TWD TUAS B4 KJE ENTRANCE** involving our client's vehicle **SJY 2916 U & SLP 42 C** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle , please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



.....  
**N-51 AUTOMOTIVE PTE LTD**

MSME18118090 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 11/09/2018 17:53  
 SUBMITTED BY: Chia Pei Ying

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	11/09/2018 17:53
Date Of Accident	11/09/2018 07:15
Exact Location Of Accident	PIE TWDS TUAS BEFORE KJE ENTRANCE
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY2916U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VISION ONE PTE LTD
Co Reg No	201007671E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81212116
<b>Vehicle Particulars</b>	
Manufacturer	LEXUS
Model	IS250
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA384748
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHUA KHENG HOE
NRIC No	S7618782G
Date Of Birth	14/06/1976
Occupation	INDOOR
Date Of Driving Pass	20/07/1999
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81212116
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address BLK 67 TELOK BLANGAH DRIVE #04-216  
 Postcode 100067  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS DRIVING ALONG PIE TOWARDS TUAS DIRECTION. I WAS ON THE EXTREME RIGHT LANE. WHILE TRAVELLING STRAIGHT, THE VEHICLE IN FRONT BRAKE TO A COMPLETE STOP DUE TO HEAVY TRAFFIC. AND SO, I TOO APPLIED BRAKE TO COMPLETE STOP. WHILE I LOOKED AT MY REAR VIEW MIRROR, I SAW THE VEHICLE BEHIND ME MANAGED TO STOP IN TIME. AND SUDDENLY, I SAW THE VEHICLE JERKED AND HIT ONTO THE REAR OF MY VEHICLE. I ALIGHTED FROM MY VEHICLE AND REALISED IT WAS A VEHICLE WITH LICENCE PLATE (SLP42C) THAT COLLIDED ONTO THE REAR OF MY VEHICLE WHILE ONE MORE VEHICLE (SLW1226X) BEHIND HIM. IT WAS A CHAIN COLLISION INVOLVING 3 VEHICLES.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLP42C  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SLW1226X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

VEHICLE A - SJY 2916H  
 VEHICLE B - SLP 42C  
 VEHICLE C - SLW 1226X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG PIE TOWARDS TWS DIRECTION,  
 I WAS ON THE EXTREME RIGHT LANE.

WHILE TRAVELLING STRAIGHT, THE VEHICLE IN FRONT BRAKE TO  
 COMPLETE STOP DUE TO THE HEAVY TRAFFIC, AND SO I  
 TOO APPLIED BRAKE TO COMPLETE STOP.

WHEN I LOOKED AT MY REAR VIEW MIRROR I SAW THE  
 VEHICLE BEHIND ME MANAGED TO STOP IN TIME, AND  
 SUDDENLY I SAW THE VEHICLE JERKED AND HIT ONTO  
 THE REAR OF MY VEHICLE.

BRIGHTEN FROM MY VEHICLE AND REALIZED IT WAS  
 A VEHICLE WITH BIKENOR PLATE NUMBER (SLP 42C)  
 THAT COLLIDED TO THE REAR OF MY VEHICLE WHILE  
 ONE MORE VEHICLE (SLW 1226X) BEHIND HIM.  
 IT WAS A CHAM COLLISION INVOLVING 3 VEHICLES.

VEHICLE A - SJY 2916H  
 VEHICLE B - SLP 42C  
 VEHICLE C - SLW 1226X

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\*    
 POLICYHOLDER'S SIGNATURE

Date & Time:

\*    
 DRIVER'S SIGNATURE

(If driver is not the policyholder)  
 Date & Time:

11/9/18 2.25pm

REPORTING CENTRE PERSONNEL'S SIGNATURE  
 Name:  
 NRIC/FIN No.:

<b>Vehicle No.</b>	SY 2916U	<b>Model / Make</b>	LEXUS IS 250
Date of Accident	11/09/18		
Time of Accident	0715	HRS	
Location of Accident	PIE TOWARDS TUNAS BEFORE KJIE ENTRANCE		
Exact purpose use during accident	PARKING USE		
<b>Name of Owner</b>	VISION ONE PTE LTD		
Telephone No.	H/P:	Home:	Office:
NRIC	20100761 E		
Address	3 KIAN TEE ROAD S(628764)		
Claim type	OD THIRD PARTY REPORTING ONLY		
Insurance Company	AXA		
Type of Coverage	Comprehensive	Third Party	Third Party / Fire / Theft
Policy No.			
<b>Name of Driver</b>	As Above If NO, CHUA KHENH HOE		
NRIC	57618782G	Any Passengers: NIL	
Date of birth	14/06/1976		
Occupation	Outdoor / Indoor		
Driving License Pass Date	20 JUL 1999		
Gender	Male / Female		
Contact No.	H/P: 8121216	Home:	Office:
Address	BLK 67 TELUK BLANGAH DRIVE #04-216 S(100067)		
Driver have any own vehicle	No, If yes, Reg No.		
Relationship	Employee, If no, state		
Weather condition	Clear Raining Other		
Road Surface	Dry Wet Other		
Any Injuries	No, If Yes, Who?		
Name And Contact No.			
Name And Contact No.			
Police Report	No, If Yes, Where?		
<b>Vehicle B No.</b>	SLP 42 C	Any Passengers:	
Name of Driver		Contact No.:	
<b>Vehicle C No.</b>	SLW 1226 X	Any Passengers:	
<b>Vehicle D No.</b>		Any Passengers:	
<b>Vehicle E no.</b>		Any Passengers:	
<b>Vehicle F No.</b>		Any Passengers:	
<b>Vehicle G No.</b>		Any Passengers:	
Witness Name		Witness Contact:	
<b>Accident Portion</b>	Rear		
Camera Recorder	Yes / No		
Email Address	KH.CHUA@vision-one.com.sg / sales@n5i.com.sg		
HAVE YOU BEEN APPROACH BY UNKNOWN PERSON SOLICITING / OFFERING ACCIDENT CLAIMS ASSISTANCE?			
		Yes / No	
<b>PARTICULAR WORKSHOP</b>	N-SI AUTOMOTIVE PTE LTD		
CONTACT NO.	6842 0051 / 6744 0510		
CONTACT PERSON	IAN		
FAX NO	6741 0510		
WORKSHOP EMAIL ADDRESS	sales@n5i.com.sg		

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

✱

✱


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

VEHICLE A - SJY 2916U  
 VEHICLE B - SLP 42C  
 VEHICLE C - SLW 1226X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG PIE TOWARDS TWIS DIRECTION,  
 I WAS ON THE EXTREME RIGHT LANE.

WHILE TRAVELLING STRAIGHT, THE VEHICLE IN FRONT BRAKE TO  
 COMPLETE STOP DUE TO THE HEAVY TRAFFIC, AND SO I  
 TOO APPLIED BRAKE TO COMPLETE STOP.

WHEN I LOOKED AT MY REAR VIEW MIRROR I SAW THE  
 VEHICLE BEHIND ME MANAGED TO STOP IN TIME, AND  
 SUDDENLY I SAW THE VEHICLE JERKED AND HIT ONTO  
 THE REAR OF MY VEHICLE.

BRIGHTEN FROM MY VEHICLE AND REALIZED IT WAS  
 A VEHICLE WITH BIKER'S PLATE NUMBER (SLP 42C)  
 THAT COLLIDED TO THE REAR OF MY VEHICLE WHILE  
 ONE MORE VEHICLE (SLW 1226X) BEHIND HIM.

IT WAS A CHAMAN COLLISION INVOLVING 3 VEHICLES.

VEHICLE A - SJY 2916U  
 VEHICLE B - SLP 42C  
 VEHICLE C - SLW 1226X

DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 \* \* \*

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/IN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7671E
<b>Vehicle Details</b>	
Vehicle No.:	SJY2916U
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4GR0191306
Chassis No.:	JTHBK262702014133
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$36,638.00
Original Registration Date:	25 Aug 2006
First Registration Date:	25 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$40,302.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Aug 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$54,463.00
COE Rebate Amount:	\$43,101.00
<b>Total Rebate Amount:</b>	<b>\$43,101.00</b>

The information contained herein is correct as at 25 Sep 2018

OK

# MOTORCAR (Rear)

## Rear Portion

Vehicle No: **SJY 2916U**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 8

Assessor: \_\_\_\_\_

TECim *lim*  
 27/9/18

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iris Auth'ed	Status
Main	12 Sep 2018 <a href="#">Edit Reg</a>		12 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>CHAN BEE WAH HELEN</b> , ID: S1618041F		
Main Claimant:	-		
Vehicle Reg. No.:	<b>SJY2916U</b>	Date of Loss:	11/09/2018 00:00 - :59 [144 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 29745587985G</b>	Policy/Cover Note No.:	1700017351
Vehicle Reg. No. (Insured):	<b>SLP42C</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 21/09/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJY2916U (2974558798SG)**  
**[SLP42C]**  
**TP**  
**-**

**Sep 11 2018 12:00AM**  
**[CHAN BEE WAH HELEN]**  
**N-51 Automotive Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			View <input type="button" value="View in Browser"/>
<b>Assessment Reports</b>			1 per page <input type="button" value="Print"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail
1	13/09/18 13:25	<b>Accident Statement</b> From:SC - Reg. No: SLP42C, Claimant: CHAN BEE WAH HELEN	Load HTM
<b>Photos/Images</b>			3 per page <input type="button" value="Print"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	25/09/18 09:42	<b>General View</b>	Load JPG
2	25/09/18 09:42	<b>General View</b>	Load JPG
3	25/09/18 09:42	<b>General View</b>	Load JPG
4	25/09/18 09:42	<b>General View</b>	Load JPG
5	25/09/18 09:42	<b>General View</b>	Load JPG
6	25/09/18 09:42	<b>General View</b>	Load JPG
7	25/09/18 09:42	<b>General View</b>	Load JPG
8	25/09/18 09:42	<b>General View</b>	Load JPG
9	25/09/18 09:42	<b>General View</b>	Load JPG
10	25/09/18 09:42	<b>General View</b>	Load JPG
11	25/09/18 09:42	<b>General View</b>	Load JPG
12	25/09/18 09:42	<b>General View</b>	Load JPG
13	25/09/18 09:42	<b>General View</b>	Load JPG
14	25/09/18 09:42	<b>General View</b>	Load JPG
15	25/09/18 09:42	<b>General View</b>	Load JPG
16	25/09/18 09:42	<b>General View</b>	Load JPG
17	25/09/18 09:42	<b>General View</b>	Load JPG
18	25/09/18 09:42	<b>General View</b>	Load JPG
19	25/09/18 09:42	<b>General View</b>	Load JPG
20	25/09/18 09:42	<b>General View</b>	Load JPG
21	25/09/18 09:42	<b>General View</b>	Load JPG
22	25/09/18 09:42	<b>General View</b>	Load JPG
23	25/09/18 09:42	<b>General View</b>	Load JPG
24	25/09/18 09:42	<b>General View</b>	Load JPG
25	25/09/18 09:42	<b>General View</b>	Load JPG
26	25/09/18 09:42	<b>General View</b>	Load JPG
27	25/09/18 09:42	<b>General View</b>	Load JPG
28	25/09/18 09:47	<b>Photographs of Damaged Parts</b>	Load JPG
29	25/09/18 09:47	<b>Photographs of Damaged Parts</b>	Load JPG
30	25/09/18 09:47	<b>Photographs of Damaged Parts</b>	Load JPG
31	25/09/18 09:47	<b>Photographs of Damaged Parts</b>	Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	25/09/18 09:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	25/09/18 09:47	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
80	25/09/18 09:47	<b>Photo After Spray</b>	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016623/R1CD3S2

Date: 02/10/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700017351  
 Claimant Vehicle No: SJY2916U Insured Vehicle No: SLP42C  
 Date of Loss: 11/09/2018 Nature of Claim: TP Claim No: 2974558798SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJY2916U**  
 Make & Model: LEXUS IS250, 2.5 (A) Engine No: 4GR0191306  
 Reg. Date: 25/08/2006 (Man. Year: 2006) Chassis No: JTHBK262702014133  
 Colour: White Odometer: 132569 km  
 Engine Capacity: 2500 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 12/09/2018  
 Date Inspected: 12/09/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)  
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
 Singapore 417921  
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
6	1		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*BOOTLID	Repair	0.00 F	*- F
10	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
11	1		*BOOTLID LOCK	Bent	0.00 F	*- F
12	1		*BOOTLID RUBBER	Cut	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**
**0.00**
**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >