

ASS. REC. BY:

REF: CS3/AIG18016624/Rlcd3⁵² Special Instruction:

Survey of: ASSIGNMENT (Office)

From (Person): Mei men Chin lee ying of AIG Date/Time: 12/11/18 @ 9:36am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 6498H Insured: SKW 5170H

at Workshop m/s: Shin Automobik Tel: 6385 5922

of 15 kaki Bkt Rd 4 # 01-46

Policy No: 2100436535 Claim No: 6302934970SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02/09/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement: _____

Date/Time: 10:12am @ 12/11/18 Person Contacted: Kent Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SMD 6498H - X
	SKW 5170 H - X
	9886 8827
	Dismantle: 13/9/2018

Pass

REF: AIG

866A

ASSIGNMENT

From: _____ Date: 12/09/18

Estimated Cost: _____

OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 6498H

at Workshop n/s: Shin Automobile

of: 15 kaki Bkt Rd 4 # 01-46 Bertley Biz Centre.

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Kent @ 63855922

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. 1-24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SMD 6498H Yr Regn: 2018

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Freed 1.5 c.c. 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 000610 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 6671066473

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modf: Nil / Rim / STD A/Rim or

Tyre Size: F: 185/65R15
R: _____

BS: DUR / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 02/09/18	D.O.I. 12/09/18

Survey held at: SHIN AUTOMOBILE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
2/10	Submit DAR report.
Repair days 4	

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: DAR

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

3) \$ + RS. \$ _____

4) Photos _____

5) Other _____

TOTAL: _____

TG Lim
Lim
11/10/18

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 12/9/2018 9:36:08 AM
Attachments:  [6498.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS

Our Ref : SMD 6498H(aj)

Your Ref :

3 September 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTENTION: MOTOR CLAIMS DEPARTMENT

BY EMAIL

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : GOH BEE HOCK
ACCIDENT INVOLVING SMD 6498H & SKW 5170H ALONG DUNEARN ROAD TRAFFIC
JUNCTION BEFORE NEWTON CIRCUS ON 02 SEP 2018

1. We act for **GOH BEE HOCK**, the owner of motor vehicle no. SMD 6498H, which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKW 5170H for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Shin Automobile & Trading Pte Ltd
Address	15 Kaki Bukit Road 4 #01-46 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Pei Han (6385 5922)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next **two (2) working days** (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

Our Ref : SMD 6498H(aj)

PRE-REPAIR SURVEY (1)

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 12:39
Date Of Accident	02/09/2018 11:45
Exact Location Of Accident	DUNEARN RD TRAFFIC JUNCTION BEFORE NEWTON CIRCUS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6498H
Insured/Policyholder	
Name Of Registered Owner	GOH BEE HOCK
NRIC No	S7418666A
Email Address	BEEHOCK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96666024
Alternative Phone No	OTHERS-96666024

Vehicle Particulars

Manufacturer	HONDA
Model	FREED-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800101950
Cover Note Number	

Driver

Name of Driver	NG LAY LAY
NRIC No	S7623641J
Date Of Birth	13/08/1976
Occupation	INDOOR
Date Of Driving Pass	21/12/2001
Driving Experience	16 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90122874
Fax Number	
Contact Number	
EMail Address	NOEMAIL


01/11/2017 10:00 AM
Page 3 of 22

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2nd Sept, ~~4th~~ 11:45am, I stopped my car at the traffic light junction at Dunearn Road towards Newton Circus. After few seconds, a car banged onto the back of my car. The driver has admitted that it was her fault. J

Important:


You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

	- Reporting Only
	- Claim OD
	- Claim TP
✓	- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.


 Policyholder's signature
 Date & Time
 3/9/18
 12:55pm


 Driver's Signature
 (if driver not the policyholder)
 Date & Time 12:55pm


 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8666A
Vehicle Details	
Vehicle No.:	SMD6498H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB5599491
Chassis No.:	GB71066473
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,872.00
Original Registration Date:	29 Aug 2018
First Registration Date:	29 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$18,221.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2028
PARF Rebate Amount:	\$13,665.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,605.00
COE Rebate Amount:	\$37,321.00
Total Rebate Amount:	\$50,986.00

The information contained herein is correct as at 25 Sep 2018

OK



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : GOH BEE HOCK
Period of Insurance : 29 Aug 2018 To 28 Aug 2019
Engine No. : LEB5599491
Chassis No. : GB71066473

Vehicle No. : SMD6498H
Policy No. : 1800101950
Endorsement No. :
Issued Date : 30 Aug 2018

ABOUT THE COVER

Make/Model : HONDA FREED
Engine Capacity/Tonnage : 1,496.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Persons or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1800cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1997 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

GOH BEE HOCK - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorized Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorized Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1997 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504641000

ASSURE INSURANCE AGENCY

29 KELANTAN ROAD #01-111 KELANTAN COURT
 SINGAPORE 200029

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SAP/AD

Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



(1) Deformed (6) Shifted (9) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check ()
 (4) Not Consistent (N/C)

Vehicle No: SMD 6498H

Rear Portion

NAC	INC	Item	CON	AC	Q5
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	R	X
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM		
1159	993327	Rear End Panel	DD	R	X
1160	993339	Rear End Panel Top Garnish	DM		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD		✓
1182	991328	Tailgate Emblem	NEC		✓ 3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC		✓
1196	994607	Tailgate Glass Sealant	NEC		✓
1197	994629	Tailgate Lock	BT		✓
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	BT		✓

NAC	INC	Item	CON	AC	Q5
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994023	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

[Signature]
 11/10/2018

No of Items: 4 Assessor: _____

TALim *[Signature]* 11/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'ed	Status
Main	03 Sep 2018 Edit Reg		12 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	TSANG PAULINE MRS PAULINE ONG, ID: S0547699B		
Main Claimant:	-		
Vehicle Reg. No.:	SMD6498H	Date of Loss:	02/09/2018 00:00 - :59 [4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6302934970SG	Policy/Cover Note No.:	2100436535 (Comprehensive)
Vehicle Reg. No. (Insured):	SKW5170H	Policy No. (Claimant):	
		Excess:	
Repairer:	SHIN AUTOMOBILE & TRADING PTE LTD (HQ) 15 Kaki Bukit Rd 4, #01-46 BARTLY BIZ CENTRE, 417808 Kaki Bukit - Tel: 68355922/96868827		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/09/2018]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
• AIG_SG (13/09/2018): Request To Upload TP GIA Report			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SMD6498H (6302934970SG)
[SKW5170H]**

TP

-

**Sep 2 2018 12:00AM
[TSANG PAULINE MRS PAULINE ONG]
SHIN AUTOMOBILE & TRADING PTE LTD**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▼	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/09/18 13:20	Accident Statement From: SC - Reg. No: SKW5170H, Claimant: TSANG PAULINE MRS PAULINE ONG		Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
7	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
15	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
16	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
17	25/09/18 11:05	General View		Load JPG	<input checked="" type="checkbox"/>
18	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
19	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
20	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
21	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
22	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
23	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
24	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
25	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
26	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
27	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
28	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
29	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
30	25/09/18 11:06	General View		Load JPG	<input checked="" type="checkbox"/>
31	25/09/18 11:06	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
33	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
34	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
35	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
36	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
37	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
38	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
39	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
40	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
41	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
42	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
43	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
44	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓
45	25/09/18 11:06	Photographs of Damaged Parts	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016624/R1CD3S2
Date: 02/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100436535
Claimant Vehicle No : SMD6498H **Insured Vehicle No :** SKW5170H
Date of Loss: 02/09/2018 Nature of Claim: TP Claim No: 6302934970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD6498H**
Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5599491
Reg. Date: 29/08/2018 (Man. Year: 2018) Chassis No: GB71066473
Colour: White Odometer: 610 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/09/2018
Date Inspected: 12/09/2018 Inspected At: SHIN AUTOMOBILE & TRADING PTE LTD (HQ)
15 Kaki Bukit Rd 4, #01-46 BARTLY BIZ CENTRE
Singapore 417808
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*-F
2	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
3	1		*REAR END PANEL	Repair	0.00 F	*-F
4	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*-F
5	1		*TAILGATE	Dented	0.00 F	*-F
6	3		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
7	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F
8	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
9	1		*TAILGATE LOCK	Bent	0.00 F	*-F
10	1		*TAILGATE INNER BOARD	Bent	0.00 F	*-F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >