

ASS. REC. BY:

REF: 05/MSG18016626/R1rd302 Special Instruction:

Surveint

Member

ASSIGNMENT (Office)

From (Person): Pauline Thom of MSG Date/Time: 11/9/18 @ 4:11pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 1937G Insured: SKE 9046Cat Workshop m/s Supercolors Tel: 6702 2737of 8/ceki Bkt Ave 1 # 03-14Policy No: 27311314SVP Claim No: 569826

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/09/18
(Client's Record)CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: _____Date/Time: 5:40pm @ 11/9/18 Person Contacted: soon Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 1937G-X
	SKE 9046C-X
14/09/18	15:20 p.m. revised IA to Pauline Thom via member.
	Confirmed \$4203.96, 4 days
	Red: \$205.12, 66%.

Inspector: *Rosam*

REF: MSIG

4888I

ASSIGNMENT

From: _____ Date: **12/9/18**

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SMA 1937G**

at Workshop n/s of **Supercolors**
8 Kuki Bkt Ave 4 # 03-14

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: **Yes** or No


GIA / PR Seen: _____ Consistent?: **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lump Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. **1-24 HRS** *lup*

Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**



Veh No: **SMA 1937G** Yr Regn: **2018 / MAR**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Honda Vezel 1.5 XA** C.C. **1496**

Colour: **BLACK** A/C: **Insured / Std / NI / NA**

Sp. Reading: **007757** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **Ru 31273604**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/60 R16**
R: **1"**

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. **6** mm Rear R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **09/09/18** D.O.I. **12/09/18**

Survey held at **Supercolors**

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or **O/S FR**

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
RECEIVED 15 OCT 2018	
	<i>[Signature]</i> 17/9

Date/Time, File Pass to? : Preli. Report

1) *typist* : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : **TP**

Lump Sum / I.B.I: (\$) **4203.96**

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: **200**

Transportation: _____

) S + RS, ___ \$

) Photos

) Others: **10**

TOTAL: **210**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		11 Sep 2018 16:11 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MICHELLE THAM MAY SHEAR, ID: S7639167Z, Tel: +6596384269, Email: michtham@gmail.com		
Main Claimant:	TAN KIAN TECK (CHEN JIANDE), ID: S7724888I		
Vehicle Reg. No.:	SMA1937G	Date of Loss:	09/09/2018 12:00 - :59 [3 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569826	Policy/Cover Note No.:	27311314SVP (Comprehensive) Coverage: 13/04/2018 - 12/04/2019
Vehicle Reg. No. (Insured):	SKE9046C	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Supercolors Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #03-14 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 94507920		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]		
Driver/Custodian (Insured):	MICHELLE THAM MAY SHEAR (41 / Female), NRIC: S7639167Z, Tel: +6596384269		
Adj Asg. Remarks:	Liability 50%, SJE agree - LKK, Contact : Gwen at 6702 2737		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SUPERCOLORS PTE LTD

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit,
#03-14 Singapore 415875
Tel: 6702 2737 | Fax: 6702 2767
✉ supercolors88@gmail.com

Date: 11 Sept 2018

MSIG INSURANCE (S) PTE LTD
4 Shenton Way
SGX CENTRE
Singapore 068807

claims@sg.msig-asia.com

Attn: Motor Claims Department

Dear Sir/Madam

RE: Pre-Repair Inspection for SMA1937G Accident on 9 September 2018 at 12.50pm Along Elias Road Exit to TPE involving vehicle no: SKE9046C

We are instructed by Tan Kian Teck (Chen Jiande) to notify you of a road traffic accident on **9 September 2018 at 12.50pm Along Elias Road Exit to TPE** involving our client's vehicle registration no: **SMA1937G** and vehicle no: **SKE9046C** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please contact me at 6702 2737 should you require more information.

Yours faithfully

GWEN TAY

LKK

SUPERCOLORS PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2018 14:06
Date Of Accident	09/09/2018 12:50
Exact Location Of Accident	ELIAS ROAD EXIT TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA1937G
Insured/Policyholder	
Name Of Registered Owner	TAN KIAN TECK (CHEN JIANDE)
NRIC No	S7724888I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96217572
Alternative Phone No	OTHERS-96217572

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100903272 CLASSIC
Cover Note Number	

Driver

Name of Driver	TAN KIAN TECK (CHEN JIANDE)
NRIC No	S7724888I
Date Of Birth	31/08/1977
Occupation	INDOOR
Date Of Driving Pass	03/11/1995
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96217572
Fax Number	
Contact Number	OTHERS-96217572
EMail Address	NOEMAIL

Address 03 PASIR RIS HEIGHTS #11-08 VUE 8 RESIDENCE
 Postcode 519284
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions SLIGHT DRIZZLE
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : ASHLYN
 GENDER: : FEMALE
 Passenger 2 NAME: : ASHLEY
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKE9046C
 Vehicle Make/Model/Colour PEUGEOT RCZ 1.6 TURBO MANUAL HID
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 9/10/08 11:31

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933


Tel: 67416697 Fax: 67492305

Email: caakb@singapore.com.sg

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

EXITING ~~SAHS~~ ^{ELATS} ROAD TO TPE. WHILE I HAVE COMPLETE CHANGE LANE AFTER EXIT, SKE 9046C SPEED UP BEHIND AND TRY TO CUT IN FRONT BY SWAYING INTO MY LANE HIT MY FRONT RIGHT TIRE.

I HAVE VIDEO ~~CHANGING~~ CAPTURING FROM EXIT TO IMPACT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 9/9/18 1415H

Driver's Signature

(If driver is not the policyholder)
Date & Time:

TDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SUPERCOLORS PTE LTD

8 Kaki Bukit Avenue 4 #03-14
 Premier@ Kaki Bukit Singapore 415875
 Co Reg No: 201707578M
 ✉ supercolors88@gmail.com

Vehicle No.: SMA 1937 G
 Make/ Model: HONDA VEZEL

Date: 11 September 2018

Dear Sirs,

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>DESCRIPTION:</u>	<u>AMOUNT(\$S)</u>
	<u>List Items</u>	
1	Front headlamp - LED	\$ 1,784.50 ? CRA /
1	Front headlamp lower bracket	\$ 75.30 ? x su
1	Front bumper	\$ 1,085.40 repair
1	Front bumper fog lamp	\$ 327.70 X
1	Front bumper fog lamp cover	\$ 45.20 X } su
1	Front bumper side retainer	\$ 60.30 X }
1	Front fender -R/H	\$ 580.40 BT
1	Front fender inner shield	\$ 155.50 X n
1	Front fender "HYBRID" emmblem	\$ 58.00 re -
1	Front fender wheel arch garnish	\$ 488.30 su -
1	Front wheel rim	\$ 1,350.40 S/N 800 - \$ price? su -
1	Front wheel hub	\$ 299.70 X
1	Front wheel bearing	\$ 181.50 X
1	Front shock absorber	\$ 501.20 X } su
1	Front knuckle arm	\$ 600.70 X }
1	Front lower arm	\$ 426.00 X }
1	Front drive shaft	\$ 985.00 X }
		\$ 9,005.10 2911.20
	Discount 20%	\$ 1,801.02 20%
		\$ 7,204.08 <u>2328.96</u>

Special Nett Items

1	Front bumper clip (1 set)	\$	45.00	<i>mm</i>
1	Front bumper lower spoiler	\$	750.00	<i>X</i>
1	Front fender inner shield clip (1 set)	\$	50.00	<i>X } mm</i>
1	Front tyre	\$	350.00	<i>X } 45</i>
		\$	1,195.00	

Total cost of parts : \$ 8,399.08

S/N. Labour Charges

1	To check wiring and reset headlamps focusing.	\$	80.00 30	<i>} 880</i>
2	To remove and refit front undercarriage.	\$	450.00 <i>X mm</i>	
3	To conduct wheel alignment.	\$	180.00 60	
4	To apply undercoating.	\$	200.00 40	
5	Panel beating.	\$	1,600.00 350	
6	To re-spray painting on the affected areas.	\$	1,500.00 400	
		\$	4,010.00	

Grand Total : \$ 12,409.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
4 days
P/P
12/09/18 @ 1645
Resurvey of paint
13299.08
[Signature]
7/9/18



Payment Invoice

Thank you for choosing SENSHA – No.1 Japan Crystal Coating & Paint Protection Film

Date: 17 June 2018
 Invoice Number: C8-233
 Customer ID: 96217572-C8-233


Description	Qty	Price	Discount	Amount
SENSHA 8 (Eight) Years Crystal Glow SMA1937G	1	\$1,200	30%	\$840
(SENSHA Window Crystal)	1	FOC		FOC
(SENSHA Wheel Crystal)	1	FOC		FOC
(SENSHA Bumper Crystal)	1	FOC		FOC
*FOC – Free of Charge Door Cups (PPF)	1	\$80	Package Price	\$50
-----Last Entry-----				

Bank transfer via 712380146001 OCBC

Total Amount Payable: ~~\$890~~

(L) Coating - \$150

150



Company Stamp

Mr Steve Tan
 SENSHA Customer

2328.96
 45.00
 880.00
 150.00

 3403.96
 4 days
 P/P

SENSHA Singapore
 Appointment booking/ Enquires/ Warranty Claims – (M) +65 9727 0001
 Marc Yeo (Manager/Detailing Specialist) – (M) +65 8533 4607
 Fuji Syuusuke (A.Manager/Detailing Specialist) – (M) +65 9871 9797

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		11 Sep 2018 16:11 Edit Adj Rpt	S\$4,203.96 Edit Estimates	S\$4,203.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MICHELLE THAM MAY SHEAR , ID: S7639167Z, Tel: +6596384269, Email: michtham@gmail.com								
Main Claimant:	TAN KIAN TECK (CHEN JIANDE) , ID: S7724888I								
Vehicle Reg. No.:	SMA1937G	Date of Loss:	09/09/2018 12:00 - :59 [3 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569826	Policy/Cover Note No.:	27311314SVP (Comprehensive) Coverage: 13/04/2018 - 12/04/2019						
Vehicle Reg. No. (Insured):	SKE9046C	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Supercolors Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #03-14 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 94507920								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/10/2018]								
Driver/Custodian (Insured):	MICHELLE THAM MAY SHEAR (41 / Female), NRIC: S7639167Z, Tel: +6596384269								
Adj Asg. Remarks:	Liability 50%, SJE agree - LKK, Contact : Gwen at 6702 2737								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMA1937G (569826)
[SKE9046C]
TP
TAN KIAN TECK (CHEN JIANDE)
Sep 9 2018 12:00PM
[MICHELLE THAM MAY SHEAR]
Supercolors Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print			
1	27/09/18 17:13	TP Video - Accident						Load MP4			
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print			
1	11/09/18 13:31	Accident Statement <small>From: SC - Reg. No: SKE9046C, Claimant: MICHELLE THAM MAY SHEAR</small>						Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	14/09/18 15:20	Adjuster Immediate Advice						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
2	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
3	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
4	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
5	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
6	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
7	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
8	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
9	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
10	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
11	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
12	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
13	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
14	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
15	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
16	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
17	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
18	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
19	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
20	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
21	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
22	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
23	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
24	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
25	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
26	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
27	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			
28	15/10/18 12:57	General View						Load JPG <input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
30	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
31	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
32	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
33	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
34	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
35	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
36	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
37	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
38	15/10/18 12:57	General View	Load JPG	<input checked="" type="checkbox"/>
39	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	15/10/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
51	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
52	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
53	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
54	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
55	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
56	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
57	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
58	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
59	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
60	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
61	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
62	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
63	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
64	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>
65	15/10/18 14:03	Reinspection Photo 2	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/09/18 13:36	SMA1973G E-FILE REPORT	Load PDF	
2	11/09/18 13:36	Survey Agree on SJE - LKk	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016626/R1RD3E2
Date: 18/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27311314SVP
Claimant Vehicle No : SMA1937G	Insured Vehicle No :	SKE9046C
Date of Loss: 09/09/2018	Nature of Claim:	TP
		Claim No: 569826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1937G	Engine No:	LEB5973609
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31273604
Reg. Date:	30/05/2018 (Man. Year: 2017)	Odometer:	7757 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,399.08	3,173.96	5,225.12	62.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,030.00	3,870.00	78.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,299.08	4,203.96	9,095.12	68.39

INSPECTION

Date of Assignment:	11/09/2018	
Date Inspected:	12/09/2018	Inspected At: Supercolors Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #03-14 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2018)	
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMA1937G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT HEADLAMP - LED	Cracked	1,784.50 FL	*1,784.50 FL	
2	1		*FRONT HEADLAMP LOWER BRACKET	Serviceable	75.30 FL	*- FL	
3	1		*FRONT BUMPER	Repair	1,085.40 FL	*- FL	
4	1		*FRONT BUMPER FOG LAMP	Serviceable	327.70 FL	*- FL	
5	1		*FRONT BUMPER FOG LAMP COVER	Serviceable	45.20 FL	*- FL	
6	1		*FRONT BUMPER SIDE RETAINER	Serviceable	60.30 FL	*- FL	
7	1		*FRONT FENDER - R/H	Bent	580.40 FL	*580.40 FL	
8	1		*FRONT FENDER INNER SHIELD	Not Necessary	155.50 FL	*- FL	
9	1		*FRONT FENDER HYBRID EMBLEM	Necessary	58.00 FL	*58.00 FL	
10	1		*FRONT FENDER WHEEL ARCH GARNISH	Scratched	488.30 FL	*488.30 FL	
11	1		*FRONT WHEEL RIM	Scratched	1,080.32 FS	*800.00 FS	
12	1		*FRONT WHEEL HUB	Serviceable	299.70 FL	*- FL	
13	1		*FRONT WHEEL BEARING	Serviceable	181.50 FL	*- FL	
14	1		*FRONT SHOCK ABSORBER	Serviceable	501.20 FL	*- FL	
15	1		*FRONT KNUCKLE ARM	Serviceable	600.70 FL	*- FL	
16	1		*FRONT LOWER ARM	Serviceable	426.00 FL	*- FL	
17	1		*FRONT DRIVE SHAFT	Serviceable	985.00 FL	*- FL	
18	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS	
19	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	750.00 FS	*- FS	
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS	
21	1		*FRONT TYRE	Not Necessary	350.00 FS	*- FS	
					Sub Total (S\$)	9,930.02	3,756.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,530.94	582.24
					Total Parts (S\$)	8,399.08	3,173.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	450.00	0.00
2	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
3	TO APPLY UNDERCOATING	New	200.00	40.00
4	PANEL BEATING	New	1,600.00	350.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	400.00
6	COATING & PAINT PROTECTION FILM	New	890.00	150.00
7	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
Gross Labour Cost (S\$)			4,900.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >