



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/09/18/2022

From: SMRT Taxis Pte Ltd

Date: 17/9/2018


**ACCIDENT ON 06/09/2018 INVOLVING SHC 4321L & SLK 7536A
AT THE JUNCTION OF MOUNTBATTEN RD & MARGATE RD**

This is to confirm that the daily rental rate for SHC 4321L is \$113.96 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV181200178
Date : 11.12.2018
Vehicle No. : SHC4321L
Your Ref No. : TAX/09/18/2022
Our Ref No. : 24097846
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
BUMPER FRT	1.00	\$ 482.00	(25.00)	\$ 120.50	\$ 361.50
BUMPER SUPPORT F/RH	0.00	\$ 76.40	(25.00)	\$ 0.00	\$ 0.00
LENS & BODY, FR TURN RH	1.00	\$ 511.80	(10.00)	\$ 51.18	\$ 460.62
BRACKET, FR TURN UPPER RH	0.00	\$ 24.40	(25.00)	\$ 0.00	\$ 0.00
BRACKET, FR TURN LOWER RH	0.00	\$ 26.00	(25.00)	\$ 0.00	\$ 0.00
NUMBER PLATE	1.00	\$ 15.00	0.00	\$ 0.00	\$ 15.00
NUMBER PLATE FRAME	1.00	\$ 12.00	0.00	\$ 0.00	\$ 12.00
BRACKET, FR BUMPER	1.00	\$ 110.40	(25.00)	\$ 27.60	\$ 82.80
BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$ 311.10	(25.00)	\$ 0.00	\$ 0.00
BUMPER ENERGY ABSORBER FRT	0.00	\$ 78.80	(25.00)	\$ 0.00	\$ 0.00
BUMPER REINFORCEMENT FRT	0.00	\$ 498.40	(25.00)	\$ 0.00	\$ 0.00
ARM SUB-ASSY, FR BUMPER RH	0.00	\$ 250.40	(25.00)	\$ 0.00	\$ 0.00
COVER, FR BUMPER HOLE RH	1.00	\$ 18.50	(25.00)	\$ 4.62	\$ 13.88
BUMPER FRT ABSORBER LOWER	0.00	\$ 127.70	(25.00)	\$ 0.00	\$ 0.00
HEAD LAMP RH	1.00	\$ 945.20	(10.00)	\$ 94.52	\$ 850.68
SUPPORT SUB-ASSY	0.00	\$1460.40	(25.00)	\$ 0.00	\$ 0.00
FENDER FRT/RH	1.00	\$ 723.40	(25.00)	\$ 180.85	\$ 542.55
NAME PLATE (HYBRID)	1.00	\$ 51.90	(25.00)	\$ 12.97	\$ 38.93
FENDER LINER FRT/RH	1.00	\$ 171.70	(25.00)	\$ 42.92	\$ 128.78
WHEEL DISC. FRONT	0.00	\$1484.20	(25.00)	\$ 0.00	\$ 0.00
HOOD PANEL:FOR TOYOTA PRIUS TAXI	0.00	\$ 748.10	(25.00)	\$ 0.00	\$ 0.00
BRACKET, FR TURN	0.00	\$ 58.20	(10.00)	\$ 0.00	\$ 0.00
BUMPER LIP FRT	1.00	\$ 139.60	(25.00)	\$ 34.90	\$ 104.70
Sub-Total					\$ 2611.44

Labour

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV181200178
Date : 11.12.2018
Vehicle No. : SHC4321L
Your Ref No. : TAX/09/18/2022
Our Ref No. : 24097846
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
TO REPAIR RH FRONT PORTION	1.00	\$ 400.00	0.00	\$ 0.00	\$ 400.00
Others					
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT SUPPORT PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT FENDER RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO REPSRAY FRONT HOOD	0.00	\$ 378.00	0.00	\$ 0.00	\$ 0.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	\$ 40.00	0.00	\$ 0.00	\$ 40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	1.00	\$ 148.44	0.00	\$ 0.00	\$ 148.44
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
GRAND TOTAL					\$ 3,619.88

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 06.09.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorized Signature
for SMRT Automotive Services Pte Ltd



Laid Up Report

Accident Start Date : 06/09/2018

Date Generated : 02/10/2018

Accident End Date : 03/10/2018

User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/09/18/2022	SHC4321L	SMRT Taxis Pte Ltd	TOYOTA	PRIUS	24097846	07/09/2018 12:08 PM	19/09/2018 2:30 PM

mountbatten Road

Margate Road.

A-SHC4321

B-SLK7536

[illegible]

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



07-09-18
Driver's Signature
(If driver is not the policyholder)
Date & Time:

7/9/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/09/2018 11:57
Date Of Accident	06/09/2018 20:30
Exact Location Of Accident	MOUNTBATTEN ROAD/MARGATE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4321L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN ANN KAH
NRIC No	S0218440J
Date Of Birth	01/07/1951
Occupation	OUTDOOR
Date Of Driving Pass	27/11/1975
Driving Experience	42 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRVELLING STRAIGHT ALONG MOUNTBATTEN ROAD TOWARDS EAST COAST ROAD WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. SUDDENLY A VEHICLE SLK7536A CAME OUT FROM MARGATE ROAD WITHOUT STOPPING AT THE STOP LINE, AS SUCH COLLIDED ONTO THE RIGHT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLK7536A
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver KOW TECK YONG
 NRIC/Passport Number S7034878J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Enquire Transaction History

Transaction History Details

Log Date/Time: 07 Sep 2018 / 12:19:26

Asset Type: Vehicle

Transaction Amount: \$7.49

Asset ID: SLK7536A

Transaction Type: 18.32 Insurance Enquiry (GIRO Payment)

Channel: External Agency

User ID: ESASBAH0 - BALQISH BINTE ABDUL HALIL

Business Transaction
Reference No.: 20180907121926286253

Search Date / Time: 06 Sep 2018 20:30:00

Insurance Company: **AIG ASIA PACIFIC INSURANCE PTE. LTD.**

Information displayed is correct as at the log date and time.

Enquire Related Logs

[Back to List](#)