(08/11/13)

Surveyor: Taufik

REF: ASM(AXA)

# ASSIGNMENT

WE 2022 NOV

From: Date: 13092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 2243D

at Workshop m/s Sng Ah Tee

of Blk 3 Pioneer Rd North #01-18

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 'Virtual Case'

(Policy Condition) Morning

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: $28K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJA 2243D Yr Regn: 2007 Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Airwave c.c 1496

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GJ1203693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/70R14

R: 2 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | | D.O.I. | 13/9/18 @ 3pm |

Survey held at Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | Lasting weeks. Repair limit $10K, |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ )

☐ : Interview ($ )

☐ : Tech. Invs ($ )

☐ : Weekend ($ )

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL