

22/03/2002

ASS. REC. BY:

REF:

CS3 / msln1801668 / Gcbet

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

msln

Date/Time:

12/09/2018 4.13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 723Z

Insured:

XE 306IT

at Workshop m/s

Guan Auto

Tel:

9388 4210

of

Blk 7 Sin Ming Ind Est #01-82

Policy No:

B2397 0951 MKC

Claim No:

569935

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/09/2018

CA / REV / REP. / REV 24 HRS w/p

13.09.2018

H.O.D. Endorsement:

Date/Time:

12/09/2018 4.13pm

Person Contacted:

Jacky

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLH 723Z - X

XE 306IT - X

Dismantle: 14/9/2018

PRs
Surveillance

PRs

Xhl.

REF: MSU4

13879 /

ASSIGNMENT

From: Date: 13092018

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 72232

at Workshop m/s

of Btk 7 sin ming #01-82

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. /-24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 72232 Yr Regn: 11 Oct 2016

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda civic C.C 1597

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 74897 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR HFC 5650 GT 000411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$6000 - \$7000

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I: (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	11 Sep 2018		12 Sep 2018 16:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		SAMWOH RESOURCES PTE LTD , Co. Reg. No.: 199105225W [Created by insurer]							
Main Claimant:		THAM KIN YUEN , ID: S1111387G							
Vehicle Reg. No.:		SLG7223Z	Date of Loss: 10/09/2018 11:00 - :59 [22 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:		TP / 569935	Policy/Cover Note No.: B28970951MKC (Comprehensive) Coverage: 07/06/2018 - 06/06/2019						
Vehicle Reg. No. (Insured):		XE3061T	Policy No. (Claimant): Excess: S\$2,000.00						
Repairer:		Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/09/2018]							
Driver/Custodian (Insured):		YIN JIANGUO (39 / Male), NRIC: G5241696K, Tel: +6587832017							
Adj Asg. Remarks:		SJE - DISAGREED LIABILITY : 100% Please appoint LKK AUTO CONSULTANTS ONLY for this case (SAMWOH RESOURCES PTE LTD) Kindly contact MR JACKY @ 9388 4210 to arrange for survey .							
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
<input type="checkbox"/>	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1387G
Vehicle Details	
Vehicle No.:	SLG7223Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	R16B21600519
Chassis No.:	MRHFC5650GT000411
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,541.00
Original Registration Date:	11 Oct 2016
First Registration Date:	11 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$19,541.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Oct 2026
PARF Rebate Amount:	\$14,655.00
Intended COE Rebate Details	
COE Expiry Date:	10 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$41,572.00
Total Rebate Amount:	\$56,227.00

The information contained herein is correct as at 14 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 16:51
Date Of Accident	10/09/2018 11:50
Exact Location Of Accident	JUNCTION BETWEEN OLD TAMPINES RD AND LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG7223Z
Insured/Policyholder	
Name Of Registered Owner	THAM KIN YUEN
NRIC No	S1111387G
Email Address	SIMON1660@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-90302930
Alternative Phone No	OFFICE-90302930

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 VTI (A)
Exact Purpose for which vehicle was being used at time of accident	LUNCH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V13386/VPC2/R00
Cover Note Number	

Driver

Name of Driver	THAM KIN YUEN
NRIC No	S1111387G
Date Of Birth	20/06/1955
Occupation	INDOOR
Date Of Driving Pass	19/11/1976
Driving Experience	41 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90302930
Fax Number	
Contact Number	OFFICE-90302930
EEmail Address	SIMON1660@YAHOO.COM.SG

Address	APT BLK 972 HOUGANG STREET 91 #13-194
Postcode	530972
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3061T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YIN JIANGUO
NRIC/Passport Number	G5241696K
Contact Number	90914838
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Vehicle No SLG 7223ZSKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Loyang Avenue



Old Tampines Road

Please continue in Annex E

Sketch Plan Pg. 2

Vehicle No SLG 72232


Annex E

Describe Circumstances of the Accident


On 10/9/18 at about 11.30 hrs, I was driving along old tampines road heading towards Luyang Avenue.
 Due to On coming traffic at Luyang Avenue, I slow my car down to a stop at the junction of old Tampines Road and Luyang Avenue as my car stationary.
 Suddenly, vehicle B XT 2061-T come from behind and hit into the rear of my car.

Declaration

We declare the foregoing particulars are true in every respect.

 10/9/2018 @ 16:20hrs.
 Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		12 Sep 2018 16:13 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SAMWOH RESOURCES PTE LTD , Co. Reg. No.: 199105225W									
Main Claimant: THAM KIN YUEN , ID: S1111387G									
Vehicle Reg. No.: SLG7223Z		Date of Loss: 10/09/2018 11:00 - :59 [22 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 569935		Policy/Cover Note No.: B28970951MKC (Comprehensive) Coverage: 07/06/2018 - 06/06/2019							
Vehicle Reg. No. (Insured): XE3061T		Policy No. (Claimant):							
		Excess: S\$2,000.00							
Repairer: Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 13/09/2018]									
Driver/Custodian (Insured): YIN JIANGUO (39 / Male), NRIC: G5241696K, Tel: +6587832017									
Adj Asg. Remarks: SJE - DISAGREED LIABILITY : 100% Please appoint LKK AUTO CONSULTANTS ONLY for this case (SAMWOH RESOURCES PTE LTD) Kindly contact MR JACKY @ 9388 4210 to arrange for survey .									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents








































***SLG7223Z (569935)**
[XE3061T]
TP
THAM KIN YUEN
Sep 10 2018 11:00AM
[SAMWOH RESOURCES PTE LTD]
Guan Auto Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	12/09/18 10:02	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: XE3061T, Claimant: SAMWOH RESOURCES PTE LTD</small>	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	16/09/18 21:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	16/09/18 21:19	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
32	16/09/18 21:19	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
33	17/09/18 11:31	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/09/18 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	17/09/18 11:31	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/09/18 10:02	TPD SLG7223Z GIA REPORT From: SC - Reg. No: XE3061T, Claimant: SAMWOH RESOURCES PTE LTD		Load PDF	
2	12/09/18 10:13	Reject email to TP Lawyer & appoint LKK AUTO		Load PDF	
3	12/09/18 10:13	TPD SLG7223Z - PRI		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016668/GCBE2

Date: 18/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28970951MKC

Claimant Vehicle No : SLG7223Z

Insured Vehicle No : XE3061T

Date of Loss: 10/09/2018

Nature of Claim: TP

Claim No: 569935

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG7223Z

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B21600519

Reg. Date: 11/10/2016 (Man. Year: 2016)

Chassis No: MRHFC5650GT000411

Colour: Silver

Odometer: 34897 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/09/2018

Date Inspected: 13/09/2018 Inspected At:

Guan Auto Service (Sin Ming)
Block 7 Sin Ming Industrial Estate Sector
C, #01-80/ # 01-82
Singapore 575642

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2018)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7223Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >