

ASS. REC. BY:

REF:

CS3/CT118016673/Rldbet

Special Instruction:

Surveyor:

Rusell

ASSIGNMENT (Office)

Mummen

From (Person):

Irene Tay

of

CT1

Date/Time:

12092018 4:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 2278Y

Insured:

GBC 2046R

at Workshop m/s

Freecion Autodrive

Tel:

8702 3533

of

25 Kaki Bukit Rd 4 #03-33

Policy No:

DMCVSN 30588 71804

Claim No:

SNM18D04413002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08092018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

12092018 14:44pm

Person Contacted:

Limki

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKS 2278Y - X
	GBC 2046R - X
	Diamond: 13/9/2018
	After repair: 17/9/2018

Surveyor: PRM

REF:

3887A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKS 22784at Workshop m/s PRECISIONof 25, KKK, RMT RD 4 #03-33Insured: CTI, PRS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKS 22784 Yr Regn: 2010 / MAYType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante 1.6 A c.c. 1891Colour: PURPLE A/C: Insured / Std / NI / NASp. Reading: 109032 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM H0U41BMA4019768Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/452R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 08/05/18 D.O.I. 12/09/18Survey held at PRECISION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S PRS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$3,000 - \$4,000

Date/Time, File Pass to?

☐: Preli. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: _____

Photos

Others

TOTAL

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)Report Format: PRS.

Lump Sum / I.B.I: (\$ _____)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		12 Sep 2018 16:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CHEONG WING HUNG JOEL		
Vehicle Reg. No.:	SKS2278Y	Date of Loss:	08/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04413C02	Policy/Cover Note No.:	DMCVSN3038871804
Vehicle Reg. No. (Insured):	GBC2046R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Freesion Autodrive (Kaki Bukit) 25 Kaki Bukit Rd 4, Synergy @KB #03-33, 417800 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3889A
Vehicle Details	
Vehicle No.:	SKS2278Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	G4FCAU848544
Chassis No.:	KMH DU41BMAU019768
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,463.00
Original Registration Date:	26 May 2010
First Registration Date:	26 May 2010
Transfer Count:	2
Actual ARF Paid:	\$11,463.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2020
PARF Rebate Amount:	\$6,304.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$24,229.00
COE Rebate Amount:	\$3,433.00
Total Rebate Amount:	\$9,737.00

The information contained herein is correct as at 17 Sep 2018

OK

MSME18116867 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 10/09/2018 12:19
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 12:19
Date Of Accident	08/09/2018 22:00
Exact Location Of Accident	ALONG CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS2278Y
Insured/Policyholder	
Name Of Registered Owner	CHEONG WING HUNG JOEL
NRIC No	S8613889A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81333412
Alternative Phone No	OFFICE-81333412

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA393993
Cover Note Number	

Driver

Name of Driver	CHEONG WING HUNG JOEL
NRIC No	S8613889A
Date Of Birth	11/05/1986
Occupation	INDOOR
Date Of Driving Pass	17/12/2007
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81333412
Fax Number	
Contact Number	OFFICE-81333412
Email Address	NOEMAIL

Address BLK 7 COMMONWEALTH AVE #12-654
 Postcode 140007
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180909/7000.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC2046R
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
 - (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Name: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Sketch Plan #2 Pg. 1

PLAN



A = SKS2278Y

B = GBC2046R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report.

DECLARATION

We declare the foregoing particulars are true in every respect

[Signature]

Witness's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

10/9/18 f 9.55AM

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1


LETTER OF UNDERTAKING

I/We, Cheong Wing Hung, Joel, the owner of vehicle no. SKS2278Y

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Fraction Auto

Signed and Acknowledge by:

S8613889A 

.....
Nric no. and signature of policyholder

.....
Company Stamp

10/09/2018
Date

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180909/7000

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180909/7000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2018 09:04		Vide Report No.:	Station Diary No.:
Informant's Particulars			
Name of Informant: CHEONG WING HUNG, JOEL		Address: APT BLK 7 COMMONWEALTH AVENUE #12-654 SINGAPORE 140007	
ID Type / ID No.: NRIC NO / S8613889A		Contact No.: Home/Office: Mobile: 81333412	
Nationality: SINGAPORE CITIZEN		Email: leoic2@gmail.com	
Sex: Male	Age: 32	Date of Birth: 11/05/1986	Type of Informant: Vehicle Owner
Race: Chinese		Language: English	Institution / School Name:
Occupation: Marine engineer (shore-based)		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 08/09/2018 22:00	Type of Location: Straight Road
Location: CLEMENTI ROAD				
Weather: Cloudy		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC2046R	Van	OTHERS	UNKNOWN	White	Slightly Damaged	1
SKS2278Y	Car	HYUNDAI	Avante 1.6 AT ABS D/AB 2D 4DR	Maroon	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180909/7000

2 of 3

Report No. T/20180909/7000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBC2046R		UNKNOWN		
SKS2278Y	AXA INSURANCE SINGAPORE PTE LTD	GA393993/1	29/08/2018	28/08/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	CHEONG WING HUNG, JOEL	ID No.	S8613889A
Related Vehicle	NIL	Contact No.	81333412
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Parked vehicle along single yellow line along Clementi Rd towards Bukit Timah at 9.15pm. Location around 5 Clementi Road, opposite Fong Seng food shop. Returned at approximately 11.00pm and found the front right headlight, bumper and hood area to be damaged. Checked dashboard camera recording and found at 9.58pm a van had swiped my car while attempting to turn left. Van vehicle number: GBC2046R. I have pictures and videos exceeding 2 MB.

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180909/7000

3 of 3

Report No. T/20180909/7000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
09/09/2018 09:04

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2018		12 Sep 2018 16:02 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: CHEONG WING HUNG JOEL									
Vehicle Reg. No.: SKS2278Y		Date of Loss: 08/09/2018 00:00 - :59 [99 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04413C02		Policy/Cover Note No.: DMCVSN3038871804							
Vehicle Reg. No. (Insured): GBC2046R		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Freesion Autodrive (Kaki Bukit) 25 Kaki Bukit Rd 4, Synergy @KB #03-33, 417800 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/09/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS2278Y (SNM18D04413C02)
[GBC2046R]
TP
CHEONG WING HUNG JOEL
Sep 8 2018 12:00AM
[-]
Freesion Autodrive

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

17/09/18 17:07

General View

Load PDF

2

17/09/18 17:07

Photographs of Damaged Parts

Load PDF

3

24/09/18 18:58

Photo After Spray

Load PDF

Documentation

1 per page

No

Finalized On

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Thumbnail

Print

1

12/09/18 16:02

PRS WITH TP GIA

Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016673/R1CBE2

Date: 25/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3038871804

Claimant Vehicle
No : SKS2278YInsured Vehicle
No : GBC2046R

Date of Loss: 08/09/2018

Nature of Claim: TP

Claim
No: SNM18D04413C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS2278Y

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Reg. Date: 26/05/2010 (Man. Year: 2010)

Colour: Purple

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G4FCAU848544

Chassis No: KMHDU41BMAU019768

Odometer: 109032 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17

Rear Tyre Size: 215/45Z R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/09/2018

Date Inspected: 12/09/2018 Inspected At:

Freesion Autodrive (Kaki Bukit)
25 Kaki Bukit Rd 4, Synergy @KB #03-33
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS2278Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >