

ASS. REC. BY:

REF:

183 / CT118016674 / Gcb

Special Instruction:

SIMVAJOY
MELIMAN

ASSIGNMENT (Office)

From (Person):

Elaine Cheung

of

CTI

Date/Time:

22/09/2018 3:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 8222Z

Insured:

GBC 9018B

at Workshop m/s

Speedy Motor

Tel:

of

Blk 10 Park Ind Ind Park 2A #05-21

Policy No:

DMCVSN3007431602

Claim No:

SNM180DL410C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/09/2018

CA / REV / REP. / REV 24 HRS WPI

13-09-2018

H.O.D. Endorsement:

Date/Time:

13/09/2018 12:46pm

Person Contacted:

Mr. Lim

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBE 8222Z - CCB/AXA 11020529 / Ahdf1 DCA: 03.10.11
	GBC 9018B - X
	Dismantle: 14/9/2018
	No CIA


PRS
Khal

REF: CTZ

ASSIGNMENT

From: _____ Date: 13092018
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBE 8222
at Workshop m/s Speedy meter
of B1k 10 AMK Ind Park St #05-21
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rport: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: FBE 8222 Yr Regn: Aug 09
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda CB 400 c.c 399
Colour: Blsek A/C: Insured / Std / NI / NA
Sp. Reading: 126374 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JH 2NC 429 18 M 0000 18
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Oil / S/Rim / STD A/Rim or
Tyre Size: F: 120 / 60ZR17
R: 160 / 60ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 5 mm Rear R/Bal. 5 mm
L/Bal. mm L/Bal. mm
D.O.A. D.O.I. 13-09-18
Survey held at W/S 1:30 pm
Des. of Damages: Frt / Rear / DIS / NIS / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$2000 - \$3000

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?
2)
Report Format : PRS
Lump Sum / I.B.I: (\$)

Days Of Repair: 3
Resurvey No. of Trip: 1
Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
Survey Fee: 150
Transportation: _____ S + RS, SI
Photos
Others
TOTAL 150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		12 Sep 2018 15:46 Assign				New Assignment Cancel Case

[Main](#) [Reference](#) [Claim Details](#) [Documents](#) [Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MUHAMAD FADLY BIN ASMAWI		
Vehicle Reg. No.:	FBE8222Z	Date of Loss:	07/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04410C02	Policy/Cover Note No.:	DMCVSN3007431802
Vehicle Reg. No. (Insured):	GBC9018B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE8222Z		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CB400		
Chassis No. :	JH2NC42918M000018		
Propellant :	Petrol		
Engine No. :	NC42E1003071		
Engine Capacity :	399 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	384 kg		
Unladen Weight :	194 kg		
Year Of Manufacture :	2008		
Original Registration Date :	07 Aug 2009		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$902.00		
COE Expiry Date :	06 Aug 2019		
Road Tax Expiry Date :	06 Aug 2019		
Inspection Due Date :	06 Aug 2019		
Intended Transfer Date :	24 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1794H
Vehicle Details	
Vehicle No.:	FBE8222Z
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	NC42E1003071
Chassis No.:	JH2NC42918M000018
Maximum Power Output:	-
Open Market Value:	\$8,632.00
Original Registration Date:	07 Aug 2009
First Registration Date:	07 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$1,295.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Aug 2019
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$902.00
COE Rebate Amount:	\$78.00
Total Rebate Amount:	\$78.00

The information contained herein is correct as at 24 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2018 12:57
Date Of Accident	07/09/2018 12:15
Exact Location Of Accident	JUNCTION OF BEDOK NORTH AVE 3 & BEDOK NORTH ST 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE8222Z
Insured/Policyholder	
Name Of Registered Owner	MUHAMAD FADLY BIN ASMAWI
NRIC No	S8101794H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97471925
Alternative Phone No	OFFICE-97471925

Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5092625516-01
Cover Note Number	

Driver

Name of Driver	MUHAMAD FADLY BIN ASMAWI
NRIC No	S8101794H
Date Of Birth	19/01/1981
Occupation	INDOOR
Date Of Driving Pass	26/12/2000
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97471925
Fax Number	
Contact Number	OFFICE-97471925
EMail Address	NOEMAIL

Address APT BLK 401 BEDOK NORTH AVENUE 3 #08-303
 Postcode 460401
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions DRIZZLING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name AZZERI
 Phone Number 91820102
 Email Address

Details of Witness 2

Name ZY
 Phone Number 93878230
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC9018B
 Vehicle Make/Model/Colour
 Details Of Properties

Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMAD FADLY BIN ASMAWI
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBE8222Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: _____


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: _____


 Reporting Centre Personnel's Signature
 Name: Jerleen
 NRIC/FIN No.: _____

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report NO: T/20180907/2132

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver's not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Jereen
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180907/2132

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 3

Report No. T/20180907/2132

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBE8222Z	NTUC Income Insurance Co-Operative Limited	5092625516-01	07/08/2018	06/08/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMAD FADLY BIN ASMAWI	ID No.	S8101794H
Related Vehicle	FBE8222Z (Motorcycle)	Contact No.	97471925
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 7/9/2018 at around 1215hrs, I was riding with a speed of about 40km/h along Bedok North Avenue 3 when suddenly one van sped out from Bedok North St 2 without stopping at the stopping line. The road was wet due to rain and that point of time it was drizzling. The incident happened so fast when i applied my brake and horned to warn the driver. The van driver suddenly stopped the van when 3/4 of the rear body was still in the yellow box which was in front of my travelling path. Upon seeing that, I braked hard to avoid the collision and horned at the van to alert him. However it was too sudden, hence I was unable to avoid the collision and hit rear right part of the van. After the collision, a passerby rendered assistance to call for ambulance and brought me to the side of the road for safety. However I wished to state that the van driver did not render assistance to me at all. I have two witnesses who came forward and assisted me.

Details of the witnesses as follows:

- 1) Name: Azzeri
Contact number: 91820102
- 2) Name: ZY
Contact number: 93878230

I was conveyed into Changi General Hospital and was given 7 days outpatient sick leaves, dated from 7/9/2018 to 13/9/2018, EMD201875125.



**SINGAPORE
POLICE FORCE**



T/20180907/2132

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20180907/2132

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
G /
Sgt 3 TAN MENG LIANG *cm*

Signature Of Informant:

[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
07/09/2018 20:09

Officer In Charge Of Case:
TP / GIT /
Sgt 2 LIM HONG LEE
Contact No.: 65476438

Classification Of Case:

Authentication Stamp
NP168

 SINGAPORE
POLICE FORCE
cm
SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2018		12 Sep 2018 15:46 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	MUHAMAD FADLY BIN ASMAWI			
Vehicle Reg. No.:	FBE8222Z	Date of Loss:	07/09/2018 00:00 - :59 [109 Months From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM18D04410C02	Policy/Cover Note No.:	DMCVSN3007431802	
Vehicle Reg. No. (Insured):	GBC9018B	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/09/2018]			
Adj Asg. Remarks:	NO EST, CASE W/O SJE.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***FBE8222Z (SNM18D04410C02)**

[GBC9018B]

TP

MUHAMAD FADLY BIN ASMAWI

Sep 7 2018 12:00AM

[-]

Speedy Motor Cycle Service Centre

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
2	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
3	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
4	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
5	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
6	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
7	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
8	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
9	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
10	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
11	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
12	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
13	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
14	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
15	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
16	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
17	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
18	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
19	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
20	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
21	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
22	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
23	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
24	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
25	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
26	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
27	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
28	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
29	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
30	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
31	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
32	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
33	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
34	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
35	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
36	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>
37	16/09/18 20:56	General View	 Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
39	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
40	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
41	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
42	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
43	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
44	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
45	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
46	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
47	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
48	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
49	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
50	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
51	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
52	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
53	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
54	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
55	16/09/18 20:56	General View	Load JPG	<input checked="" type="checkbox"/>
56	16/09/18 20:57	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
57	16/09/18 20:57	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
58	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	17/09/18 11:23	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/09/18 15:46	PRS	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118016674/GCBE2

Date: 25/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3007431802	
Claimant Vehicle No: FBE8222Z	Insured Vehicle No: GBC9018B	
Date of Loss: 07/09/2018	Nature of Claim: TP	Claim No: SNM18D04410C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE8222Z		Engine No: NC42E1003071
Make & Model: HONDA CB400, 399cc		Chassis No: JH2NC42918M000018
Reg. Date: 07/08/2009 (Man. Year: 2008)		Odometer: 126374 km
Colour: Black		
Engine Capacity: 399 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17	Rear Tyre Size: 160/60Z R17
Front Left Side: Michelin 5 mm	Rear Left Side: Michelin 5 mm
Front Right Side: 0 mm	Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/09/2018	
Date Inspected:	13/09/2018 Inspected At:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21 Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 25 Sep 2018)
Parts:	N/A HONDA CB400 399cc (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE8222Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >