

ASS. REC. BY:

REF:

CS3 / CTU8016718 / Gc bek

Special Instruction:

Surveyor

Gho Chang

ASSIGNMENT (Office)

Melimen

From (Person):

Elaine Cheong

of

CTU

Date/Time:

13092018 1:25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 1482R

Insured:

SIL 245D

at Workshop m/s

N-51 Automotive

Tel:

6812 1051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

DMPCSN 3015611700

Claim No:

SNM18D04364002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01-09-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI'

H.O.D. Endorsement:

Date/Time:

13092018 1:32pm

Person Contacted:

Elynn

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	
	SJK 1482R - NA/INC18016111/24	DA: 01092018
	SIL 245D - N/A CTU8016500/Y	DA: 01092018
	Dismantle: 27/9/2018	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18016718/Gcb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-09-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJL 245D	Veh. Inspected	SJK 482R
Policy No.	DMCVSN3015611700	Coverage (\$)	0.00
Claim No.	SNM18D04364C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	13/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/09/2018	Inspection Date	26/09/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		13 Sep 2018 13:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SATISH KUMAR S/O SETHURAMAN, ID: S6898075E		
Main Claimant:	XU WEIHUA, JONATHAN@ADAM XU, ID: S8328160Z		
Vehicle Reg. No.:	SJK482R	Date of Loss:	01/09/2018 18:00 - :59
Claim Type:	TP / SNM18D04364C02	Policy/Cover Note No.:	DMPCSN3015611700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJL245D	Policy No. (Claimant):	5084361567-01
		Excess:	S\$0.00
Repairer:	N-51 Automotive Pte Ltd (Kaki Bukit Autohub) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]		
Driver/Custodian (Insured):	S SELVARANI (50 / Female), NRIC: S6804132E, Tel: +6592215566		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8160Z

Vehicle Details

Vehicle No.:	SJK482R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	1NZX804250
Chassis No.:	MR053HY9305082532
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	02 Oct 2008
First Registration Date:	02 Oct 2008
Transfer Count:	3
Actual ARF Paid:	\$11,834.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2018
PARF Rebate Amount:	\$5,917.00

Intended COE Rebate Details

COE Expiry Date:	30 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$10.00
Total Rebate Amount:	\$5,927.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 15:01
Date Of Accident	01/09/2018 18:35
Exact Location Of Accident	ADAM RD FOOD CENTRE OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK482R
Insured/Policyholder	
Name Of Registered Owner	XU WEIHUA, JONATHAN@ADAM XU
NRIC No	S8328160Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98586890
Alternative Phone No	OFFICE-98586890

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084361567-01
Cover Note Number	

Driver

Name of Driver	XU WEIHUA, JONATHAN@ADAM XU
NRIC No	S8328160Z
Date Of Birth	07/09/1983
Occupation	INDOOR
Date Of Driving Pass	23/07/2016
Driving Experience	2 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98586890
Fax Number	
Contact Number	OFFICE-98586890
EEmail Address	NOEMAIL

Address	BLK 136 POTONG PASIR AVENUE 3 #07-158
Postcode	350136
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POTONG PASIR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 142 POTONG PASIR AVENUE 3 , POSTCODE: 350142 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2829999 - FAX NO: 62815964
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180901/2171.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL245D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Police Report

03/09/2018

0040a9db-5821-4426-9c7b-2f19b02aad8d.JPG



**SINGAPORE
POLICE FORCE**



T20180901/2171

Police Station Of Origin:
Potong Pasir NPP
142 Potong Pasir Avenue 3 #01-240
SINGAPORE 350142
Tel No: 1800-2829999

1 of 3
Report No: T20180901/2171

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 01/09/2018 21:42	Vide Report No.	Station Diary No. 58
---	-----------------	-------------------------

Informant's Particulars

Name of Informant: XU WEIHUA, JONATHAN		Address: APT BLK 136 POTONG PASIR AVENUE 3 #07-158 SINGAPORE 350136	
ID Type / ID No: NRIC NO / S8328160Z		Contact No: Home/Office: Mobile: 98586890	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 34	Date of Birth: 07/09/1983	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 2B.3 Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive No	Date/Time of Accident: 01/09/2018 18:35	Type of Location: Car Park
--	----------------	--	-------------------------------

Location:
Along Road 1
ADAM ROAD

Open spaced carpark of Adam road food centre lot 32

Weather:	Road Surface:	Road Speed Limit:
Traffic Flow:	Traffic Control: Not Controlled	Traffic Volume:

Type of Collision: Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: No
---	-------------------------------------

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJK482R	Car	TOYOTA	VIOS E AUTO	Red	Seriously Damaged	0
SJL245D	Car	TOYOACE	WISH 1.8 AUTO			0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJK482R	NTUC Income Insurance Co-Operative Limited	5084361567-01	02/10/2017	01/10/2018

Police Report

03/09/2018

82986a32-a461-4a68-95ae-a8413c02b090.JPG



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Potong Pasir NPP
142 Potong Pasir Avenue 3 #01-240
SINGAPORE 350142
Tel No: 1800-2829999



Report No.

CONTINUATION OF REPORT

Brief Details.

On 1/9/18 at about 1830hrs, I parked my vehicle bearing plate number sjk482r at the open spaced carpark of Adam food centre Lot number 32. Everything was intact.

Subsequently at about 1850hrs, I returned back to my vehicle and discovered that my rear bumper was damaged. As such, I went to view the camera footage from the rear camera installed in my vehicle. From the footage, I discovered that at about 1834hrs, there is one vehicle bearing plate number SJL245D was trying to reverse into the parallel parking lot number 31 behind me. The said driver's vehicle rear portion then knocked onto the rear of my vehicle while he was reversing before the driver drove away. I wish to state that the rear bumper of my vehicle was damaged and there is also a crack at the rear bumper near the exhaust.

Police Report

03/09/2018

6f12ea18-7510-4496-bc12-6f4476ebf1e8.JPG

**SINGAPORE
POLICE FORCE**

Location Of Origin:
NPP
Pasir Avenue 3 #01-240
SINGAPORE 350142
Tel: 1800-2829999


Barcode: T/20180901/2171

3 of 3
Report No. T/20180901/2171

CONTINUATION OF REPORT

Sketch Plan
Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report E/ Sgt 2 LIM BRANDON	Signature Of Informant 
Signature Of Interpreter Not applicable	Date/Time 01/09/2018 21:42
Officer In Charge Of Case TP / HRT / SSI GOH GEOK LYE Contact No: 65475148	Classification Of Case

Authentication Stamp
WP188

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		13 Sep 2018 13:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SATISH KUMAR S/O SETHURAMAN , ID: S6898075E									
Main Claimant: XU WEIHUA, JONATHAN@ADAM XU , ID: S8328160Z									
Vehicle Reg. No.: SJK482R		Date of Loss: 01/09/2018 18:00 - :59 [118 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04364C02		Policy/Cover Note No.: DMPCSN3015611700 (Comprehensive)							
Vehicle Reg. No. (Insured): SJL245D		Policy No. (Claimant): 5084361567-01							
		Excess: S\$0.00							
Repairer: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/09/2018]									
Driver/Custodian (Insured): S SELVARANI (50 / Female), NRIC: S6804132E, Tel: +6592215566									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK482R (SNM18D04364C02)
[SJL245D]
TP
XU WEIHUA, JONATHAN@ADAM XU
Sep 1 2018 6:00PM
[SATISH KUMAR S/O SETHURAMAN]
N-51 Automotive Pte Ltd (kaki Bukit Autohub)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	04/09/18 15:13	Accident Statement	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
2	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
3	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
4	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
5	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
6	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
7	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
8	04/09/18 15:10	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	13/09/18 13:24	PRS	Load PDF		
2	13/09/18 13:24	OI GIA	Load PDF		














Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	04/09/18 15:10	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
2	04/09/18 15:10	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
3	04/09/18 15:10	Police Report <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
4	04/09/18 15:10	Police Report <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	
5	04/09/18 15:10	Police Report <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	04/09/18 15:13	Accident Statement	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
---------------	--	--	--	------------	-------------------------------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	04/09/18 15:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/09/18 15:10	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 15:10	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 15:10	Police Report		Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 15:10	Police Report		Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 15:10	Police Report		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016718/GCBE2

Date: 04/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3015611700

Claimant Vehicle
No: SJK482RInsured Vehicle
No: SJL245D

Date of Loss: 01/09/2018

Nature of Claim: TP

Claim
No: SNM18D04364C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK482R

Make & Model: TOYOTA VIOS, 1.5 (A)

Reg. Date: 02/10/2008 (Man. Year: 2008)

Colour: Red

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZX804250

Chassis No: MR053HY9305082532

Odometer: 145375 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Membat 6 mm

Rear Left Side: Membat 6 mm

Front Right Side: Membat 6 mm

Rear Right Side: Membat 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 26/09/2018 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit
 Autohub) (HQ)
 KAKI BUKIT AUTOHUB 2 KAKI BVUKIT
 AVE 2 #01-18
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 -\$2,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK482R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >