

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 14 Sep 2018

## **Preliminary Advice**

|                    |                                                                                           |                         |              |
|--------------------|-------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBD232C                                                                                 |                         |              |
| TP Vehicle No      | : SHC6265C                                                                                | Accident Date           | : 12/09/2018 |
| Make               | : KIA OPTIMA                                                                              | Assignment Date         | : 13/09/2018 |
| Date of Inspection | : 13/09/2018                                                                              | Est. Duration of Repair | : 3 days     |
| Inspection At      | : Premier Taxis Pte Ltd - Changi (HQ)<br>23 Changi South Ave 2 #03-02<br>Singapore 486443 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,667.55 |
| Revised Amount              | :S\$ | 1,486.15 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,486.15 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.