

ASS. REC. BY:

REF: CS3/CTL18016730 / Ncbcr Special Instruction:

Surveyor

Meimien

NAZ

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CL

Date/Time: 13092018 1047am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCG 363E

Insured:

SLA 9966G

at Workshop m/s:

Kent Seng

Tel:

9004 8759

of

1016 Yishun Ind Park A #01-238

Policy No:

DMPCSN 3025911802

Claim No:

9NM18DD4414102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06092018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

13092018 11:20am

Person Contacted:

Ah Seng

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SCG 363E - CS3/NAH 13021242 / PT24

DOA: 12-11-13

SLA 9966G - X

Dismantle: 17/9/2018

After repair: 20/9/2018

Surveyor: NA2

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGG 363 E Yr Regn: 2016 / Jun 12
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: 27 TOYOTA HARRIER c.c. 1986
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 27,288 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZSU 60-0065499
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235 / 55 R18
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. _____ D.O.I. 13/9/18
Survey held at KENT SENG
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 5000/2 - 6000/2

RECEIVED 09 OCT 2018

8/10/2018

IGIM

5/10/18

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : PRS

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 150

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)) S + RS. \$
☐ : Interview (\$ _____)) Photos
☐ : Tech. Invs (\$ _____)) Others
☐ : Weekend (\$ _____))

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018		13 Sep 2018 10:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:																								
Main Claimant: CHANG LANG LIN																								
Vehicle Reg. No.: SCG363E		Date of Loss: 06/09/2018 00:00 - :59																						
Claim Type: TP / SNM18D04414C02		Policy/Cover Note No.: DMPCSN3025911802																						
Vehicle Reg. No. (Insured): SLA9966G		Policy No. (Claimant):																						
		Excess: S\$0.00																						
Repairer: Kent Seng Car Services (Yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:																								
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]																								
Adj Asg. Remarks: NO EST, CASE W/O SJE.																								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

⇒ Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/K2/1812631/st
Your Reference : SLA 9966G

Date : 11 September 2018

BY EMAIL: claimsdept@sg.cntaiping.com ONLY

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 6/9/2018 INVOLVING VEHICLE NOS. SCG 363E AND SLA 9966G ALONG SECOND LINK TOWARDS SINGAPORE.**

We are instructed by CHANG LANG LIN (owner of motor vehicle no. SCG 363E) and/or KENT SENG CAR SERVICES (the motor workshop for SCG 363E) to notify you of a road traffic accident on 6/9/2018 at about 1700 hours along SECOND LINK TOWARDS SINGAPORE involving our client's vehicle registration number [SCG 363E] and [SLA 9966G] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO
(Branch Office)

Encl

c.c. 1) TOH ZI PENG

(Vehicle : SLA 9966G)

- 2) **NAME OF WORKSHOP:**
KENT SENG CAR SERVICES
Blk 1016 Yishun Industrial Park A
#01-238 Singapore 768758
Tel: 9004-8759

(Vehicle: SCG 363E)

(Contact person: Ah Seng)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5972G
Vehicle Details	
Vehicle No.:	SCG363E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB684302
Chassis No.:	ZSU600065499
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,381.00
Original Registration Date:	12 Jan 2016
First Registration Date:	12 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$23,934.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2026
PARF Rebate Amount:	\$17,950.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$42,328.00
Total Rebate Amount:	\$60,278.00

The information contained herein is correct as at 02 Oct 2018

OK

MCA118116302 / City Auto Pte Ltd - HQ
ENTRY DATE & TIME: 08/09/2018 10:32
SUBMITTED BY: Jason Quak Leng Hui

K2/1812631

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/09/2018 10:32
Date Of Accident 06/09/2018 17:00
Exact Location Of Accident 2ND LINK TOWARDS SINGAPORE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCG383E
Insured/Policyholder
Name Of Registered Owner CHANG LANG LIN
NRIC No S7205972G
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-81880363
Alternative Phone No OTHERS-81880363
Vehicle Particulars
Manufacturer TOYOTA
Model HARRIER
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5077137266-02
Cover Note Number
Driver
Name of Driver CHANG LANG LIN
NRIC No S7205972G
Date Of Birth 19/02/1972
Occupation INDOOR
Date Of Driving Pass 17/10/1992
Driving Experience 25 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-81880363
Fax Number
Contact Number OTHERS-81880363
Email Address NOEMAIL

Address 48 PARK VALE
 #03-09 THE PARK VALE
 Postcode 208564
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES

Number of Passengers (Including Driver) 4

Passenger 1

NAME: : NA

GENDER: : MALE

Passenger 2

NAME: : NA

GENDER: : MALE

Passenger 3

NAME: : NA

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AS SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA9986G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Sketch Plan

SKETCH PLAN

VEHICLE NO.: _____
 INSURER : _____
 DATE & TIME: _____

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GUA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and my relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/inbox packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes").
 - (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
 - (c) my Personal Information may be disclosed by any of the insurers and/or GIA to third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
 Date & Time:

Driver's Signature
 or Driver is not the policyholder
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NSIC/MS No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6 September at Spm, I was Travelling along 2nd Link towards Singapore. As the traffic was heavy, my vehicle SG363E was stationary waiting to move on. SLA 996G suddenly hit onto my car from behind. I am doing this report to claim my damages against SLA 996G.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

REC'D IN No.:

() Reporting Only

() Claim Third Party

() Claim OD/TP at other workshop

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		13 Sep 2018 10:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: CHANG LANG LIN									
Vehicle Reg. No.: SCG363E		Date of Loss: 06/09/2018 00:00 - :59 [31 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04414C02		Policy/Cover Note No.: DMPCSN3025911802							
Vehicle Reg. No. (Insured): SLA9966G		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 24/09/2018]									
Adj Asp. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCG363E (SNM18D04414C02)
[SLA9966G]

TP

CHANG LANG LIN

Sep 6 2018 12:00AM

[-]

Kent Seng Car Services (yishun)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 18:01	General View	 Load JPG	☒
2	13/09/18 18:01	General View	 Load JPG	☒
3	13/09/18 18:01	General View	 Load JPG	☒
4	13/09/18 18:01	General View	 Load JPG	☒
5	13/09/18 18:01	General View	 Load JPG	☒
6	13/09/18 18:01	General View	 Load JPG	☒
7	13/09/18 18:01	General View	 Load JPG	☒
8	13/09/18 18:01	General View	 Load JPG	☒
9	13/09/18 18:01	General View	 Load JPG	☒
10	13/09/18 18:01	General View	 Load JPG	☒
11	13/09/18 18:01	General View	 Load JPG	☒
12	13/09/18 18:01	General View	 Load JPG	☒
13	13/09/18 18:01	General View	 Load JPG	☒
14	13/09/18 18:01	General View	 Load JPG	☒
15	13/09/18 18:01	General View	 Load JPG	☒
16	13/09/18 18:01	General View	 Load JPG	☒
17	13/09/18 18:01	General View	 Load JPG	☒
18	13/09/18 18:01	General View	 Load JPG	☒
19	13/09/18 18:01	General View	 Load JPG	☒
20	13/09/18 18:01	General View	 Load JPG	☒
21	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
22	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
23	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
24	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
25	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
26	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
27	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
28	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
29	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
30	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
31	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
32	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
33	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
34	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
35	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
36	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
37	02/10/18 18:24	Photographs of Damaged Items	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
39	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
40	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
41	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
42	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
43	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
44	02/10/18 18:24	Photographs of Damaged Items	 Load JPG	☒
45	02/10/18 18:25	Photo After Spray	 Load JPG	☒
46	02/10/18 18:25	Photo After Spray	 Load JPG	☒
47	02/10/18 18:25	Photo After Spray	 Load JPG	☒
48	02/10/18 18:25	Photo After Spray	 Load JPG	☒
49	02/10/18 18:25	Photo After Spray	 Load JPG	☒
50	02/10/18 18:25	Photo After Spray	 Load JPG	☒
51	02/10/18 18:25	Photo After Spray	 Load JPG	☒
52	02/10/18 18:25	Photo After Spray	 Load JPG	☒
53	02/10/18 18:25	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/09/18 10:47	PRS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016730/NCBE2
Date: 10/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3025911802
Claimant Vehicle No: SCG363E Insured Vehicle No: SLA9966G
Date of Loss: 06/09/2018 Nature of Claim: TP Claim No: SNM18D04414C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCG363E Engine No: 3ZRB684302
Make & Model: TOYOTA HARRIER, 2.0 (A) Chassis No: ZSU600065499
Reg. Date: 12/01/2016 (Man. Year: 2015) Odometer: 27288 km
Colour: Black
Engine Capacity: 1986 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/09/2018
Date Inspected: 13/09/2018 Inspected At: Kent Seng Car Services (yishun) (HQ)
Blk 1016 Yishun Industrial Park A #01-238
Singapore 768758
Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2018)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCG363E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >