

22/03/2002

ASS. REC. BY:

REF:

CS/CTL18016739 / TITher

Special Instruction:

Survivor:
Machmen

Twelfth

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTL

Date/Time:

13092018 207pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8H 3430G

Insured:

SFA 182G

at Workshop m/s

Volkswagen

Tel:

of

1 Kampong Ampot off Macpherson Rd

Policy No:

DMPCSN 30877 31801

Claim No:

SNM18D01419602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-09-2018

(Client's Record)

18-09-2018 @ 10am

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

13092018 312pm

Person Contacted:

Steven

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

G8H 3430G - X

SFA 182G - X

Part by Part \$12,407.04 (Red: 4907.24, 28%)

Signature: *Taufik*
Mulmen

REF: CTL

ASSIGNMENT

From: _____ Date: 18/02/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 343067

at Workshop m/s Volkswagen

of 1 Kampong Ampat UPP Mayherson Rd

Insured:

Policy No.

Claims No.

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 343067 Yr Regn: 2018 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen - T6 Van - c.c. 1968

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 15127 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ~~WV1727~~ WV1727-7MEHH12479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 FEB 2019

Date/Time. File Pass to?

1) 15/2 Typist ☐: Preli. Report ☒: Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$)

☐: Interview (\$)

☐: Tech. Invs (\$)

☐: Weekend (\$)

Survey Fee: 200

Transportation: _____

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / C.B.I: (\$ 12,407.04)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 13 Sep 2018 | | 13 Sep 2018 15:07 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All |
|---|---|------------------------|-------------------------------------|----------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | |
| Insured: | SUSAN, ID: S7374929H | | | |
| Main Claimant: | CHRISTOPHER NG KOK CHUAN, ID: S7601236I | | | |
| Vehicle Reg. No.: | GBH3430G | Date of Loss: | 11/09/2018 16:00 - :59 | |
| Claim Type: | TP / SNM18D04419C02 | Policy/Cover Note No.: | DMPCSN3087731801 (Comprehensive) | |
| Vehicle Reg. No. (Insured): | SFA182G | Policy No. (Claimant): | | |
| | | Excess: | S\$0.00 | |
| Repairer: | Volkswagen Centre Singapore (MacPherson) 1 KAMPONG AMPAT, 368314 Macpherson - Tel: | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia] | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018] | | | |
| Adj Asg. Remarks: | EST \$17,433.35, CASE WITH SJE. | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | |
| There are no mail for this case. | | | | |
| <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> | | | | |
| No results. | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|-------------------------------|
| Date Of Report | 11/09/2018 17:47 |
| Date Of Accident | 11/09/2018 16:55 |
| Exact Location Of Accident | BEFORE HAIG RD TRAFFIC LIGHT |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | GBH3430G |
| Insured/Policyholder | |
| Name Of Registered Owner | SHAO FENG TRADING |
| Co Reg No | 53014917J |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-91007712 |
| Alternative Phone No | OFFICE-91007712 |
| Vehicle Particulars | |
| Manufacturer | VOLKSWAGEN |
| Model | T6 VAN TDI NWB 110 (DSG) WGDR |
| Exact Purpose for which vehicle was being used at time of accident | WORKING PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |
| Insurance Company | |
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMCPHQ18-002614 |
| Cover Note Number | |
| Driver | |
| Name of Driver | CHRISTOPHER NG KOK CHUAN |
| NRIC No | S7601236I |
| Date Of Birth | 19/01/1976 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 22/03/2011 |
| Driving Experience | 7 YEARS AND 5 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91007712 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|--------------------------------------|
| Address | APT BLK 308C PUNGGOL WALK #13-352 |
| Postcode | 823308 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---|
| Vehicle Registration Number | SFA182G |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | SUSAN |
| NRIC/Passport Number | S7374929H |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SGN2702M |
|-----------------------------|----------|

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MUHAMMAD KHALIL BIN RAMLAN

NRIC/Passport Number

S8542027E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purpose of fraud detection, investigation and management in present and all future claims.
 - (ii) for complying with requirements under any regulations, laws or court orders.

MOBILE: +65 9100 7712
#03-27 SINGAPORE 417842
NO. 9 KAKI BUKIT ROAD 2
AIR-CON SERVICES & MAINTENANCE
SHAO FENG TRADING
Policyholder's Signature

Date & Time: 5.50pm
11/9/2018


Driver's Signature
(If driver is not the policyholder)

Date & Time: 5.50pm
11/9/2018



Reporting Centre Personnel's Signature
Name: Steven
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/07/2018 at 4.54pm, before Hidy Rd traffic light, I stopped at before traffic light due to red light, while I stationary I feel a huge impact from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

SHAO FENG TRADING
R-CON SERVICES & MAINT.
NO. 9 KAKI BUKIT ROAD 2
#03-27 SINGAPORE 417842
MOBILE: 9859 000 7712

Date & Time: 5.50pm
11/9/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 5.50pm
11/9/2018

Reporting Centre Personnel's Signature
Name: Steven
NRIC/FIN No.:



Sketch Plan #3 Pg. 1

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N



Quote Ref : PIMCP18-001065

MOTOR COVER NOTE - COMMERCIAL

Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third Party Risks and Compensation) Rules 1960
Road Transport Act 1987 (Malaysia)
Motor Vehicles (Third Party Risks and Compensation) Rules 1959 (Malaysia)

| SCHEDULE | | | |
|-----------------------|------------------------------------|---------------------|--|
| Intermediary Name : | Agnes Tan Sock Leng | Intermediary Code : | A000209 |
| Policy No. | DMCPHQ18-002614 | Cover Note No : | CMCPHQ18-000165 |
| Name of Insured | Shao Feng Trading | | |
| Registration Number | To Be Advised | | |
| Make / Model | VOLKSWAGEN | | |
| Year of Registration | 2018 | | |
| Tonnage | 1.2 | | |
| Engine Number | CXH068821 | | |
| Chassis Number | WV1ZZZ7HZHH124793 | | |
| Cover Type | Comprehensive | | |
| Est. Sum Insured | Market Value At The Time Of Loss | | |
| Period of Insurance | 30/04/2018 TO 29/04/2019 | | |
| Hire Purchase Company | Ethoz Capital Ltd | | |
| Excess | Section 1: YEID: WindScreen: | Additional | S\$500.00 S\$3,000.00 All Claims S\$100.00 |

The Insured having proposed for insurance the Motor Vehicle as described herein, we hereby confirm we HOLD COVER this risk for the period as stated in the Schedule, subject to the terms and conditions of the Company's standard Motor Policy. In the event this cover is terminated by us in written notice, a proportionate part of the annual premium will be charged for the time the Company has been on risk.

We hereby certify that this Cover Note is issued in accordance with the provisions of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

EQ Insurance Company Limited

Authorised Signatory

Note

Young, Elderly &/or Inexperience Driver (YEIDR) refers to any person authorized to drive who is below 26 years old or above 70 years old and/or the holder of a qualified driving licence of less than 2 years duration.

Issued Date : 30/04/2018 09:04

This Cover Note is valid for 30 days from the first day of the Policy Period.

PREMIUM WARRANTY

Applicable To Individual Policyholder

Please note that the premium in full must be paid before the inception date shown above in order for the insurance cover to be valid.


 Licence Number **S76012361**
 Name
CHRISTOPHER NG KOK CHUAN
(CHRISTOPHER HUANG
GUOCHUAN)
 Birth Date: **19 Jan 1976**
 Issue Date: **22 Mar 2011**


001949067K

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S76012361



 Name
CHRISTOPHER NG KOK CHUAN
(CHRISTOPHER HUANG
GUOCHUAN)
黄国川
 Race
CHINESE
 Date of birth: **19-01-1976** Sex: **M**
 Country of birth: **SINGAPORE**

YOU ARE PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)
 EFFECTIVE DATE

| | | |
|----------|---|-------------|
| Class 2B | Motorcycles <= 200 CC | 06 May 2013 |
| Class 3 | Motor cars <= 3600 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg | 22 Mar 2011 |

S76012361
S / No. 9000182400


Licence No: S76012361

428A


NRIC No. S76012361


 Date of issue
10-02-2008

APT BLK 308C PUNGGOL WALK #13-352
SINGAPORE 823308
NRIC No: S76012361
 Date: **23/11/2018**

Supplementary or Omitted List



VEHICLE NUMBER: **GBH3430G**
T6 VAN TDI NWB 110
MODEL **(DSG) WGDR**

CLAIMS DETAILS

| LABOUR DESCRIPTION | | | | AMOUNT | | | |
|--------------------|--------------------------|--|--|--------|-----------|----------|-----------|
| | | | | Qty | Unit | Discount | Amount |
| 1 | SPRAY PAINTING END PANEL | | | 1 | \$ 800.00 | ✓ | \$ 800.00 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | \$800.00 |

| No. | Item No. | Description | Qty | Unit Pricing | Discount | | Amount |
|-----|----------------|-------------|-----|--------------|----------|---|----------|
| 1 | 7E0853630D DPJ | VW SIGN | 1 | \$75.30 | | ✓ | \$75.30 |
| 2 | D 004660M2 | 2K GLUE | 1 | \$159.35 | | ✓ | \$159.35 |
| 3 | D 00920002 | PRIMER | 1 | \$ 29.06 | | ✓ | \$29.06 |
| 4 | D 00950025 | APPLICATOR | 2 | \$ 10.60 | | ✓ | \$21.20 |
| 5 | D 181802M1 | ACTIVATOR | 1 | \$ 26.52 | | ✓ | \$26.52 |
| | | | | | | | |
| | | | | | | | \$311.43 |

Total Labour & Parts

\$1,111.43

Survey By

TAUFIK (LKK)

17404.28



PDI TUAS

PDI TUAS

SHAO FENG TRADING
308C PUNGGOL WALK
#13-352 WATERWAY TERRACES
Singapore, 823308
Singapore

Tanpin 9249549
- NP
18/9/18 @ 1000
Rising before part
sure 11/10/18
6-7 days.

19/9/18

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV040665
Quote No. SER/QUO/18C00034
QuoteDate 11/09/18
Salesperson MARCUS LIU
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make | Model Description | Mileage | Service Advisor |
|----------------------|-------------------------------|----------------------|-----------------|
| Light Commercial Veh | T6 VAN TDI NWB 110 (DSG) WGDR | 10,487 | STEVEN CHEE |
| License No. | VIN | Initial Registration | Sales Advisor |
| GBH3430G | WV1ZZZ7HZHH124793 | 30/04/18 | MARCUS LIU |
| Engine Code | Labor Type | Engine No. | Model Code |
| | 62 | CXH 068821 | SGA1F7 |

| No. | Description | Qty. | UoM | Unit Price | Amount |
|--------------------|--------------------------------|------|---------|------------|------------------|
| P B&P MACP LABOUR | LABOUR | 5 | UNIT | 2520 | 4,200.00 |
| P B&P MACP LABOUR | R&R REAR WINDSCREEN | 2 | UNIT | 840 | 1,680.00 |
| P B&P MACP PAINT | SPRAY PAINT | 4 | UNIT | 2400 | 3,200.00 |
| P B&P NUMBER PLATE | STICKER 70KM/H | 1 | pcs | 20.00 | 20.00 |
| P B&P NUMBER PLATE | STICKER 12PAX | 1 | pcs | 20.00 | 20.00 |
| P B&P SENSOR | SUPPLY & INSTALL REVERSE SE | 1 | Pieces | 400.00 | 400.00 |
| P B&P DIAG | PROGRAMMING & CALIBRATION | 1 | Time Un | 480.00 | 480.00 |
| P B&P MECH | ELECTRICAL CHECK OR MECHA | 1 | Time Un | 280.00 | 280.00 |
| | Sum Labor | | | | 10,280.00 |
| P 7E0807305C | REINFORCEMENT | 1 | Pieces | 261.84 | 261.84 |
| P 7E0807393C | REAR BUMPER SIDE BRACKET L | 1 | Pieces | 31.92 | 31.92 |
| P 7E0807394C | REAR BUMPER SIDE BRACKET | 1 | Pieces | 31.92 | 31.92 |
| P 7E0807417E 9B9 | REAR BUMPER | 1 | Pieces | 951.09 | 951.09 |
| | Use Predecessor 7E0807417A 9B9 | | | | |
| P 7E0827505B | RHS LOCK | 1 | Pieces | 56.97 | 56.97 |
| P 7E0827506A | LHS LOCK | 1 | Pieces | 56.97 | 56.97 |
| P 7E0829193T | WEATHER SEAL | 1 | Pieces | 146.55 | 146.55 |
| P 7E0853687 739 | NAME PLATE TRANSPORTER | 1 | Pieces | 39.27 | 39.27 |
| P 7E0945097H | THIRD BRAKELIGHT LHS | 1 | Pieces | 108.14 | 108.14 |
| P 7E0945097J | THIRD BRAKELIGHT RHS | 1 | Pieces | 108.14 | 108.14 |
| P 7E0945105A | REFELCTOR LH | 1 | Pieces | 57.11 | 57.11 |
| P 7E0945106A | REFLECTOR RH | 1 | Pieces | 57.11 | 57.11 |
| P 7H0827091AQ | WING DOOR LHS | 1 | Pieces | 1,770.75 | 1,770.75 |
| P 7H0827092AQ | WING DOOR RHS | 1 | Pieces | 1,770.75 | 1,770.75 |
| P 7H0827512B | LATCH | 2 | Pieces | 85.80 | 85.80 |
| | Sum carried forward | | | | 15,814.33 |

Payments to: - BBN: - Acc.-No.:



PDI TUAS

PDI TUAS

SHAO FENG TRADING
308C PUNGGOL WALK
#13-352 WATERWAY TERRACES
Singapore, 823308
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV040665
Quote No. SER/QUO/18C00034
QuoteDate 11/09/18
Salesperson MARCUS LIU
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make | Model Description | Mileage | Service Advisor |
|----------------------|-------------------------------|----------------------|-----------------|
| Light Commercial Veh | T6 VAN TDI NWB 110 (DSG) WGDR | 10,487 | STEVEN CHEE |
| License No. | VIN | Initial Registration | Sales Advisor |
| GBH3430G | WV1ZZZ7HZHH124793 | 30/04/18 | MARCUS LIU |
| Engine Code | Labor Type | Engine No. | Model Code |
| | 62 | CXH 068821 | SGA1F7 |

| Continued | | | 15,814.33 |
|-----------------|-------------------------------|----------|-----------|
| P 7H0827512B | VW SIGN | 1 Pieces | 42.90 |
| P 7H0827709F | LHS DOOR SEAL | 1 Pieces | 81.33 |
| P 7H0867299 01C | CLIP | 5 Pieces | 7.25 |
| | Use Predecessor 701867299 01C | | |
| P 7H0898529 | RHS DOOR SEAL | 1 Pieces | 65.54 |
| P D 002000A2 | CLEANER | 1 Pieces | 99.84 |
| P D 004660M2 | 2K GLUE | 1 Pieces | 122.58 |
| P D 00920002 | PRIMER | 1 Pieces | 22.36 |
| P D 00950025 | APPLICATOR | 2 Pieces | 16.32 |
| P D 181802M1 | ACTIVATOR | 1 Pieces | 20.40 |
| | Sum Item | | 6,012.85 |

Explanations

P = Proportionately Charged

Payment Terms

No Credit

| | | | |
|--|--|---------------------|-----------|
| LKK Auto Consultants hence notify the Repairer of the following: | | Sum Labor | 10,280.00 |
| • To resurvey before/after spray painting | | Sum Item | 6,012.85 |
| • To display damaged part(s) during resurvey | | Total SGD | 16,292.85 |
| • Parts prices are subject to confirmation | | 7% GST | 1,140.50 |
| • Third party survey is on a "Without Prejudice" basis | | Total SGD Incl. GST | 17,433.35 |
| • No illegal modification(s) is allowed | | | |
| • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company | | | |
| Acknowledged by Repairer | | | |
| Signature: | | | 16658.75 |
| Date: | | | |

Payments to:

- BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 18IP2410

CUSTOMER NO.: CV040665

CUSTOMER NAME: SHAO FENG TRADING

TELEPHONE NO.:

ADDRESS: 308C PUNGGOL WALK #13-352 WATERWAY TERRACES

Singapore

VEH No.: GBH3430G

Order Date: 18/09/18

Reg Date: 30/04/18

KM: 16,216

VIN NO.: WV1ZZZ7HZHH124793

ENGINE NO:

SA: STEVEN CHEE

MODEL: T6 VAN TDI NWB 110 (DSG) WGD MODEL NO.: SGA1F7

| No. | DESCRIPTION | QTY | UOM | UNIT PRICE | DISC % | AMOUNT |
|--------------|--|-----|------|------------|--------|-------------------|
| Labor | | | | | | |
| 1 | B&P MECH ELECTRICAL CHECK OR MECHANICAL REPAIR | 1 | TU | 280 | | 280 |
| 2 | B&P DIAG PROGRAMMING & CALIBRATION-NETT | 1 | TU | 480 | | 480 |
| 3 | B&P MACP LABOUR LABOUR | 3 | UNIT | 840 | | 2,520 ✓ |
| 4 | B&P MACP LABOUR R&R REAR WINDSCREEN | 1 | UNIT | 840 | | 840 ✓ |
| 5 | B&P MACP PAINT SPRAY PAINT + end panel | 3 | UNIT | 800 | | 2,400 |
| 6 | B&P NUMBER PLATE STICKER 70KM/H | 1 | ST | 20 | | 20 |
| 7 | B&P NUMBER PLATE STICKER 12PAX | 1 | ST | 20 | | 20 |
| 8 | EXT00037 Tow SVC- Quality Recovery Services | 1 | UNIT | 0 | | 0 |
| 9 | B&P SENSOR SUPPLY & INSTALL REVERSE SENSOR | 1 | PCS | 400 | | 400 |
| 10 | EXT00037 Tow SVC- Quality Recovery Services | 1 | UNIT | 0 | | 0 |
| Item | | | | | | |
| 11 | 7H0827091AQ WING DOOR LHS | 1 | PCS | 1,770.75 | | 1,770.75 ✓ |
| 12 | 7H0827092AQ WING DOOR RHS | 1 | PCS | 1,770.75 | | 1,770.75 ✓ |
| 13 | 7H0827709F LHS DOOR SEAL | 1 | PCS | 81.33 | | 81.33 ✓ |
| 14 | 7H0898529 RHS DOOR SEAL | 1 | PCS | 65.54 | | 65.54 ✓ |
| 15 | 7E0829193T WEATHER SEAL | 1 | PCS | 146.55 | | 146.55 ✓ |
| 16 | D 004660M2 2K GLUE | 1 | PCS | 159.35 | | 159.35 (CP) net ✓ |
| 17 | D 002000A2 CLEANER | 1 | PCS | 99.84 | | 99.84 ✓ |
| 18 | D 00920002 PRIMER | 1 | PCS | 29.06 | | 29.06 (CP) net ✓ |
| 19 | D 00950025 APPLICATOR | 2 | PCS | 10.60 | | 21.20 (CP) net ✓ |
| 20 | D 181802M1 ACTIVATOR | 1 | PCS | 26.52 | | 26.52 (CP) net ✓ |
| 21 | 7E0853687 739 NAME PLATE TRANSPORTER | 1 | PCS | 39.27 | | 39.27 ✓ |
| 22 | 7E0807417E 9B9 REAR BUMPER | 1 | PCS | 951.09 | | 951.09 ✓ |
| 23 | 7H0867299 01C CLIP | 5 | PCS | 1.45 | | 7.25 ✓ |
| 24 | 7E0945105A REFELCTOR LH | 1 | PCS | 57.11 | | 57.11 ✓ |
| 25 | 7E0853630D DPJ VW SIGN | 1 | PCS | 75.30 | | 75.30 (CP) net ✓ |
| 26 | D 004660M2 2K GLUE | 1 | PCS | 159.35 | | 159.35 ✓ |
| 27 | D 00920002 PRIMER | 1 | PCS | 29.06 | | 29.06 ✓ |
| 28 | D 00950025 APPLICATOR | 2 | PCS | 10.60 | | 21.20 ✓ |

Service Order Confirmation

SERVICE ORDER NO: 18IP2410

CUSTOMER NO.: CV040665

CUSTOMER NAME: SHAO FENG TRADING

TELEPHONE NO.:

ADDRESS: 308C PUNGGOL WALK #13-352 WATERWAY TERRACES
Singapore

VEH No.: GBH3430G

Order Date: 18/09/18

Reg Date: 30/04/18 KM: 16,216

VIN NO.: WV1ZZZ7HZHH124793 ENGINE NO:

SA: STEVEN CHEE

MODEL: T6 VAN TDI NWB 110 (DSG) WGD MODEL NO.: SGA1F7

| <u>No.</u> | <u>DESCRIPTION</u> | <u>QTY</u> | <u>UOM</u> | <u>UNIT PRICE</u> | <u>DISC %</u> | <u>AMOUNT</u> |
|------------|----------------------|------------|------------|-------------------|---------------|---------------|
| 29 | D 181802M1 ACTIVATOR | 1 | PCS | 26.52 | | 26.52 |

Remarks : CHINA TAIPING DIRECT

DOA : 11/09/2018

T/P VECH : SFA182G

SURVEY BY TAUFIK (LKK)

| | |
|--------------|-----------|
| TOTAL | 12,497.04 |
| GST AMOUNT | 874.79 |
| TOTAL AMOUNT | 13,371.83 |

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 13 Sep 2018 | | 13 Sep 2018 15:07 Edit Adj Rpt | S\$12,497.04 Edit Estimates | S\$12,497.04 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | SUSAN , ID: S7374929H | | | | | | | | |
| Main Claimant: | CHRISTOPHER NG KOK CHUAN , ID: S7601236I | | | | | | | | |
| Vehicle Reg. No.: | GBH3430G | Date of Loss: | 11/09/2018 16:00 - :59 [4 Months and 12 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM18D04419C02 | Policy/Cover Note No.: | DMPCSN3087731801 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SFA182G | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Volkswagen Centre Singapore (MacPherson) 1 KAMPONG AMPAT, 368314 Macpherson - Tel: | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/09/2018] | | | | | | | | |
| Adj Asg. Remarks: | EST \$17,433.35, CASE WITH SJE. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*GBH3430G (SNM18D04419C02)
[SFA182G]

TP













































CHRISTOPHER NG KOK CHUAN


Sep 11 2018 4:00PM

[SUSAN]












Volkswagen Centre Singapore

| | | | | | | | | | | |
|--------------------|-----------------|--|---------------|-----------|-------------------------------------|--|------------|--|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | Compose New Letter | | View | | View in Browser | |
| Assessment Reports | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | | Thumbnail | Print | | | | | |
| 1 | 12/09/18 15:21 | Accident Statement | | Load HTM | | | | | | |
| Photos/Images | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | | Thumbnail | Print | | | | | |
| 1 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 2 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 3 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 4 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 5 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 6 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 7 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 8 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 9 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 10 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 11 | 12/09/18 15:18 | Accident Photo [Linked Accident Report Documents] | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | |
| 1 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 2 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 3 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 4 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 5 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 6 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 7 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 8 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 9 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 10 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 11 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 12 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 13 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 14 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 15 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 16 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 17 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 18 | 15/02/19 11:11 | General View | | Load JPG | <input checked="" type="checkbox"/> | | | | | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 19 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 15/02/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|--|--|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 69 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 15/02/19 11:11 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 13/09/18 15:06 | EMAIL FM VWG |  Load PDF | |
| 2 | 13/09/18 15:06 | REPAIR EST WITH TP GIA |  Load PDF | |
| 3 | 13/09/18 15:06 | OI GIA |  Load PDF | |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 12/09/18 15:18 | Accident Sketch Plan [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/09/18 15:18 | Accident Sketch Plan [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/09/18 15:18 | Identification Card [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/09/18 15:18 | Driving Licence [Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 15/02/19 15:28 | Supplementary |  Load PDF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 12/09/18 15:21 | Accident Statement |  Load HTM | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 12/09/18 15:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Jin Auto Services Pte Ltd (Defu) | Thumbnail | Print |
| 1 | 12/09/18 15:18 | Accident Sketch Plan |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/09/18 15:18 | Accident Sketch Plan |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/09/18 15:18 | Identification Card |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/09/18 15:18 | Driving Licence |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016739/T1TBE2

Date: 18/02/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3087731801

Claimant Vehicle
No: GBH3430GInsured Vehicle
No: SFA182G

Date of Loss: 11/09/2018

Nature of Claim: TP

Claim
No: SNM18D04419C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH3430G**Make & Model: VOLKSWAGEN XC60 T6, 3.0 AT ABS D/AB HID
4WD 5DR TC (A)

Engine No: CXH068821

Reg. Date: 30/04/2018 (Man. Year: 2017)

Chassis No: WV1ZZZ7HZHH124793

Colour: Silver

Odometer: 15127 km

Engine Capacity: 1968 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 6,818.75 | 5,977.04 | 841.71 | 12.34 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 9,840.00 | 6,520.00 | 3,320.00 | 33.74 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 16,658.75 | 12,497.04 | 4,161.71 | 24.98 |
| + GST 7.00/7.00% (S\$) | 1,166.11 | 874.79 | 291.32 | 24.98 |
| Nett Amount (S\$) | 17,824.86 | 13,371.83 | 4,453.03 | 24.98 |

INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 18/09/2018 Inspected At:

Volkswagen Centre Singapore
(MacPherson)
1 KAMPONG AMPAT
Singapore 368314

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 15 Feb 2019) | |
| Parts: | N/A | VOLKSWAGEN XC60 T6 3.0 AT ABS D/AB HID 4WD 5DR TC (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBH3430G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *STICKER 70KM/H | Necessary | 20.00 FS | *20.00 FS |
| 2 | 1 | | *STICKER 12PAX | Necessary | 20.00 FS | *20.00 FS |
| 3 | 1 | | *REVERSE SENSOR | Not Working | 400.00 FS | *400.00 FS |
| 4 | 1 | | *REINFORCEMENT | Not Necessary | 261.84 FS | *- FS |
| 5 | 1 | | *REAR BUMPER SIDE BRACKET L | Not Necessary | 31.92 FS | *- FS |
| 6 | 1 | | *REAR BUMPER SIDE BRACKET | Not Necessary | 31.92 FS | *- FS |
| 7 | 1 | | *REAR BUMPER | Deformed | 951.09 FS | *951.09 FS |
| 8 | 1 | | *RHS LOCK | Not Necessary | 56.97 FS | *- FS |
| 9 | 1 | | *LHS LOCK | Not Necessary | 56.97 FS | *- FS |
| 10 | 1 | | *WEATHER SEAL | Cut | 146.55 FS | *146.55 FS |
| 11 | 1 | | *NAME PLATE TRANSPORTER | Necessary | 39.27 FS | *39.27 FS |
| 12 | 1 | | *THIRD BRAKELIGHT LHS | Not Necessary | 108.14 FS | *- FS |
| 13 | 1 | | *THIRD BRAKELIGHT RHS | Not Necessary | 108.14 FS | *- FS |
| 14 | 1 | | *REFLECTOR LH | Cracked | 57.11 FS | *57.11 FS |
| 15 | 1 | | *REFLECTOR RH | Not Necessary | 57.11 FS | *- FS |
| 16 | 1 | | *WING DOOR LHS | Bent | 1,770.75 FS | *1,770.75 FS |
| 17 | 1 | | *WING DOOR RHS | Bent | 1,770.75 FS | *1,770.75 FS |
| 18 | 2 | | *LATCH | Not Necessary | 85.80 FS | *- FS |
| 19 | 1 | | *VW SIGN | Not Necessary | 42.90 FS | *- FS |
| 20 | 1 | | *LHS DOOR SEAL | Necessary | 81.33 FS | *81.33 FS |
| 21 | 5 | | *CLIP | Necessary | 7.25 FS | *7.25 FS |
| 22 | 1 | | *RHS DOOR SEAL | Necessary | 65.54 FS | *65.54 FS |
| 23 | 1 | | *CLEANER | Necessary | 99.84 FS | *99.84 FS |
| 24 | 1 | | *2K GLUE | Necessary | 159.35 FS | *159.35 FS |
| 25 | 1 | | *PRIMER | Necessary | 29.06 FS | *29.06 FS |
| 26 | 2 | | *APPLICATOR | Necessary | 21.20 FS | *21.20 FS |
| 27 | 1 | | *ACTIVATOR | Necessary | 26.52 FS | *26.52 FS |
| 28 | 1 | | *VW SIGN | Necessary | 75.30 FS | *75.30 FS |
| 29 | 1 | | *2K GLUE | Necessary | 159.35 FS | *159.35 FS |
| 30 | 1 | | *PRIMER | Necessary | 29.06 FS | *29.06 FS |
| 31 | 2 | | *APPLICATOR | Necessary | 21.20 FS | *21.20 FS |
| 32 | 1 | | *ACTIVATOR | Necessary | 26.52 FS | *26.52 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|-----------------|-----------------|
| Total Parts (\$\$) | 6,818.75 | 5,977.04 |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---------------------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR | New | 4,200.00 | 2,520.00 |
| 2 | R&R REAR WINDSCREEN | New | 1,680.00 | 840.00 |
| 3 | SPRAY PAINT | New | 3,200.00 | 2,400.00 |
| 4 | PROGRAMMING & CALIBRATION | New | 480.00 | 480.00 |
| 5 | ELECTRICAL CHECK OR MECHANICAL REPAIR | New | 280.00 | 280.00 |
| Gross Labour Cost (\$\$) | | | 9,840.00 | 6,520.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >