

LAWSON

INS. CASE OWNER:

CC 7/1501801 6747, 416679

LKK:

IDAC:

Surveyor:

MURKUS

DOI:

ASSIGNMENT/

11/11/18

Date / Time:

11/11/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GT 7458D

Name of Insured:

DANUWE KIANE SHON

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

11/11/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN TEN SON

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

DM18H1024857

Policy No.:

DM18H1024857-110676

Make / Model:

TOYOTA

Place of Accident:

5077 AME IND PARK 2

OI GLA REPORT: YES / NO

☒ YES

TP GLA REPORT: YES / NO

☒ YES

Insured Liability:

Final ? Yes / No

SKC 122GR

INSRS:
WSP:
Tel:
Liability:
RMKS:

ckc

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SELIMAR 7 AM/11/11/18 6074 AM/11/18
GT 7458D

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	
After call Itr to OI:	
Documentation Check List:	Handler Typist
Notification Itr (if non-pickup)	<input type="checkbox"/>
After call Itr to OI:	<input type="checkbox"/>
Authorisation To Act:	<input type="checkbox"/>
Release Voucher:	<input type="checkbox"/>
Final Repair Bill:	<input type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>
LTA / GLA:	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PIR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD:	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

TP reversing into lot. OI not at fault.

TP VIDEO FOOTAGE IN. V DRIVE/INFORMATION
BE WITHIN PROSECUTION.SEND EMAIL TO TP TO WITHIN
PROSECUTION.

TO CLERK.

RECEIVED 7 DEC 2018

VIC
for
06-12-18

PRELIMINARY ADVICE Date/Time: 20/09/18 Sent By: bco

FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28. Ass. Lia:	
Repair Cost:	\$5			
Loss of Rental (LOR):	\$5	(days)		
Loss of Use (LOU):	\$5	(5 x days)		
Loss of Income (LOI):	\$5	(5 x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LO <input type="checkbox"/>	(Tick only one)	
GLA/LTA Search	\$5			
Medical:	\$5			
Disbursement:	\$5	(e.g. Tow/ Independent)		
Legal Cost:	\$5			
Total:	\$5	Global Sum \$5:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5	Name 1:		
Payee 2: (Strike if N.A.)	\$5	Name 2:		
Payee 3: (Strike if N.A.)	\$5	Name 3:		

COPY SENT

1) Claim status: Normal/☒ Private Settle
2) Report Format:
3) Survey fee: \$400.00

REF: E61

ASSIGNMENT

Front: Date: 19-09-2018

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SKC 1225 R

at Workshop m/s Cyle & Carriage
of No. 330 Ubi Rd 3

Insured

Policy No.

Claims No.

Sum Insured Excess:

(Client's Record)

Make of Veh. Murs

10um

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS LA 49927

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKC 1225 R Yr Regn: 10 / 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make KIA Cerato K3 cc 1591

Colour Red A/C: Insured / Std / NI / NA

Sp. Reading 8895 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAF2411MJE749231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 11/9/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 19/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have video of lorry

- UNCONFINED R/P \$7,718.00

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photo

) Other

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18016743/Uhb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 13-09-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GT 7458D	Veh. Inspected	SKC 1225R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/09/2018	Inspection Date	19/09/2018
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQ118016743/Uhb3

Date: 20.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKC1225R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.09.2018 at the premises of M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	12,093.00
Revised Estimate Amount	: S\$	7,718.00
"Check" Items Amount	: S\$	1,560.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name LCV01675/Ms Ho Yuet Chun
Contact No	Reg No/Reg Date SKC1225R / 31/10/2017
	Date In/Mileage 11/09/2018/ 0
	Chassis No KNAFZ411MJ5749231
	Engine No G4FGHH683954
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim K3R / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	13/09/2018/ 12:44	DS	218 / MarsLer	64868

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S MIPNT88088 TO REPLACE FRONT BUMPER,BODY KIT,RH HEADLAMP,RHF FENDER,ETC STRIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS				2400.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				300.00
S MIPNT88088 TO PERFORM COMPUTERIZE WHEEL ALIGNMENT				180.00
S MIPNT88088 WHEEL BALANCING				50.00
S MIPNT98088 SPRAY PAINTING ON RH & FRONT ACCIDENT AFFECTED AREAS				2100.00
M KS 86511 A7 810 COVER - FRONT BUMPER	1.00	633.00	0.00	633.00
M KS 86568 A7 800 RH DUCT ASSY-AIR CUR	1.00	6.00	0.00	6.00
M KS 86513 A7 000 LH SIDE BRACKET-FR B	1.00	12.00	0.00	12.00
M KS 86514 A7 000 RH SIDE BRACKET -FR	1.00	12.00	0.00	12.00
M KS 95720 A7 0009 P ULTRASONIC SENSOR AS	1.00	177.00	0.00	177.00
M SUK11010113-K3 K3 BODY KIT	1.00	1680.00	0.00	1680.00
P KS 92102 A7 610 RH HEADLAMP ASSY	1.00	2209.00	0.00	2209.00
P KS 84142 A7 000 INSULATOR - FENDER	1.00	28.00	0.00	28.00
M KS 66321 A7 000 RH FENDER PANEL	1.00	396.00	0.00	396.00
M KS 52910 A7 CA0 WHEEL ASSY - ALUMINI	1.00	1560.00	0.00	1560.00
P KS 0G032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00

Estimate

NOTES

ACCIDENT ON 11/09/2018 AT 5022 ANG MO KIO INDUSTRIAL PARK 2 CAR PARK

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # GT7458D TP INS : EQ

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (illegal modification) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Parts	6,733.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,360.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	12,093.00

Authorized signatory and company stamp

Acknowledged by Repairer

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6873E
Vehicle Details	
Vehicle No.:	SKC1225R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	G4FGHH683954
Chassis No.:	KNAFZ411MJ5749231
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$15,829.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$15,829.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2027
PARF Rebate Amount:	\$11,871.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$38,056.00
Total Rebate Amount:	\$49,927.00

The information contained herein is correct as at 19 Sep 2018

OK



COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : Ho Yuet Chun
 Period of Insurance : 30 Oct 2017 to 30 Oct 2018
 Engine No. : G4FGHH683954
 Chassis No. : KNAFZ411MJ5749231



Vehicle No. : SKC/225R
 Cover Note No. : 1700071251
 Endorsement No. :
 Issued Date : 26 Oct 2017

ABOUT THE COVER

Make/Model : KIA Cerato K3 1.6 SX
 Engine Capacity/Tonnage : 1,591.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 3 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
Ho Yuet Chun

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 63884501
 2. Cycle & Carriage Customer Service Centre (For Windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278900
 3. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately. We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0500710050

C&C FULCO-CORP SALES

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik
 AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Chin Esue

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-140568

Date of Request: 11/09/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date: 11/09/2018
Enquiry By: Mars Ler Yeong Cherng
TP Vehicle No: GT7458D
Accident Date: 11/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GT7458D	EQ Insurance Company Ltd	02/11/2017-01/11/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-140568

Date of Request: 11/09/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 11/09/2018
Enquiry By Mars Ler Yeong Cherng
TP Vehicle No. GT7458D
Accident Date 11/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Shu Pei (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 21 September 2018 9:19 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving GT7458D (OI : EQI -DM18HO02428/JT) AND SKC1225R (TP : LKK REF - CC3/EQI18016743/hb3) on 11.09.2018
Attachments: Preliminary_Advice.pdf; TP ESTIMATE- MARKED.PDF; SAS2470052.pdf

Dear Shu Pei

OI report as attached.

Third party reversing into lot, OI not at fault.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, September 20, 2018 6:48 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GT7458D (OI : EQI - TBA) AND SKC1225R (TP : LKK REF - CC3/EQI18016743/hb3) on 11.09.2018

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

We had inspected TP vehicle SKC 1225R at M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 31, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Thursday, 13 September 2018 4:30 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: Direct Settlement - Accident Involving GT7458D (OI : EQJ - TBA) AND SKC1225R (TP : LKK REF - CC3/EQI18016743/hb3) on 11.09.2018

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case from M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd.

Enclosed for your perusal is:

- TP's EST & GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 31, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 6 December, 2018 9:45 AM
To: Mars Ler
Cc: Chris Bulaclac; Admin A; Vic (LKKAUTO)
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK REF:CC3/EQI18016743/Uhb3
Attachments: 37dbea1f-337d-4b9d-a36d-78fd34f944b7 (online-video-cutter.com) (2).mp4

Without Prejudice

Dear Mars Ler,

We refer further to the below email.

Please be informed that our principal had further reviewed the matter and based on the available information and evidence provided, our principal is in the view that our Insured is not liable of this accident. Based on the footage, our principal is in the view that your client just swerved towards the right and did not even slowed down/stop to look out for traffic before attempting to reverse when our Insured vehicle drove past him.

As such, we have our principal's instruction to maintain our position and we are unable to look further into your client's claim.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Mars Ler [<mailto:mars.ler@ccfulco.com.sg>]
Sent: Thursday, 29 November, 2018 4:57 PM
To: janet.tan@eqinsurance.com.sg
Cc: Vic (LKKAUTO); Chris Bulaclac
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK REF:CC3/EQI18016743/Uhb3

Dear Janet ,

As per video footage for your reference , please advise liability if we can do Direct Settlement on this case .

Thank You,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

From: Chris Bulaclac
Sent: Tuesday, 27 November, 2018 8:17 AM
To: Vic (LKKAUTO)
Cc: Admin A; Mars Ler
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK
REF:CC3/EQI18016743/Uhb3

Hi Vic,

Kindly advice on this case.

Thank you,

Best Regards,

Christopher L. Bulaclac
Assistant Manager – Customer Service
H/P 96552177 D/D 65949160
email : chris.bulaclac@ccfulco.com.sg
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 UBI Road 3 Singapore 408650
Tel : 67461000 Fax : 64875857

From: Mars Ler
Sent: Monday, 19 November 2018 14:34
To: Vic (LKKAUTO)
Cc: Admin A; Chris Bulaclac
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK
REF:CC3/EQI18016743/Uhb3

Dear Vic ,

Please advise liability if we can do Direct Settlement on this case .

Thank You,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

From: Mars Ler
Sent: Wednesday, 14 November, 2018 4:48 PM

Vic (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 5 December, 2018 9:42 AM
To: Vic (LKKAUTO)
Cc: Admin A; Joel Goh
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK REF:CC3/EQI18016743/Uhb3
Attachments: 37dbea1f-337d-4b9d-a36d-78fd34f944b7 (online-video-cutter.com) (2).mp4

Dear Vic,

As mentioned in our earlier tel-conversation, third party did not even pause to look out for traffic before he attempted to reverse. It was at this time our insured vehicle drove past.

We maintain that our insured should not be held liable for the damages sustained by third party.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Wednesday, December 5, 2018 9:38 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Joel Goh <joel.goh@eqinsurance.com.sg>
Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK REF:CC3/EQI18016743/Uhb3
Importance: High

Dear Janet,

We refer to the below email from TP repairer.

Please advise.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Mars Ler [<mailto:mars.ler@ccfulco.com.sg>]

Sent: Thursday, 29 November, 2018 4:57 PM

To: janet.tan@eqinsurance.com.sg

Cc: Vic (LKKAuto); Chris Bulaclac

Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK

REF:CC3/EQI18016743/Uhb3

Dear Janet ,

As per video footage for your reference , please advise liability if we can do Direct Settlement on this case .

Thank You,

Best regards

Mars Ler

B & P Service Advisor

Cycle & Carriage Fulco Motor Dealer Pte Ltd

330 Ubi Road 3 Singapore 408650

D/D 65949163 H/P 91792566

From: Chris Bulaclac

Sent: Tuesday, 27 November, 2018 8:17 AM

To: Vic (LKKAuto)

Cc: Admin A; Mars Ler

Subject: RE: Accident On 11/09/2018 Involving Our Insured SKC1225R And Your Insured GT7458D ***LKK

REF:CC3/EQI18016743/Uhb3

Hi Vic,

Kindly advice on this case.

Thank you,

Best Regards,

Christopher L. Bulaclac

Assistant Manager – Customer Service

H/P 96552177 D/D 65949160

email : chris.bulaclac@ccfulco.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI18016743/Uhb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 18-12-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 7458D	Veh. Inspected	SKC 1225R	
Policy No.	DMCFHQ17-006196	Coverage (\$)	0.00	
Claim No.	DM18HO02428/JT	Excess (\$)	0.00	
Assign From		Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO K3 (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAFZ411MJ5749231	Colour	RED	
Odometer	8895	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	GOODYEAR	7 mm	
L/H Front Tyre	215/45 R17	GOODYEAR	7 mm	
R/H Rear Tyre	215/45 R17	GOODYEAR	7 mm	
L/H Rear Tyre	215/45 R17	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2018	Inspection Date	19/09/2018	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 1225R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER -FRONT BUMPER (SN)	DISTORTED	633.00	633.00
1	RH DUCT ASSY -AIR CUR (SN)	NECESSARY	6.00	6.00
1	LH SIDE BRACKET ,FR B (SN)	NECESSARY	12.00	12.00
1	RH SIDE BRACKET -FR (SN)	NECESSARY	12.00	12.00
1	ULTRASONIC SENSOR AS (SN)	NOT NECESSARY	177.00	-
1	K3 BODY KIT (SN)	CRACKED	1,680.00	1,680.00
1	RH HEADLAMP ASSY (SN)	SCRATCHED	2,209.00	2,209.00
1	INSULATOR -FENDER (SN)	NOT NECESSARY	28.00	-
1	RH FENDER PANEL (SN)	DENTED	396.00	396.00
1	WHEEL ASSY -ALUMINI (SN)	TO REPAIR SEE LABOUR	1,560.00	-
10	CLIP -BUMPER (SN)	NECESSARY	20.00	20.00
			6,733.00	4,968.00
	LABOUR			
	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS.		80.00	60.00
	DIAGNOSTIC /SCANNING.		250.00	250.00
	TO REPLACE FRONT BUMPER,BODY KIT ,RH HEADLAMP ,RHF FENDER ,ETC		2,400.00	900.00
	STRAIGHTEN ,REFORM ,ALIGN ON FRONT ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF WHEEL ASSY -ALUMINI .			
	TO APPLY SEALANT KIT ON NEW PANEL.		300.00	100.00
	TO PEFORM COMPUTERIZE WHEEL ALIGNMENT.		180.00	180.00
	WHEEL BALANCING.	NOT NECESSARY	50.00	-
	SPRAY PAINTING ON RH & FRONT ACCIDENT AFFECTED AREAS .		2,100.00	1,260.00
			-	-
			-	-
			-	-
			5,360.00	2,750.00
	GRAND TOTAL		12,093.00	7,718.00

Report Ref No. CC3/EQI18016743/Uhb3q2



RECOMMENDED COST OF REPAIRS			7,718.00
-----------------------------	--	--	----------

Report Ref No. CC3/EQI18016743/Uhb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on this Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.