

22/03/2002

ASS. REC. BY:

REF: CS3 / MSC18016748 / R1cb02

Special Instruction:

Surveyor

Mummen

ASSIGNMENT (Office)

From (Person):

Chhica Nyuk Pui

of

MS11

Date/Time:

13/09/2018 404pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFT 9702

Insured:

SDT 715T

at Workshop m/s

Neo Automotive

Tel:

9109 5745

of

53 Ubi Ave 1 #05-44

Policy No:

24027600QMX

Claim No:

570079

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11-09-2018

CA / REV / REP. / REV 24 HRS

14-09-2018

H.O.D. Endorsement:

Date/Time:

13/09/2018 429pm

Person Contacted:

Mr Neo

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( X ) Estimate
	SFT 9702 - NA / DMC18013117 / ZH
	SDT 715T - X
	Dismantle: 14/9/2018
	After repair: 20/9/2018

DUA: 18/07/2018



## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		13 Sep 2018 16:04 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	HUM KOW TOON, ID: S1467657J			[Created by insurer]					
Main Claimant:	PRESTIGE LEASIN PTE LTD, Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	SFT970Z	Date of Loss:	11/09/2018 17:00 - :59 [116 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570079	Policy/Cover Note No.:	29027600QMX (Comprehensive) Coverage: 22/09/2017 - 21/09/2018						
Vehicle Reg. No. (Insured):	SDT715T	Policy No. (Claimant):							
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:		Excess: S\$700.00						
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/09/2018]								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: MR NEO 9109 5745								
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
View All Compose Case Mail									
<b>ALL ASSOCIATED TASKS</b>									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3326H
Vehicle Details	
Vehicle No.:	SFT970Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A5201489
Chassis No.:	GJ11301337
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,718.00
Original Registration Date:	23 Dec 2008
First Registration Date:	23 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$15,718.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2018
PARF Rebate Amount:	\$7,859.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,200.00
COE Rebate Amount:	\$168.00
<b>Total Rebate Amount:</b>	<b>\$8,027.00</b>

The information contained herein is correct as at 14 Sep 2018

OK

11,000  
8,027  

---

2,973

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/09/2018 15:08
Date Of Accident	11/09/2018 17:35
Exact Location Of Accident	JUNC GEYLANG RD & ALJUNIED RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFT970Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PRESTIGE LEASING PTE LTD
Co Reg No	201723326H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91449265
Alternative Phone No	OFFICE-91449265

### Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE 1.5M A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5094838100
Cover Note Number	

### Driver

Name of Driver	TENG HEONG CHEONG
NRIC No	S1398313E
Date Of Birth	13/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	11/10/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90286198
Fax Number	
Contact Number	OFFICE-90286198
Email Address	NOEMAIL

Address	BLK 636 BEDOK RESERVOIR ROAD #13-27
Postcode	410636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20180912/2080.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDT715T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HUM KOW TOON
NRIC/Passport Number	S1467657J
Contact Number	98170715
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

TENG HEONG CHEONG

Approximate Age

Injuries Sustain

NECK, SHOULDER & BACK

Injured person in which vehicle?

SFT970Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:



### Accident Sketch Plan

### SKETCH PLAN

SKETCH PLAN

pt. Gough

A: SF 709702

B: SD 7715T

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 7/20180912/280

### DECLARATION

I/We declare the foregoing particulars are true in every respect.



**Policyholder's Signature**  
**Date & Time:**

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:




































### ...CLAIM SUBFOLDER...(Pending for Survey Report)


































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2018		13 Sep 2018 16:04 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>







































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	<b>HUM KOW TOON</b> , ID: S1467657J								
Main Claimant:	<b>PRESTIGE LEASIN PTE LTD</b> , Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	<b>SFT970Z</b>	Date of Loss:	11/09/2018 17:00 - :59 [116 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 570079</b>	Policy/Cover Note No.:	29027600QMX (Comprehensive) Coverage: 22/09/2017 - 21/09/2018						
Vehicle Reg. No. (Insured):	<b>SDT715T</b>	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	<b>Neo Automotive Pte Ltd (HQ)</b> 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Imm.Advice due 14/09/2018]								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: MR NEO 9109 5745								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFT970Z (570079)  
[SDT715T]  
TP  
PRESTIGE LEASIN PTE LTD  
Sep 11 2018 5:00PM  
[HUM KOW TOON]  
Neo Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
2	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
3	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
4	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
5	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
6	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
7	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
8	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
9	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
10	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
11	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
12	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
13	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
14	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
15	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
16	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
17	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
18	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
19	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
20	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
21	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
22	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
23	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
24	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
25	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
26	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
27	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
28	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
29	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
30	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
31	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
32	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
33	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
34	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
35	24/09/18 14:43	General View								Load JPG	<input checked="" type="checkbox"/>	
36	24/09/18 14:44	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
37	24/09/18 14:44	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	24/09/18 14:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	24/09/18 14:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/09/18 11:14	PRI - LEGAL OPTIONS LLC	 Load PDF	
2	13/09/18 11:14	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
3	13/09/18 11:14	SFT970Z TP E-FILE REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016748/R1CBE2

Date: 25/09/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29027600QMX

Claimant Vehicle  
No : SFT970Z

Insured Vehicle No : SDT715T

Date of Loss: 11/09/2018

Nature of Claim: TP

Claim No: 570079

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFT970Z

Make &amp; Model: HONDA AIRWAVE, 1.5 M (A)

Engine No: L15A5201489

Reg. Date: 23/12/2008 (Man. Year: 2008)

Chassis No: GJ11301337

Colour: Black

Odometer: 289192 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R14

Rear Tyre Size: 185/65 R14

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 14/09/2018 Inspected At:

Neo Automotive Pte Ltd (HQ)  
53 UBI AVE 1, #05-44 PAYA UBI  
INDUSTRIAL PARK  
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500.00 -\$8,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
<b>Parts:</b>	M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFT970Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >