

22/03/2002

ASS. REC. BY:

REF: CS3/MSG/8016750/Gcbez

Special Instruction:

SURVIVOR
MULIMEN

ASSIGNMENT (Office)

From (Person): Katherine Wong of MSG Date/Time: 13/02/18 4:00pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 8818A Insured: SDH 2393M

at Workshop m/s MG Solution Tel: 6744465

of 23 Kaki Bukit Ave 4 #02-03B

Policy No: A804133630MX Claim No: 570052

Sum Insured: Excess:

Make of Veh: D.O.A. 11-09-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

14-09-2018

H.O.D. Endorsement:

Date/Time: 13/02/18 4:27pm Person Contacted: Hong Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJG 8818A - X
	SDH 2393M - X


PRS
Xnd

REF: MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TR / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s MG Solution
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJG8818A Yr Regn: 04 Sep 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A3 1.0 c.c 999
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 25897 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8V3J1009303
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rport.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 14-09-18
 Survey held at W/S 10:50AM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$5500 - \$6500</u>
RECEIVED 17 SEP 2018	

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 5
 Resurvey No. of Trip: -

Report Format: PRS
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: 120
 Transportation: _____
 S + RS: \$ _____
 Photos: _____
 Others: 10
 TOTAL: 130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		13 Sep 2018 16:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NG SING CHYE SIMON, ID: S1501869J [Created by insurer]		
Main Claimant:	TEO GEK HONG, ID: S1179769E		
Vehicle Reg. No.:	SJG8818A	Date of Loss:	11/09/2018 13:00 - :59
Claim Type:	TP / 570052	Policy/Cover Note No.:	A80413363QMX (Comprehensive) Coverage: 14/11/2017 - 13/11/2018
Vehicle Reg. No. (Insured):	SDH2393M	Policy No. (Claimant):	
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/09/2018]		
Driver/Custodian (Insured):	NG SING CHYE SIMON (), NRIC: S1501869J		
Adj Asg. Remarks:	SJE AGREE LKK. LIAB 50%. PLS CONTACT JAMIE YAN @ 6744 4165		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9769E
Vehicle Details	
Vehicle No.:	SJG8818A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	CHZ521094
Chassis No.:	WAUZZZ8V3J1009303
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,475.00
Original Registration Date:	04 Sep 2017
First Registration Date:	04 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$16,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2027
PARF Rebate Amount:	\$12,198.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$38,484.00
Total Rebate Amount:	\$50,682.00

The information contained herein is correct as at 14 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2018 15:01
Date Of Accident	11/09/2018 14:15
Exact Location Of Accident	MARINA BOULEVARD BESIDE MBFC (STRAITS VIEW)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG8818A
Insured/Policyholder	
Name Of Registered Owner	TEO GEK HONG
NRIC No	S1179769E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97827592
Alternative Phone No	OTHERS-97827592

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80460818 QMY (COMP)
Cover Note Number	

Driver

Name of Driver	WEE HUI CHING
NRIC No	S8826605F
Date Of Birth	22/07/1988
Occupation	INDOOR
Date Of Driving Pass	23/04/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97827592
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	218 UPPER PAYA LEBAR ROAD
Postcode	534884
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDH2393M
Vehicle Make/Model/Colour	TOYOTA CAMRY 2.0 AUTO ABS AIRBAG
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@sinanet.com.sg

Policyholder's Signature
Date & Time:


X
Driver's Signature
(if driver is not the policyholder)
Date & Time:

12 SEP 2018

Reporting Centre Personnel's signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/09/2018 at about 1415 hrs at along Marina Boulevard beside Marina Bay Financial Centre (Straits View). I was travelling on the 3rd lane from the left and suddenly a Vehicle (B) on my Right veered into my lane without checking his blindspot and without cautious hence collided onto my whole Right Portion of my Vehicle (A) causing damages to my vehicle.

(A) SJG 8818A
 (B) SDH 2393 M

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

12 SEP 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
 Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2018		13 Sep 2018 16:02 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	NG SING CHYE SIMON , ID: S1501869J		
Main Claimant:	TEO GEK HONG , ID: S1179769E		
Vehicle Reg. No.:	SJG8818A	Date of Loss:	11/09/2018 13:00 - :59 [12 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570052	Policy/Cover Note No.:	A80413363QMX (Comprehensive) Coverage: 14/11/2017 - 13/11/2018
Vehicle Reg. No. (Insured):	SDH2393M	Policy No. (Claimant):	
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 14/09/2018]		
Driver/Custodian (Insured):	NG SING CHYE SIMON (), NRIC: S1501869J		
Adj Asg. Remarks:	SJE AGREE LKK. LIAB 50%. PLS CONTACT JAMIE YAN @ 6744 4165		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJG8818A (570052)
[SDH2393M]
TP
TEO GEK HONG
Sep 11 2018 1:00PM
[NG SING CHYE SIMON]
MG Solution Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>
Video									1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print				
1	13/09/18 10:38	Video - Accident(Front)		Load MP4					
2	13/09/18 10:40	Video - Accident(Rear)		Load MP4					
Assessment Reports									1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print				
1	13/09/18 11:14	Accident Statement <small>From:SC - Reg. No: SDH2393M, Claimant: NG SING CHYE SIMON</small>		Load HTM					
Photos/Images									3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
2	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
3	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
4	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
5	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
6	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
7	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
8	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
9	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
10	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
11	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
12	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
13	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
14	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
15	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
16	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
17	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
18	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
19	16/09/18 21:27	General View		Load JPG	<input checked="" type="checkbox"/>				
20	16/09/18 21:27	Chassis Number		Load JPG	<input checked="" type="checkbox"/>				
21	16/09/18 21:27	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>				
Documentation									1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print				
1	13/09/18 09:58	PRI		Load PDF					
2	13/09/18 11:13	SJE AGREE LKK		Load PDF					
3	13/09/18 11:15	Third Party Accident Report <small>From:SC - Reg. No: SDH2393M, Claimant: NG SING CHYE SIMON</small>		Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016750/GCBE2
Date: 18/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80413363QMX
Claimant Vehicle No : SJJ8818A	Insured Vehicle No :	SDH2393M
Date of Loss: 11/09/2018	Nature of Claim:	TP
		Claim No: 570052

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ8818A		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CHZ521094
Reg. Date:	04/09/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V3J1009303
Colour:	Brown	Odometer:	25897 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	14/09/2018 Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 -\$6,500.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2018)
Parts: 144	AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG8818A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >