

ASS. REC. BY:

REF: CS/MSG 18016751 (Kvbnz) Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

Merimen

From (Person): Elaine Ngu

of

MSLH

Date/Time: 13/09/2018 4:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 5679P

Insured:

FBB 3720B

at Workshop m/s

Accord Auto

Tel:

6481 9517

of

Blk 10 AMK Ind Park 2A # 03-11

Policy No:

MSD / VMT / 18-989613-WTT

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI

17/09/2018

H.O.D. Endorsement:

Date/Time:

13/09/2018 4:18pm

Person Contacted:

Jessie

Vehicle-IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

2831-60

SKQ 5679P - X

FBB 3720B - X

18/9/18

Send preli revised via merimen

11/10

2831-60

Confirmed by email

(Ref 4694-80, 6090) (No LS)

REF:

MCG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 5679P.

at Workshop m/s Accord Auto.

of 10 AUG #03-11.

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKQ 5679P Yr Regn: 12 14

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1496

Colour:

M-Black

A/C: Insured / Std / NI / NA

Sp.Reading

5680

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM 42A8F 0156785

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MITSUBISHI / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 13/9/18

D.O.I. 17/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/9 All parts to Customer

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 11/10 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee.

Transportation.

S + RS. St

Photos

Others

Report Format:

merimen

Lump Sum / I.B.I. (\$

2831.60

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

150

10

160

RECEIVED 11 OCT 2018

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 18 Sep 2018

Preliminary Advice

Insured Vehicle No	: FBB3720B	Accident Date	: 13/09/2018
TP Vehicle No	: SKQ5679P	Assignment Date	: 13/09/2018
Make	: MAZDA M3	Est. Duration of Repair	: 4.00
Date of Inspection	: 17/09/2018		
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,526.40
Revised Amount	:S\$	2,831.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,831.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018 14:45		13 Sep 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BAHARUDDIN BIN MAMUD, ID: S1119049I								
Main Claimant:	JIANG GUODONG, ID: S6979826H								
Vehicle Reg. No.:	SKQ5679P	Date of Loss:	13/09/2018 07:00 - :59 [45 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/18-989613-WTT Coverage: 21/02/2018 - 20/02/2019						
Vehicle Reg. No. (Insured):	FBB3720B	Policy No. (Claimant):							
		Excess:							
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/09/2018]								
Adj Asg. Remarks:	oi non reporting. Liability not clear. TP agree with SJE - assign Kenneth Kong of LKK Auto Consultants Pte Ltd.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle No.:	SKQ5679P
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme:	Normal
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No.:	JM6BM42A8F0156785
Propellant:	Petrol
Engine No.:	P520242852
Engine Capacity:	1496 cc
Maximum Power Output:	88.0 kW (118 bhp)
Maximum Laden Weight:	1835 kg
Unladen Weight:	1339 kg
Year Of Manufacture:	2014
Original Registration Date:	10 Dec 2014
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$67,089.00
COE Expiry Date:	09 Dec 2024
Road Tax Expiry Date:	09 Dec 2018
PARF Eligibility Expiry Date:	09 Dec 2024
Inspection Due Date:	09 Dec 2019
Intended Transfer Date:	13 Sep 2018
CO2 Emission:	135.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 09 Dec 2018. You may renew the road tax from 10 Sep 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 09 Dec 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 10 Dec 2018 to 09 Jun 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 10 Dec 2018 to 09 Dec 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2018 10:59
Date Of Accident	13/09/2018 07:00
Exact Location Of Accident	WOODLANDS AVE 12 TWDS SLE (LP 54A)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ5679P
Insured/Policyholder	
Name Of Registered Owner	JIANG GUODONG
NRIC No	S6979826H
Email Address	GDJIANG2710@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91868596
Alternative Phone No	OFFICE-91868596

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 L 4-DOOR SEDAN SP.6EAT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01015235
Cover Note Number	

Driver

Name of Driver	JIANG GUODONG
NRIC No	S6979826H
Date Of Birth	27/10/1969
Occupation	INDOOR
Date Of Driving Pass	25/08/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91868596
Fax Number	
Contact Number	OFFICE-91868596
Email Address	GDJIANG2710@GMAIL.COM

Address	BLK 298 YISHUN STREET 20 #03-49
Postcode	760298
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : HUANG LIYU GENDER: : FEMALE
Passenger 2	NAME: : JOLYN JIANG ZINI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT. (REPORT NO: T/20180913/2022)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB3720B
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MAHALRUDIN

NRIC/Passport Number
Contact Number 81419433
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name MAHALRUDIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBB3720B
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers (who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be stored / used:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court order.


Policyholder's Signature
Date & Time: 15/04/2018
10:50am


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personal's Signature
Name: Jessie Siew
NRIC No.: 92251012W

Accident Sketch Plan Pg. 1

SKETCH PLAN Vehicle A: SKG 569P Vehicle B: FBG 3730 B



Woodlands, AL 367

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident: 12/01/2018 Time of Accident: 7:00 am

Please refer to Police Report. (Report No: T/20180913/2633)

DECLARATION

I/we declare the foregoing statements are true and correct.

Policyholder's Signature
Date & Time: 12/01/2018
11:50 am

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Center Contact No: 18195247
Name: Jessy Doe
SRIC / PIN No.: 026010720



Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180913/2022

1 of 4

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180913/2022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/09/2018 09:22		Vide Report No.: F/20180913/0072		Station Diary No.: 59	
Informant's Particulars					
Name of Informant: JIANG GUODONG			Address: APT BLK 298 YISHUN STREET 20 #03-49 SINGAPORE 760298		
ID Type / ID No.: NRIC NO / S6979826H			Contact No.: Home/Office: Mobile 91868596		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 27/10/1969	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: ENGINEERING MANAGER			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive No	Date/Time of Accident: 13/09/2018 00:00	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS AVENUE 12 TOWARDS SLE NEAR LF 54A				
Weather: Clear		Road Surface: Dry		Road Speed Limit
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB3720B	Motorcycle	HONDA			Slightly Damaged	0
SKQ5679P	Car	MAZDA	MAZDA3 4- DOOR SEDAN 1.5L SP 6EAT	Black	Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180813/2022

2 of 4

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No: T/20180813/2022

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SKQ5679P	TENET SOMPO INSURANCE PTE LTD.	D17MTPV0101523 5	10/12/2017	09/12/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	JIANG GUODONG		ID No.	S6979826H
Related Vehicle	NIL		Contact No.	91868586
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Rider				
Name	MAHALRUDIN		ID No.	NIL
Related Vehicle	NIL		Contact No.	81419433
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 13/09/2018 at about 0715hrs, I was driving my vehicle bearing registration plate number SKQ5678P, Black Mazda 3 on the right of 3 lanes. There is a heavy traffic ahead. As such, I slowed down and applied my brakes and came to a stop, when suddenly felt an impact on the rear right of his vehicle. I alighted my vehicle immediately and saw a motorcycle bearing registration plate number FBB3720B, Blue Honda landed on the road which was on the right side of my vehicle. The rider fell and landed on the divider. My vehicle's rear right side and the brake light was cracked and dented. I called the police and ambulance was called by the other drivers. The ambulance arrived first and assessed the rider's injury and conveyed him to the hospital conscious. Shortly after, the traffic police arrived and advised me to lodge a traffic accident report. My passenger and I were not injured during the incident.

Police Report Pg. 1



SINGAPORE
POLICE FORCE



T/20180913/2022

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 4

Report No: T/20180913/2022

CONTINUATION OF REPORT

Police Report Pg. 1



SINGAPORE
POLICE FORCE



T/20180913/2022

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

4 of 4

Report No. T/20180913/2022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474665 stating the report number as reference

Signature Of Officer Recording The Report:

J /
Staff Sgt SAW HUI YING

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

13/09/2018 09 22

Officer In Charge Of Case:

TP / GIT /
Sgt 3 RASHIDAH BINTE AZMAN
Contact No.: 65476216

Classification Of Case:

Authentication Stamp:

RP168

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Accident Claims Department

Date :

13/09/2018

Vehicle No :

SKW5679P

Veh Make/Model :

Mazda 3 Sedan 1.5L

YOM :

2014

Chassis No :

JM6BM42A8F0156785

Date of Accident :

13/09/2018

No	Qty	Description	Amount S
List Items:-			
1	1	Rear bumper	\$ Bu/nr 1,075.00 ✓
2	1	Rear bumper reflector (RH)	\$ R 51.00 X
3	1	Rear bumper side retainer	\$ nr 37.00 ✓
4	10	Rear bumper clip	\$ R 50.00 ✓
5	1	Rear bumper reinforcement	\$ R 538.00 X
6	1	RH tail lamp	\$ Bu 915.00 ✓
7	1	Rear RH fender	\$ R 1,175.00 X
8	1	Rear RH fender splash shield	\$ R 146.00 X
9	10	Rear RH fender splash shield clip	\$ nr 50.00 X
10	1	Rear windscreen glass moulding	\$ nr 120.00 X
11	1	Rear RH door assy	\$ R 999.00 X
12	1	Rear RH door glass outer chrome	\$ R 141.00 X
13	1	Rear RH door outer handle	\$ R 61.00 X
Total - List Item			\$ 5,358.00
Less 20%			\$ 1,071.60
Total			\$ 4,286.40
Special Nett Items:-			
1	1 Set	Rear reverse sensor	\$ R 380.00 X
2	1	Rear windscreen glass sealant/gum	\$ nr 80.00 X
3	1	Rear RH tyre	\$ R 450.00 X
Total - SN Item			\$ 910.00
Balance b/f			\$ 5,196.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG1806751/KVBN2

Date: 12/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-989613-WTT	Claim No:	MSCV/18-001336
Claimant Vehicle No :	SKQ5679P	Insured Vehicle No :	FBB3720B		
Date of Loss:	13/09/2018	Nature of Claim:	TP		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ5679P	Engine No:	P520242852
Make & Model:	MAZDA M3, 1.6 (A)	Chassis No:	JM6BM42A8F0156785
Reg. Date:	10/12/2014 (Man. Year: 2014)	Odometer:	56180 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,196.40	1,661.60	3,534.80	68.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,170.00	1,160.00	49.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,526.40	2,831.60	4,694.80	62.38
+ GST 7.00/7.00% (\$\$)	526.85	198.21	328.64	62.38
Nett Amount (\$\$)	8,053.25	3,029.81	5,023.44	62.38

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	17/09/2018	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2018)
Parts: 143	MAZDA M3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ5679P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,075.00 FL	*1,075.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Serviceable	51.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER	Distorted	37.00 FL	*37.00 FL
4	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	538.00 FL	*- FL
6	1		*RH TAIL LAMP	Broken	915.00 FL	*915.00 FL
7	1		*REAR RH FENDER	Repair	1,175.00 FL	*- FL
8	1		*REAR RH FENDER SPLASH SHIELD	Serviceable	146.00 FL	*- FL
9	10		*REAR RH FENDER SPLASH SHIELD CLIP	Not Necessary	50.00 FL	*- FL
10	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	120.00 FL	*- FL
11	1		*REAR RH DOOR ASSY	Repair	999.00 FL	*- FL
12	1		*REAR RH DOOR GLASS OUTER CHROME	Serviceable	141.00 FL	*- FL
13	1		*REAR RH DOOR OUTER HANDLE	Serviceable	61.00 FL	*- FL
14	1		*SET REAR REVERSE SENSOR	Serviceable	380.00 FS	*- FS
15	1		*REAR WINDSCREEN GLASS SEALANT/GUM	Not Necessary	80.00 FS	*- FS
16	1		*REAR RH TYRE	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,268.00	2,077.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,071.60	415.40
Total Parts (\$\$)	5,196.40	1,661.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	800.00	600.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	900.00	500.00
3	TO APPLY ANTI RUST TREATMENT	New	120.00	-
4	TO CHECK & ADJUST WHEEL ALIGNMENT	New	60.00	-
5	TO CHECK WIRING SYSTEM & LIGHT	New	80.00	20.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	150.00	-
8	TO TRANSFER REAR RH DOOR MECHANISM	New	100.00	-
Gross Labour Cost (\$\$)			2,330.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >