		-		18016753 / 6				
UNALOV				MENT (Office)			2.44	250
Mulmin From (Person):	Muhd	Achilk	of	MSLh	Da	te/Time: _	13092018	SSIPM
Estimated Cost:				Bill to:				
op reprws	TP RES /	OD RES/EV	A/INV/MV	// CS		09900	0. 9/200002	
To Inspect Veh	icle No:	Src	7801X		Insured:	SL	U 6621R	
at Workshop m	/s	Hua	mena		Tel:	6746	5519	
of		81k 1	Kaki Bukit	Ave 6 #0	1-61	0.00		
Policy No:	ASOH	50966amx		Claim No:	569	179		
Sum Insured:_				Excess:				
Make of Veh: (Client's Record)					D	.o.A.	10092018	
CA / REV /	REP. / RI	EV 24 HRS 1	1.101			H.O.D. Ende	orsement:	
				ed: June		^	-	
W-91 500	·		/					-
Date/Time	Action/Ins		() Estim	A STATE OF THE PARTY OF THE PAR				
2619-	Sent	via me	vinen I	pending es	timate-			
		Miles aparts						
	11	Sur \$	ar-nort	cred: 3.	134.7)	1550	0	
	lump	SWW A	CKXIII	0 - 0 0 .			1	

ASSIGNMENT

From: Date:	Veh No: SLC 480(X · Yr Regn. 2013, July.
Estimated Cost:	Type: M.Can / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hyundai i45 cc 1999.
at Workshop m/s	Colour While. A/C: Insured/Std/NI/NA
of	Sp.Reading 119526 . T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KMHEC41AMEAS77939.
Claims No.	Gen. Cond. Good) Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil S/Rim / STD A/Rim or
	Tyre Size: F: 225/45 R18
(Policy Condition)	R: 225/4548.
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO OF
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? ; Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 13/09/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Hua Meny.
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S Nu/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
TP MS19-	Otronto
MV: 651C RECEIVED 2	8/05/0/13
MV: 651C RECEIVED 2	1 026/11/2010
Nett: 5.5 IC	
1007 - 301	
	Days Of Repair: 4
Date/Time. File Return to?	Resurvey No. of Trip: Survey Fee: Transportation: \S0
2) Add Fee	
	: Interview (\$) Photos
Report Format:	: Tech. Invs. (\$) Olives
Lump SAy / LB.I: (\$ 2600 \-	: Weekend (\$ -)
	70TAL 160

Due Date

No results.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	11 Sep 2018		13 Sep 2018 15:59 Assign				New Assignme Cancel Case	ent 	
	Main		Reference	CI	aim Details	Doc	uments	Show All	
CLAIM S	UBFOLDER DET	TAILS				1	Created by insu	irer]	
Insured:		SEOV	V JUN YUAN EUG	ENE, ID: 5901	0951), Tel: +6598	376951		220-20	
Main Clair	mant:	тон	TECK HWEE, II	: S1567308G					
Vehicle Re	eg. No.:	SLC	4801X	D	ate of Loss:	1		9/2018 18:00 - :59 Months and 6 Days From LTA Date (Man Yr)]	
Claim Type:		TP /	569971	Pr	Policy/Cover Note No.:		A80450966QMX (Comprehension Coverage: 20/10/2017 - 19/10/2018		
Vehicle Re	g. No. (Insured)	: SLU6	621R	Po	olicy No. (Claimant):		13/10/2010		
				E	ccess:		5\$100.00		
Repairer:			Meng Spray Pain Bukit - Tel: 67478		(HQ) No 1 Kaki Bul	kit Avenue 6, #0	I-61 Autobay@Kak	i Bukit, 417883	
Handling :	Insurer:		Insurance (Sin 2548]	gapore) Pte. Lt	d. (HQ) - Tel: +65	5827 7888 [Ha	andled by Muhd A	shik B Madi -	
Adjuster:			Auto Consultants	Pte Ltd (HQ)	Tel: 6256-3561	Imm.Advice	due 14/09/201	[8]	
Driver/Cu	stodian (Insured)	A		SENE (28 / Male), NRIC: S9010951J, Tel: +6598376951					
Adj Asg. F	Remarks:	5519	LITY: 100% Pleas	e appoint appoir	t LKK AUTO to cond	uct the survey . I	Kindly contact MS	JUNE @ 6746	
ASSOCIA	ATED MAIL REC	EIVED				Vi	ew All Comp	ose Case Mail	
There are	no mail for this o	case.							

Subject Handler

Assigned By

Completed On

Created On

Done?

MSME18117774 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 11/09/2018 13:19 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	^	n	2	-	ī	į	ΑΤ	-		п	٠	ī
А	u	u	u			0	ΑΙ		vi	-	м.	и

Date Of Report

11/09/2018 13:19

Date Of Accident

10/09/2018 18:15

Exact Location Of Accident

CARPARK OF TAMPINES 1

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLC4801X

Insured/Policyholder

Name Of Registered Owner

TOH TECK HWEE

NRIC No

S1567308G

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-94509736

Alternative Phone No.

OFFICE-94509736

Vehicle Particulars

Manufacturer

HYUNDAI

Model

145

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5091736467-01

Cover Note Number

Driver

Name of Driver

TOH TECK HWEE

NRIC No

S1567308G

Date Of Birth

21/11/1962

Occupation

INDOOR

Date Of Driving Pass

31/10/1983

Driving Experience

34 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-94509736

Fax Number

Contact Number

OFFICE-94509736

EMail Address

NOEMAIL

Address

BLK 416 TAMPINES ST 41 #09-337

Postcode

520416

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY PARKED INSIDE THE LOT OF TAMPINES 1 ON 10/09/2018 AT 1815HRS. WHEN I COME BACK FROM SHOPPING CENTRE, NEED TO TAKE THE CAR. I SAW A NOTE ON MY WINDSCREEN THAT VEHICLE B HAS COLLIDED ONTO MY FRONT LEFT PORTION WHEN HE REVERSING HIS CAR WHEN ENTERING HIS LOT. I ALSO SAW A NOTE OF ONE WITNESS SEE THE WHILE ACCIDENT HAPPENED. THE WITNESS SENT ME THE VIDEO FOOTAGE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH TP WORKSHOP

Was there any audio recorded?

NO

Details of Witness 1

Name

Phone Number

96222733

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLU6621R

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Senatur

Date & Time

Driver's Signature

(If driver's not the policyhalder)


Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.

HUA MERCE

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1	was	Station	ay 1	anked	7452	de :	he	104
of	Tampi	nes	1 on	10.09	2 2018	@181	5 hrs	
Wh	ien (come	bac	k fro	m sh	oppn	e ce	whe
nee	d to	take	the	Car.	- 1	san	a i	rote
DK	my ,	vindser	een	that	VLLY	ue r	3 1	as
2011	ided	outo	му	front	left	portn	n l	meh
he	VIVE	very	his	car	when	net	uny	his
lot.	l	also	Saw	a b	iote	v-P 0	ue 1	vithes
see	the	who	e a	widen	t ha	perel	1.7	'he
1 74	uess 1	ent n	ne +	the '	video	fout	als	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder (Signature)

Oriver y Signature (If dover y bot the policyholder) 119/18 + 10.55AM
Reporting Centre Personnel's Signature
Name:

NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars		die e
Owner ID Type:	Singapore NRIC	
Owner ID:	7308G	
Vehicle Details		Fire C
Vehicle No.:	SLC4801X	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	13 Sep 2018	
Vehicle Make:	HYUNDAI	
Vehicle Model:	I45 2.0 AT ABS D/AB SR	
Primary Colour:	White	_
Manufacturing Year:	2013	
Engine No.:	G4NADA235558	
Chassis No.:	KMHEC41AMEA577939	
Maximum Power Output:	119.0 kW (159 bhp)	
Open Market Value:	\$19,197.00	
Original Registration Date:	04 Jul 2013	
First Registration Date:	04 Jul 2013	
Transfer Count:	1	_
Actual ARF Paid:	\$19,197.00	
Intended PARF Repate Details		ESIST.
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	03 Jul 2023	
PARF Rebate Amount:	\$13,437.00	
Intention COE Reparte Details	Marian and Militiate and the contract of the second	4
COE Expiry Date:	03 Jul 2023	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$75,000.00	
COE Rebate Amount:	\$36,039.00	
Total Rebate Amount:	\$49,476.00	

The information contained herein is correct as at 13 Sep 2018









Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

r classifieds for parallel import cars, Toyota, Honda, Nilssan, Missubishi & BMW, There are plenty of cars for sale, from vans, trucks, and in cars, luxury cars, sports igons, ScV, MPV, hatchback, to CDE cars & GPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find 45 Singapore, used 45 Singapore. car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results

All pr and other information displayed on sigCarMart.com are gathered from sources and based on algorithms that are believed by sigCarMart.com to be reliable, but no assurance can be given. that the information is accurate, complete or current, sociarhart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

Follow sgCarMart.com











About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart, All rights reserved,

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883 Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TOH TECK HWEE

BLK 416 TAMPINES ST 41

#09-337

\$ 520416

TP MS (6)

Vehicle no

Make/Model

XMHEC41AME A \$ 777 Accident date

Date :01.10.2018

Vehicle no :SLC 4801 X

Make/Model :HYUNDAI I45

cident date :10.09.2018

\$ 520416	KWHICHIMITY	Accident date	:10.09	.2018
No DESCR	RIPTION	Qty	SERVE ST	Amount (S\$)
List Items				
1 Front bumper schould.	22	1	\$	625.5 / 508
2 Front bumper side holder @	\$42.40 LH NEW	2	\$	84.8-42.40 .
3 Front bumper LH fog lamp	NITE NEW	1	\$	205.5×.
4 Front bumper sponge AR	New	300861	\$	167.9 ×
5 Front bumper clips (1set)	en	1	\$	85 30 -
6 Front LH head lamp (A		3008 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$	2619.9 - 228
7 Front LH fender Zeric		1	\$	572 ×
8 Front LH fender inner shield		1	\$	107.8
9 Front LH fender inner shield	d clips (1set)	1	\$	75 30
			\$	4543.4
		Less 20% Disc	\$	908.68
		Total	\$	3634.72
Labour Cost				
1 Remove ,replace & repair c	onsistent to the accident	760	\$	1200 400
2 Respray painting		820	\$	1000 450 .
		Total	\$	2200
		Grand Total	\$	5834.72

LKK Auto Consultant	
the Repairer of the fo	
. To resurvey before after	it is carbed.
 To display demaged by: 	SUVEY
 Parts prices are subject 	
. Third party survey is a	Ereplante basis
. No illegal modification is	
 Supplementary item(s) in is subject to final approve 	nub or result/eyed and at from Insurance Company
Acknowledged by Repaire	
Signature:	
Date:	

Hotal: 3256.88 L/S: 2.6K 048mp

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18016753/AGTBN2

Date:

29/11/2018

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A80450966QMX

Insurer: Claimant

SLC4801X

Insured Vehicle No: SLU6621R

011100040

Vehicle No : Date of Loss:

10/09/2018

Nature of Claim:

TP

Claim No: 569971

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLC4801X

Make & Model:

HYUNDAI 145, 2.0 (A)

Engine No:

G4NADA235558

Reg. Date:

04/07/2013 (Man. Year: 2013)

Chassis No:

KMHEC41AMEA577939

Colour: Engine Capacity: White 1999 cc Odometer:

119526 km

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification: Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

225/45R18

Rear Tyre Size:

225/45R18

Front Left Side:

Vakahama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 3,634.72 0.00	Adjuster's 2,406.88 0.00	1,227.84 0.00	Diff % 33.78
Labour Paintwork Labour	2,200.00 0.00	850.00 0.00	1,350.00 0.00	61.36
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,834.72	3,256.88	2,577.84	44.18
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	5,834.72	2,600.00	3,234.72	55.44

INSPECTION

Date of Assignment:

13/09/2018

Date Inspected:

13/09/2018 Inspected At:

Hua Meng Spray Painting Workshop

(HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 29 Nov 2018)

Parts:

143

HYUNDAI I45 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC4801X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	com	men	ded	Parts
1/6	COLL	11101	ueu	I allo

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	625.50 FL	*508.90 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/s Necessary	84.80 FL	*42.40 FL
3	1		*FRONT BUMPER LH FOG LAMP *FRONT BUMPER SPONGE	Not Necessary Not Necessary	205.50 FL 167.90 FL	*- FL *- FL
5 6	1		*SET FRONT BUMPER CLIPS *FRONT LH HEAD LAMP	Necessary Cut	85.00 FL 2,619.90 FL	*30.00 FL *2,289.50 FL
7 8	1		*FRONT LH FENDER *FRONT LH FENDER INNER SHIELD	Repair Torn	572.00 FL 107.80 FL	*- FL *107.80 FL
9 F=Fra	1 anchise	part. L=ListIt	*SET FRONT LH FENDER INNER SHIELD CLIPS emDisc.	Necessary	75.00 FL	*30.00 FL
			- List Item Discount on L Items :	Sub Total (S\$) 20.00/20.00% (S\$)	4,543.40 908.68	3,008.60 601.72
				Total Parts (S\$)	3,634.72	2,406.88

Report was unsubmitted during this print-out

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	REMOVE.REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
2	RESPRAY PAINTING	New	1,000.00	450.00
	Gross Labo	ur Cost (S\$)	2,200.00	850.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >