

ASS. REC. BY:

REF: CS / C7218016755 / Grb

Special Instruction

Summary

ASSIGNMENT (Office)

တစ်ခုလုံး

From (Person): Irene Tay

of CU

Date/Time: 13092018 327pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE 1387H

Insured:

GBE 7867 U

nt Workshop m/s

All swell motor

Tet

of

25 Detu² Lane 9

Policy No:

DTM TVSN 130 30 61800

Claim No:

SNM18D 04378C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/11/2018

CA / REV / REP. / REV 24 HRS 'WJ'

14-09-2018 @ 9am

H.O.D. Endorsement

Date/Time: 13092018 3:30 pm

Person Contacted:

Ben

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SJE 1387H - X
	GBE 7827U - X

Springer

Xed.

REF:

cli

ASSIGNMENT

(-2023)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Alls well Motor
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJE1387H Yr Regn: 16 Apr 2008
 Type: M/Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Att's c.c. 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 171326 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRO53ZEE106105789
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / SD / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kapsen
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 14-09-18
 Survey held at w/s 9AM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
14/9 Finalized \$1432.65 with Ben.

Red: \$2194.45, 60%.

RECEIVED 12 OCT 2018

Date/Time. File Pass to?

☐

: Preli. Report

1) typist

☒

: Final Report

Date/Time. File Returns to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation

\$ - RS - \$

Photos

Other

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$ 1432.65)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	10 Sep 2018		13 Sep 2018 15:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	G-MES INTERNATIONAL PTE LTD, Co. Reg. No.: 201437499W								
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z								
Vehicle Reg. No.:	SJE1387H	Date of Loss:	08/09/2018 11:00 - :59						
Claim Type:	TP / SNM18D04378C02	Policy/Cover Note No.:	DMCVSN1808061800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE7867U	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]								
Adj. Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 201432541Z

Owner ID Type: Company

Owner Name: ALLSWELL LEASING & LIMOUSINE PTE LTD

Registered Address:
100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001

Mailing Address: -

Birth Date: -

Vehicle Particulars

Vehicle No.: SJE1387H

Previous Vehicle No.: -

Effective Date of Ownership: 11 Nov 2016

Original Regn Date: 16 Apr 2008

Registration Date: 16 Apr 2008

Year of Manufacture: 2008

Private Hire (Chauffeur) Motor Car

Vehicle Type:

Vehicle Scheme:

Vehicle Attachment 1:

No Attachment

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA ALTIS 1.6 AUTO

Primary Colour:

Silver

Secondary Colour:

Passenger Capacity:

4

Chassis No.:

MR053ZEE106105789

Engine No.:

3ZZ4755814

Engine Capacity / Power Rating:

1598 cc / -

Maximum Power Output:

80.0 kW (107 bhp)

Propellant:

Petrol

Max Unladen Weight:

1195 kg

Maximum Laden Weight:

1630 kg

Open Market Value:

\$16,994.00

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	1
IU Label No.:	1121969604
COE No.:	2008050101000040H
COE Expiry Date:	15 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Registration Category:	A - Car (1600cc & below)
Quota Premium (QP) / Prevailing Quota Premium:	\$16,930.00 / -
PQP Paid:	\$19,328.00
QP (Regn Cat):	\$16,930.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$16,930.00
Additional Registration Fee Rate:	100.00 %
Actual ARF Paid:	\$16,994.00
Vehicle Lifespan Expiry Date:	No Lifespan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2541Z

Vehicle Details

Vehicle No.:	SJE1387H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4755814
Chassis No.:	MR053ZEE106105789
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,994.00
Original Registration Date:	16 Apr 2008
First Registration Date:	16 Apr 2008
Transfer Count:	1
Actual ARF Paid:	\$16,994.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	15 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,328.00
COE Rebate Amount:	\$17,728.00
Total Rebate Amount:	\$17,728.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Sep 2018

OK

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

3 Days.
part by part.
Guo Qi'ap.
14/9/18

(3rd party claim against CTI insured GBE786TU)

Estimate repair

Vehicle No. : SJE 138TH
Make & Model : Toyota Altis
Chassis No. : _____
Date of survey : _____

Submitted by
COE expiry
Engine No.

LKK Auto Consultants hence notify the Repairer of the following:

• To survey before after spray painting

• To display damaged part(s) during resurvey

• Prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper / <u>OE</u>	01	\$866.10	476.2	
02	RH rear fender <u>X Repair</u>	01	\$621.0	X	* repair
03	RH Rear Lamp <u>/ CRA</u>	01	\$371.0	/	
04	RH rearview (rear) <u>- CRA</u>	01	\$47.00	/	
	<u>Special nett</u>				894.2
					25% 670.65
01	Clips for bumper (1) \$11.00 x 2 <u>/ NCL</u>	01	\$22.00	/	
	<u>Labour Description</u>				
01	Disassemble / Assembly of affected parts	01	\$260.0	260 100	
	holes				
02	Make square holes for new bumper <u>28</u>	01	\$160.0	40	
03	Spray painting on affected parts	01	\$460.0	400	
04	Panel beating of RH rear fender	01	\$260.0	100	
05	RH rear corner end <u>panel</u> panel beating	01	\$260.0	100	
				740	
			3621.1		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

1432.65

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018		13 Sep 2018 15:27 Edit Adj Rpt	S\$1,432.65 Edit Estimates	S\$1,432.65 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	G-MES INTERNATIONAL PTE LTD , Co. Reg. No.: 201437499W								
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD , Co. Reg. No.: 201432541Z								
Vehicle Reg. No.:	SJE1387H	Date of Loss:	08/09/2018 11:00 - :59 [124 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04378C02	Policy/Cover Note No.:	DMCVSN1808061800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE7867U	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/09/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJE1387H (SNM18D04378C02)
[GBE7867U]**

TP

ALLSWELL LEASING & LIMOUSINE PTE LTD

Sep 8 2018 11:00AM

[G-MES INTERNATIONAL PTE LTD]

Allswell Motor Traders

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	10/09/18 13:27	Accident Statement							Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
2	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
3	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
4	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
5	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
6	10/09/18 12:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
7	10/09/18 13:08	SCENE [Linked Accident Report Documents]							Load JPG	☒	
8	10/09/18 13:08	SCENE [Linked Accident Report Documents]							Load JPG	☒	
9	10/09/18 13:08	SCENE [Linked Accident Report Documents]							Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/09/18 21:29	General View							Load JPG	☒	
2	16/09/18 21:29	General View							Load JPG	☒	
3	16/09/18 21:29	General View							Load JPG	☒	
4	16/09/18 21:29	General View							Load JPG	☒	
5	16/09/18 21:29	General View							Load JPG	☒	
6	16/09/18 21:29	General View							Load JPG	☒	
7	16/09/18 21:29	General View							Load JPG	☒	
8	16/09/18 21:29	General View							Load JPG	☒	
9	16/09/18 21:29	General View							Load JPG	☒	
10	16/09/18 21:29	General View							Load JPG	☒	
11	16/09/18 21:29	General View							Load JPG	☒	
12	16/09/18 21:29	General View							Load JPG	☒	
13	16/09/18 21:29	General View							Load JPG	☒	
14	16/09/18 21:29	General View							Load JPG	☒	
15	16/09/18 21:29	General View							Load JPG	☒	
16	16/09/18 21:29	General View							Load JPG	☒	
17	16/09/18 21:29	General View							Load JPG	☒	
18	16/09/18 21:29	General View							Load JPG	☒	
19	16/09/18 21:29	General View							Load JPG	☒	
20	16/09/18 21:31	General View							Load JPG	☒	
21	16/09/18 21:31	Chassis Number							Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
Documentation				
			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/09/18 15:26	PRS		Load PDF
2	13/09/18 15:26	TP GIA		Load PDF
3	13/09/18 15:27	OI GIA		Load PDF
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 12:31	Sketch Plan [Linked Accident Report Documents]		Load JPG ☒
2	10/09/18 12:31	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG ☒
3	10/09/18 12:31	Sketch Plan #3 [Linked Accident Report Documents]		Load JPG ☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 13:27	Accident Statement		Load HTM
Photos/Images				
			3 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 12:31	Accident Photo		Load JPG ☒
2	10/09/18 12:31	Accident Photo		Load JPG ☒
3	10/09/18 12:31	Accident Photo		Load JPG ☒
4	10/09/18 12:31	Accident Photo		Load JPG ☒
5	10/09/18 12:31	Accident Photo		Load JPG ☒
6	10/09/18 12:31	Accident Photo		Load JPG ☒
7	10/09/18 13:06	SCENE		Load JPG ☒
8	10/09/18 13:06	SCENE		Load JPG ☒
9	10/09/18 13:06	SCENE		Load JPG ☒
Documentation				
			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 12:31	Sketch Plan		Load JPG ☒
2	10/09/18 12:31	Sketch Plan #2		Load JPG ☒
3	10/09/18 12:31	Sketch Plan #3		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016755/GRBQ2

Date: 23/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1808061800

Claimant Vehicle
No: SJE1387HInsured Vehicle
No: GBE7867U

Date of Loss: 08/09/2018

Nature of Claim: TP

Claim
No: SNM18D04378C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE1387H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4755814

Reg. Date: 16/04/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106105789

Colour: Silver

Odometer: 171326 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,927.10	692.65	1,234.45	64.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	740.00	960.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,627.10	1,432.65	2,194.45	60.50
+ GST 7.00/7.00% (S\$)	253.90	100.29	153.61	60.50
Nett Amount (S\$)	3,881.00	1,532.94	2,348.06	60.50

INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 14/09/2018

Inspected At:

Allswell Motor Traders (HQ)

25 Defu Lane 9

Singapore 539266

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE1387H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	866.10 F	*476.20 FL
2	1		*RH REAR BUMPER	Repair	621.00 F	*- FL
3	1		*RH REAR LAMP	Cracked	371.00 F	*371.00 FL
4	1		*RH RETAINER (REAR)	Cracked	47.00 F	*47.00 FL
5	2		*CLIPS FRT BUMPER	Necessary	22.00 FS	*22.00 FS
					Sub Total (S\$)	1,927.10
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	1,927.10
						692.65

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE /ASSEMBLY OF AFFECTED PARTS	New	380.00	100.00
2	MAKE SENSOR HOLES FOR NEW BUMPER	New	160.00	40.00
3	SPRAY PAINTING ON AFFECTED PARTS	New	460.00	400.00
4	PANEL BEATING OF RH REAR FENDER	New	380.00	100.00
5	RH REAR CORNER END PANEL BEATING	New	380.00	100.00
Gross Labour Cost (\$\$)			1,700.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >