

ASS. REC. BY:

REF: CS/CT118016756/Kvb02 Special Instruction:

SUNVAJOY

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTL Date/Time: 13092018 316pm

Estimated Cost: _____ Bill to: _____

OD / TD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJZ 638E Insured: 91I 5044L

at Workshop m/s Ah Lim Motor Tel: _____

of Blk 10 AMK Ind Park 2A #01-09

Policy No: DMPSCN1815191800 Claim No: SNM18D0437402

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08092018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

14092018 @ 12pm at Blk 176 Sin Ming Ave #05-12
H.O.D. Endorsement: _____

Date/Time: 13092018 327pm Person Contacted: Mei Li Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJZ 638E -x</u>
	<u>91I 5044L -x</u>
<u>29/10/18</u>	<u>@ 411pm Mui Hong said vehicle has not send in for repair, pending liability</u>
<u>21/11/18</u>	<u>@ 347pm Mui Hong said vehicle has not send in for repair, pending liability</u>

09/1/19
Singapore

REF: C7L

ASSIGNMENT

From: Date: 14092018

Veh No: S67 638 E Yr Regn: 07 / 13

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: S1Z 638 E

Make: Audi TT (A) C.C. 1984

at Workshop m/s

Ah Lim Motor

Colour: White A/C: Insured / Std / NI / NA

of Blk 176 Sun Ming Drive #05-12

Sp Reading: 24960 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: TRU 888 8 JXC 100 6200

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

12pm



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: R: 295/45R17

Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

IDAC Accident Rpt: Consistent? : Yes or No

Front Rear R/Bal. 7 mm R/Bal. 7 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 7 mm L/Bal. 7 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 8/9/18 D.O.I. 14/9/18

Lum Sum: % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
19 File pass to Catherine

3/12/18 @ 3:22pm Mei Li said vehicle has not send in for repair, pending liability
11/1/19 @ 3:37pm Mei Li said vehicle has not send in for repair, pending liability

14/1/19 Submit preli report

RECEIVED 14 JAN 2019

14/1/19 Kenneth

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 1

1)

Resurvey No. of Trip: -

Date/Time, File Return to?

2) 14/1 - typist

Add Fee: : Site Insp (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format: Merimen

Lump Sum / I.B.I: (\$)

: Weekend (\$)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2018		13 Sep 2018 15:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]																	
Insured:	MOHAMAD NAZALI BIN MOHAMAD, ID: S1821335D																		
Main Claimant:	PEK SIOK LIAN, ID: S6841401F																		
Vehicle Reg. No.:	SJZ638E	Date of Loss:	08/09/2018 21:00 - :59																
Claim Type:	TP / SNM18D04374C02	Policy/Cover Note No.:	DMPSCN1815191800 (Comprehensive)																
Vehicle Reg. No. (Insured):	SLZ5044L	Policy No. (Claimant):	GA318831																
		Excess:	\$50.00																
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244																		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]																		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288																		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]																		
Driver/Custodian (Insured):	MOHAMAD NAZALI BIN MOHAMAD (50 / Male), NRIC: S1821335D																		
Adj Asg. Remarks:	EST \$1101.98, ASSIGN KENNETH KONG AS SJE.																		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail																
There are no mail for this case.																			
<div style="border: 1px solid #ccc; padding: 5px;"> <p>ALL ASSOCIATED TASKS</p> <table border="0" style="width: 100%;"> <tr> <td style="text-align: right;">View All</td> <td style="text-align: right;">Search Tasks</td> <td style="text-align: right;">Create New Task</td> <td style="text-align: right;">Complete</td> </tr> <tr> <td style="text-align: right;">Due Date</td> <td style="text-align: right;">Priority</td> <td style="text-align: right;">Type</td> <td style="text-align: right;">Task Group</td> </tr> <tr> <td style="text-align: right;">Subject</td> <td style="text-align: right;">Handler</td> <td style="text-align: right;">Assigned By</td> <td style="text-align: right;">Completed On</td> </tr> <tr> <td style="text-align: right;">Created On</td> <td style="text-align: right;">Done?</td> <td></td> <td></td> </tr> </table> <p>No results.</p> </div>				View All	Search Tasks	Create New Task	Complete	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
View All	Search Tasks	Create New Task	Complete																
Due Date	Priority	Type	Task Group																
Subject	Handler	Assigned By	Completed On																
Created On	Done?																		

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1401F
Vehicle Details	
Vehicle No.:	SJZ638E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	TT ROADSTER 2.0 TFSI
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CES016661
Chassis No.:	TRUZZZ8JXC1006200
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$54,027.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$69,249.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2023
PARF Rebate Amount:	\$48,474.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,802.00
COE Rebate Amount:	\$37,188.00
Total Rebate Amount:	\$85,662.00

The information contained herein is correct as at 10 Sep 2018

OK



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PEK SIOK LIAN
39 NAMLY PLACE
SINGAPORE 267183

Estimate No: MCS1102533
Date: 10 Sep 2018
Policy No: GA318831
Veh Reg No: SJZ638E
Make/Model: AUDI TT

ATTN:
Your Ref No: SJZ638E
Claim Type: Third Party
Accident Date: 08/09/2018
TP Veh Reg No: SLZ5044L

Not Authorised
Murray Ate Pain

Estimate Repair Cost to Vehicle No :SJZ638E

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER REFLECTOR RH	1 PC	366.54	?
		366.54	
	Less 10%	36.65	329.89
LABOUR			
2 TO REPAIR AND REFIT REAR BUMPER	1 PC	400.00	250
3 TO SPRAY PAINT REAR BUMPER	1 PC	300.00	220
		700.00	700.00
Total			SS 1,029.89
Add GST @ 7%			72.09
Total Amount Payable			SS 1,101.98

TOTAL: SINGAPORE DOLLAR ONE THOUSAND ONE HUNDRED AND ONE AND CENTS NINETY EIGHT ONLY

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016756/KVBN2
Date: 14/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPSCN1815191800
Claimant Vehicle No :	SJZ638E	Insured Vehicle No :	SLZ5044L
Date of Loss:	08/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04374C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ638E	Engine No:	CES016661
Make & Model:	AUDI TT, 2.0 TFSI Roadster (8J) (A)	Chassis No:	TRUZZZ8JXC1006200
Reg. Date:	31/07/2013 (Man. Year: 2011)	Odometer:	24960 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	329.89	0.00	329.89	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	470.00	230.00	32.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,029.89	470.00	559.89	54.36
+ GST 7.00/7.00% (S\$)	72.09	32.90	39.19	54.36
Nett Amount (S\$)	1,101.98	502.90	599.08	54.36

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	14/09/2018 Inspected At:	Bik 176 Sln Ming Drive #05-12 Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIR.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$329.89 NETT)

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 14 Jan 2019)
Parts:	N/A AUDI TT 2.0 TFSI Roadster (8J) (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ638E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REFLECTOR RH	*Check	366.54 FL	*- FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (\$\$)	366.54	0.00
				- List Item Discount on L Items 10.00/10.00% (\$\$)	36.65	0.00
				Total Parts (\$\$)	329.89	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR AND REFIT REAR BUMPER	New	400.00	250.00
2	TO SPRAY PAINT REAR BUMPER	New	300.00	220.00
Gross Labour Cost (S\$)			700.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >