
CS/TP18016783/Agbnz
ASSIGNMENT REF:

From: Date:	Veh No: SLH 2026D Yr Regn: 2011 /NOV
Estimated Cost:	Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Volkswager Fetter c.c 1380 Colour Red A/C: Insured/Std/NI/NA
at Workshop m/s	Colour Red A/G: Insured / Std / NI / NA
pl	Sp.Reading   12252 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: WYWZZZI6ZBMIIIZ30
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /8/Rim / STD A/Rim or
	Tyre Size: F: 235(40 Rts
(Policy Condition)	Tyre Size: F: 235/40R18
Remark: The veh had commenced its N/S O/S	7
repair at the time of inspection.	TOYOTYOKO OF FIRMS.
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 66 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. Oh mm L/Bal. Ob, mm
Est Repairs: 3 days Res.: Yes or No	D.O.A. D.O.I. 13/09/18 .
Lum Sum: % 3 Val.: Yes or No	Survey held at Modern .
CA / REV / REP. / 24 HRS	Des. of Damages Fro I Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/O	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	- C.K.
TP SCDF Independent.	
mv: HOK-	
PV:33.2K Nett: 6.8K RECEIVED	E 007 2010
Nett: 6.81C RECEIVED	g & UCT 2010
1 12000 2 Jan 1000	1 40 20 × 10 ×31/2
15 \$ 2700, 3 days (Red	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
105/10 MNIN : Final Report	Resurvey No. of Trip: Survey Fee: 140
Date/Time, File Return to?	Transportation: 50
2) Add F	ee: Site Insp (# ) S+RS_SI
70	Interview (\$ ) Photos 5)
Report Format:	: Tech, Invs (4)
Lump Sum / LDCI: (\$ 2700)	: Weekend (\$ )
	TOTAL 371





Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

Price ▼ Depreciation ▼

one car classifieds for penalliel import cars, Toyota, Honda, Nissan, Mitsubishi B. BMW. There are plenty of cars for sale, from vens, trucks, sedan cars, luxury cars, sports some SLW, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, lock up car loans, low mileage cars, car brands, carpark rates & car insurance. Find Support, used Jetta Singapore, used setta, used vehicles Singapore or even buy used Jetta Singapore. We have new car dealers comprising parallel importers, authorised COPS OF SUIT buy inted in cur desiers on our site. Find new car price lists, new car bunches and new car promotions. Visit our partner sites for Job openings for Singapore Jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing 8, COE results.

All prices are all information displayed on against coming gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given his information is accurate, complete or current, spCarMart.com does not assume any responsibility for errors or o s or warrant the accuracy of this information

Follow sgCarMart.com

▼ Model











« Back (12) Next »



Veh Type ▼

20 ▼ results/page

Rieg Date ▼ 🚉 Eng Cap ▼ 📦 Mileage ▼ 🥞

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

For old advertisements, view Expired ads

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	35721	
Wehicle Details	Appendix of the property of th	C 1974 W. C. S. C.
Vehicle No.:	SLH2026D	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	13 Sep 2018	
Vehicle Make:	VOLKSWAGEN	
Vehicle Model:	JETTA 1.4 TSI AT 1623Q5	
Primary Colour:	Red	
Manufacturing Year:	2011	
Engine No.;	CAV302855	
Chassis No.:	WVWZZZ16ZBM111230	
Maximum Power Output:	118.0 kW (158 bhp)	
Open Market Value:	\$24,015.00	
Original Registration Date:	03 Nov 2011	
First Registration Date:	03 Nov 2011	
Transfer Count:	1	
Actual ARF Paid:	\$24,015.00	
Intended PARE Rebate Details	100 SEPTEMBER 1995 1996 1995 1996 1996 1996 1996 1996	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	02 Nov 2021	
PARF Rebate Amount:	\$15,609.00	
Intended COE Robate Details	。 第16章:"我们是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就	HONOR MANAGEMENT
COE Expiry Date:	02 Nov 2021	
COE Category:	A - Car (1600cc & below)	
COE Period(Years);	10	
QP Paid:	\$56,112.00	
COE Rebate Amount:	\$17,603.00	
Total Rebate Amount:	\$33,212.00	

The information contained herein is correct as at 13 Sep 2018

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available atoresaid.

### ACCIDENT STATEMENT

Date Of Report

10/09/2018 13:29

Date Of Accident

08/09/2018 22:00

Exact Location Of Accident

BLK 151 SIMEI STREET 1 OSCP

SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLH2026D

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

FAWZIAH BINTE MAHMOOD

NRIC No.

S1583572I

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-90105234

Alternative Phone No

OTHERS-90105234

Vehicle Particulars

Manufacturer

VOLKSWAGEN

Model

**JETTA** 

Exact Purpose for which vehicle was being used at

time of accident

LEISURE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5087024614-01

Cover Note Number

DRIVO CLASSIC

Driver

Name of Driver

FAWZIAH BINTE MAHMOOD

NRIC No Date Of Birth

S1583572I 08/10/1963

Occupation

INDOOR

Date Of Driving Pass

**Driving Experience** 

06/10/1985

32 YEARS AND 11 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-90105234

Fax Number

Contact Number

OTHERS-90105234

**EMail Address** 

NOEMAIL

Address

BLK 153 #03-49 SIMEI STREET 1

Postcode

520153

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident Was any body injured in the Accident? 2 NO

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

1000

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

CHANGI N.P.C

POAD: 9 SIME

Police Station Address

ROAD: 9 SIMEI STREET 2, POSTCODE: 529914, COUNTRY:

SINGAPORE

Was notice of intended Prosecution given?

TEL NO: - FAX NO:

If Yes, against whom?

Police Station Contact

NO

Circumstances of Accident

Refer to police report

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

QX1235E

Vehicle Make/Model/Colour

Details Of Properties

GOVERNMENT

Vehicle Category

CO RICHARD BRYAN ANG

Name of Driver NRIC/Passport Number

S8975630H

Contact Number

96230452

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 18

#### Sketch Plan Pg. 1

INCOME MOTOR SURVICE CENTRE

Report No. 311

DELA: 08-09-2018 lune 22:00 hrs

10-09-2018 15:21 Report Date & Start Time Vehicle No SLH2026D Reporting Paper

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

10-09-18 / 13:21

10-09-18 / 13:21


Alan Tang (\$098825) Customer Care Executive Motor Service Centre

Wilnessed by Reporting Centre Peron

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

# Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
Refer to police report	

#### Declaration

I/We declare the foregoing particulars are true in every respect.

, 10-09-18 / 13:21 Policyholder's Signature / Date & Time

10-09-18 / 13:21

Alan Tang (S098825) Customer Care Executive Motor Service Centre

Ky

Driver's Signature (If driver is not the policyholder) / Date & Time Wilnessed

Witnessed by Reporting Centre Personnel





1 of 3

Police Station Of Origin Changi N.P.C 9 Simei Street 2 SINGAPORE 529914 Tel No. 1800-5872999

Report No. T/20180909/2029

REPORT OF	A TRAFFIC	ACCIDENT		Station Diary No.	
Date/Time Report Made 09/09/2018 12.44			Vide Report No.	18	
Informan	t's Partice	ulars			
Name of I		AHMOOD	Address: APT BLK 153 SIMEI STREET	1 #03-49 SINGAPORE 520153	
ID Type / ID No.: NRIC NO / S1583572I			Contact No.: Home/Office: Mobile: 90105234		
Nationality: SINGAPORE CITIZEN			Email:		
Sex:         Age:         Date of Birth:           Female         54         08/10/1963			Type of Informant: Driver		
Race: Malay			Language: English	Institution / School Name:	
Occupation: SECRETARY			Driving Licence Information: Class: 3 Date of Expiry:		

Seneral Infor	mation of the Accident			T Claration	
Type of Accident	ype of Non-Injury  Government Vehicle		Date/Time of Accident: 08/09/2018 22:00	Type of Locatio Car Park	
Location: Along Road 1 SIMEI STREI		OPEN SPACE CA	ARPARK AREA		
Weather: Ro		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume:	
Type of Collis Between Mor	sion: ving Vehicles - Head To Re	ar	a	nyone conveyed by mbulance: lo	

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX1235E	AMBULANCE	A CONTRACTOR OF THE PARTY OF TH	SPRINTER	White		4
SLH2026D	Car	VOLKSWAGO N	JETTA 1.4 TSI AT 1623Q5	Red	Slightly Damaged	0

	ehicle Insurance	Insurance No	Effective	Expiry Date
A SELLINGTON LAND			00/40/0047	22/12/2018
SLH2026D	NTUC Income Insurance Co-Operative Limited	5087024614-01	23/12/2017	22/12/2016

## Police Report Pg. 2



Police Station Of Origin Changi N.P.C 9 Simei Street 2 SINGAPORE 529914 Tel No. 1800-5872999

Report No. T/20180909/2029.

CONTINUATION OF REPORT

and the second of					
Any Pedestrian In	Volved, NO	Use of Pedes	strian	Cross	ing: NA
No. of Pedestrian	s Injured. NIL	1000011			
Driver	SO DIGUADO DOVAN ANO	11	O No.		S8975630H
Name	CO RICHARD BRYAN ANG		TO THOS		2000 2000 COMMISSION - 4000
	AVVIOLET MARRIE ANCEN	0	Contac	t No.	96230452
Related Vehicle	QX1235E (AMBULANCE)		,01110	9.13.53	
		- 0	class	of	Class: NIL
Hospital/Clinic	NIL	1000	Driving		Date of Expiry: NIL
			icenc	50 0000 88	
		E	Expiry	Date	
	Kill Comments	Date Discha		NIL	
Date Treatment	NIL ted Medical Leave NIL	Degree of In		NIL	
	ted Medical Leave NIL	Degree or in	10.7		
Driver	THE MALINOOD		D No.		S1583572I
Name	FAWZIAH BINTE MAHMOOD		D 140		
	01 110000D (C)		Conta	ct No.	90105234
Related Vehicle	SLH2026D (Car)		* 500000		
	X10	(	Class	of	Class: 3
Hospital/Clinic	NIL		Driving Licence &		Date of Expiry: NIL
	1	1.0	T1110000000000000000000000000000000000	Date	
	NIL	Date Discha		NIL	
Date Treatment					

On the above mentioned date and time, I was on the way home at the aforesaid location when I saw an ambulance stationary in front of me, therefore I stopped behind the ambulance. Suddenly, the ambulance reversed a bit and I did not move my vehicle as I thought it was just a slight reverse. However, the ambulance suddenly reverse further and I did not have the time to react, I did horned at the ambulance but to no avail. As such, the ambulance rear knocked onto my car's front portion, resulting in an impact causing my number plate to drop off, and the front bumper area parts dropped as well, together with some scratches and dent marks. We then came down from our vehicles and the ambulance driver told me that he reversed as he went to the wrong block. We exchanged particulars as well and I took a few pictures of the car's damage and scene in my mobile phone. We then left the scene. No one was injured at that point of time. I wish to state that the ambulance blinkers was on at that point of time and the road we are travelling on was a one lane road, and the area was not so well-lit. The paramedics also handed me a 'Notice of accident involving SCDF vehicles' form and advised me to lodge a Police report asap as well.





3 of 3

Report No. T/20180909/2029

Police Station Of Origin Changi N P C 9 Simei Street 2 SINGAPORE 529914 Tel No. 1800-5872999

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  G / Sgt 2 LIONEL NEO SOON JIE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/09/2018 12:44
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168 SIGNATUR	RE.

# MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 67484422 / 67454422 Fax: 6747- 6720 REG NO 200501102H

			350 000000	
Acciden	t Claims Officer		Quotatio	
Transpo	ort Services Branch, Logistics Department	DATE	. 11.09.2	
HO Sinc	gapore Civil Defence Force	VEH NO		
91 Ubi /		MODEL		agen Jetta
	ore 408827 Yes Chr.	DOA	: 08.09.2	
Singapa	01E 40002.	YR REF	: QX123	5E
Tol	6848 3613			
Tel:	6848 3644			
Fax:				
RE:	ESTIMATE FOR ACCIDENT REPAIR SLH2	026D (VOLKSWAC	EN JETTA	l'
	Description	City		Ant
Item	<u>Gessimber</u>			
NO	LIST ITEMS			
		1		93.00 /
1	Front Number Plate Garnish Defaul	1		998:00
2	Front Bumper H	1 set		30.00
3	Front Bumper Clips	2		90.00
4	Front Bumper Side Holder - LH & RH	7		275.00
5	Front Bumper Lower Grille Deland	w 2		530.00 ×
6	Front Bumper Fog Lamp - LH & RH	LH MASSIM 2		174.00 87
7	Front Bumper Fog Lamp Cover - LH & RH	0 2		670.00
8	Front Bumper Reinforcement 344	2.5		84.00 *
9	Front Bumper Sponge - LH & RH NH NH		1000	89.00
10	Front Bumper Top Beam Dond	1	2388	583.00
11	Front Grille W	1.0	2683.59	95.00
12	Front Grille Logo PW	1		1,532.00
13		1 H could		96.00 48
14	Headlamp - LH & RH Air Con Condenser Side Guide - LH & RH	LH could 2		5,339.00
				(533.90)
	Le	ss 10%		4,805.10
			\$	4,605.10
	S/NETT ITEMS			
	Front Number Plate Sext	60 1		30.00
1	Front Number Plate Holder	1		30.00
2	LIQUIT MULLIDEL LIQUE LIQUES			- 14 Ja-29-
	To	otal Parts	\$	4,865,10
	LABOUR CHARGE			
1	To knocking & pull out front portion & rener	w above parts	\$	400.00 300

 RE:
 ESTIMATE FOR ACCIDENT REPAIR SLH2026D (VOLKSWAGEN JETTA)

 2
 To putty & spray up paint works
 \$ 409.00 × 50

 3
 To check wiring
 \$ 50.00 30

 Total Labour
 \$ 850.00

 Grand Total
 \$ 5,715.10

GST will be reflected in the final bills.

580

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

totul: 3325.20 1/3: 2650 2700 03. Days

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	tionale Des Experts En Auton	nobile
MOI	DERN AUTOMOTI	VE PTE LTD	Ref : CS/TP1801678	3/Aqbn2
4087	717	1 #01-61 SINGAPORE	Date: 09-10-2018 Code: TP177	
1.		Policy Particula	rs :- THIRD PARTY CLAI	IM
	Insured Veh.		Veh. Inspected	SLH 2026D
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	13/09/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	VOLKSWAGEN JETTA	c.c	1390
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WVWZZZ16ZBM111230	Colour	RED
	Odometer	112252	Steering	IN ORDER
F	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Conc	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	235/40 R18	FIRENZA	6 mm
	L/H Front Tyre	235/40 R18	FIRENZA	6 mm
	R/H Rear Tyre	235/40 R18	FIRENZA	6 mm
	L/H Rear Tyre	235/40 R18	FIRENZA	6 mm
4.		Descrip	otion of Damages	
		STAINED DAMAGES AT THE	FRONT PORTION.	
_	DAMAGES SEE D	ATALASTIC SECTION AND AND AND AND AND AND AND AND AND AN		
5.	Applied Deta	08/09/2018	eral Information	13/09/2018
	Accident Date	MODERN AUTOMOTIVE PT	Inspection Date	13/03/2010
	Survey held at		LLID	
		BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"VICE TO YOUR INSTRUCTIONS	VITHOUT PREJUDICE" BAS , WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.		Estima	te Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	ys



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2026D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT NUMBER PLATE GARNISH	DEFORMED	93.00	93.00
1	FRONT BUMPER	DEFORMED	998.00	998.00
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
2	FRONT BUMPER SIDE HOLDER-LH & RH	NECESSARY	90.00	90.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	275.00	275.00
2	FRONT BUMPER FOG LAMP-LH & RH	NOT NECESSARY	530.00	100
2	FRONT BUMPER FOG LAMP COVER-LH & RH	N/S MISSING	174.00	87.00
1	FRONT BUMPER REINFORCEMENT	BENT	670.00	670.00
2	FRONT BUMPER SPONGE-LH & RH	NOT NECESSARY	84.00	
1	FRONT BUMPER TOP BEAM	DAMAGED	89.00	89.00
1	FRONT GRILLE	CUT	583.00	583.00
1	FRONT GRILLE LOGO	NECESSARY	95.00	95.00
2	HEADLAMP-LH & RH	NOT NECESSARY	1,532.00	
2	AIR CON CONDENSER SIDE GUIDE-LH & RH	N/S CRACKED	96.00	48.00
	LESS 10% DISCOUNT		-533.90	-305.80
			4,805.10	2,752.20
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
	8 5		60.00	60.00
	LABOUR			
	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS.		400.00	300.00
	TO PUTTY & SPRAY UP PAINT WORKS.		400.00	250.00
	TO CHECK WIRING.		50.00	30.00
	pervisional description of 180 days of 190 days and		850.00	580.00
	GRAND TOTAL	2	5,715.10	3,392.20

RECOMMENDED COST OF LUMP SUM REPAIRS	2,700.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP18016783/Aqbn2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.