

ASS. REC. BY:

REF:

CS/CT13016808/Krb n2

Special Instruction:

Surveyor  
Mummen

Kenneth

## ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CT

Date/Time:

14/09/2018 9:29am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

96T 877Z

Insured:

G8D 54686

at Workshop m/s

Car Times

Tel:

6471 511

of

160 Sin Ming Dm #02-04

Policy No:

DMCVSN3036161800

Claim No:

SNM18D0440302

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

14/09/2018 9:51am

Person Contacted:

Angela

Vehicle: ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

96T 877Z - X

G8D 54686 - NA/DMC15019686/h4

DCA 18/11/15

8/11 11pm @ 34000 email Carfun  
(Red. \$ 7736.00, 69%.)

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGT 8772

Yr Regn:

12, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1.896

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

18019

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU3

1248227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/9/18

D.O.A.

14/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19 File pass to Catherine

RECEIVED 9 NOV 2018

Date/Time, File Pass to?



: Prell. Report



: Final Report

1) typist

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - P.S. SI

FAXIOS

Others

TOTAL

110

Report Format :

Lump Sum / H.B. (\$

3400.00

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018		14 Sep 2018 09:29 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SHENTON CAKE SHOP, Co. Reg. No.: 52823163D								
Main Claimant:	JIA JIE SERVICES PTE LTD, Co. Reg. No.: 201227311H								
Vehicle Reg. No.:	SGT877Z	Date of Loss:	11/09/2018 11:00 - :59						
Claim Type:	TP / SNM18D04403C02	Policy/Cover Note No.:	DMCVSN3036161800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBD5468G	Policy No. (Claimant):	C0078095						
		Excess:	S\$0.00						
Repairer:	Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity, 575722 Sin Ming - Tel: 6471 5111								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]								
Driver/Custodian (Insured):	CHAN CHOON LENG (60 / Male), NRIC: S1259792D, Tel: +6598433918								
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7311H
<b>Vehicle Details</b>	
Vehicle No.:	SGT877Z
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	LEB5948243
Chassis No.:	RU31248227
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,107.00
Original Registration Date:	06 Dec 2017
First Registration Date:	06 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$57,000.00
COE Rebate Amount:	\$52,120.00
<b>Total Rebate Amount:</b>	<b>\$55,870.00</b>

The information contained herein is correct as at 13 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/09/2018 09:17
Date Of Accident	11/09/2018 11:45
Exact Location Of Accident	OPEN CARPARK BLK.214 SERANGOON AVE 4(LOT NO.529)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGT877Z
Insured/Policyholder	
Name Of Registered Owner	JIA JIE SERVICES PTE LTD
Co Reg No	201227311H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92268123
Alternative Phone No	OFFICE-92268123
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 X HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	C0078095
Driver	
Name of Driver	ONG XIANG YUAN,JOHN(WANG XIANGYUAN)
NRIC No	S8829837C
Date Of Birth	19/07/1988
Occupation	INDOOR
Date Of Driving Pass	20/09/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92268123
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK.211 SERANGOON AVE 4,#07-18
Postcode	550211
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD5468G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims [including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages]; and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN

Bldg. 214 Serangoon Ave 4



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I went home at 11:30am and parked my car behind block 214  
 On 11/Sept/2018 at Lot 529. At 1:16pm I <sup>went</sup> to my car and  
 saw a note left there claiming that he had bumped my car and left  
 contact details. I called him and he claimed that his dad accidentally  
 bump hit my car and we both agree to also report to the  
 insurance

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:



Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



# CARTIMES

autolution

Not Authorized  
1-B7  
Resurvey B4 print

Kenneth  
HP: 96910663

4 days

61 Sm 83400.

VEHICLE NO:SGT 877 Z

MODEL:HONDA VEZEL HYBRID

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>			
1	FRONT BUMPER	mgm 820.00	✓
1	FRONT BUMPER LOWER GARNISH	sm 465.00	X
2	FRONT BUMPER SIDE RETAINER	sm 135.00	X
1	FRONT REINFORCEMENT BAR	n 345.00	X
2	FRONT RHS & LHS HEADLAMP	n/s mgm 3570.00	2T 1785
2	FRONT HEADLAMP BRACKET	sm 80.00	X
2	FRONT RH SIDE RETAINER	sm 80.00	X
1	FRONT BONNET	B 685.00	✓
1	FRONT BONNET LOCK	n 185.00	X
1	FRONT BONNET INSULATOR	sm 165.00	X
2	FRONT BONNET HINGES	n 125.00	X
1	FRONT GRILLE	cm 425.00	✓
1	FRONT GRILLE OUTER CHROME	cm 85.00	✓
1	FRONT GRILLE LENS	cm 295.00	✓
1	FRONT LOWER GRILLE	sm 135.00	X
1	FRONT TOW COVER	sm 45.00	X
1	FRONT SUPPORT PANEL	n 525.00	X
1	RADIATOR TOP GARNISH	sm 75.00	X
1	RADIATOR	sm 1145.00	X
1	CONDENSER	sm 650.00	X
2	FRONT BUMPER AIRDUCT RH & LH	sm 100.00	X
2	FRONT RH & LH BUMPER BEAM	n 190.00	X
1	"H" logo	me 45.00	✓
		10370.00	
		20% 2074.00	
		8293.00	
<b>SPECIAL NETT ITEMS</b>			
1 set	FRONT BUMPER CLIPS	me 60.00	50 ✓
1 set	INSULATOR CLIPS	me 40.00	X
1	FRONT NUMBER PLATE W/HOLDER	sm 45.00	X
1 set	FRONT SENSOR	sm 280.00	X
1 set	FRONT NUMBER PLATE W/HOLDER	sm 45.00	X
<b>TOTAL PARTS</b>		<b>8766.00</b>	

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# CARTIMES

autolution

VEHICLE NO:SGT 877 Z

MODEL:HONDA VEZEL HYBRID

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00 400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	700.00 440	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	150.00 20	
4	Remove & replace condenser & topup gas	~ 120.00 X	
5	Remove & replace radiator & topup gas	~ 100.00 X	
6	To remove & replace front sensor & check for proper function	120.00 50	
7	To provide anti-rust treatment on affected areas	180.00 30	
	Labour Total :	2370.00	
	<b>TOTAL (PARTS &amp; LABOUR):</b>	<b>11136.00</b>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016808/KRBN2

Date: 13/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3036161800
Claimant Vehicle No :	SGT877Z	Insured Vehicle No :	GBD5468G
Date of Loss:	11/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04403C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGT877Z	Engine No:	LEB5948243
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Chassis No:	RU31248227
Reg. Date:	06/12/2017 (Man. Year: 2017)	Odometer:	18014 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,766.00	3,362.00	5,404.00	61.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	940.00	1,430.00	60.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,136.00</b>	<b>4,302.00</b>	<b>6,834.00</b>	<b>61.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,136.00</b>	<b>3,400.00</b>	<b>7,736.00</b>	<b>69.47</b>

## INSPECTION

Date of Assignment:	14/09/2018	
Date Inspected:	14/09/2018	Inspected At:
		Car Times Autolution Pte Ltd (HQ)
		160 Sin Ming Drive #02-04, AutoCity
		Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGT877Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	820.00 FL	*820.00 FL
2	1		*FRONT BUMPER lower garnish	Serviceable	465.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Serviceable	135.00 FL	*- FL
4	1		*FRONT REINFORCEMENT BAR	Repair	345.00 FL	*- FL
5	1		*FRONT RHS & LHS HEADLAMP	Ns Mtg Cracked/Os Serviceable	3,570.00 FL	*1,785.00 FL
6	2		*FRONT HEADLAMP BRACKET	Serviceable	80.00 FL	*- FL
7	2		*FRONT RH SIDE RETAINER	Serviceable	80.00 FL	*- FL
8	1		*FRONT BONNET	Bent	685.00 FL	*685.00 FL
9	1		*FRONT BONNET LOCK	Repair	185.00 FL	*- FL
10	1		*FRONT BONNET INSULATOR	Serviceable	165.00 FL	*- FL
11	2		*FRONT BONNET HINGES	Repair	125.00 FL	*- FL
12	1		*FRONT GRILLE	Cracked	425.00 FL	*425.00 FL
13	1		*FRONT GRILLE OUTER CHROME	Cracked	85.00 FL	*85.00 FL
14	1		*FRONT GRILLE LENS	Cracked	295.00 FL	*295.00 FL
15	1		*FRONT LOWER GRILLE	Serviceable	135.00 FL	*- FL
16	1		*FRONT TOW COVER	Serviceable	45.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Repair	525.00 FL	*- FL
18	1		*RADIATOR TOP GARNISH	Serviceable	75.00 FL	*- FL
19	1		*RADIATOR	Serviceable	1,145.00 FL	*- FL
20	1		*CONDENSER	Serviceable	650.00 FL	*- FL
21	2		*FRONT BUMPER AIRDUCT RH & LH	Serviceable	100.00 FL	*- FL
22	2		*FRONT RH & LH BUMPER BEAM	Repair	190.00 FL	*- FL
23	1		*H LOGO	Necessary	45.00 FL	*45.00 FL
24	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
25	1		*SET INSULATOR CLIPS	Not Necessary	40.00 FS	*- FS
26	1		*FRONT NUMBER PLATE W/HOLDER	Serviceable	45.00 FS	*- FS
27	1		*SET FRONT SENSOR	Serviceable	280.00 FS	*- FS
28	1		*SET FRONT NUMBER PLATE W/HOLDER	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,840.00</b>	<b>4,190.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,074.00</b>	<b>828.00</b>
<b>Total Parts (\$\$)</b>	<b>8,766.00</b>	<b>3,362.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,000.00	400.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	700.00	440.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	150.00	20.00
4	REMOVE & REPLACE CONDENSER & TOPUP GAS	New	120.00	-
5	REMOVE & REPLACE RADIATOR & TOPUP GAS	New	100.00	-
6	TO REMOVE & REPLACE FRONT SENSOR & CHECK FOR PROPER FUNCTION	New	120.00	50.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,370.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >