

22/03/2002

ASS. REC. BY:

REF:

CS3/CTU8016812/Gerber

Special Instruction:

Surveyor

GID

ASSIGNMENT (Office)

Mentmen

From (Person):

Chong Boon Sen

of

CTL

Date/Time:

14092018 1:04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 7000Z

Insured:

GBD 1864Y

at Workshop m/s

Allan's Workshop.

Tel:

9344 1674

of

21 Defu Lane 3

Policy No:

DMCVSN 3064481701

Claim No:

SNM18D03050C02.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 1wp

H.O.D. Endorsement:

Date/Time:

14092018 1:18pm

Person Contacted:

Allan

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	YP 7000Z - x
	GBD 1864Y. NA / CTL 7000402 / Y
	DLA = D4012017

Surveyor

X612.

ASSIGNMENT

From: Date: 14/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

YP 7000Z

at Workshop m/s

Allan's Workshop

of

21 Dehu Lane 3

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9344 1627 - Allan

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 7000Z

Yr Regn:

Oct / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Fuso Canter

c.c

2998

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

—

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FEB 21 EA 20674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/85R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5/5

mm

L/Bal.

5

mm

L/Bal.

5/5

mm

D.O.A.

D.O.I.

14-09-18

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 2000 - \$ 3000

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

—

Survey Fee:

150

Transportation:

— S + RS. — SI

Photos

Others

TOTAL

150

Report Format :

PRB.

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2018		14 Sep 2018 13:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	HOLIAN SANITARY & PLUMBING PTE LTD, Co. Reg. No.: -			
Main Claimant:	VITE LOGISTICS PTE. LTD., Co. Reg. No.: 200720354K			
Vehicle Reg. No.:	YP7000Z	Date of Loss:	18/06/2018 08:00 - :59	
Claim Type:	TP / SNM18D03050C02	Policy/Cover Note No.:	DMCVSN3064481701 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBD1864Y	Policy No. (Claimant):	5094675372	
		Excess:	S\$0.00	
Repairer:	Allan's Workshop (HQ) NO 21 DEFU LANE 3, DEFU INDUSTRIAL ESTATE, 539446 Defu Lane - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]			
Driver/Custodian (Insured):	TEH YU SIN (61 / Male), NRIC: S2530268J, Tel: +6596635472			
Adj Asg. Remarks:	NO EST, CASE W/O SJE.			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All Search Tasks Create New Task Complete</div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> </div>				
No results.				

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	YP7000Z		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	CANTER FEB21ER3SDEB		
Chassis No. :	FEB21EA20674		
Propellant :	Diesel		
Engine No. :	4P10C24829		
Engine Capacity :	2998 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	5000 kg		
Unladen Weight :	2400 kg		
Year Of Manufacture :	2016		
Original Registration Date :	17 Oct 2016		
Lifespan Expiry Date :	16 Oct 2036		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$4,897.00		
COE Expiry Date :	16 Oct 2026		
Road Tax Expiry Date :	16 Oct 2018		
Inspection Due Date :	16 Oct 2018		
Intended Transfer Date :	17 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 16 Oct 2018. You may renew the road tax from 17 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 16 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 17 Oct 2018 to 16 Apr 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Amount Payable (From 17 Oct 2018 to 16 Oct 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0354K
Vehicle Details	
Vehicle No.:	YP7000Z
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C24829
Chassis No.:	FEB21EA20674
Maximum Power Output:	-
Open Market Value:	\$32,464.00
Original Registration Date:	17 Oct 2016
First Registration Date:	17 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$1,624.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,897.00
COE Rebate Amount:	\$3,956.00
Total Rebate Amount:	\$3,956.00

The information contained herein is correct as at 17 Sep 2018

OK

MJAS18078686 / Jin Auto Services Pte Ltd - Defu
 ENTRY DATE & TIME: 19/06/2018 09:22
 SUBMITTED BY: Soh Wah Jin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2018 09:22
Date Of Accident	18/06/2018 08:00
Exact Location Of Accident	EUNOS LINK JUNCTION TOWARDS KPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7000Z
Insured/Policyholder	
Name Of Registered Owner	VITE LOGISTICS PTE. LTD.
Co Reg No	200720354K
Email Address	JEFRI-VITE@MAIL.COM
Mobile Phone No	
Alternative Phone No	Office-98892911

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094675372
Cover Note Number	

Driver

Name of Driver	HAMZAH BIN OMAR
NRIC No	S1711996F
Date Of Birth	15/11/1964
Occupation	OUTDOOR
Date Of Driving Pass	13/08/2002
Driving Experience	15 YEARS AND 10 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-98140412
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLOCK 405 HOUGANG AVENUE 10 #04-1138
Postcode	530405
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

LORRY, YP7000Z WAS DRIVEN BY HAMZAH BIN OMAR, S1711996F WAS GOING STRAIGHT AT THE EUNOS LINK JUNCTION TOWARDS KPE TO TPE/SLE. GREEN LIGHT WAS IN FAVOUR OF HIM. ON THE OPPOSITE LANE, LORRY, GBD1864Y DRIVEN BY TEH YU SIN, S2530268J WAS TURNING RIGHT TOWARDS DEFU LANE LANE WITH ALSO GREEN LIGHT FOR THE TRAFFIC. WHEN YP7000Z HAVE ALREADY PASSED THE CENTER JUNCTION, GBD1864Y MADE A RIGHT TURN ON THE OPPOSITE LANE WITH THE GREEN LIGHT ON BUT WITHOUT THE RIGHT TURN ARROW ON. AS A RESULT, GBD1864Y COLLIDED WITH YP7000Z IN THE MIDDLE OF THE JUNCTION BOX. YP7000Z WAS GOING STRAIGHT WITH GREEN LIGHT ON HIS FAVOUR. THIS HAPPENED ON 18/06/2018 AT APPROXIMATELY 0800HRS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

9/17/2018

E-FILE

Vehicle Registration Number	GBD1864Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TEH YU SIN
NRIC/Passport Number	S2530268J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

BK 13, Sector B, Sin Ming Industrial Estate, #01-27 / 29 Singapore 575657
Telephone: 64532797, 64531517 Fax: 64534948
Business Reg. No.: 310910/00E

AH KENG MOTOR REPAIRER

亞欽摩哆廠




Accident Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

18-06-2018 2.40pm




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LOGISTICS FIELD
REG. NO. 2007042700
NIP

REPORTING CENTRE PERSONNEL
REG. NO. 2007042700
NIP

Accident Sketch Plan

SKETCH PLAN


Sketch Plan attach

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach statement.

Policyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time:Reporting Company's Signature
Name:
NRIC/Pass No.:


Sketch



Statement

LORRY YP7000Z DRIVEN BY HAMZAH BIN OMAR, S1711996F
WAS GOING STRAIGHT AT THE GUNOS LINK JUNCTION TOWARDS RPE
TO THE SLE. GREEN LIGHT WAS IN FAVOR FOR HIM. ON THE OPPOSITE
LANE, LORRY GBD 1864Y DRIVEN BY TEH YU SIN, S2530268J
WAS TURNING RIGHT TOWARDS DEFO LANE WITH ALSO GREEN
LIGHT FOR THE TRAFFIC.

WHEN LORRY YP7000Z HAVE ALREADY PASS THE CENTER JUNCTION,
LORRY GBD 1864Y MADE A RIGHT TURN ON THE OPPOSITE LANE
WITH THE GREEN LIGHT ON BUT WITHOUT THE RIGHT TURN ARROW
ON. GBD 1864Y COLLIDED WITH YP7000Z IN THE MIDDLE
OF THE JUNCTION BOX. YP7000Z WAS GOING STRAIGHT WITH
GREEN LIGHT ON HIS FAVOR. THIS HAPPENED ON 18/2/18 AT
APPROX 0800 HRS.



Identification Card































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 13:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HOLIAN SANITARY & PLUMBING PTE LTD , Co. Reg. No.: -									
Main Claimant: VITE LOGISTICS PTE. LTD. , Co. Reg. No.: 200720354K									
Vehicle Reg. No.: YP7000Z		Date of Loss: 18/06/2018 08:00 - :59 [20 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03050C02		Policy/Cover Note No.: DMCVSN3064481701 (Comprehensive)							
Vehicle Reg. No. (Insured): GBD1864Y		Policy No. (Claimant): 5094675372							
		Excess: S\$0.00							
Repairer: Allan's Workshop (HQ) NO 21 DEFU LANE 3, DEFU INDUSTRIAL ESTATE, 539446 Defu Lane - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/09/2018]									
Driver/Custodian (Insured): TEH YU SIN (61 / Male), NRIC: S2530268J, Tel: +6596635472									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP7000Z (SNM18D03050C02)**
[GBD1864Y]
TP
VITE LOGISTICS PTE. LTD.
Jun 18 2018 8:00AM
[HOLIAN SANITARY & PLUMBING PTE LTD]
Allan's Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	19/06/18 09:57	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	19/06/18 09:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/09/18 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
19	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
20	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
21	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
22	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
23	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
24	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
25	17/09/18 09:18	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/09/18 13:04	PRS		Load PDF	
2	14/09/18 13:04	OI GIA		Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	19/06/18 09:53	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	19/06/18 09:53	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 09:53	Sketch [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	19/06/18 09:53	Statement [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	19/06/18 09:53	Identification Card [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	19/06/18 09:53	Driving Licence [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		1 per page	<input checked="" type="checkbox"/>
1	19/06/18 09:57	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	19/06/18 09:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	19/06/18 09:53	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	19/06/18 09:53	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 09:53	Sketch		Load JPG	<input checked="" type="checkbox"/>
4	19/06/18 09:53	Statement		Load JPG	<input checked="" type="checkbox"/>
5	19/06/18 09:53	Identification Card		Load JPG	<input checked="" type="checkbox"/>
6	19/06/18 09:53	Driving Licence		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)[Save](#)[Print](#)**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016812/GCBE2

Date: 18/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3064481701

Claimant Vehicle
No : YP7000ZInsured Vehicle
No : GBD1864Y

Date of Loss: 18/06/2018

Nature of Claim: TP

Claim
No: SNM18D03050C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP7000Z

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M)

Engine No: 4P10C24829

Reg. Date: 17/10/2016 (Man. Year: 2016)

Chassis No: FEB21EA20674

Colour: White

Odometer: 0 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15

Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5/5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/09/2018

Date Inspected: 14/09/2018 Inspected At:

Allan's Workshop (HQ)
NO 21 DEFU LANE 3, DEFU INDUSTRIAL
ESTATE
Singapore 539446

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source:**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YP7000Z)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >