



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016819/Kba3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 27-04-2020



ATTN: LYNN KHONG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |            |                       |            |
|---------------------|------------|-----------------------|------------|
| <b>Insured Veh.</b> | FBK 3187T  | <b>Veh. Inspected</b> | SLJ 7873G  |
| <b>Policy No.</b>   | AN3166682  | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | S8M00TGA   | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | LYNN KHONG | <b>Assign Date</b>    | 17/09/2018 |

### 2. Vehicle Particulars & Condition

|                         |                        |                     |                    |
|-------------------------|------------------------|---------------------|--------------------|
| <b>Make &amp; Model</b> | MERCEDES BENZ C180 (A) | <b>c.c</b>          | 1796               |
| <b>Engine No.</b>       | HIDDEN                 | <b>Year of Reg.</b> | 2010               |
| <b>Chassis No.</b>      | WDD2040492A396279      | <b>Colour</b>       | METALLIC GREY      |
| <b>Odometer</b>         | 107451                 | <b>Steering</b>     | IN ORDER           |
| <b>Brakes</b>           | IN ORDER               | <b>Modification</b> | STANDARD ALLOY RIM |
| <b>General</b>          | GOOD                   |                     |                    |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 225/45ZR17  | MICHELIN    | 4 mm           |
| <b>L/H Front Tyre</b> | 225/45ZR17  | MICHELIN    | 4 mm           |
| <b>R/H Rear Tyre</b>  | 225/45ZR17  | MICHELIN    | 4 mm           |
| <b>L/H Rear Tyre</b>  | 225/45ZR17  | MICHELIN    | 4 mm           |

### 4. Description of Damages

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

### 5. General Information

|                       |                                                                                           |                        |            |
|-----------------------|-------------------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 11/08/2018                                                                                | <b>Inspection Date</b> | 17/09/2018 |
| <b>Survey held at</b> | S & H MOTOR PTE LTD<br>160 SIN MING DRIVE<br>#07-02 SIN MING AUTOCITY<br>SINGAPORE 575722 |                        |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>2 Working Days</b> |
|-------------------------------------|-----------------------|