



陳林際喺私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SKK2393P

Date of Accident : 13 September 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Tran-Sports Alliance

Date : 13 September 2018

Estimate To Repair SKC3871L - Hyundai Elantra 1.6GLS

Chassis No : KMHDH41CMCU221693

| S/No | Quantity | Description | Amount |
|------|----------|--|-------------|
| | | <u>LIST ITEMS</u> | |
| 01 | 1 pc | right rear door | \$ 1,208.00 |
| 02 | 1 pc | right rear door window frame tape front | \$ 27.00 |
| 03 | 1 pc | right rear door window frame tape rear | \$ 27.00 |
| 04 | 1 pc | right rear door window frame tape top | \$ 27.00 |
| 05 | 1 pc | right rear door window glass outer weatherstrip moulding | \$ 88.00 |
| 06 | 1 pc | right rear door window glass channel weatherstrip | \$ 115.00 |
| 07 | 1 pc | right rear door power window motor | \$ 297.00 |
| 08 | 1 pc | right rear door regulator | \$ 251.00 |
| 09 | 1 pc | right rear door inner lock | \$ 191.00 |
| 10 | 1 pc | right rear door inner lock striker | \$ 25.00 |
| 11 | 1 pc | right rear door weatherstrip | \$ 112.00 |
| 12 | 1 pc | right rear fender | \$ 1,768.00 |
| 13 | 1 pc | right rear fender inner liner | \$ 114.00 |
| 14 | 6 ps | right rear fender inner liner clips @ \$5.00 | \$ 30.00 |
| 15 | 1 pc | right rear fender air vent | \$ 29.00 |
| 16 | 1 pc | rear windscreen glass moulding | \$ 145.00 |
| 17 | 1 pc | rear bumper | \$ 459.00 |
| 18 | 1 pc | right rear bumper side retainers | \$ 26.00 |
| 19 | 10 ps | rear bumper clips @ \$5.00 | \$ 50.00 |
| 20 | 1 pc | right rear bumper end splashshield cover | \$ 38.00 |
| 21 | 1 pc | right rear shock absorber | \$ 291.00 |
| 22 | 1 pc | right rear wheel bearing with hub | \$ 155.00 |
| 23 | 1 pc | rear axle beam assy | \$ 978.00 |
| | | | \$ 6,451.00 |
| | | Less 20 % | \$ 1,290.20 |
| | | | \$ 5,160.80 |
| | | <u>SPECIAL NETT ITEMS</u> | |
| 24 | 1 pc | rear windscreen glass sealant | \$ 120.00 |
| 25 | 1 pc | rear windscreen glass inner sponge seal | \$ 80.00 |
| 26 | 1 pc | right rear wheel rim | \$ 650.00 |
| 27 | 1 pc | right rear wheel tyre | \$ 400.00 |
| | | | \$ 1,250.00 |
| | | <u>LABOUR & MISC. CHARGES</u> | |
| 01 | | To transfer of right rear door fittings and perform water seepage test. | \$ 180.00 |
| 02 | | To rust-proofing of the affected areas. | \$ 200.00 |
| 03 | | To remove and refit interior fittings, trimmings, garnish and other, to enable repair. | \$ 180.00 |



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SKK2393P
Date of Accident : 13 September 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Tran-Sports Alliance

Date : 13 September 2018

Estimate To Repair SKC3871L - Hyundai Elantra 1.6GLS
Chassis No : KMHDH41CMCU221693

| S/No | Quantity | Description | Amount |
|------|----------|--|-------------|
| | | <u>LABOUR & MISC. CHARGES</u> | |
| 04 | | To check steering geometry and computer wheel alignment. | \$ 150.00 |
| 05 | | To reinstall of rear bumper parking sensor. | \$ 120.00 |
| 06 | | To check electrical lighting concerned. | \$ 60.00 |
| 07 | | To remove and refit rear windscreen glass. | \$ 180.00 |
| 08 | | To transfer of tyre, rim and on wheel balancing. | \$ 60.00 |
| 09 | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 1,000.00 |
| 10 | | Putty and spray painting of the affected portion. | \$ 950.00 |
| | | | \$ 3,080.00 |
| | | Total | \$ 9,490.80 |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 13/09/2018 12:12 |
| Date Of Accident | 13/09/2018 10:15 |
| Exact Location Of Accident | JUNCTION OF BT BATOK E AVE 6 AND BT BATOK E AVE 2 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKC3871L |
| Insured/Policyholder | |
| Name Of Registered Owner | TRAN-SPORTS ALLIANCE |
| Co Reg No | 53353905J |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-81685399 |

Vehicle Particulars

| | |
|--|------------------|
| Manufacturer | HYUNDAI |
| Model | ELANTRA-1.6 (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARDS |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5087391172-01 |
| Cover Note Number | 22/02/2018 TO 21/02/2019 |

Driver

| | |
|----------------------|---------------------------|
| Name of Driver | TAN CHIN HUA |
| NRIC No | S1129488Z |
| Date Of Birth | 11/10/1955 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 03/02/2014 |
| Driving Experience | 4 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81685399 |
| Fax Number | |
| Contact Number | |
| Email Address | JAMES_TAN2000@HOTMAIL.COM |

| | |
|---|---|
| Address | BLOCK 978D BUANGKOK CRESCENT #15-229 |
| Postcode | 536978 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - CROSS JUNCTION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|--|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : GRAB PASSENGER - UNKNOWN GENDER: : MALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

Refer to sketch plan

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SKK2393P |
| Vehicle Make/Model/Colour | SKODA |
| Details Of Properties | SALOON CAR |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | 9651 6123 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/09/18 01220h




Reporting Centre Personnel's Signature
Name: Lam Yee Shing
NRIC/FIN No:

G6864052K

Sketch Plan Pg. 2

Bukit Batok East Avenue 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/09/2018 at about 1015hrs, I was driving my vehicle (A: SKC 3871 L) on the extreme left lane along Bukit Batok East Avenue 6 towards R/E direction. Upon reaching the junction of Bukit Batok East Avenue 2, the traffic light was amber and in my favour and I proceed straight. Suddenly the vehicle (B: SKK 2393 P) which was travelling from the opposite direction make a right turn without green arrow and hit onto my vehicle's right rear portion. Nobody was injured in this accident.

vehicle A (SKC 3871 L) - 1 male adult Grab passenger on board

vehicle B (SKK 2393 P) - No passenger on board.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/09/2018 0920hr



Reporting Centre Personnel's Signature
Name: Lam Wei Sheng
NRIC/FIN No.: G6664052R

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 3905J

Vehicle Details

Vehicle No.: SKC3871L
Vehicle to be Exported: No
Intended Deregistration Date: 13 Sep 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour: Silver
Manufacturing Year: 2011
Engine No.: G4FGBU283820
Chassis No.: KMHDH41CMCU221693
Maximum Power Output: 95.6 kW (128 bhp)
Open Market Value: \$13,662.00
Original Registration Date: 22 Aug 2011
First Registration Date: 22 Aug 2011
Transfer Count: 1
Actual ARF Paid: \$13,662.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Aug 2021
PARF Rebate Amount: \$8,197.00

Intended COE Rebate Details

COE Expiry Date: 21 Aug 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$49,301.00
COE Rebate Amount: \$14,485.00
Total Rebate Amount: \$22,682.00

The information contained herein is correct as at 13 Sep 2018

OK