

22/03/2002

ASS. REC. BY:

REF:

C93/CTU18016837 / R1 doc1

Special Instruction:

Surveyor

Rahil

ASSIGNMENT (Office)

Maimun

From (Person):

Catherine Trila

of

CTU

Date/Time:

14/05/2018 3:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 2452P

Insured:

SLD 592U

at Workshop m/s

Rae Works motor

Tel:

62732203

of

Blk 1008 Bukit Merah Lane 3 #01-26

Policy No:

0MPCSN3053141802

Claim No:

SNM18D04443C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpl

H.O.D. Endorsement:

Date/Time:

14/05/2018 3:43pm

Person Contacted:

Norman

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

FBJ 2452P - X

SLD 592U - X

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 2452Pat Workshop m/s RACE WORKZof 1008, 8m Lw 3 #01-26Insured: CTI / PRS

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBJ 2452P Yr Regn: 2014 / F6BType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W R1200 GS C.C. 1170Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 82947 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WB10A 0105 E2134367Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70R19R: 170/60R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 01/07/18 D.O.I. 18/09/18Survey held at RACE WORKZ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$4,000 - \$5,000.

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: -

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

) S + RS. SI

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format : PRG

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 15:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>LIM ZI YAN, JORDAN</b>									
Vehicle Reg. No.:		<b>FBJ2452P</b>	Date of Loss:	01/09/2018 00:00 - :59					
Claim Type:		<b>TP / SNM18D04443C02</b>	Policy/Cover Note No.:	DMPCSN3053141802					
Vehicle Reg. No. (Insured):		<b>SLD592U</b>	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer: <b>Race Werks Motor Sports (HQ)</b> 1008 Bukit Merah Lane 3, #01-26 Alexandra Village Industrial Estate, 159722 Bukit Merah - Tel: 6273-2203									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7154E
<b>Vehicle Details</b>	
Vehicle No.:	FBJ2452P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	R1200GS
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	122EN43130102
Chassis No.:	WB10A0105EZ134367
Maximum Power Output:	-
Open Market Value:	\$20,332.00
Original Registration Date:	12 Feb 2014
First Registration Date:	12 Feb 2014
Transfer Count:	3
Actual ARF Paid:	\$3,050.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Feb 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,051.00
COE Rebate Amount:	\$1,635.00
<b>Total Rebate Amount:</b>	<b>\$1,635.00</b>

The information contained herein is correct as at 01 Oct 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 13:44
Date Of Accident	01/09/2018 22:45
Exact Location Of Accident	ESSO PETROL STATION - WOODLANDS AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ2452P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM ZI YANG, JORDAN
NRIC No	S9137154E
Email Address	DESTINY_EVOLUTIONZ91@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-85335454
Alternative Phone No	OTHERS-85335454

### Vehicle Particulars

Manufacturer	BMW
Model	R1200GS
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTMC01003587
Cover Note Number	25/06/18 - 11/08/19

### Driver

Name of Driver	LIM ZI YANG, JORDAN
NRIC No	S9137154E
Date Of Birth	16/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	11/11/2014
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85335454
Fax Number	
Contact Number	OTHERS-85335454
Email Address	DESTINY_EVOLUTIONZ91@HOTMAIL.COM

Address	BLK 798 WOODLANDS DRIVE 72 #09-75
Postcode	730798
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	SHELTERED
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD592U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KENG WEI YANG
NRIC/Passport Number	S9105315B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: 1B72492P  
INSURER: Sompo  
DATE & TIME: 17/10/22 45

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 1/9/18, I, S913746 LAM ZI YANG JORDAN WAS REFUELING MY BIKE BMW R1200GS (FBJ2452P) AT ESSO PETROL STATION WOODLANDS AVE 1, PUMP 17. AFTER I HAD DONE REFUELING, I THEN PROCEED TO THE COUNTER FOR PAYMENT. AFTER PAYMENT, I NOTICE THAT MY BIKE WAS BEING KNOCK DOWN BY SLD 592U, DRIVER KENG WEI YANG, S9105315B. I DID NOT WITNESS THE ACCIDENT, BY THE TIME OF MY ARRIVAL, THE BIKE WAS ON THE GROUND, THE PUMP MACHINE WAS DENTED DUE TO THE IMPACT OF THE FALL. PARTICULAR WAS EXCHANGED, OWNER OF THE VEHICLE, S9107566C, TAN MEI YUN EILEEN WAS ALSO NOTIFIED. WAS INFORMED BY THE PUMP MANAGER THAT THE VIDEO FOOTAGE IS LIABLE FOR PAYMENT IF RETRIEVED THEY ARE ABLE TO ASSIST IN THIS INVESTIGATION.

BIKE FBJ2452P  
CAR SLD 592U

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

( ) Claim Own Policy ( / ) Claim Third Party ( ) Reporting Only  
( ) Claim CD/TP at other workshop ( )

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 15:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>LIM ZI YAN, JORDAN</b>								
Vehicle Reg. No.:	<b>FBJ2452P</b>	Date of Loss:	01/09/2018 00:00 - :59 [54 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04443C02</b>	Policy/Cover Note No.:	DMPCSN3053141802						
Vehicle Reg. No. (Insured):	<b>SLD592U</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Race Werks Motor Sports (HQ)</b> 1008 Bukit Merah Lane 3, #01-26 Alexandra Village Industrial Estate, 159722 Bukit Merah - Tel: 6273-2203								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 25/09/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FBJ2452P (SNM18D04443C02)**  
**[SLD592U]**  
**TP**  
**LIM ZI YAN, JORDAN**  
**Sep 1 2018 12:00AM**  
**[-]**  
**Race Werks Motor Sports**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 16:24	<b>General View</b>	 <a href="#">Load PDF</a>	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/09/18 15:37	<b>PRS WITH TP GIA</b>	 <a href="#">Load PDF</a>	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016837/R1CBE2

Date: 11/10/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3053141802

Claimant Vehicle  
No: FBJ2452PInsured Vehicle  
No: SLD592U

Date of Loss: 01/09/2018

Nature of Claim: TP

Claim  
No: SNM18D04443C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBJ2452P

Make &amp; Model: BMW R1200GS, 1.2 (M)

Reg. Date: 12/02/2014 (Man. Year: 2013)

Colour: Black

Engine Capacity: 1170 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 122EN43130102

Chassis No: WB10A0105EZ134367

Odometer: 82947 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	120/70 R19	Rear Tyre Size:	170/60 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/09/2018

Date Inspected: 18/09/2018 Inspected At:

Race Werks Motor Sports (HQ)  
1008 Bukit Merah Lane 3, #01-26  
Alexandra Village Industrial Estate  
Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 11 Oct 2018)

**Parts:** N/A BMW R1200GS 1.2 (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBJ2452P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >