

INS. CASE OWNER:

CC 6 / A16180 16889 / Ueasg

LAA:

IDAC:

Surveyor:

Marpus

DOI:

17/1/18

Date / Time:

17/1/18

Registered in Merimen:

17/1/18

Pre-assign / CCU / FTE

SLP 20990



Insured Vehicle No.:

CAR COVE LARANG P/L

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

14/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Mr Kye Hong
01883459

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

KIA CERATO

Place of Accident:

COMPAI VANG ST

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

tan him



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/1/18
AshuSPN 6616M - CASH (4000000000) - DDA 10/1/2018
SLP 20990 - X

File Review: Liability to claim.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

Email: 20-11-18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Oes

Repair Cost: 4s \$53,100

(4 days) Reduction: 4s %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 31.12.18

Confirm with: JONATHAN

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

WKA:

\$53,110.00

DD PRP ENVOI TP

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 40.00

(\$ 80 x 5 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5 7.49

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost:

\$5 -

Total:

\$53,804.49

Global Sum \$5:

FINAL PAYMENT

Date/Time: 31.12.18

Confirm with: JONATHAN

Email ☒ Call ☐

Payee 1:

\$53,804.49

Name 1:

Tan Jun Hong P/L ID.

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320 + \$20

COMPLAINT
31/1/18

REF: A77

ASSIGNMENT

From: Date: 17092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDN 6616M

at Workshop m/s

Tan Lim

of

51 Detu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

A 166

IDAC Accident Report:

Consistent? : Yes or No

PR Seen

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 12224

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SDN 6616M

Yr Regn:

5-06

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAT

Make:

Honda civic

CC

1799

Colour:

white

A/C

Insured / Std / NI / NA

Sp Reading:

166040

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH/MFD/163065207872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodride

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/9/18

D.O.I.

17/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear n/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24hrs. 7hrs. until 10/5/2021
net 3776

17/9/18 confirmed L/S \$3100 with max lye.

- (RED) * 2,122.64 41/4

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RE TR

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLP2699U
Date of Accident : 14 September 2018

Mr Goh Kai Meng (Wu Jiemin)

Date : 14 September 2018

Estimate To Repair SDN6616M - Honda Civic 1.8LA
Chassis No : JHMFD16306S207872

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	n/s bootlid reflector <i>CNE</i>	\$ 152.80
02	1 pc	bootlid centre emblem badge <i>neu</i>	\$ 49.60
03	1 pc	n/s rear lamp <i>CNE</i>	\$ 268.70
04	3 pc	rear lamp clip holder @ \$12.50 <i>11</i>	\$ 37.50
05	1 pc	n/s rear lamp panel <i>D.S</i>	\$ 100.60
06	1 pc	rear bumper <i>D.S</i>	\$ 658.70
07	2 pc	rear bumper side retainer @ \$46.90 <i>Set</i>	\$ 93.80
08	10 pc	rear bumper clips @ \$5.90 <i>neu</i>	\$ 59.00
09	2 pc	rear bumper side holder @ \$28.60 <i>11</i>	\$ 57.20
10	1 pc	rear end panel <i>B.S.D</i>	\$ 355.40
11	1 pc	rear end panel inner trim <i>11</i>	\$ 252.80
12	1 pc	rear end panel inner trim clips <i>11</i>	\$ 3.80
13	1 pc	n/s rear fender air vent <i>twy</i>	\$ 38.40
Less 20 %			\$ 2,128.30
			\$ 425.66
			\$ 1,702.64
SPECIAL NETT ITEMS			
14	1 pc	rear bumper lower spoiler <i>D.S</i>	\$ 900.00
15	1 pc	rear bumper parking sensor <i>11</i>	\$ 350.00
			\$ 1,250.00
LABOUR & MISC. CHARGES			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check electrical lighting concerned.	\$ 60.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
06		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,270.00
Total			\$ 5,222.64

Acknowledged by Repairer



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP021092018

Date : 24-09-2018

Your Ref : CCG/AIG 18016889 / Uea3

WITHOUT PREJUDICE

Claims Department - Motor Claims [UKK]

c/o AIG ASIA PACIFIC INSURANCE P/L

Dear Sir/Madam,

ACCIDENT INVOLVING SDN 6616M & SCP 2699M ON 14-09-2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / _____ copies of photographs _____

☒ Original Tax-invoice number

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction -

a)	Cost of repair (inclusive GST)	\$	3,317.00
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [180 x 7 days]	\$	1,260.00
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)		\$	
Total		\$	4,584.49

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 23 November 2018 2:32 PM
To: 'EDWIN@CARCOVE.COM.SG'
Subject: ACCIDENT INVOLVING SLP 2699U AND SDN 6616M ON 14/09/2018

Our Ref: CC6/AIG18016889/Uea3

23 NOV 2018

CAR COVE LEASING PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLP 2699U AND SDN 6616M ON 14/09/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, GOH KAI MENG ("the third party claimant")
of BLK 260 SENKANG EATWAY #02-474 S 544260 (address),
owner of SDN6616M (vehicle no.) hereby authorize
TAN LIM MOTOR PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SDN6616M that was
damaged pursuant to the accident which occurred on 14-09-2018 (date) along
COMPASSVALE STREET TURNING INTO COMPASSVALE CRESCENT (location)
involving vehicle no/s SLP26994 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 14th day of September (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,317.00 (Repair Cost), S\$480.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SDN 6616M that was damaged pursuant to the accident which occurred on 14/09/2018 (date) along COMPASSVALE STREET TURNING INTO COMPASSVALE CRESCENT (location) involving vehicle no/s SLP 2699U.

This is pursuant to the inspection conducted on 17/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GOH KAI MENG (WU JIEMIN) ("the third party claimant") of vehicle no. SDN 6616M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SDN 6616M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 31st (day) of December (month) 2018 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0918/022

(Please quote our reference number TP021092018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


AIG Asia Pacific Insurance Pte. Ltd

Date: 24/09/2018

Vehicle No: SDN6616M
Model: HONDA CIVIC 1.8L A

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,100.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$3,107.00
Add 7% GST	\$217.49
Total	\$3,324.49



Tan Lim Motor Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SLP2699U As At 14 Sep 2018 / 14:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MISC-CM

Current Owner Details

Owner ID Type: Company

Owner ID: 201602573M

Owner Name: CAR COVE LEASING PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 1557

Registered Street Name: KEPPEL ROAD

Registered Unit No.: # 01 - 02

Registered Building Name: -

Registered Postal Code: 089066

Current Vehicle Details

Vehicle No.: SLP2699U

Make Description/Model: KIA / CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018 Edit Reg		17 Sep 2018 00:00 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CAR COVE LEASING PTE LTD , Co. Reg. No.: 201602573M								
Main Claimant:	GOH KAI MENG (WU JIEMIN) , ID: S6922831C								
Vehicle Reg. No.:	SDN6616M	Date of Loss:	14/09/2018 14:00 - :59 [148 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7254975137SG	Policy/Cover Note No.:	0999994595 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLP2699U	Policy No. (Claimant):	5099249667						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (19/09/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDN6616M (7254975137SG)
[SLP2699U]**




































TP




























GOH KAI MENG (WU JIEMIN)

Sep 14 2018 2:00PM

[CAR COVE LEASING PTE LTD]

Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼		
Letters/Correspondences			1 per page ▼ <input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	
Photos/Images			1 per page ▼ <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/09/18 18:43	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	17/09/18 18:43	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
4	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
5	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
6	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
7	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
8	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
9	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
10	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
11	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
12	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
13	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
14	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
15	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
16	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
17	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
18	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
19	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
20	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
21	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
22	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
23	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
24	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
25	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
26	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
27	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
28	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
29	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
30	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
31	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
32	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
33	17/09/18 18:44	General View		Load JPG	<input checked="" type="checkbox"/>
34	17/09/18 18:44	General View		Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/09/18 10:18	TP ESTIMATE - MARKED	 Load PDF	
2	19/09/18 10:18	TP GIA REPORT	 Load PDF	
3	07/01/19 09:05	WORKSHOP INVOICE	 Load PDF	
4	07/01/19 09:05	AUTHORISATION TO ACT FORM	 Load PDF	
5	07/01/19 09:05	Release Voucher	 Load PDF	
6	07/01/19 09:05	LTA SEARCH	 Load PDF	
7	07/01/19 09:05	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/09/18 09:41	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLP2699U (Insd veh)	Model:	HONDA CIVIC 1.8 L (A)
	SDN6616M (TP veh)		
Date of Accident:	14/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	5,588.22	
Final Repair Cost	: \$	3,317.00	
Loss of Use	: \$	480.00	6.00 days at \$80.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.49	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	3,804.49	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	3,804.49
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

07 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016889/UEA3Q2

Date: 07/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994595
Claimant Vehicle No : SDN6616M **Insured Vehicle No :** SLP2699U
 Date of Loss: 14/09/2018 Nature of Claim: TP Claim No: 7254975137SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN6616M**
 Make & Model: HONDA CIVIC, 1.8 L (A) Engine No: R18A11026706
 Reg. Date: 11/05/2006 (Man. Year: 2006) Chassis No: JHMF16306S207872
 Colour: White Odometer: 166040 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
 Front Left Side: Goodride 6 mm Rear Left Side: Goodride 6 mm
 Front Right Side: Goodride 6 mm Rear Right Side: Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,952.64	2,183.20	769.44	26.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,710.00	560.00	24.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,222.64	3,893.20	1,329.44	25.46
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	5,222.64	3,100.00	2,122.64	40.64
+ GST 7.00/7.00% (S\$)	365.58	217.00	148.58	40.64
Nett Amount (S\$)	5,588.22	3,317.00	2,271.22	40.64
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,804.49		

INSPECTION

Date of Assignment: 17/09/2018
 Date Inspected: 17/09/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S BOOTLID REFLECTOR	Cracked	152.80 FL	*152.80 FL
2	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	49.60 FL	*30.60 FL
3	1		*N/S REAR LAMP	Cracked	268.70 FL	*268.70 FL
4	3		*REAR LAMP CLIP HOLDER	Not Necessary	37.50 FL	*- FL
5	1		*N/S REAR LAMP PANEL	Dented	100.60 FL	*100.60 FL
6	1		*REAR BUMPER	Distorted	658.70 FL	*658.70 FL
7	2		*REAR BUMPER SIDE RETAINER	Bent	93.80 FL	*93.80 FL
8	10		*REAR BUMPER CLIPS	Necessary	59.00 FL	*30.00 FL
9	2		*REAR BUMPER SIDE HOLDER	Not Necessary	57.20 FL	*- FL
10	1		*REAR END PANEL	Badly Dented	355.40 FL	*355.40 FL
11	1		*REAR END PANEL INNER TRIM	Not Necessary	252.80 FL	*- FL
12	1		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	3.80 FL	*- FL
13	1		*N/S REAR FENDER AIR VENT	Twisted	38.40 FL	*38.40 FL
14	1		*REAR BUMPER LOWER SPOILER	Distorted	900.00 FS	*800.00 FS
15	1		*REAR BUMPER PARKING SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,378.30	2,529.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	425.66	345.80
Total Parts (\$\$)	2,952.64	2,183.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	80.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	50.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	950.00	800.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	700.00
Gross Labour Cost (\$\$)			2,270.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >