

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18016891/Aga3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG			Date: 04-05-2020  Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
<u> </u>	Insured Veh.	PZ 1311U	Veh. Inspected	SJS 9199H	
$\vdash$	Policy No.	P1656875	Coverage (\$)	0.00	
-	Claim No.	S8M00VJL	Excess (\$)	0.00	
$\vdash$	Assign From	RICHARD ANG	Assign Date	14/09/2018	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ A180	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WDD1760422J380351	Colour	GREY	
	Odometer	22838	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	12/09/2018	Inspection Date	14/09/2018	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	n. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				