Surveyor	Adron -	ASSIGNM	IENT (Office)		
From (Person)	Catherine Thia	of	CTL	Dat	e/Time: 17192018 455pm
Estimated Co.	d.		Bill to:		
To Inspect Ve	strprestodrestev chicle No:	A/INV/MV/	CS	Insured:	GBF 88197
at Workshop	0 -	Seng muti		Tel:	P216 F4Fd
of		1 Kat Bulkt	t Ave 6 #01	-69	
	POFCOE NOVÔMO		Claim No:	A 14. 1/	3D04479coz.
Sum Insured:			Excess:		
Make of Veh				D.0	D.A. 14092018
(Client's Recor CA / REV Date/Time:	1) / REP. / REV 24 HRS 11 17092018 535 pm [וקט Person Contacted	18092018		H.O.D. Endorsement:
Date/Time	Action/Instruction (×	Estima	te		
	SJC 3129D - NS	/INC 15022	946 /Hlybn2		DOA: 24-11-15
	GBF 9819Y - MA	-			DOA: 1409-18
	Diamantle: 19/9/				
	After repair: st			y - m - m m	
	india it had . O. I	11000			

ASSIGNMENT

From: Date:	Veh No: SJC3229D. Yr Regn: 2008, teb.
Estimated Cost:	Type M.Cap/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Suburn Zypreza c.c 1597 Colour Blue: A/C: Insured/Std/NI/NA
at Workshop m/s	Colour Blue A/C: Insured / Std / NI / NA
of	Sp.Reading 4/863. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: JF1605KR579072402
Claims No.	Gen. Cond: Good PFair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
	Tyre Size: F: 195/60R15.
(Policy Condition)	R: 135/60 R15
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF Habilead
Bal. or Market Value:	<u>Front</u> Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. p6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 18/09/18.
Lum Sum: % 3 Val.: Yes or No	Survey held at Gee Sery .
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S V U/C / Rooftop or
Vehicle: IN / OUT	The state of the s
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction TP Um PRS.	COE Expiry: 12/02/23.
MV : 251C	
QV 1 18-61C	
- Estimated repair range	strang conte
- Estimated that table	40,000
	10/10/5015
	Days Of Repair:
	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to? Add Fee:	Transportation:
2) Add Fee.	Interview (\$) Photos
Report Format : PRQ .	Tech Invs (\$) Obers
Lump Sum / LB.I: (\$	Weekend (\$
Property of the Control of the Contr	TOTAL

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	17 Sep 2018		17 Sep 2018 16:55 Assign				New Assignme Cancel Case	nt
	Main	R	eference		Claim Details	Doc	uments	Show All
LAIM S	UBFOLDER DET	AILS		THE REAL PROPERTY.		1	Created by insu	er]
ain Clair	mant:	LAU N	GANG KIM					
ehicle Re	eg. No.:	SJC3	229D		Date of Loss:		4/09/2018 00:00 -	- PA
laim Typ	e:	TP /	5NM18D044790		Policy/Cover Note No.:			
thicle Re	eg. No. (Insured):				Policy No. (Claimant):		DMCVSN3027081800	
					Excess:	5	S\$0.00	
epairer:		Gee S	Gee Seng Motor Service (HQ) Blk 1 Kaki Bukit Ave 6, #01-69 Autobay @ Kaki Bukit, 417883 Kaki Bukit - To					
	Insurer:	China	Taiping Insuran	ce (Singapor	e) Pte. Ltd. (HQ) - To	el: 6389 6111	[Handled by Cath	erine Thial
ljuster:	recount -	LKK A	uto Consultants	Pte Ltd (HQ)	- Tel: 6256-3561 [Final Rpt due	26/09/20181	erme rmaj
ij Asg. R	lemarks:	NO ES	r,CASE W/O SJE.			•		
SSOCIA	TED MAIL REC	FTVED						
000000000000000000000000000000000000000	no mail for this ca					Vie	w All Compo	se Case Mail
rere are	no mail for this Ca	ise.					401	
LL ASS	OCIATED TASK	5			View All Se	arch Tasks	Create New Task	Complete
Due Da		Type Task	Group Subject	t Handle		Completed		



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327
Fax: (65) 6253 0120 (Conveyancing), (66) 6536 5368 (Liligation)
Email: juseq@singnet.com.sg website: www.juseq.com.sg

Our Ref.

JEQ/180733/0918/ GS (zi)

Your Ref:

GBF8819Y

17 September 2018

MYCOOL PTE LTD

193A Guillemard Road Singapore 399725 By Post Only

CHINA TAIPING INSURANCE SINGAPORE PTE LTD

By Fax: 6224 7478

Singapore

Dear Sir


ACCIDENT INVOLVING SJC3229D & GBF8819Y ON 14.09.2018

We act for the owner of vehicle no. SJC3229D.

We hereby notify you of a road traffic accident on 14 September 2018 at about 1825 hrs, at PIE involving our client's vehicle and vehicle registration no. GBF8819Y driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle further reference to you.

Yours faithfully



CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

MVACISITOTZO (VAC - KALI BURN ENTRY DATE & TIME: 15/09/2010 10:12 SUBMITTED BY: SITI FADHLON BTE ADDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- Z. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provised must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the incurance companies,
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Ascocimion of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the longement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid,	The state of the s	or or the report pelling limite available
	ACCIDENT STATEMENT	
Date Of Report	15/09/2018 10:12	
Date Of Accident	14/09/2018 18:25	
Exact Location Of Accident	PIE > HOUGANG AVE 3	
Country/State of Loss	\$INGAPORE .	9
	DETAILS OF OWN VEHICLE	12/4/2011 (\$25/6)
Vehicle Registration Number	SJC3229D	
Name Of Registered Owner	_ LAU NGANG KIM	ters and account of the state of the same
NRIC No	S1249151D	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96944644	

OTHERS-96944644

Alternative Phone No
Vehicle Particulars

Manufacturer SUBARU
Model IMPREZA 4AT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

NO

Type Of Coverage COMPREHENSIVE

Figet Policy NO

Policy Number 5097929662

Cover Note Number

Drivet
Name of Driver
LAU NGANG KIM

 NRIC No
 S1249151D

 Date Of Birth
 16/11/1957

 Occupation
 INDOOR

 Date Of Driving Pass
 31/05/1977

Driving Experience 41 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +85-96944644

Fax Number

Contact Number OTHERS-96944644

EMail Address NOEMAIL

Address

BLK 659 #11-138 JALAN TENAGA

Postcode

410659

Was driver an employee of the Insured's Company NO If No. Relationship of the Oriver with the insured

OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Detalls of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION, I WAS STATIONERY AT THE TRAFFIC LIGHT JUNCTION, WAITING FOR IT TO TURN GREEN. WHILE IN THE MIDST OF WAITING, THAT IS WHEN VEHICLE B-GBF8819Y UNABLE TO STOP ON TIME AND THUS COLLIDED ONTO MY VEHICLE REAR PORTION, WHICH RESULTED TO SUSTAIN

Attachment(a)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF8819Y

Vehicle Make/Model/Colour

TOYOTA DYNA 3.0 MANUAL

Details Of Proporties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the occident to spead up she claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy fiability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any faist reporting may be referred to the Police for investigation,
- G. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workthop and the General insurance Association of Singapore ("GIA") may/are-permitted to collect, use, disclose and/or process my personal deta/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident that be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the daims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (III) carrying out and/or dealing with my instructions or responding to any anguiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, uso, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law anforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

- L

Policyhpider's Signature Dato & Time:


to the substance of the state of the second

Oriver's Signature (If driver is not the policyholder) Date & Time: IDAC KAKI BUKIT (VAC)

Reporting Canta Makingthistiname 4
Name: Singapore 415933
NRIC/TEN-67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



Section the foregoing particulars are true in every respect.

Policyholoere signacura a co 1

The in such the diagnost and the

Can of the Life San time, 24

65365368

Oriver's Signature (If driver is not the policyholder) Date & Tine:

IDAC KAKI BUKIT (VAC) Reporting Centre Personnel's France

Name: Singapare 415750 NAICHAING 7416697 Fox: 67492305 Email: yackb@singnet.com.sg

GEZ SENG. MOTOR. SVE 67472429

Page 4 of 11

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 2. Please report correctly the details of the accident to speed up the claims process,
- 2. This Form must be completed by the Policyholder and for the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate noticy liability.
- A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any fairs reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available eforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (3) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this occident (all insurer(s) who have insured vehicle(s) involved in this accident shell be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my daints;
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me,
 which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the
 external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/ere permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lewyers/law firms), which may be alted outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile dalms history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Line

Policyholder's Signature Dole & Time:

TANK SHIP TONG DEED

Oriver's Signature (If driver is not the policyholder) Data & Time: IDAG KAKI BUKIT (VAG)

Reporting Centra PSQUAREUPITABUE 4
Name: SIngapore 415933

Name: Singapore 413333 NRIC/1041067416697 Fax: 67492305

Email: vackb@singnet.cem.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		Control (Con
Owner ID Type:	Singapore NRIC	
Owner ID:	9151D	
Vehicle Details	White the second of the second	
Vehicle No.:	SJC3229D	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	18 Sep 2018	
Vehicle Make:	SUBARU	
Vehicle Model:	IMPREZA 4AT	
Primary Colour:	Blue	
Manufacturing Year:	2007	
Engine No.:	EJ16D140162	
Chassis No.:	JF1GD5KR57G072402	
Maximum Power Output:	70.0 kW (93 bhp)	
Open Market Value:	\$10,847.00	
Original Registration Date:	13 Feb 2008	
First Registration Date:	13 Feb 2008	
Transfer Count:	1	
Actual ARF Paid:	\$11,932.00	
Intended PARF Rebate Details		tion of the last the
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details	生物的AMOSE 在1.1000年1000年12月1日 3月1日 3月1日 3月1日 3日 1日	AKO LONE
COE Expiry Date:	12 Feb 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	5	
PQP Paid:	\$21,061.00	
COE Rebate Amount:	\$18,550.00	
Total Rebate Amount:	\$18,550.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Sep 2018

SGCARMART.COM

Login | Sign up f Connect **New Cars Used Cars** Sell My Car Directory Products Insurance Articles Forum Resources


Private Property prices.....still up or down? Part II

Sports

Available

Available

- Liverpool Football Club 2018/19 season YNWA
- COE Bidding 2nd Round of September 2018



Owner Consignment Unit, Low Depreciation, Good Condition 5D STI For Sale That Is Already Renewed, Everything In Good Condition, 6 Months Free Servicing By Reputable Workshop With 40 Years Experience I... Posted 15-Sep-2010 Tags: 2008 Subaru Impreza, Subaru Impreza, Subaru, Impreza, Used Subaru

STI (COE till 05/2028)

Subaru Impreza 5D 2.0A S-GT

ipare 💪

\$39,000

Hatchback (COE till 07/2023) Good For COE Extension, You Never Get Another Worthy Car To Renew COE Except For This One, Can Add-In After Market Parts To Enhance Full Satisfying Performance One Can Ask For.

\$8,020 Avr

29-Jul-2008

1.994 cc

129,500 km



...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subi	HILLER	Ins Auth'ed	Status		
Main	17 Sep 2018		17 Sep 2018 16:55 Edit Adj Rpt	S\$0.00 Edit Estimat	es	S\$0.00 View Rp	ot		Pending for Surve Report Cancel Case		vey
	Main	Re	ference	С	laim C	etails		Docume	nts		Show All
CLAIM SU	BFOLDER DE	TAILS			a Alarman de		[Create	d by insurer]			
nsured:	-, Co. Re	g. No.: -									
Main Claimant:	LAU NGA	NG KIM									
Vehicle Reg. No.:	Date of Loss: 14/09/2018 00:00 - :59 [127 Months and 1 Days From LTA Reg Date (Man						Man Yr)]				
Claim Type:	TP / SNN	418D04479C02			Policy	y/Cover No.:	DMCVSN	13027081800			
Vehicle Reg. No. (Insured):	GBF8819	Y			Policy (Clair	y No. mant):					
S-0-110-110-110-110-1					Exce	ss:	S\$0.00				
Repairer:	Gee Seng	Motor Service (HQ) Blk 1 Kaki B	lukit Ave 6, #	01-69	Autobay	@ Kaki Bu	ukit, 417883 Kak	Bukit - Tel:	8	
Handling Insurer:	18800000170017016	ping Insurance (me entrancement				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Han	dled by A	ADRIAN L	LING] [Final	Rpt due	26/09/2	018]
Adj Asg. Remarks:	NO EST, CA	ASE W/O SJE.	94 8000					30 19			
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compose	Case Ma
There are n	o mail for this	case.									
ALL ASSO	CIATED TAS	sks⊡					View A	II Search Tasks	Create N	ew Task	Complet
Due Date	Priority	Type Task	Group Subj	ect Hand	ler	Assign	ed By	Completed C	n Cre	ated On	Done
No results.	23.09303	TERROY		vende septem	A. (12.1)			and the second of the second	100		

Claim Documents

*SJC3229D (SNM18D04479C02) [GBF8819Y] LAU NGANG KIM Sep 14 2018 12:00AM [-] Gee Seng Motor Service

Upi	oad Documents Up	ts Upload Photos Compose New Letter View in Br		Browser ▼
Doc	umentation		1 per page	Y .
No.	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumb	nail Print
1	17/09/18 16:54	PRS	€ Load F	PDF
2	17/09/18 16:54	TP GIA REPORT	€ Load F	PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI18016941/ACBS2

Date:

17/10/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte.

Policy No:

DMCVSN3027081800

Claimant Vehicle

SJC3229D

Insured Vehicle No

GBF8819Y

No: Date of Loss:

14/09/2018

Nature of Claim:

TP

Claim No:

SNM18D04479C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJC3229D

Make & Model:

Engine Capacity:

Sum Insured (S\$):

SUBARU IMPREZA 4, 1.6 (A)

Engine No:

EJ16D140162

Reg. Date:

13/02/2008 (Man. Year: 2007)

Chassis No:

JF1GD5KR57G072402

Colour:

Blue

1597 cc

Odometer:

41863 km

Market Value/New Car Price:

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable):

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Engine Modification:

No

Front Tyre Size:

195/60R15

Rear Tyre Size:

195/60R15

Front Left Side: Front Right Side:

Habilead 6 mm Habilead 6 mm Rear Left Side: Rear Right Side: Habilead 6 mm Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment:

17/09/2018

18/09/2018 Inspected At:

Gee Seng Motor Service (HQ)

Blk 1 Kaki Bukit Ave 6, #01-69 Autobay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair:

7.0 days

Adjuster: ADRIAN LING Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2018)

Parts: SUBARU IMPREZA 4 1.6 (A) (Catalogue:Merimen Singapore 1.0) 143

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJC3229D)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >