

22/03/2003

ASS. REC. BY:

REF:

CS3 / SMO 18016965 / R1632

Special Instruction:

Surveyor:

Maimin

ASSIGNMENT (Office)

From (Person):

(Tan) Pau Long

of

SMO

Date/Time:

18092018 12.22pm

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G86 3679L

Insured:

FS 43218

at Workshop m/s

New Pioneer Auto

Tel:

9615 8550

of

1 Soon Lee St #01-50

Policy No:

Claim No:

CMTD1804027

Sum Insured:

Excess:

D.O.A.

14092018

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS WP

Date/Time:

18092018 1:15pm

Person Contacted:

Mr. Tan

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	G86 3679L - x
	TS 113218 - NBA / msh/14006862 / d2
	Dismantle: 19/9/2018
	After repair: 24/9/2018

DFA: 200314

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		18 Sep 2018 12:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUHAMMAD MUZAMMIL BIN ABDUL RAHIM, ID: S9140499								
Main Claimant:	NEW PIONEER AUTO PTE LTD, Co. Reg. No.: 201319665W								
Vehicle Reg. No.:	GBG3679L	Date of Loss:	14/09/2018 14:00 - :59						
Claim Type:	TP / CMTD1804027	Policy/Cover Note No.:	D18MTMC01000250 (Third Party Only)						
Vehicle Reg. No. (Insured):	FS4321B	Policy No. (Claimant):							
		Excess:							
Repairer:	New Pioneer Auto Pte Ltd (HQ) 1 SOON LEE STREET #01-50 PIONEER CENTRE, 627605 Pioneer - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> SOMPO_SG (18/09/2018): TP SURVEY 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 18 September, 2018 12:23 PM
To: accident@kscgp.com; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: motor@kscgp.com; Gnoh, Pau Loong; Henry, Irene James; Ye, Yong Kang Melvin
Subject: CMTD1804027/GPL - SUV(LKK)/ 2nd Notice to Conduct Pre-Repair Survey - Your Ref: CMTD1804027/GPL Our Ref: GBG 3679L/NP/sy/wl

Our Reference : CMTD1804027/GPL
Your Reference: GBG 3679L/NP/sy/wl

Without Prejudice

Date: 18th September 2018

Attention:
M/S KSCGP Juris LLP

Dear Wei Lin

ACCIDENT INVOLVING FS4321B & GBG3679L ON 14.09.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompso SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompso Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: accident@kscgp.com [mailto:accident@kscgp.com]

Sent: Tuesday, September 18, 2018 12:14 PM

To: Teo, Grace

Cc: motor@kscgp.com; Gnoh, Pau Loong; Henry, Irene James; Ye, Yong Kang Melvin

Subject: 2nd Notice to Conduct Pre-Repair Survey - Your Ref: CMTD1804027/GPL Our Ref: GBG 3679L/NP/sy/wl

Dear Sirs,

Please find enclosed herein the 2nd Notice to conduct Pre-Repair Survey. Our client is not agreeable to your proposed list of motor surveyors.

The workshop's contact details are as follows:

New Pioneer Auto Pte Ltd
1 Soon Lee Street
#01-50 Pioneer Centre
Singapore 627605
Contact: Mr Tan Tick Cuan / 9615 8550/ 6339 0500

Thank you.

Regards,

Wei Lin

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Teo, Grace [mailto:grace.teo@sompso.com.sg]

To: accident@kscgp.com

Cc: motor@kscgp.com, PauLoong.Gnoh@sompso.com.sg, irene.henry@sompso.com.sg,

melvin.ye@sompo.com.sg

Sent: Tue, 18 Sep 2018 01:08:37 +0000

Subject:

Our Reference : CMTD1804027/GPL

Your Reference: GBG 3679L/NP/sy/wl

Without Prejudice

Date: 18th September 2018

Attention:

M/S KSCGP Juris LLP

Dear Wei Lin

ACCIDENT INVOLVING FS4321B & GBG3679L ON 14.09.2018

We refer to your Notice of Accident dated 17/09/2018.

Please be informed that Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: accident@kscgp.com [mailto:accident@kscgp.com]

Sent: Monday, September 17, 2018 4:51 PM

To: Claims - Motor Survey

Cc: motor@kscgp.com

Subject: Notice to Conduct Pre-Repair Survey - Your insured's vehicle: FS 4321B Our ref: GBG 3679L/NP/sy/wl

Dear Sirs,

Please find enclosed herein the Notice to conduct Pre-Repair Survey, for your attention and necessary action.

Thank you.

Regards,

Wei Lin

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2018 10:50
Date Of Accident	14/09/2018 14:00
Exact Location Of Accident	CLEMENTI AVE 2 SLIP ROAD TO CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG3679L
Insured/Policyholder	
Name Of Registered Owner	NEW PIONEER AUTO PTE LTD
Co Reg No	201319665W
Email Address	NEWPIONEER@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96158550
Alternative Phone No	OFFICE-96158550

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093021898-01
Cover Note Number	

Driver

Name of Driver	LIM CHUAN SENG
NRIC No	S1226146B
Date Of Birth	20/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	19/12/1979
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82920601
Fax Number	
Contact Number	
EMail Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD MUZAMIL BIN ABDUL RAHIM
Approximate Age	
Injuries Sustain	MINOR ABRASIONS
Injured person in which vehicle?	FS4321B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)


Reporting Centre Personnel's Signature
Name

17/9/18

Sketch Plan #2

Site Visit Form



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer police report T/20180915/2074

DECLARATION

I/We declare that the particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name: 17/9/18



**SINGAPORE
POLICE FORCE**



T/20180915/2074

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20180915/2074

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2018 14:17	Vide Report No.:	Station Diary No.: 121
--	------------------	---------------------------

Informant's Particulars

Name of Informant: LIM CHUAN SENG			Address: APT BLK 835 JURONG WEST STREET 81 #11-37 SINGAPORE 640835		
ID Type / ID No.: NRIC NO / S1226146B			Contact No.: Home/Office: Mobile: 82920601		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 20/05/1957	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Cleaning supervisor			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/09/2018 14:00	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI AVENUE 2				
SLIP ROAD TO CLEMENTI ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FS4321B	Motorcycle				Slightly Damaged	0
GBG3679L	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		



**SINGAPORE
POLICE FORCE**



T/20180915/2074

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20180915/2074

CONTINUATION OF REPORT

Rider			
Name	MUHAMMAD MUZAMIL BIN ABDUL RAHIM	ID No.	S9140499J
Related Vehicle	FS4321B (Motorcycle)	Contact No.	92365755
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	LIM CHUAN SENG	ID No.	S1226146B
Related Vehicle	GBG3679L (Car)	Contact No.	82920601
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 14/09/2018 at about 1400hrs, I was travelling with my company rented vehicle (GBG3679L) along Clementi Avenue 2. As I was approaching the slip road junction towards Clementi Road, I then stopped my vehicle and check for the oncoming traffic.

I then slowly move out after the traffic was cleared. As I slowly inched forward, suddenly I heard a loud noise which came from the rear side of my vehicle. I then stopped at the nearby bus stop and discovered that there were some damages on the rear bumper of my vehicle. I have then discovered that there was a motorcyclist who had fall down at the said junction and approached me after he had recovered.

The said rider has then apologized to me and wish to have a private settlement, however my rental company has rejected and advised him to lodge a police report. He has suffered from minor injury during the said accident. There was in-car camera installed in my vehicle and was operating during the accident.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9665W
Vehicle Details	
Vehicle No.:	GBG3679L
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	263A50008092368
Chassis No.:	ZFA26300006G75598
Maximum Power Output:	-
Open Market Value:	\$19,567.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$979.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,566.00
COE Rebate Amount:	\$26,068.00
Total Rebate Amount:	\$26,068.00

The information contained herein is correct as at 01 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		18 Sep 2018 12:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD MUZAMMIL BIN ABDUL RAHIM, ID: S9140499J		
Main Claimant:	NEW PIONEER AUTO PTE LTD, Co. Reg. No.: 201319665W		
Vehicle Reg. No.:	GBG3679L	Date of Loss:	14/09/2018 14:00 - :59 [13 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804027	Policy/Cover Note No.:	D18MTMC01000250 (Third Party Only)
Vehicle Reg. No. (Insured):	FS4321B	Policy No. (Claimant):	
		Excess:	
Repairer:	New Pioneer Auto Pte Ltd (HQ) 1 SOON LEE STREET #01-50 PIONEER CENTRE, 627605 Pioneer - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- SOMPO_SG (18/09/2018): TP SURVEY

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG3679L (CMTD1804027)**
[FS4321B]

TP

NEW PIONEER AUTO PTE LTD



































Sep 14 2018 2:00PM

[MUHAMMAD MUZAMMIL BIN ABDUL RAHIM]

New Pioneer Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 12:09	General View	 Load JPG	✓
2	09/10/18 12:09	General View	 Load JPG	✓
3	09/10/18 12:09	General View	 Load JPG	✓
4	09/10/18 12:09	General View	 Load JPG	✓
5	09/10/18 12:09	General View	 Load JPG	✓
6	09/10/18 12:09	General View	 Load JPG	✓
7	09/10/18 12:09	General View	 Load JPG	✓
8	09/10/18 12:09	General View	 Load JPG	✓
9	09/10/18 12:09	General View	 Load JPG	✓
10	09/10/18 12:09	General View	 Load JPG	✓
11	09/10/18 12:09	General View	 Load JPG	✓
12	09/10/18 12:09	General View	 Load JPG	✓
13	09/10/18 12:09	General View	 Load JPG	✓
14	09/10/18 12:09	General View	 Load JPG	✓
15	09/10/18 12:09	General View	 Load JPG	✓
16	09/10/18 12:09	General View	 Load JPG	✓
17	09/10/18 12:09	General View	 Load JPG	✓
18	09/10/18 12:09	General View	 Load JPG	✓
19	09/10/18 12:09	General View	 Load JPG	✓
20	09/10/18 12:09	General View	 Load JPG	✓
21	09/10/18 12:09	General View	 Load JPG	✓
22	09/10/18 12:09	General View	 Load JPG	✓
23	09/10/18 12:09	General View	 Load JPG	✓
24	09/10/18 12:09	General View	 Load JPG	✓
25	09/10/18 12:09	General View	 Load JPG	✓
26	09/10/18 12:09	General View	 Load JPG	✓
27	09/10/18 12:09	General View	 Load JPG	✓
28	09/10/18 12:09	General View	 Load JPG	✓
29	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
30	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
31	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
32	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
33	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
34	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓
35	09/10/18 12:17	Photographs of Damaged Parts	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
37	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
38	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
39	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
40	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
41	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
42	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
43	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
44	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
45	09/10/18 12:17	Photographs of Damaged Parts	Load JPG	✓
46	09/10/18 12:17	Photo After Spray	Load JPG	✓
47	09/10/18 12:17	Photo After Spray	Load JPG	✓
48	09/10/18 12:17	Photo After Spray	Load JPG	✓
49	09/10/18 12:17	Photo After Spray	Load JPG	✓
50	09/10/18 12:17	Photo After Spray	Load JPG	✓
51	09/10/18 12:17	Photo After Spray	Load JPG	✓
52	09/10/18 12:17	Photo After Spray	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	18/09/18 09:02	Third Party E-filed GIA report	Load PDF	
2	18/09/18 12:18	Pre-Repair Survey - 2ND	Load PDF	
3	18/09/18 12:24	Pre-Repair Survey - LKK AUTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18016965/R1CBS2

Date: 18/10/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01000250
 Claimant Vehicle No: GBG3679L Insured Vehicle No: FS4321B
 Date of Loss: 14/09/2018 Nature of Claim: TP Claim No: CMTD1804027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG3679L**
 Make & Model: FIAT DOBLO, 1.2 D 1.3M (M) Engine No: 263A50008092368
 Reg. Date: 27/07/2017 (Man. Year: 2017) Chassis No: ZFA26300006G75598
 Colour: White Odometer: 16859 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/09/2018
 Date Inspected: 18/09/2018 Inspected At: New Pioneer Auto Pte Ltd (HQ)
 1 SOON LEE STREET #01-50 PIONEER CENTRE
 Singapore 627605
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2018)

Parts: M1-MPV FIAT DOBLO 1.2 D 1.3M (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG3679L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >