

22/03/2002

ASS. REC. BY:

REF:

CS3 / CT18017015 / R1 doez

Special Instruction:

SURVAYOR
MURLINASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

18092018 420pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8D 7032S

Insured:

YM 7721S

at Workshop m/s

8 Paragon

Tel:

of

71 Woodlands Ave 10 #01-10

Policy No:

DMCVSN 3053961800

Claim No:

SNM1820452002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15092018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

19-09-2018

H.O.D. Endorsement:

Date/Time:

18092018 1600pm

Person Contacted:

Edward

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

G8D 7032S - X

YM 7721S - NA / MSH15016237 / 02

DOA: 150915

Disassemble: 20/9/2018

After repair: 25/9/2018

Surveyor: Paran

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBO 7032Sat Workshop m/s 8 PARAGONof 71, WOODLANDS AVE 10 #01-10Insured: CTI / PRS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBO 7032S Yr Regn: 2015 / Mar 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV 200 1.5L c.c 1461Colour: WHITE A/C: Insured / Std / NI / NASp.Reading: 159422 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: USKY BAM 2020093368

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAX

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/05/08 D.O.I. 19/05/08Survey held at 8 PARAGON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Estimated repair range \$6,000 - \$7,000.</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2Survey Fee: 150

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

150Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		18 Sep 2018 16:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		[Created by insurer]							
Main Claimant:		THE CAKE SHOP PTE LTD							
Vehicle Reg. No.:		GBD7032S							
Claim Type:		Date of Loss:	15/09/2018 00:00 - :59						
Vehicle Reg. No. (Insured):		Policy/Cover Note No.:	DMCVSN3053961800						
		Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:		8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]							
Adj Asg. Remarks:		NO EST, CASE W/O SJE.							
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3068N
Vehicle Details	
Vehicle No.:	GBD7032S
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	K9KC400D054244
Chassis No.:	VSKYBAM20Z0093368
Maximum Power Output:	-
Open Market Value:	\$20,544.00
Original Registration Date:	11 Mar 2015
First Registration Date:	11 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$1,028.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,365.00
COE Rebate Amount:	\$15,640.00
Total Rebate Amount:	\$15,640.00

The information contained herein is correct as at 09 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Sep 2018		18 Sep 2018 16:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div style="border: 1px solid black; padding: 5px;"> <div style="display: flex; justify-content: space-between;"> CLAIM SUBFOLDER DETAILS [Created by insurer] </div> <div style="display: flex;"> <div style="flex: 1;"> <p>Insured: -, Co. Reg. No.: -</p> <p>Main Claimant: THE CAKE SHOP PTE LTD</p> <p>Vehicle Reg. No.: GBD7032S</p> <p>Claim Type: TP / SNM18D04520C02</p> <p>Vehicle Reg. No. (Insured): YM7721S</p> <p>Repairer: 8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:</p> <p>Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</p> <p>Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/09/2018]</p> <p>Adj Asg. Remarks: NO EST, CASE W/O SJE.</p> </div> <div style="flex: 1; border-left: 1px solid black; padding-left: 5px;"> <p>Date of Loss: 15/09/2018 00:00 - :59 [42 Months and 4 Days From LTA Reg Date (Man Yr)]</p> <p>Policy/Cover Note No.: DMCVSN3053961800</p> <p>Policy No. (Claimant):</p> <p>Excess: S\$0.00</p> </div> </div> </div>																								
<div style="border: 1px solid black; padding: 5px;"> ASSOCIATED MAIL RECEIVED View All Compose Case Mail <p>There are no mail for this case.</p> </div>																								
<div style="border: 1px solid black; padding: 5px;"> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*GBD7032S (SNM18D04520C02)
[YM7721S]

TP
THE CAKE SHOP PTE LTD
Sep 15 2018 12:00AM
[-]
8 Paragon Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 13:00	General View	Load PDF	
2	09/10/18 13:00	Photographs of Damaged Parts	Load PDF	
3	09/10/18 13:01	Photo After Spray	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/09/18 16:20	PRS	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017015/R1CBE2

Date: 16/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3053961800

Claimant Vehicle
No : GBD7032SInsured Vehicle
No : YM7721S

Date of Loss: 15/09/2018

Nature of Claim: TP

Claim
No: SNM18D04520C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD7032S**Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR
EURO 5 (M)

Engine No: K9KC400D054244

Reg. Date: 11/03/2015 (Man. Year: 2014)

Chassis No: VSKYBAM20Z0093368

Colour: White

Odometer: 199422 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: T-Surmax 6 mm

Rear Left Side: T-Surmax 6 mm

Front Right Side: T-Surmax 6 mm

Rear Right Side: T-Surmax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/09/2018

Date Inspected: 19/09/2018 Inspected At:

 8 Paragon Pte Ltd (HQ)
 71 WOODLANDS AVE 10 #01-10
 WOODLANDS INDUSTRIAL XCHANGE
 Singapore 737743

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Oct 2018)	
Parts:	N/A	NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7032S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >