

23/03/2002

ASS. REC. BY:

REF:

CS/SMD18017027/Ag bn2

Special Instruction:

Surveyor
Merrin

ASSIGNMENT (Office)

From (Person):

Agnes Chan

of

SMD

Date/Time:

18/03/18 8:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 1802E

Insured:

GBB 4391K

at Workshop m/s

People's Vehicle

Tel:

of

Blk 3023A Ubi Rd 1 #01-60

Policy No:

D18MTPCVE000488

Claim No:

CMTD1804022

Sum Insured:

Excess:

D.O.A.

14-07-2018

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'WP'

Date/Time:

18/03/18 9:40am

Person Contacted:

Janet

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Ref: 14/03/18
	GBH 1802E - NA/CCL18016946/24	
	GBB 4391K - X	
24/4/18 @	12.20pm Informed Agnes Chan, we are pending estimate from repairer.	
12/11/18 @	3.30pm revised to Agnes Chan via Merrin.	
	Final Est @ 3148.20, 4 days. (Fed @ 1732.67, 35%.)	

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH1802E.

Yr Regn:

2018, March.

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Suzuki Every

c.c 658

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

9677

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

DA17N262984

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

145/80R12

R:

145/80R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

19/08/18

Survey held at

People

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Somp

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/11/18 Train

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

MER-TP

3148.20

250

10

260

11/12/2018

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 12 Nov 2018

Preliminary Advice

Insured Vehicle No	: GBB4391K	Accident Date	: 14/09/2018
TP Vehicle No	: GBH1802E	Assignment Date	: 18/09/2018
Make	: SUZUKI EVERY PC	Est. Duration of Repair	: 4.00
Date of Inspection	: 19/09/2018		
Inspection At	: PEOPLE'S VEHICLE RECOVERY SERVICE (HQ) BLK 3023A UBI RD 1, #01-60 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	4,880.87
Revised Amount	:S\$	3,148.21
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,148.21
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		18 Sep 2018 08:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SOLIDHEAT INDUSTRIES PTE LTD, Co. Reg. No.: 199600725C								
Main Claimant:	OPENSOFT PTE LTD, Co. Reg. No.: 200612880H								
Vehicle Reg. No.:	GBH1802E	Date of Loss:	14/09/2018 12:00 - :59						
Claim Type:	TP / CMTD1804022	Policy/Cover Note No.:	D18MTPCVE000488 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBB4391K	Policy No. (Claimant):							
		Excess:							
Repairer:	People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60, 408717 Ubi - Tel: 67433246								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]								
Driver/Custodian (Insured):	LEE KAH CHYE (), NRIC: S1255083I, Tel: +6598539287								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> SOMPO_SG (18/09/2018): TP SURVEY 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 24 September 2018 12:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GBH 1802E (YOUR REF: CMTD1804022)

This mail is associated with :
***GBH1802E (CMTD1804022)**
[GBB4391K]
TP
OPENSOFT PTE LTD
Sep 14 2018 12:00PM
[SOLIDHEAT INDUSTRIES PTE LTD]
People's Vehicle Recovery Service

Dear Agnes,

Please be informed that we have inspected the vehicle GBH 1802E on 19/09/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2880H

Vehicle Details

Vehicle No.:	GBH1802E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2018
Vehicle Make:	SUZUKI
Vehicle Model:	EVERY PC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	R06A2154198
Chassis No.:	DA17V262984
Maximum Power Output:	-
Open Market Value:	\$13,411.00
Original Registration Date:	06 Mar 2018
First Registration Date:	06 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$671.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	05 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,791.00
COE Rebate Amount:	\$28,673.00
Total Rebate Amount:	\$28,673.00

The information contained herein is correct as at 12 Nov 2018

OK

Sumner copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/09/2018 14:42
Date Of Accident 14/09/2018 12:00
Exact Location Of Accident ALONG WOODLANDS LINK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH1802E
Insured/Policyholder
Name Of Registered Owner M/S OPENSOFT PTE LTD
Co Reg No 200612880H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91463320
Alternative Phone No OFFICE-91463320

Vehicle Particulars

Manufacturer SUZUKI
Model EVERY PC
Exact Purpose for which vehicle was being used at time of accident WORKING
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMCVSN1807391800
Cover Note Number

Driver

Name of Driver TAN CHIN HIN
NRIC No S0106216F
Date Of Birth 14/02/1954
Occupation OUTDOOR
Date Of Driving Pass 16/07/1975
Driving Experience 43 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-85107528
Fax Number
Contact Number OFFICE-85107528
EMail Address NOEMAIL

Address BLK 113 PASIR RIS STREET 11
 #12-673
 Postcode 510113
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB4391K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LEE KAH CHYE
 NRIC/Passport Number S1255083I
 Contact Number 98539287
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

المجلس الوطني

A. ADAMS

5. 在图中画出

1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68-69-70-71-72-73-74-75-76-77-78-79-80-81-82-83-84-85-86-87-88-89-90-91-92-93-94-95-96-97-98-99-100-101-102-103-104-105-106-107-108-109-110-111-112-113-114-115-116-117-118-119-120-121-122-123-124-125-126-127-128-129-130-131-132-133-134-135-136-137-138-139-140-141-142-143-144-145-146-147-148-149-150-151-152-153-154-155-156-157-158-159-160-161-162-163-164-165-166-167-168-169-170-171-172-173-174-175-176-177-178-179-180-181-182-183-184-185-186-187-188-189-190-191-192-193-194-195-196-197-198-199-200-201-202-203-204-205-206-207-208-209-210-211-212-213-214-215-216-217-218-219-220-221-222-223-224-225-226-227-228-229-230-231-232-233-234-235-236-237-238-239-240-241-242-243-244-245-246-247-248-249-250-251-252-253-254-255-256-257-258-259-260-261-262-263-264-265-266-267-268-269-270-271-272-273-274-275-276-277-278-279-280-281-282-283-284-285-286-287-288-289-290-291-292-293-294-295-296-297-298-299-300-301-302-303-304-305-306-307-308-309-310-311-312-313-314-315-316-317-318-319-320-321-322-323-324-325-326-327-328-329-330-331-332-333-334-335-336-337-338-339-340-341-342-343-344-345-346-347-348-349-350-351-352-353-354-355-356-357-358-359-360-361-362-363-364-365-366-367-368-369-370-371-372-373-374-375-376-377-378-379-380-381-382-383-384-385-386-387-388-389-390-391-392-393-394-395-396-397-398-399-400-401-402-403-404-405-406-407-408-409-410-411-412-413-414-415-416-417-418-419-420-421-422-423-424-425-426-427-428-429-430-431-432-433-434-435-436-437-438-439-440-441-442-443-444-445-446-447-448-449-450-451-452-453-454-455-456-457-458-459-460-461-462-463-464-465-466-467-468-469-470-471-472-473-474-475-476-477-478-479-480-481-482-483-484-485-486-487-488-489-490-491-492-493-494-495-496-497-498-499-500-501-502-503-504-505-506-507-508-509-510-511-512-513-514-515-516-517-518-519-520-521-522-523-524-525-526-527-528-529-530-531-532-533-534-535-536-537-538-539-540-541-542-543-544-545-546-547-548-549-550-551-552-553-554-555-556-557-558-559-560-561-562-563-564-565-566-567-568-569-570-571-572-573-574-575-576-577-578-579-580-581-582-583-584-585-586-587-588-589-590-591-592-593-594-595-596-597-598-599-600-601-602-603-604-605-606-607-608-609-610-611-612-613-614-615-616-617-618-619-620-621-622-623-624-625-626-627-628-629-630-631-632-633-634-635-636-637-638-639-640-641-642-643-644-645-646-647-648-649-650-651-652-653-654-655-656-657-658-659-660-661-662-663-664-665-666-667-668-669-670-671-672-673-674-675-676-677-678-679-680-681-682-683-684-685-686-687-688-689-690-691-692-693-694-695-696-697-698-699-700-701-702-703-704-705-706-707-708-709-710-711-712-713-714-715-716-717-718-719-720-721-722-723-724-725-726-727-728-729-730-731-732-733-734-735-736-737-738-739-740-741-742-743-744-745-746-747-748-749-750-751-752-753-754-755-756-757-758-759-760-761-762-763-764-765-766-767-768-769-770-771-772-773-774-775-776-777-778-779-780-781-782-783-784-785-786-787-788-789-790-791-792-793-794-795-796-797-798-799-800-801-802-803-804-805-806-807-808-809-810-811-812-813-814-815-816-817-818-819-820-821-822-823-824-825-826-827-828-829-830-831-832-833-834-835-836-837-838-839-840-841-842-843-844-845-846-847-848-849-850-851-852-853-854-855-856-857-858-859-860-861-862-863-864-865-866-867-868-869-870-871-872-873-874-875-876-877-878-879-880-881-882-883-884-885-886-887-888-889-890-891-892-893-894-895-896-897-898-899-900-901-902-903-904-905-906-907-908-909-910-911-912-913-914-915-916-917-918-919-920-921-922-923-924-925-926-927-928-929-930-931-932-933-934-935-936-937-938-939-940-941-942-943-944-945-946-947-948-949-950-951-952-953-954-955-956-957-958-959-960-961-962-963-964-965-966-967-968-969-970-971-972-973-974-975-976-977-978-979-980-981-982-983-984-985-986-987-988-989-990-991-992-993-994-995-996-997-998-999-1000-1001-1002-1003-1004-1005-1006-1007-1008-1009-1010-1011-1012-1013-1014-1015-1016-1017-1018-1019-1020-1021-1022-1023-1024-1025-1026-1027-1028-1029-1030-1031-1032-1033-1034-1035-1036-1037-1038-1039-1040-1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to statement

DECLARATION

DECLARATION
I/We declare that foregoing particulars are true in every respect.



Policyholders Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Sketch Plan

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY PARKED ON THE PARKING LOT OF WOODLANDS LINK. I COME BACK FROM LUNCH AND REALIZE THAT VEHICLE B REVERSED AND HIT ONTO MY VEHICLE FRONT PORTION.

> Back to OneMotoring

Stow 6329 5170 / 6461 6555



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 17 Sep 2018 / 17:00:21

Receipt Date/Time : 17 Sep 2018 / 17:00:21

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180917-001809

Previous Receipt No. :

S/N Item Description/

Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GBB4391K

As at 14 Sep 2018/12:00:00

Insurance Co; SOMPO INSURANCE SINGAPORE PTE. LTD.

1 Insurance Enquiry - GBB4391K

Enquiry Fee

20180917165924503231

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

20180917165938874 Direct Debit: eNETS Debit
(Internet Banking)

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
Tel No. : 67433246/ 67438552 Fax No. : 67430013
E-Mail : peoplevehicle@gmail.com
Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #05-01/08
S'PORE LAND TOWER 048623

Attention : Motor Claim Department
Contact : 6461 6555 Fax No. : 6221 3147

Estimate : ES18039

Date : 17/09/2018
Vehicle Num. : GBH 1802 E
Make/Model : SUZUKI EVERY
Chassis/Eng# :
Accident Date : 14/09/2018
Claim No. : TP 316-18
Reference : GBB 4391 K
Policy No. : CHINA DMCVSN1807391800

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BONNET <i>Painted</i>		652.00 ✓
2.	1	BONNET LOGO <i>new</i>		64.20 ✓
3.	1	BONNET LOCK <i>new</i>		56.20 ✓
4.	2	HEAD LAMP <i>Crushed</i>	2727.30	1,240.80 ✓
5.	1	BUMPER FRT <i>Painted</i>		770.30 ✓
6.	1	SUPPORT PANEL FRT <i>Not new</i>	2318.20	558.70 ✓
List Total S\$:				3,342.20
15.00% Discount S\$:				501.33
				2,840.87
LABOUR :				
REMOVE & REPLACE ACCIDENT DAMAGED PARTS			830	900.00 ✓
SPRAY PAINTING ACCIDENT EFFECT PARTS				800.00 ✓
REMOVE & REPLACE RADIATOR				120.00 ✓
REMOVE & REFIX AIR CON CONDESNER AND GAS				160.00 ✓
CHECKING WIRING				60.00 ✓
Labour Total S\$:				2,040.00

SingDollars : Four Thousand Eight Hundred Eighty & Cents Eighty-Seven Only

E. & O.E. Total S\$: 4,880.87

LKK Auto Consultants hence notify
the Repairer of the following:

PEOPLE'S VEHICLE RECOVERY SERVICE

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

total: 314820
CP/P)

Adrian Lim
P/P 19/09/18
04 Aug.

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017027/AQBN2
Date: 13/11/2018

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd.
Claimant Vehicle No: GBH1802E
Date of Loss: 14/09/2018
Policy No: D18MTPCVE000488
Insured Vehicle No: GBB4391K
Nature of Claim: TP
Claim No: CMTD1804022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH1802E
Make & Model: SUZUKI EVERY, 658cc GA (A)
Reg. Date: 06/03/2018 (Man. Year: 2017)
Colour: White
Engine Capacity: 658 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price
Engine No: R06A2154198
Chassis No: DA17V262984
Odometer: 9677 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes
Handbrake (Serviceable): Yes
Steering (Serviceable): Yes
Engine Modification: No
Footbrake (Serviceable): Yes
Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 145/80 R12
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Tyre Size: 145/80 R12
Rear Left Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,840.87	2,318.20	522.67	18.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	830.00	1,210.00	59.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,880.87	3,148.20	1,732.67	35.50
+ GST 7.00/7.00% (S\$)	341.66	220.37	121.29	35.50
Nett Amount (S\$)	5,222.53	3,368.57	1,853.96	35.50

INSPECTION

Date of Assignment: 18/09/2018
Date Inspected: 19/09/2018 Inspected At: People's Vehicle Recovery Service (HQ)
Blk 3023A Ubi Rd 1, #01-60
Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Nov 2018)
 Parts: N/A SUZUKI EVERY 658cc GA (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBH1802E)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	652.00 FL	*652.00 FL
2	1		*BONNET LOGO	Necessary	64.20 FL	*64.20 FL
3	1		*BONNET LOCK	Not Necessary	56.20 FL	*- FL
4	2		*HEAD LAMP	Cracked	1,240.80 FL	*1,240.80 FL
5	1		*BUMPER FRT	Deformed	770.30 FL	*770.30 FL
6	1		*SUPPORT PANEL FRT	Not Necessary	558.70 FL	*- FL
Sub Total (S\$)					3,342.20	2,727.30
- List Item Discount on L Items 15.00/15.00% (S\$)					501.33	409.10
Total Parts (S\$)					2,840.87	2,318.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	900.00	400.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	800.00	400.00
3	REMOVE & REPLACE RADIATOR	New	120.00	-
4	REMOVE & REPLACE AIR CON CONDENSER AND GAS	New	160.00	-
5	CHECKING WIRING	New	60.00	30.00
Gross Labour Cost (S\$)			2,040.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >