

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18017041/Gcd3k

Special Instruction:

Surveyor: (Quo Giong)

ASSIGNMENT (Office)

From (Person): Mehen

of MSIG

Date/Time: 19/9/18 @ 10:06am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 2036 R

Insured:

SLT 5507A

at Workshop m/s

EK 52 Auto

Tel:

9373 5378

of

1 Kaki Bkt Ave 6 # 01-53

Policy No:

129043854AVW

Claim No:

570582

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/09/2008

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:24am @ 19/9/18

Person Contacted:

Koey

Vehicle:

☒ IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJS 2036R - NA / GAI 17024285/24
	SLT 5507A - X
	Dismantle: 21/9/2018

DOA: 21/12/17

DATE

MSL  
xhl.

REF: MS19

C8058K

# ASSIGNMENT

From: Date: 19109118

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SJS 2036R

at Workshop m/s EK 52 AUTO

of 1 kak: Bkt Ave 6 #01-53

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Koey 9373 5378

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$16k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. 1-24 HRS 'up'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS 2036R

Yr Regn:

(-2019)  
01 Aug 2019

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan latio

G.C

1498

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

1845901

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1FAAC11Z0010780

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19-08-18

Survey held at

w/s

5:10pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

120

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

10

130

Report Format:

PREL.

Lump Sum / I.B.I: (\$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18017041/Gcd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 19-09-2018		
		Code : MSG		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLT 5507A	Veh. Inspected	SJS 2036R	
Policy No.	A29043854AVW	Coverage (\$)	0.00	
Claim No.	570532	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	19/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	09/09/2018	Inspection Date	19/09/2018	
Survey held at	EK 52 AUTO- 1 KAKI BUKIT AVE 6#01-53			
Repairer	-			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Sep 2018		19 Sep 2018 10:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>GREEN ENGINEERING &amp; CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201009623R		
Main Claimant:	<b>AIMZ AUTOMOBILE PTE LTD</b> , Co. Reg. No.: 208708058K		
Vehicle Reg. No.:	<b>SJS2036R</b>	Date of Loss:	09/09/2018 13:00 - :59 [109 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 570532</b>	Policy/Cover Note No.:	A29043854AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
Vehicle Reg. No. (Insured):	<b>SLT5507A</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Ek52 Auto Pte Ltd (HQ)</b> 1 KAKI BUKIT AVENUE 6, #01-53 BLK C AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 9373 5378		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 20/09/2018]		
Driver/Custodian (Insured):	MOHAMED HUSSAIN BASHEER AHMED (), NRIC: S7484181C, Tel: +6590267357		
Adj Asg. Remarks:	Liability 50%. Contact Person: Koey Goh / 9373 5378. TP disagree with our SJE list, proceed to appoint LKK.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	8058K

### Vehicle Details

Vehicle No.:	SJS2036R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO SPORT BASE 1.5L AT ABS D/AB 2WD 5D
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	HR15155983B
Chassis No.:	JN1FAAC11Z0010780
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,485.00
Original Registration Date:	01 Aug 2009
First Registration Date:	01 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$17,485.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2019
PARF Rebate Amount:	\$8,742.00

### Intended COE Rebate Details

COE Expiry Date:	31 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$1,319.00
<b>Total Rebate Amount:</b>	<b>\$10,061.00</b>

The information contained herein is correct as at 20 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/09/2018 15:22
Date Of Accident	09/09/2018 13:10
Exact Location Of Accident	TPE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2036R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AIMZ AUTOMOBILE PTE LTD
Co Reg No	208708058K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97907430
Alternative Phone No	OFFICE-97907430

### Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097355975
Cover Note Number	

### Driver

Name of Driver	THNG ENG CHONG
NRIC No	S7316458C
Date Of Birth	08/05/1973
Occupation	OUTDOOR
Date Of Driving Pass	24/01/1998
Driving Experience	20 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97885050
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	2 SIMS DRIVE #17-05
Postcode	S387388
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

ON THE STATED DATE AND TIME AT THE STATED VENUE, I VEHICLE A SJS2036R WAS TRAVELLING STRAIGHT ON MY RIGHTFUL LANE. VEHICLE B SLT5507A FROM THE LEFT LANE CUT INTO MY LANE JAMMED BRAKE ABRUPTLY INFRONT OF MY VEHICLE CAUSING THE COLLUSION

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT5507A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN → TPE towards Changi




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time at the stated venue,  
 I vehicle 'A' SJS 2036R was travelling straight on my  
 rightful lane. Vehicle 'B' SLT 5507A from the left lane  
 cut onto my lane jammed brake abruptly in front  
 of my vehicle causing the collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



AIMZ AUTOMOBILE PTE LTD

Policyholder's Signature

Date & Time:

*[Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MSME 18117154 Vehicle Registration No: SJS 2036 R  
Name (as shown in NRIC) : Thng Eng Chong NRIC/FIN/Passport No : S 7316458C  
(\*Vehicle Driver / ~~Vehicle Owner~~)(\*) Please delete as appropriate  
Address : 2 Sims Drive #17-05 Singapore ( 387386 )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 9788 5050  
Email Address : togetheride@gmail.com  
Date of Accident : 09/09/2018 Time of Accident : 1310 hrs  
Place of Accident : TPE towards Changi  
Insurance Company : Ntuc

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Passenger - Male

Was injured in the accident and given 7 days mc  
at Singapore General Hospital.

\_\_\_\_\_  
Policyholder / Driver's Signature  
Date:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Sep 2018		19 Sep 2018 10:06 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>GREEN ENGINEERING &amp; CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201009623R									
Main Claimant: <b>AIMZ AUTOMOBILE PTE LTD</b> , Co. Reg. No.: 208708058K									
Vehicle Reg. No.: <b>SJS2036R</b>		Date of Loss: 09/09/2018 13:00 - :59 [109 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 570532</b>		Policy/Cover Note No.: A29043854AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018							
Vehicle Reg. No. (Insured): <b>SLT5507A</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ek52 Auto Pte Ltd (HQ)</b> 1 KAKI BUKIT AVENUE 6, #01-53 BLK C AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 9373 5378									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 20/09/2018]									
Driver/Custodian (Insured): <b>MOHAMED HUSSAIN BASHEER AHMED ()</b> , NRIC: S7484181C, Tel: +6590267357									
Adj Asg. Remarks: Liability 50%. Contact Person: Koey Goh / 9373 5378. TP disagree with our SJE list, proceed to appoint LKK.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJS2036R (570532)  
[SLT5507A]  
TP  
AIMZ AUTOMOBILE PTE LTD  
Sep 9 2018 1:00PM  
[GREEN ENGINEERING & CONSTRUCTION PTE LTD]  
Ek52 Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
17	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
18	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
19	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
20	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
21	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
22	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
23	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
24	20/09/18 11:34	General View						 Load JPG	<input checked="" type="checkbox"/>	
25	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
26	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
27	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
28	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
29	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
30	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
31	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
32	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
33	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
34	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
35	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
36	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
37	24/09/18 18:34	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 18:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/18 10:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017041/GCD3E2

Date: 10/10/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29043854AVW

Claimant Vehicle No : SJS2036R

Insured Vehicle No : SLT5507A

Date of Loss: 09/09/2018

Nature of Claim: TP

Claim No: 570532

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJS2036R

Make &amp; Model: NISSAN LATIO, 1.5 Sports (A)

Engine No: HR15155983B

Reg. Date: 01/08/2009 (Man. Year: 2009)

Chassis No: JN1FAAC11Z0010780

Colour: Red

Odometer: 145901 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/09/2018

Date Inspected: 19/09/2018 Inspected At:

Ek52 Auto Pte Ltd (HQ)  
1 KAKI BUKIT AVENUE 6, #01-53 BLK C  
AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

## REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2018)
Parts:	144	NISSAN LATIO 1.5 Sports (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2036R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >