

**VAC AUTO CENTRE PTE LTD** UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Mailing: Bukit Panjang Post Office PO Box 180 Singapore 916806

Tel: 6636 5355 / 9371 6639 / 9371 6693 | Fax: 6636 5355

Regn No : SGV9998M

Vehicle Make/Model : Volvo S60 T4

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
List Items:				
1	Front Bumper <i>do/torn</i>	1	\$ 1,950.00	\$ 1,950.00 ✓
2	Front Bumper Tow Cover <i>To-n</i>	1	\$ 36.00	\$ 36.00 ✓
3	Front Bumper Lamp - RH <i>one</i>	1	\$ 245.00	\$ 245.00 ✓
4	Front Bumper Lower Grille <i>11</i>	1	\$ 102.00	\$ 102.00 ✓
5	Front Bumper Lower Spoiler <i>11</i>	1	\$ 850.00	\$ 850.00 ✓
6	Front Bumper Side Grille - RH <i>11</i>	1	\$ 115.00	\$ 115.00 ✓
7	Front Bumper Inner <i>Spoiler NF</i>	1	\$ 136.00	\$ 136.00 ✓
8	Front Bumper Inner Frame Pad <i>270-1</i>	1	\$ 189.00	\$ 189.00 ✓
9	Front Bumper Reinforcement <i>270-1</i>	1	\$ 765.00	\$ 765.00 ✓
10	Front Bumper Side Retainers <i>o/s Bent</i>	2	\$ 45.00	\$ 90.00 ✓
11	Front Bumper Clips <i>one</i>	10	\$ 5.00	\$ 50.00 ✓
12	Front Headlamp - RH <i>one</i>	1	\$ 1,855.00	\$ 1,855.00 ✓
13	Front Headlamp Lower Bracket <i>11</i>	1	\$ 65.00	\$ 65.00 ✓
14	Front Grille Assembly <i>one</i>	1	\$ 895.00	\$ 895.00 ✓
			Sub-total	\$ 7,343.00
			Less 5%	\$ 367.15
			List Items Total	\$ 6,975.85

Special Nett Items:

1	Rear Number Plate with holder <i>11</i>	1	\$ 60.00	\$ 60.00 ✓
			S/Nett Items Total	\$ 60.00

Labour Charge Items:

1	To checking front electrical wiring		\$ 50.00	20
2	To respray painting & etc		\$ 500.00	400
3	Panel beating, cut, weld, remove and replacing above parts		\$ 500.00	400
			Labour Charge Total	\$ 1,050.00

Estimate Parts & Labour**Grand total \$ 8,085.85**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
Here
d/s 400
19/9/18
The del. the repairer