

ASS. REC. BY:

REF:

C93 / III 18017051 / Ricber

Special Instruction:

Surveyor:

Ragyl

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

11-12-2018 857am

Estimated Cost:

Bill to:

~~OD~~ / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SW 5509M

Insured:

SFF 8583D

at Workshop m/s

Miracle Works

Tel:

of

48 Toh Guan Rd East #04-126

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13092018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

11-12-2018 1034am

Person Contacted:

Nicole

Vehicle ~~IN~~ / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SW 5509M - C93 / FCL18017051 / Ricber
	SFF 8583D - NA / INC15011615 / d2
	Dismantle: 12/12/2018 @ 5pm.

DOA: 30122017

DOA: 10072015

GUYANA

Roue

REF:

4370C

## ASSIGNMENT

EXP EXPIRY: 2027/July

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGW 5509M

at Workshop m/s MIRACLE WORKZ

of 48, TOL LUNAR RD GOS # 04-126

Insured: III / PRS

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGW 5509M

Yr Regn: 2007 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA S2000 2.2M C.C. 2156

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 119234 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AP 21001878

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/09/18 D.O.I. 12/12/18 @ 9.52am

Survey held at MIRACLE WORKZ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: PRS

Lump Sum / I.B.I. (\$)

TOTAL

120

10

130

## Catherine Chong (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 11 December, 2018 8:57 AM  
**To:** Lheny; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** C Meenachi - III  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGW5509M(Accident involving SGW5509M and SFF8583D on 13.09.2018)  
**Attachments:** sff8583d\_20181210163158.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SGW5509M  
III INSURED VEHICLE NO. : SFF8583D  
DATE OF LOSS : 13.09.18

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Meena**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**  
**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Lheny [mailto:lheny@yoga-legal.com]  
**Sent:** 10 December, 2018 4:58 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGW5509M(Accident involving SGW5509M and SFF8583D on 13.09.2018)

**WITHOUT PREJUDICE**

Dear Sirs

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC  
883 North Bridge Road  
#19-05 Southbank  
Singapore 198785

Tel: 6292 5838  
Fax: 6292 5938

Email: [lheny@yoga-legal.com](mailto:lheny@yoga-legal.com)

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Monday, 10 December, 2018 4:42 PM

**To:** Lheny

**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. SGW5509M(Accident involving SGW5509M and SFF8583D on 13.09.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



883 North Bridge Road  
#11-03 Southbank  
Singapore 198785  
T: 6292 5838  
F: 6292 5938  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.SGW5509M.18.MW(HW).wp(Lh)

Your Ref : Your Insured vehicle SFF 8583D

19 September 2018

10 DEC 2018

**REMINDER**

**YEO ENG KIAT**

c/o The Motor Claims Department  
**India International Insurance Pte Ltd**  
64 Cecil Street #04/#05 IOB Building  
Singapore 049711

**BY Fax No: 6224 4174**

**URGENT**


Dear Sirs


**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGW 5509M & SFF 8583D ON 13.09.2018 @ 22:00HRS ALONG BLOCK 223 YISHUN ST 21 OSCP**

We are instructed by TAN SIEW HOON PAULINE to notify you of a road traffic accident on 13.09.2018 @ 22:00hrs involving our client's customer's vehicle registration number SGW 5509M and vehicle registration number SFF 8583D driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
**C. Yogarajah LLC**  
Enc



Cc: M/s. Miracle Works Pte Ltd  
48 Toh Guan Road East  
#04 - 126 Enterprise Hub  
Singapore 608586  
Nicole (82045858 / 96472568 / 64683096)  
Fax no : 6515 5434

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimer: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4370C
<b>Vehicle Details</b>	
Vehicle No.:	SGW5509M
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	S2000 2.2 M
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	F22C1001885
Chassis No.:	AP21001878
Maximum Power Output:	178.0 kW (238 bhp)
Open Market Value:	\$37,909.00
Original Registration Date:	23 Jul 2007
First Registration Date:	23 Jul 2007
Transfer Count:	0
Actual ARF Paid:	\$41,700.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Jul 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,473.00
COE Rebate Amount:	\$44,870.00
<b>Total Rebate Amount:</b>	<b>\$44,870.00</b>

The information contained herein is correct as at 03 Jan 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/09/2018 15:11
Date Of Accident	13/09/2018 22:00
Exact Location Of Accident	BLK 223 YISHUN ST 21 OSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGW5509M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN SIEW HOON PAULINE
NRIC No	S7424370C
Email Address	PAULINETAN@STAFFINGNETWK.COM
Mobile Phone No	(LOCAL) +65-97651987
Alternative Phone No	OTHERS-96999665
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	S2000-2.2 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA257513
Cover Note Number	23/07/2018 - 22/07/2019
<b>Driver</b>	
Name of Driver	ON SHAW MING
NRIC No	S7714070J
Date Of Birth	07/05/1977
Occupation	INDOOR
Date Of Driving Pass	05/01/2004
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96999665
Fax Number	
Contact Number	OTHERS-97651987
Email Address	ONFERRE@GMAIL.COM

Address	BLK 223 YISHUN ST 21 #09-475
Postcode	760223
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFF8583D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15/09/18  
1042

  
Reporting Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

Date of accident: 130918 Time: 2200hrs Location: Blk 223 Yishun St 21 OSEP  
 My Vehicle A: SGW 5509 M Vehicle B: SFF 8583D Vehicle C: \_\_\_\_\_  
 SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

which was  
 On 130918 at about 2200hrs, my car is parked at Yishun St 21 carpark, just next to Blk 223 got hit by another car, vehicle B. I was not inside the car, vehicle A.  
 On 140918 in the morning when I got into my car, I realized there was damage and my in-car camera prompted me of an accident. I also found a note on my windscreen stating that the driver had accidentally hit my car and would like to request for private mutual settlement.  
 I called AXA to report and subsequently went to the authorised workshop Ah Lim Motors to provide details.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: onferie@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 15/09/18  
 10001072

Reporting Personnel's Signature  
 Name:  
 NRIC/FIN No.:



AH LIM MOTOR COMPANY

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jan 2019 15:48 <a href="#">Edit Reg</a>		11 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>TAN SIEW HOON PAULINE</b> , ID: S7424370C								
Vehicle Reg. No.:	<b>SGW5509M</b>	Date of Loss:	13/09/2018 22:00 - :59 [133 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SFF8583D</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Miracle Work Pte Ltd (HQ)</b> 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>C. Meenachi</b> - 6347 6073]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 07/02/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SGW5509M**  
**[SFF8583D]**  
**TP**  
**TAN SIEW HOON PAULINE**  
**Sep 13 2018 10:00PM**  
**[-]**  
**Miracle Work Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a>
<b>Photos/Images</b>		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	28/01/19 13:17	<b>General View</b>
2	28/01/19 13:17	<b>Photographs of Damaged Parts</b>
<b>Documentation</b>		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)
1	28/01/19 08:56	<b>Singapore Accident Statement</b>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<input type="button" value="v"/> <input type="button" value="v"/>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18017051/R1CBE2

Date: 28/01/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle  
No : SGW5509M

Insured Vehicle No : SFF8583D

Date of Loss: 13/09/2018

Nature of Claim:

TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGW5509M

Make &amp; Model: HONDA S2000, 2.2 (A)

Engine No: F22C1001885

Reg. Date: 23/07/2007 (Man. Year: 2007)

Chassis No: AP21001878

Colour: White

Odometer: 119234 km

Engine Capacity: 2156 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 12/12/2018 Inspected At:

Miracle Work Pte Ltd (HQ)  
48 TOH GUAN ROAD EAST #04-126  
ENTERPRISE HUB  
Singapore 608586

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
<b>Parts:</b>	M1-COUPE	HONDA S2000 2.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGW5509M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >