

22/03/2002

ASS. REC. BY:

REF:

CS3 / SMO / 8017061 / Gcd3p

Special Instruction:

Surveyor: Guo Qiang
Meimen

ASSIGNMENT (Office)

From (Person): Agnes Chan

of SMO

Date/Time: 20/9/18 @ 11:57am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 6098Z

Insured: YM 293G

at Workshop m/s MSM Logistics

Tel: 9489 6649

of 160 Sin Ming Drive # 01-12

Policy No: D18M7PCVE001327

Claim No: CMTD1803931

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 07/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 12:55pm @ 20/9/18

Person Contacted: Mr. chen

Vehicle IN / OUT

Date/Time	Action/Instruction (X)	Estimate
	PC 6098Z - X	
	YM 293G - X	
	After repair: 27/9/2018	

PRS
XSL

REF: fci


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s MSM Logistics
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PC60983 Yr Regn: Aug / 11
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota c.c. 4009
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: 213130 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JT6EP538506000320
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or _____
 Brake: Good / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/75 R17.5
 R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6/6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6/6</u> mm
D.O.A. _____	D.O.I. <u>20-09-18</u>
Survey held at <u>w/s</u>	<u>5:20pm</u>
Des. of Damages : Frt / <u>Rear</u> / O/S / N/S / U/C / Rooftop or _____	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range 6,000/- - 7,000/-</u>

RECEIVED 09 OCT 2018

[Signature]
8/10/2018

TGcim

[Signature]

5/10/18

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation: 100

Photos: 60

Others: 10

TOTAL

100
60
10
170

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : PRS

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		20 Sep 2018 11:57 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KEPPEL CONTAINER LINE PTE LTD, Co. Reg. No.: -								
Main Claimant:	MSM LOGISTICS PTE LTD								
Vehicle Reg. No.:	PC6098Z	Date of Loss:	07/09/2018 11:00 - :59						
Claim Type:	TP / CMTD1803931	Policy/Cover Note No.:	D18MTPCVE001327 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	YM293G	Policy No. (Claimant):							
		Excess:							
Repairer:	- Not Applicable - (-)								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/10/2018]								
Driver/Custodian (Insured):	YAP SOON HENG (), NRIC: S1575425G, Tel: +6583062618								
Adj Asg. Remarks:	Kindly refer to TPPD Pre-Repair document for location and contact.								
ASSOCIATED MAIL RECEIVED <input type="button" value="View All"/> <input type="button" value="Compose Case Mail"/>									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="button" value="View All"/> <input type="button" value="Search Tasks"/> <input type="button" value="Create New Task"/> <input type="button" value="Complete"/>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Henry, Irene James

From: Natalie Ng <natalie_ng@rssolomon.com>
Sent: Thursday, 20 September, 2018 11:40 AM
To: Henry, Irene James
Cc: Chan, Shu Hui Agnes; khian hen Chen
Subject: Re: FW: SOMPO REF: CMTD1803931/ YR RE: RSS / 1809 - 43u (Y L) (P D)
Attachments: image001.jpg

Dear Ms Irene,

We thank you for your email of 19th September 2018.

We are pleased to inform that our client wish to appoint LKK Auto Consultants as the SJE.

Kindly arrange the Surveyor to contact Mr. Chen of MSM Logistics Pte Ltd at mobile no. 94896649 (1st prior) /91074212 for a pre-repair survey of our clients' vehicle located at No. 160 Sin Ming Drive #01-12 Sin Ming Autocity Singapore 575722.

Best Regards,

Natalie Ng | Office Manager 人事与行政经理



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

R. S. Solomon LLC | 正氣律師事務所

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | **Branch:** Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e natalie_ng@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

On Wed, 19 Sep 2018 at 17:35, Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference : CMTD1803931

Your Reference: RSS / 1809 - 43u (Y L) (P D)

Without Prejudice

Date: 19TH September 2018

Attention:

M/S R.S SOLOMON LLC

Dear Sirs,

ACCIDENT INVOLVING PC 6098Z & YM 293G ON 9TH SEPTEMBER 2018

We refer to your Notice of Accident via email dated 19/09/2018.

Please be informed that Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS3/FCI18017061/Gcd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-09-2018	
		Code : FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YM 293G	Veh. Inspected	PC 6098Z
Policy No.	D18MTPCVE001327	Coverage (\$)	0.00
Claim No.	CMTD1803931	Excess (\$)	0.00
Assign From	MERIMEN (AGNES CHAN)	Assign Date	19/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/09/2018	Inspection Date	19/09/2018
Survey held at	160 SIN MING DRIVE #01-12		
Repairer	MSM LOGISTICS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	PC6098Z		
Vehicle Type:	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1:	Air-Conditioned		
Vehicle Scheme:	Public Service Vehicle (Others)		
Vehicle Make:	TOYOTA		
Vehicle Model:	COASTER SUPER LWB		
Chassis No.:	JTGEP538506000320		
Propellant:	Diesel		
Engine No.:	N04CUH14551		
Engine Capacity:	4009 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	5600 kg		
Unladen Weight:	3720 kg		
Year Of Manufacture:	2011		
Original Registration Date:	05 Aug 2011		
Lifespan Expiry Date:	04 Aug 2031		
COE Category:	C - Goods Vehicle & Bus		
Quota Premium:	\$31,089.00		
COE Expiry Date:	04 Aug 2021		
Road Tax Expiry Date:	04 Feb 2019		
Inspection Due Date:	04 Aug 2019		
Intended Transfer Date:	26 Sep 2018		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1646H
Vehicle Details	
Vehicle No.:	PC6098Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COASTER SUPER LWB
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	N04CUH14551
Chassis No.:	JTGEP538506000320
Maximum Power Output:	-
Open Market Value:	\$80,387.00
Original Registration Date:	05 Aug 2011
First Registration Date:	05 Aug 2011
Transfer Count:	2
Actual ARF Paid:	\$4,020.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,089.00
COE Rebate Amount:	\$8,883.00
Total Rebate Amount:	\$8,883.00

The information contained herein is correct as at 26 Sep 2018

OK

MLHM18119718 / Lai Hui (Meng Kee) Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 15/09/2018 09:51
 SUBMITTED BY: Poh Kwee Choo

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 17/09/2018 15:57

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/09/2018 09:51
Date Of Accident	09/09/2018 20:15
Exact Location Of Accident	OPEN SPACE HEAVY CARPARK AT SIN MING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC6098Z
Insured/Policyholder	
Name Of Registered Owner	M/S MSM LOGISTICS PTE LTD
Co Reg No	0
Email Address	KHIENHEN@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-94896649
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COASTER SUPER LWB
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMB2SN1744621801
Cover Note Number	
Driver	
Name of Driver	CHEN KHIAN HEN
Passport No/FIN	G7785187Q
Date Of Birth	16/07/1987
Occupation	OUTDOOR
Date Of Driving Pass	22/04/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94896649
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 250 JURONG EAST STREET 24
#07-138
Postcode 600250
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20180915/2029.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM293G
Vehicle Make/Model/Colour LORRY - MITSUBISHI FM657MSRDEC
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180915/2029

1 of 3

Report No. T/20180915/2029

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2018 09:36	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHEN KHIAN HEN		Address: APT BLK 250 Jurong East Street 24 #07-138 SINGAPORE 600250	
ID Type / ID No.: NRIC NO / G7765187Q		Contact No.:	Mobile: 94896649
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 31	Date of Birth: 26/07/1987	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: MANAGER		Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/09/2018 20:15	Type of Location: Car Park
Location: Along Road 1 SIN MING ROAD				
Heavy Vehicle Car Park				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC6098Z	Bus/Coach/Minibus	TOYOTA	COASTER SUPER LWB	White	Slightly Damaged	0
YM293G	Lorry	MITSUBISHI	FM657MSR DEC	White		0

POLICE REPORT Pg. 2

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999



T/20180915/2029

2 of 3

Report No. T/20180915/2029

CONTINUATION OF REPORT

Brief Details.

On 7 Sep 2018 at about 7am, I parked my company's bus (PC6098Z) at Sin Ming Road heavy vehicle car park and affirmed everything was intact.

On 9 Sep 2018 at about 8.30pm, a friend of mine (Linda, Hp: 94889005) informed me that a lorry (YM293G) had hit onto my bus. She showed me a picture of the damage as well as the lorry's plate number.

I went to make a check and discovered that my bus's rear emergency door was dented. No injury to anyone. I got to know that the lorry is from Keppel Container Line Pte Ltd.

I do not have an in car camera installed. I am lodging for insurance claim purposes.

POLICE REPORT Pg. 3



SINGAPORE
POLICE FORCE



T/20180915/2029

3 of 3

Report No. T/20180915/2029

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E /	Signature Of Informant:
Sgt 3 NUR MARISSA SYAQILA BINTE SAMSAIDI	
Signature of Interpreter: Not applicable	Date/Time: 15/09/2018 09:36
Officer in Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No.: 65476079	Classification Of Case:
Authentication Stamp NP168	

POLICE REPORT Pg. 4

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		20 Sep 2018 11:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KEPPEL CONTAINER LINE PTE LTD, Co. Reg. No.: -								
Main Claimant:	MSM LOGISTICS PTE LTD								
Vehicle Reg. No.:	PC6098Z	Date of Loss:	07/09/2018 11:00 - :59 [85 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1803931	Policy/Cover Note No.:	D18MTPCVE001327 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	YM293G	Policy No. (Claimant):							
Repairer:	- Not Applicable - (-)								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/10/2018]								
Driver/Custodian (Insured):	YAP SOON HENG (), NRIC: S1575425G, Tel: +6583062618								
Adj Asg. Remarks:	Kindly refer to TPPD Pre-Repair document for location and contact.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC6098Z (CMTD1803931)
 [YM293G]
 TP
 MSM LOGISTICS PTE LTD
 Sep 7 2018 11:00AM
 [KEPPEL CONTAINER LINE PTE LTD]

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/09/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/09/18 19:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
16	28/09/18 19:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
17	28/09/18 19:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
18	28/09/18 19:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
19	28/09/18 19:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/18 10:59	PRI FAX DT 19.9.18 FR R.S SOLOMON ALONGWITH ENCLS	Load PDF	
2	20/09/18 11:58	TPPD Pre-Repair Survey	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; padding: 5px;"> <!-- Empty text area for remarks --> </div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18017061/GCD3E2

Date: 08/11/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd.	Policy No: D18MTPCVE001327	
Claimant Vehicle No: PC6098Z	Insured Vehicle No: YM293G	
Date of Loss: 07/09/2018	Nature of Claim: TP	Claim No: CMTD1803931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC6098Z	Engine No: N04CUH14551	
Make & Model: TOYOTA COASTER, 4.0 D SUPER LWB (M)	Chassis No: JTGEP538506000320	
Reg. Date: 05/08/2011 (Man. Year: 2011)	Odometer: 213130 km	
Colour: White		
Engine Capacity: 4009 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5	Rear Tyre Size: 215/75 R17.5 (D)
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/09/2018		
Date Inspected: 20/09/2018	Inspected At:	160 SIN MING DRIVE #01-12 Repairer : MSM LOGISTICS PTE LTD
Estimated Period of Repair: 6.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Oct 2018)	
Parts:	N/A	TOYOTA COASTER 4.0 D SUPER LWB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6098Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >