

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 20 September 2018 1:19 PM
To: 'Iryani Amin'
Cc: KKLau; SUR; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 18/09/2018, SLC 7390U (TP VEHICLE), FV 8341B (OI VEHICLE)
Attachments: SLC7390 PR.pdf; SLC7390 GIA.pdf

Dear Iryani,

Please be informed that we had inspected the vehicle SLC 7390U M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883 on 19/09/2018

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2011 Mercedes Benz E-Class. E200 CGI At \$59K.

Single Owner. Low Mileage
58.4K. Very Well Maintained.
Silver With Grey Interior
Direct Owner StarAd



Browse by Category ▼





« Back (1 2 3 4 5 6 7 8) Next »

Sort by

143 vehicles

Honda Vezel

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Honda Vezel		Any	Any	2016	Any	
	Honda Vezel 1.5A X		\$70,800	\$8,400 /yr	20-Jul-2016	1,496 cc	28
	Sept 2018 Offer, \$0 Down-payment/ Can Overloan Up To \$4K / COE Car Owner Act Now PHV DEAL!!No Hidden Cost! \$0 Down. Cash Less Than \$2500. \$790 Monthly. Call Now Posted: 19-Sep-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda						
	Honda Vezel 1.5A X Honda Sensing		\$67,800	\$8,070 /yr	14-Jun-2016	1,496 cc	68
	No Need To Compare, Absolute The Best Value, 100% Accident Free. Drives And Smell Like A New Car. Most Popular Su Maintenance, High On Fuel Efficiency, Very Well Maintained By Onl... Posted: 19-Sep-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda						
	Honda Vezel 1.5A S		\$79,888	\$8,220 /yr	13-Apr-2016	1,496 cc	51
	Down Payment \$8K Only! From \$1,150 Monthly. High Scrap Value At \$17.6k! Top Dog Model For The Honda Vezels! Met Fervent Owner, Always Parked Under Shelter! No Expenses Spared On... Audax Auto Pte Ltd Posted: 19-Sep-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda						
	Honda Vezel 1.5A X		\$67,300	\$8,090 /yr	16-May-2016	1,496 cc	
	\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hi Condition! Low Mileage! Accident Free! In House Loan Or Bank ... 88 Motor Trading Posted: 19-Sep-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda						

Car Buying

Car Selling

Car Ownership

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6213Z
Vehicle Details	
Vehicle No.:	SLC7390U
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4034452
Chassis No.:	RU11114445
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,821.00
Original Registration Date:	25 May 2016
First Registration Date:	25 May 2016
Transfer Count:	0
Actual ARF Paid:	\$9,821.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2026
PARF Rebate Amount:	\$7,365.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$36,111.00
Total Rebate Amount:	\$43,476.00

The information contained herein is correct as at 19 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2018 14:56
Date Of Accident	18/09/2018 14:00
Exact Location Of Accident	CENTRAL EXPRESWAY TWDS CITY NEAR TO MOOLMEIN EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7390U
Insured/Policyholder	
Name Of Registered Owner	JEREMY TAN WEI JIE
NRIC No	S9046213Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98210040
Alternative Phone No	OFFICE-98210040

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102789136
Cover Note Number	

Driver

Name of Driver	ANTHONY TAN HOCK LAI
NRIC No	S1406785Z
Date Of Birth	05/12/1960
Occupation	INDOOR
Date Of Driving Pass	14/05/1982
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98210040
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 10ABENDEMEER RD #39-105
Postcode	331010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NPP
Police Station Address	ROAD: 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FV8341B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	GOH GUAN LIN
NRIC/Passport Number	S9871711J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	ANTHONY TAN HOCK LAI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLC7390U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
(understand, acknowledge, agree and consent that)
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

See police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FPV No.:

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20180919/2079

3 of 3

Report No. T/20180919/2079

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 TAN MENG LIANG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH

Contact No.: 65476367

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

19/09/2018 13:09

Classification Of Case:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180919/2079

1 of 3

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

Report No. T/20180919/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/09/2018 13:09		Vide Report No.:		Station Diary No.: 21	
Informant's Particulars					
Name of Informant: ANTHONY TAN HOCK LAI			Address: APT BLK 10A BENDEMEER ROAD #39-105 SINGAPORE 331010		
ID Type / ID No.: NRIC NO / S1406785Z			Contact No.: Home/Office: Mobile: 98210040		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 05/12/1960	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Private Hired Driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Driver: No	Date/Time of Accident: 18/09/2018 13:30	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY Central Expressway towards city near to Moulmein exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Colour	Condition	Number of Passengers
FV8341B	Motorcycle	HONDA	NF125MD	Red	Slightly Damaged	1
SLC7390U	Car	HONDA	VEZEL 1.5X CVT	Black	Seriously Damaged	1

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective Date	Expiry Date	
SLC7390U	NTUC Income Insurance Co-Operative Limited	5102789136	13/08/2018	12/08/2019	

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180919/2079

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 3

Report No. T/20180919/2079

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name			
GOH GUAN LIN		ID No.	S9871711J
Related Vehicle			
FV8341B (Motorcycle)		Contact No.	NIL
Hospital/Clinic			
NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL	Date Discharge
NIL		NIL	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury
NIL		NIL	Slight
Name			
ANTHONY TAN HOCK LAI		ID No.	S1406785Z
Related Vehicle			
SLC7390U (Car)		Contact No.	98210040
Hospital/Clinic			
FINEST HEALTH MEDICAL CENTRE		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment		19/09/2018	Date Discharge
19/09/2018		19/09/2018	19/09/2018
No. of Days granted Medical Leave		03	Degree of Injury
03		03	Serious

Brief Details.

On the 18/9/2018 at around 1330hrs, I was traveling along CTE expressway near to Moulmein exit and I was rear-ended by motor bike FV8341B. I did not notice much of injury at the point of time. But when I reached home after the accident, I felt discomfort on my neck and my back area. I then when went to seek treatment at Finest Health Medical Centre and I was given 3 days MC, MC number: #2314. The rider had suffered cuts on his right hand. No police or paramedic attended to the accident.

VEHICLE NO:

8LC73900

VEHICLE NO.

VEZEL


DATE OF ACCIDENT	18 / 9 / 2018		
TIME OF ACCIDENT	2:00 AM/PM		
LOCATION OF ACCIDENT	Central Expressway towards city near to Moulmein exit		
NAME OF OWNER	JEREMY TAXI WELSH		
TELP NO	98210040		
NRIC	S9046213Z		
CLAIM TYPE	OD / THIRD PARTY / Reporting Only		
INSURANCE CO.	MTUC		
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft		
POLICY NO.			
NAME OF DRIVER	As above / If No: ANTHONY TAN HOCK LAI		
NRIC	Any passengers: /		
DATE OF BIRTH	05 / 12 / 1960		
OCCUPATION	Outdoor / Indoor		
DATE OF DRIVING PASS	14 / May / 1982		
GENDER	Male / Female		
CONTACT NO.	98210040	Office:	Home:
ADDRESS			
DRIVER HAVE ANY OWN Vehicle	NO / If yes: Reg No:		
RELATIONSHIP	Employee / If No:		
WEATHER CONDITION	Clear / Raining / Other:		
ROAD SURFACE	Dry / Wet / Other:		
ANY INJURIES	No / If yes: Who?		
CONTACT NO.			
POLICE REPORT	No / If yes: Where?		
VEHICLE B NO.	FV83418	Any Passenger: /	
NAME			
CONTACT NO.			
VEHICLE C NO.	Any Passenger: /		
VEHICLE D NO.	Any Passenger: /		
VEHICLE E NO.	Any Passenger: /		
VEHICLE F NO.	Any Passenger: /		
ANY WITNESS			
WITNESS CONTACT NO.			
PARTICULAR WORKSHOP	Sme Motor Pte Ltd		
TELP NO	1 Kaki Bukit ave 6 #02-15		
CONTACT PERSON	Autobay @ kaki bukit		
FAX NO.	Singapore 417883		
	Telp: 67476106 (6 lines)		
	Fax: 67442368		

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20180919/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/09/2018 13:09	Vide Report No.:	Station Diary No.: 21
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ANTHONY TAN HOCK LAI			Address: APT BLK 10A BENDEMEER ROAD #39-105 SINGAPORE 331010	
ID Type / ID No.: NRIC NO / S1406785Z			Contact No.: Home/Office:	Mobile: 98210040
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 57	Date of Birth: 05/12/1960	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Private Hired Driver			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/09/2018 13:30	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Central Expressway towards city near to Moulmein exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FV8341B	Motorcycle	HONDA	NF125MD	Red	Slightly Damaged	1
SLC7390U	Car	HONDA	VEZEL 1.5X CVT	Black	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLC7390U	NTUC Income Insurance Co-Operative Limited	5102789136	13/08/2018	12/08/2019



**SINGAPORE
POLICE FORCE**



T/20180919/2079

2 of 3

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20180919/2079

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	GOH GUAN LIN	ID No.	S9871711J
Related Vehicle	FV8341B (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	ANTHONY TAN HOCK LAI	ID No.	S1406785Z
Related Vehicle	SLC7390U (Car)	Contact No.	98210040
Hospital/Clinic	FINEST HEALTH MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/09/2018	Date Discharge	19/09/2018
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On the 18/9/2018 at around 1330hrs, I was traveling along CTE expressway near to Moulmein exit and I was rear-ended by motor bike FV8341B. I did not notice much of injury at the point of time. But when I reached home after the accident, I felt discomfort on my neck and my back area. I then when went to seek treatment at Finest Health Medical Centre and I was given 3 days MC, MC number: #2314. The rider had suffered cuts on his right hand. No police or paramedic attended to the accident.



**SINGAPORE
POLICE FORCE**



T/20180919/2079

3 of 3

Report No. T/20180919/2079

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 TAN MENG LIANG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN

ABDULLAH

Contact No.: 65476367

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

19/09/2018 13:09

Classification Of Case:

FASTECH AUTO PTE LTD
1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not authorized
taken
2/5 + 4500/-
19/9/18
Hdy.

VEHICLE NO: SLC 7390 U

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN 1250
1 PCS	REAR WINDSCREEN MOULDING
2 PCS	REAR WINDSCREEN INNER SIDE GARNISH @\$105.00
1 PCS	TAILGATE
1 PCS	TAILGATE OUTER GARNISH
1 PCS	TAILGATE 'H' LOGO
2 PCS	TAILGATE REFLECTORS @\$460.10 264.60
1 PCS	TAILGATE REAR WIPER ARM 165.30
1 PCS	TAILGATE REAR WIPER MOTOR 540.00
1 PCS	TAILGATE REAR WIPER BLADE
1 PCS	TAILGATE INNER TRIM BOARD
1 PCS	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE 'VEZEL' EMBLEM
1 PCS	REAR BUMPER 762.70
2 PCS	REAR BUMPER SIDES @\$295.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.00
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$480.00
1 PCS	REAR BUMPER LOWER UNDER COVER

SAO	\$1,488.50	—
rer	\$121.30	—
11	\$210.00	X
11	\$1,100.90	X
wojeb/cu	\$285.30	—
rer	\$35.80	—
n/sscr	\$920.20	IPC
cu	\$205.30	—
Buflgm	\$665.20	—
11	\$60.80	X
de/toa	\$321.70	—
rer	\$50.00	—
11	\$299.20	X
11	\$288.20	X
rer	\$56.20	—
toa	\$810.20	—
11	\$590.00	X
11	\$130.00	X
11	\$514.00	X
11	\$188.00	X
11	\$960.00	X
de/toa	\$321.00	—
	\$9,621.80	

(202)

1 PCS	S.NETT
1 PCS	REAR WINDSCREEN SOLAR FILM
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR WINDSCREEN INNER SEAL
1 PCS	REAR WINDSCREEN PRIVATE HIRE STICKER
1 PCS	REAR WINDSCREEN V-KOOL STICKER
1 SET	REAR VIEW VIDEO-CAM
1 SET	REAR BUMPER REVERSE SENSOR
1 SET	REAR REVERSE CAMERA
1 PCS	TAILGATE TOP THIRD BRAKE LIGHT

rer	\$300.00	200
rer	\$50.00	40
rer	\$50.00	40
rer	\$30.00	—
11	\$30.00	X
11	\$380.00	X
11	\$280.00	X
Shub	\$380.00	—
cu	\$600.00	300

LABOUR CHARGES:

TO CHECK WIRING

\$80.00 30

TO DISMANTLE & REPLACING REAR WINDSCREEN

\$150.00 120

P-4173-9
3339.12

TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY
TO DISMENTLE & REFIX TAILGATE MECHANISM
TO DISMENTLE & REFIX REVERSE SENSOR
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

TOTAL

\$150.00 60
\$120.00 60
\$80.00 50
11 \$80.00 X
\$800.00 400
\$1,500.00 600
\$14,681.80

2310

5649.12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18017068/UTD3N2

Date: 28/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/17-987365-WTT
Claimant Vehicle No :	SLC7390U	Insured Vehicle No :	FV8341B
Date of Loss:	18/09/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-001279

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC7390U	Engine No:	L15B4034452
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11114445
Reg. Date:	25/05/2016 (Man. Year: 2016)	Odometer:	48133 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,721.80	4,329.12	7,392.68	63.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,320.00	1,640.00	55.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,681.80	5,649.12	9,032.68	61.52
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	14,681.80	4,500.00	10,181.80	69.35
+ GST 7.00/7.00% (S\$)	1,027.73	315.00	712.73	69.35
Nett Amount (S\$)	15,709.53	4,815.00	10,894.53	69.35

INSPECTION

Date of Assignment: 27/09/2018

Date Inspected: 19/09/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC7390U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Broken	1,488.50 F	*1,250.00 FL
2	1	*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
3	2	*REAR WINDSCREEN INNER SIDE GARNISH	Not Necessary	210.00 F	*- FL
4	1	*TAILGATE	Repair	1,100.90 F	*- FL
5	1	*TAILGATE OUTER GARNISH	Warped/Cracked	285.30 F	*285.30 FL
6	1	*TAILGATE H LOGO	Necessary	35.80 F	*35.80 FL
7	1	*TAILGATE REFLECTORS	N/s Scratched	920.20 F	*264.60 FL
8	1	*TAILGATE REAR WIPER ARM	Cracked	205.30 F	*165.30 FL
9	1	*TAILGATE REAR WIPER MOTOR	Bent/Jammed	665.20 F	*540.00 FL
10	1	*TAILGATE REAR WIPER BLADE	Not Necessary	60.80 F	*- FL
11	1	*TAILGATE INNER TRIM BOARD	Deformed/Torn	321.70 F	*321.70 FL
12	1	*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
13	1	*TAILGATE INNER LOCK	Not Necessary	299.20 F	*- FL
14	1	*TAILGATE WEATHERSTRIP	Not Necessary	288.20 F	*- FL
15	1	*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
16	1	*REAR BUMPER	Torn	810.20 F	*762.70 FL
17	2	*REAR BUMPER SIDES	Not Necessary	590.00 F	*- FL
18	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
19	1	*REAR END PANEL	Repair	514.00 F	*- FL
20	1	*REAR END PANEL TOP GARNISH	Not Necessary	188.00 F	*- FL
21	2	*TAILLAMPS	Not Necessary	960.00 F	*- FL
22	1	*REAR BUMPER LOWER UNDER COVER	Deformed/Torn	321.00 F	*321.00 FL
23	1	*REAR WINDSCREEN SOLAR FILM	Necessary	300.00 FS	*200.00 FS
24	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
25	1	*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
26	1	*REAR WINDSCREEN PRIVATE HIRE STICKER	Necessary	30.00 FS	*30.00 FS
27	1	*REAR WINDSCREEN V-KOOL STICKER	Not Necessary	30.00 FS	*- FS
28	1	*SET REAR VIEW VIDEO-CAM	Not Necessary	380.00 FS	*- FS
29	1	*SET REAR BUMPER REVERSES ENSOR	Not Necessary	280.00 FS	*- FS
30	1	*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*380.00 FS
31	1	*TAIL GATE TOP THIRD BRAKE LIGHT	Cracked	600.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,721.80	5,163.90
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	834.78
Total Parts (S\$)	11,721.80	4,329.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMENTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
3	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	60.00
4	TO DISMENTLE & REFIX TAILGATE MECHANISM	New	120.00	60.00
5	TO DISMENTLE & REFIX REVERSE SENSOR	New	80.00	50.00
6	TO SPRAY RUST PROOFING	New	80.00	-
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	400.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (S\$)			2,960.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >