

(08/11/13) wel

ASS. REC. BY: Moraw

REF:

CS/TP 18017070/Uvd3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: G3E1769Jat Workshop m/s Bur

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 48

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIR / PR Seen: 1 Consistent?: Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1-349C

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G3E1769JYr Regn: 8, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Nissan NV350c.c. 2488Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 161236

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC2E2670025010Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or racingmaxFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/8/18D.O.I. 19/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Int.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/10/18 2/5 to 5000 (Red 3286.10, 409)

RECEIVED 05 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

5/10 - typistReport Format: TPLump Sum / I.B.I. (\$) 5000/-Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

160
50
50 + 50
78
80
468

Ref. No. : <u>CS/TP 180170 To UvdBn2</u>	Res. Date: <u>20/9/18</u>	Date Received:
Veh. No. : <u>GBE1769</u>	SP:	WKSP: <u>B-1</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	Message:
3. Indicate Res. Date On Photo Page?	YES / NO	
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

Get your \$30 Trading Bonus*

*T&Cs apply. Trading involves
can result in the loss of

Post an Advertisement


Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 10 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly
From \$988 Onwards. Lowest
3.18%P.A@Gv Cars Financing
GV Credit Pte Ltd StarAd



6 vehicles

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

Search Selection

Nissan NV350

Any

Any

2015

Any



Nissan NV350 2.5M

\$47,800

\$7,240 /yr

27-Apr-2015

2,488 cc

37

Fuel Type: Diesel

Low Mileage, 1 Owner, Well Maintain By Owner, Look As Good As New, Don't Miss It, Call Now For Appointment!

ABWIN (1994) Pte Ltd

Posted: 19-Sep-2018 Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



Nissan NV350 2.5M

\$48,800

\$6,700 /yr

30-Dec-2015

2,488 cc

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 08-Sep-2018 Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



Nissan NV350 2.5A

\$64,900

\$9,700 /yr

28-May-2015

2,488 cc

63

Fuel Type: Diesel

10 Seaters Excursion Bus In Excellent Condition. Well Maintained And Regularly Serviced. Call Now For Viewing Appointment

Posted: 06-Sep-2018 Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan



Nissan NV350 2.5A

\$53,800

\$7,420 /yr

17-Dec-2015

2,488 cc

85

Fuel Type: Diesel

Reliable And Powerful Workhorse. Servicing Done Regularly. Warranty Still Valid By Tan Chong. Not For Picky Buyers. As Top Condition, But Will Get It Nicely Done Up Once C...

Posted: 05-Sep-2018 Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)
[Compare](#)

► Buy
► Later

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5349C
Vehicle Details	
Vehicle No.:	GBE1769J
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	YD25379352A
Chassis No.:	JN1MC2E26Z0005010
Maximum Power Output:	-
Open Market Value:	\$23,450.00
Original Registration Date:	25 Sep 2015
First Registration Date:	25 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$1,173.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$38,035.00
COE Rebate Amount:	\$26,677.00
Total Rebate Amount:	\$26,677.00

The information contained herein is correct as at 19 Sep 2018

OK

MKKH1811756-01 / K Kim Hin Auto Pte Ltd - MO
 ENTRY DATE & TIME: 29/08/2018 10:21
 SUBMITTED BY: Wong Shi Man

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 29/08/2018 10:21
 Date Of Accident 28/08/2018 09:20
 Exact Location Of Accident JUNCTION OF NEW BRIDGE ROAD & MERCHANT ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE1769J
Insured/Policyholder
 Name Of Registered Owner ANN CHIN COMPANY PTE LTD
 Co Reg No 200805349C
 Email Address ANNCHINCOMPANYPTLTD@GMAIL.COM
 Mobile Phone No (LOCAL) +65-81894699
 Alternative Phone No OFFICE-81894699
Vehicle Particulars
 Manufacturer NISSAN
 Model NV350-2.5 D PANEL VAN (M)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
Insurance Company
 Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA269724
 Cover Note Number
Driver
 Name of Driver LIU XING
 Passport No/FIN G2319421Q
 Date Of Birth 22/01/1978
 Occupation INDOOR
 Date Of Driving Pass 11/10/2014
 Driving Experience 3 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-82342256
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address C/O 16B LORNIE RD
 Postcode 298703
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name JANIE
 Phone Number 96453685
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR5755Y
 Vehicle Make/Model/Colour TOYOTA
 Details Of Properties
 Vehicle Category PRIVATE HIRE
 Name of Driver SOFIAN BIN OSMAN
 NRIC/Passport Number S8015467D
 Contact Number 91461643
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 29/2/2018 @
10/11/18

Sketch Plan Pg. 2

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Merchant Rd

At 9:20am on 28th August 2018 along ~~Merchant Road~~ 'T' junction
 Turning Right towards New Bridge Road while all vehicles were about
 to take off as the traffic light turn green. CAR B that was on third
 lane turn/cut into second lane ^{very} (CAR A GBE 1769J) direction abruptly
 Thus hitting the front left of CAR A (GBE 1769J). THERE WAS AN
 EYE WITNESS when accident happened. Her name is Jamie (HP: 96453685)

DECLARATION

I/We declare that foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

29/8/2018 @
10 AM.

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 4 Raffles Quay #18-00 Singapore 048589
 Tel (65) 6724 0010 Fax (65) 6724 0030
 Operating Hours: Monday to Friday, 9:00 - 17:00
 UEN: S85500220 / GST Reg. No.: M400617733

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MKKH1811756 Vehicle Registration No: GBE 1769J
 Name(s) shown in NRIC: Ann Chin Company Pte Ltd NRIC/FIN/Passport No: 200205349C
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: _____ Singapore ()
 Contact (Tel): 97575614 (Ms Pamela) Mobile No.: 81894699
 Email Address: _____
 Date of Accident: 28/8/2018 Time of Accident: 0920Hrs
 Place of Accident: Junction of New Bridge Road and Merchant Road
 Insurance Company: ATA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- ① Location of Accident should be:
Junction of New Bridge Road and Merchant Road
- ② Enclosed witness statement.
- ③ I wish to state that there was another vehicle (Veh C) beside my vehicle, which was ^{lightly} touched by my vehicle wingmirror due to the impact from Veh B. However, Vehicle C driver did not express any intention to claim. (Amended sketch plan enclosed)

Policyholder / Driver's Signature: _____
 Date: _____

Reporting Centre Personnel's Signature: Shuman
 Name: _____
 NRIC/FIN No.: 31/8/18
 Date: _____



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-20/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg

- Third party Co. Reg. No. 200704951N
- No illegal GST Reg. No. 200704951N
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

GSE17697

Acknowledged by Reparer

Signature:

Date:

No PA for 1st
 1/5 + 1000/-
 6h.

NOTE item

Front bumper	DIS	\$14.70 N	✓
Front bumper reinforcement	11	481.00 N	X
Front bumper side retainer n/s	CR	147.00 N	✓
Front bumper fog lamp cover n/s	2L	72.00 N	✓
Front bumper fog lamp n/s	CR	295.40 N	✓
1 set Front bumper clips	CR	35.00 N	✓
headlamp n/s	CR	473.00 N	✓
Front door n/s	10/set	1232.90 N	✓
Front door inner rubber n/s	CR	159.40 N	✓
Front door outer pillar n/s	70	693.00 N	✓
2 prs front door hinges @105.00	lower set	210.00 N	1pc
Front door inner lock n/s	11	166.70 N	X
Front step panel for inside n/s	DIS	105.00 N	✓
Front step panel n/s	324	188.20 N	✓
cooler n/s	Front/Car	483.20 N	✓
cooler cowl n/s	CR	185.00 N	✓
		5446.10	4688.2
(10h)			
To check w.ring		80.00	20
To spray rust proofing		80.00	✓
To Dismantle & replacing cooler		80.00	50
To transfer front door mechanism		100.00	80
To conduct wheel alignment	11	100.00	X
labour for panel beating & replacing parts		1200.00	1000
To putty & spray painting		1200.00	800
		TOTAL = 8286.10	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18017070/Uvd3n2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 08-10-2018



ON BEHALF OF ANN CHIN COMPANY PTE LTD

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBE 1769J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350 (A)	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1MC2E26Z0005010	Colour	WHITE
Odometer	161236	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	RACINGMAX	6 mm
L/H Front Tyre	195 R15	RACINGMAX	6 mm
R/H Rear Tyre	195 R15	RACINGMAX	6 mm
L/H Rear Tyre	195 R15	RACINGMAX	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2018	Inspection Date	19/09/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1769J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	DISTORTED	514.70	514.70
1	FRONT BUMPER REINFORCEMENT (N)	NOT NECESSARY	485.00	-
1	FRONT BUMPER SIDE RETAINER N/S (N)	CRACKED	147.00	147.00
1	FRONT BUMPER FOG LAMP COVER N/S (N)	DEFORMED	72.60	72.60
1	FRONT BUMPER FOG LAMP N/S (N)	CRACKED	295.40	295.40
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	35.00	35.00
1	HEADLAMP N/S (N)	CRACKED	473.00	473.00
1	FRONT DOOR N/S (N)	DENTED / BENT	1,232.90	1,232.90
1	FRONT DOOR INNER RUBBER N/S (N)	NECESSARY	159.40	159.40
1	FRONT DOOR OUTER PILLAR N/S (N)	DENTED	693.00	693.00
2	FRONT DOOR HINGES @\$105.00 (N)	LOWER BENT	210.00	105.00
1	FRONT DOOR INNER LOCK N/S (N)	NOT NECESSARY	166.70	-
1	FRONT STEP PANEL N/S (N)	BENT	188.20	188.20
1	COOLER N/S (N)	BENT / PUNCTURE	483.20	483.20
1	COOLER COWLING N/S (N)	CRACKED	185.00	185.00
1	FRONT STEP PANEL GARNISH N/S (N)	DISTORTED	105.00	105.00
	LESS 10% DISCOUNT		-	-468.94
			5,446.10	4,220.46
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	20.00
	TO SPRAY RUST PROOFING.		80.00	80.00
	TO DISMANTLE & REPLACING COOLER.		80.00	50.00
	TO TRANSFER FRONT DOOR MECHANISM.		100.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
	-		-	-
	-		-	-
	-		-	-
			2,840.00	2,030.00
GRAND TOTAL			8,286.10	6,250.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/TP18017070/Uvd3n2



Report Ref No. CS/TP18017070/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.