

ASS. REC. BY:

REF: CS/FCI18017071/11qdz

Special Instruction:

Surveyor  
CWS

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

19/9/18 @ 2.20pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 3666Y

Insured:

SHC 3897Z

at Workshop m/s

Komoco Motor

Tel:

90700157

of

253 Alexander Rd

Policy No:

Claim No:

D18066858MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/09/2018

CA / REV / REP. / REV 24 HRS

(Ds)

20/09/18

H.O.D. Endorsement:

Date/Time:

2.45pm @ 19/9/18

Person Contacted:

Ayraf

Vehicle IN/OUT

| Date/Time         | Action/Instruction (✓) Estimate                            |
|-------------------|------------------------------------------------------------|
|                   | SLR 3666Y - CC4/ASM18007690/Uha 3s2 DoA: 13/2/18           |
|                   | SHC 3897Z - CC3/TM117019210/K1+bn2 DoA: 6/10/17            |
| 15/9/18 @ 1.57pm  | revised to Joanne Yong by email.                           |
| 16/10/18 @ 3.20pm | confirmed with Chris final Ag to 1809-80, 3 days by email. |
|                   | CRed # 2909.32, 62/10)                                     |

Signature

Tanghin

REF:

FCI

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLR36664

Yr Regn:

2017 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai AE 1001P

C.C.

1580

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

27085

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHC 851CVH4 041333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/9/18

Survey held at

Konnor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED

Date/Time, File Pass to?



Preli. Report

11/6/18 Tanghin



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

1) S + RS. \$

2) Photos

3) Chart

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

7P

1809-80

135

50

50

53

288



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                | Ref : CS/FCI18017071/T1qd3 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                | Date : 19-09-2018          |  |
|                                                                                                                                        |                                                                                | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                |                            |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 3897Z                                                                      | Veh. Inspected             | SLR 3666Y                                                                           |
| Policy No.                                                                                                                             |                                                                                | Coverage (\$)              | 0.00                                                                                |
| Claim No.                                                                                                                              | D18006858MFSH                                                                  | Excess (\$)                | 0.00                                                                                |
| Assign From                                                                                                                            | CWS (JOANNE YONG)                                                              | Assign Date                | 19/09/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                |                            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                | c.c                        | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN                                                                         | Year of Reg.               |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                | Colour                     |                                                                                     |
| Odometer                                                                                                                               | -                                                                              | Steering                   |                                                                                     |
| Brakes                                                                                                                                 |                                                                                | Modification               |                                                                                     |
| General                                                                                                                                |                                                                                |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                |                            |                                                                                     |
|                                                                                                                                        | Size                                                                           | Make                       | Balance                                                                             |
| R/H Front Tyre                                                                                                                         |                                                                                |                            | mm                                                                                  |
| L/H Front Tyre                                                                                                                         |                                                                                |                            | mm                                                                                  |
| R/H Rear Tyre                                                                                                                          |                                                                                |                            | mm                                                                                  |
| L/H Rear Tyre                                                                                                                          |                                                                                |                            | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                |                            |                                                                                     |
|                                                                                                                                        |                                                                                |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                |                            |                                                                                     |
| Accident Date                                                                                                                          | 15/09/2018                                                                     | Inspection Date            | 20/09/2018                                                                          |
| Survey held at                                                                                                                         | KOMOCO MOTORCYCLES PTE LTD<br>253 ALEXANDRA ROAD<br>#01-04<br>SINGAPORE 159936 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                |                            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                |                            |                                                                                     |

### MOTOR SURVEY ASSIGNMENT

|                    |                              |                               |
|--------------------|------------------------------|-------------------------------|
| Date               | 17-09-2018                   | Our Ref No. D18006858MFSH     |
| Accident Date      | 15-09-2018                   | Claim Type. Third Party       |
| Insured Vehicle    | SHC3897Z                     | Third Party Vehicle. SLR3666Y |
| Survey Location    | 253 ALEXANDRA ROAD #01-01    |                               |
| Contact Person.    | ASYRAF                       |                               |
| Contact No.        | 90700157/ 0                  | Fax No. 0                     |
| Survey Type        | DIRECT SETTLEMENT:           |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD |                               |
| Contact Person     | NA                           | Fax No. 68416315              |
| Contact Number.    | NA                           |                               |

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                   |                       |                         |
|-------------------|-----------------------|-------------------------|
| Cc : Workshop     | KOMOCO MOTORS PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                    | TP Solicitor Fax No. NA |
| Officer Incharge  | JOANNEY               |                         |

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244267)



PRI Documents



Close



## PRI Header Details

|                          |                                                    |                                              |                                                                                                                                             |                                 |              |
|--------------------------|----------------------------------------------------|----------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|--------------|
| <b>Claim No</b>          | D18006858MFSH                                      | <b>Policy No</b>                             | D-18088936MFSH                                                                                                                              | <b>Claimant S.No &amp; Name</b> | 1 & KOMOCO   |
| <b>Workshop Name</b>     | KOMOCO MOTORS PTE LTD<br>(Contact Person : ASYRAF) | <b>Survey Location &amp; Contact Details</b> | 253 ALEXANDRA ROAD #01-01<br><b>Mobile:</b> 0 , <b>Phone:</b> 90700157 , <b>Fax:</b> 0<br><b>EmailId:</b> MUHAMMAD.ASYRAF@HYUNDAIMOTORS.COM |                                 |              |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                       | <b>Instructions To Surveyor</b>              | DIRECT SETTLEMENT:                                                                                                                          |                                 |              |
| <b>Insured Name</b>      | COMFORT TRANSPORTATION PTE LTD                     | <b>Insured Vehicle No</b>                    | SHC3897Z                                                                                                                                    | <b>TP Vehicle No</b>            | SHC3897Z     |
| <b>PRI Recieved Date</b> | 18-09-2018 09:34:19 PM                             | <b>Surveyor Appointed Date</b>               | 19-09-2018 02:19:06 PM                                                                                                                      | <b>Surveyor Accept Date</b>     | 19-09-2018 0 |

## Survey Report Upload

|                                    |                      |                             |            |                                |                                            |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 19-09-2018 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|

## Vehicle Particulars

|                  |                                                 |                       |                                                  |                |                                          |
|------------------|-------------------------------------------------|-----------------------|--------------------------------------------------|----------------|------------------------------------------|
| <b>Make</b>      | <input type="text" value="Please Select Make"/> | <b>Model</b>          | <input type="text" value="Please Select Model"/> | <b>Year</b>    | <input type="text" value="Select Year"/> |
| <b>Chasis No</b> | <input type="text"/>                            | <b>Engine No</b>      | <input type="text"/>                             | <b>Mileage</b> | <input type="text"/>                     |
| <b>Color</b>     | <input type="text"/>                            | <b>Cubic Capacity</b> | <input type="text"/>                             |                |                                          |

## Multiple Documents Upload

|                                                          |               |
|----------------------------------------------------------|---------------|
| <input type="button" value="Upload Multiple Documents"/> |               |
| <b>File Name</b>                                         | <b>Action</b> |

## Surveyor Job Remarks

|                |                      |                                     |
|----------------|----------------------|-------------------------------------|
| <b>Remarks</b> | <input type="text"/> | <input type="button" value="Save"/> |
|----------------|----------------------|-------------------------------------|

**Shiau Chan (LKKAUTO)**

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 26 October 2018 3:20 PM  
**To:** 'Chris Ang'; SUR  
**Cc:** Heng Swee Hee; Eddie Ang Khea Chwee; Muhammad Asyraf Noor Azman; Ng Leng Kiat  
**Subject:** RE: SLR3666Y-Hyundai Ioniq -Authorized

Dear Chris,

WITHOUT PREJUDICE

Confirm final fig \$1,809.80 before GST and 3 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chris Ang <[chris.ang@hyundaimotors.com.sg](mailto:chris.ang@hyundaimotors.com.sg)>  
**Sent:** Thursday, 18 October 2018 6:33 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Heng Swee Hee <[shheng@hyundaimotors.com.sg](mailto:shheng@hyundaimotors.com.sg)>; Eddie Ang Khea Chwee <[eddieang@hyundaimotors.com.sg](mailto:eddieang@hyundaimotors.com.sg)>; Muhammad Asyraf Noor Azman <[muhammad.asyraf@hyundaimotors.com.sg](mailto:muhammad.asyraf@hyundaimotors.com.sg)>; Ng Leng Kiat <[ng.lengkiat@hyundaimotors.com.sg](mailto:ng.lengkiat@hyundaimotors.com.sg)>  
**Subject:** SLR3666Y-Hyundai Ioniq -Authorized

Hi Taufik,

Above attach is the before paint, (?)mark items, supplementary photo and finalise estimate for COR

I m sending on behalf of Asyraf, my colleague.

Thank you

REGARDS

*CHRIS ANG*

KOMOCO MOTORS PTE. LTD.

D:(65) 68018840

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 25 September 2018 1:57 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006858MFSH/1  
**Attachments:** CSFCI18017071T1qd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLR 3666Y.

Best Regards,

**Shiau Chan (Ms) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 19 September 2018 3:15 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006858MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 20/09/2018.

Moreover, according to the repairer, the TP vehicle number is SLR 3666Y.

BEST REGARDS,

**G.Nivitha | Admin**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 19 September 2018 2:19 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [JOANNEYONG@MSFIRSTCAPITAL.COM.SG](mailto:JOANNEYONG@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18006858MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006858MFSH

Date: 25 September 2018

Our Ref: CS/FCI18017071/T1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 3666Y**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/09/2018 at the premises of M/s KOMOCO MOTOR, and have the following to report:-

|                          |                  |
|--------------------------|------------------|
| Workshop Estimate Amount | : S\$ 4,719.12 . |
| Revised Estimate Amount  | : S\$ 1,668.36 . |
| "Check" Items Amount     | : S\$ 935.36 .   |
| Market Value             | : S\$ - .        |
| LTA Reimbursement Value  | : S\$ - .        |
| Nett Value               | : S\$ - .        |

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh  
Automotive Assessor

AXA INSURANCE PTE LTD  
8 Shenton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel:(65)63387288 Fax:(65)63382522  
Website:www.axa.com.sg  
GST Registration Number: 199903512M  
customer.service@axa.com.sg



## CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

|                                 |                                                               |                            |
|---------------------------------|---------------------------------------------------------------|----------------------------|
| <b>CERTIFICATE NO.</b>          | <b>: VFX/PI305555</b>                                         | <b>Account No. : 16418</b> |
| <b>Coverage</b>                 | <b>: Comprehensive</b>                                        |                            |
| <b>Sum Insured</b>              | <b>: Market Value At The Time Of Loss</b>                     |                            |
| <b>Name of Policy Holder</b>    | <b>: KOMOCO CAR RENTALS PTE LTD</b>                           |                            |
| <b>Vehicle Registration No.</b> | <b>: SLR3666Y</b>                                             |                            |
| <b>Period of Insurance</b>      | <b>: From 01/01/2018 To 31/12/2018 (Both Dates Inclusive)</b> |                            |

### PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### LIMITATIONS AS TO USE\*

(a) Use for the carriage of passengers or goods in connection with the Policyholder's business

(b) Use for social, domestic and pleasure purposes and business purpose of any person to whom the vehicle is hired

The Policy does not cover

(a) Use for racing, pace making, reliability trial or speed-testing

(b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle

(c) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired

(04)

### EXCESS :

Sect I - Used In S'pore Only : SGD 350.00

W/screen Excess in Singapore : SGD 100.00

Sect I - Used Outside S'pore : SGD 350.00

W/screen Excess (Outside S'pore) : SGD 100.00

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

■ We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

  
Authorized Signature

Issued by - SGOAKAS2 on 31/01/2018

### IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

FOR INDIVIDUAL CUSTOMERS : Cover Under the policy is valid only upon the payment of the full premium stated on the policy.

FOR NON-INDIVIDUAL CUSTOMERS : Please refer to the Premium Warranty Clause on the policy

REPUBLIC OF SINGAPORE

IDENTITY CARD NO: S9425282B



Name

MUHAMMAD IRWAN BIN ABDUL  
RAHIM

Race

MALAY

Date of birth

13-07-1994

Sex

M

Country of birth

SINGAPORE

12520

4343755



UIC: S9425282B

Date of issue  
23-01-2009

APT BLK 117 SIMEI STREET  
#02-556  
SINGAPORE 520117

**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**

Licence Number: **S 9 4 2 5 2 8 2 B**

Name:

**MUHAMMAD IRWAN BIN ABDUL  
RAHIM**

Birth Date: **13 Jul 1994**

Issue Date: **26 Oct 2015**



002486943G

**30**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

|          |                                                                                                                                                           |             |
|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Class 3A | Motor cars without clutch pedals (Auto) =< 3000kg<br>< 7 passengers, exclusive of the driver; and<br>other motor vehicles without clutch pedals =< 2500kg | 26 Oct 2015 |
|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|

NP 428A



Licence No: S9425282B



**KOMOCO MOTORS PTE. LTD.**  
 30 Alexandra Road #01-01 Singapore 119945  
 Tel: 65-6471 2386 Fax: 65-6471 2385 Email: info@komoco.com.sg  
 65440 98850312

( GST REGISTRATION NO: MR-8500364-4 )

Date : 18/09/2018

**MS FIRST CAPITAL INSURANCE PTE LTD**

Attn: Claim Dept.

Vehicle number : **SLR3666Y**  
 Make and model : Hyundai Ioniq 1.6 DCT S/R Hybrid  
 Registration Date : 14/8/2017  
 Chassis number : KMHC851CVHU041373  
 Engine number : G4LEHU425482

Job No. : 2018035160  
 Owner name : Komoco Car Rental  
 Date of Acc. : 15/9/2018  
 Policy number : VFX/P1305555  
 Claim Type : **OD - Excess TBC TO CLAIM**

**Rear Items :**

|    |                                   |               |    |                 | <b>Estimate</b> |
|----|-----------------------------------|---------------|----|-----------------|-----------------|
| 1  | MOULDING ASSY-RR BUMPER,CTR       | 86610-G2010   | \$ | 270.10          | One ✓           |
| 2  | REFLECTOR/REFLEX ASSY-RR LH       | 92405-G2000   | \$ | 31.90           | X m             |
| 3  | REFLECTOR/REFLEX ASSY-RR RH       | 92406-G2000   | \$ | 31.90           | ? X hn          |
| 4  | CAP-RR HOOK                       | 86688-G2000   | \$ | 9.10            | X m             |
| 5  | LAMP ASSY-LICENSE PLATE           | 92501-G2000   | \$ | 60.40           | de ✓            |
| 6  | WIRING HARNESS-BWS EXT            | 91890-G2130   | \$ | 210.10          | ? X m           |
| 7  | COVER-RR BUMPER SIDE UNDER,LH     | 86695-G2000   | \$ | 27.50           | X m             |
| 8  | COVER-RR BUMPER SIDE UNDER,RH     | 86696-G2000   | \$ | 27.50           | ? X m           |
| 9  | COVER-RR BPR UNDER CTR            | 86691-G2000   | \$ | 28.70           | ? ✓ de          |
| 10 | MOULDING-REAR BUMPER LWR,CTR      | 86689-G2000   | \$ | 47.50           | ? ✓ de          |
| 11 | COVER-RR BUMPER                   | 86611-G2000   | \$ | 459.40          | de ✓            |
| 12 | LAMP ASSY-REAR FOG                | 92405-G2100   | \$ | 201.50          | ? X hn          |
| 13 | BEAM-RR BUMPER                    | 86631-G2010   | \$ | 294.80          | One ✓           |
| 14 | BRACKET-RR BEAM LWR,CTR           | 86637-G2010   | \$ | 6.20            | de ✓            |
| 15 | BRACKET-RR BEAM LWR MTG,LH        | 86636-G2000   | \$ | 2.60            | de ✓            |
| 16 | BRACKET-RR BEAM LWR MTG,RH        | 86639-G2000   | \$ | 2.60            | de ✓            |
| 17 | STAY-RR BUMPER LH                 | 86641-G2010   | \$ | 138.10          | ? X hn          |
| 18 | STAY-RR BUMPER RH                 | 86642-G2010   | \$ | 138.10          | ? X hn          |
| 19 | ANTENNA ASSY-SMARTKEY             | 95420-G2300   | \$ | 40.50           | ? X hn          |
| 20 | SENSOR ASSY-PARKING ASSIST SYSTEM | 95720-D3000EB | \$ | 140.20          | ? X hn          |
| 21 | ULTRASONIC SENSOR ASSY-FBWS       | 95720-F2000EB | \$ | 132.00          | ? X hn          |
| 22 | BRACKET ASSY-RR BUMPER SIDE,RH    | 86614-G2000   | \$ | 33.10           | de ✓            |
| 23 | BRACKET ASSY-RR BUMPER SIDE,LH    | 86613-G2000   | \$ | 33.10           | ? X hn          |
| 24 | PANEL ASSY-BACK                   | 69100-G2500   | \$ | 532             | X m             |
| 25 | SUNDRIES                          |               | \$ | 100.00          | 30 X hn.        |
|    |                                   |               | \$ | 2,998.90        |                 |
|    | Less 20% Discount                 |               | \$ | 599.78          |                 |
|    | <b>Total</b>                      |               | \$ | <b>2,399.12</b> |                 |

**Body & Paint Repairs:**

|   |                                            |     |    | <b>Estimate</b> |
|---|--------------------------------------------|-----|----|-----------------|
| 1 | TO CARRY OUT BODY REPAIR                   | 320 | \$ | 1,280.00 320    |
| 2 | TO COMPLETE PUTTY AND SPRAY AFFECTED AREAS | 255 | \$ | 1,000.00 375    |
|   |                                            |     | \$ | 2,280.00        |

**Labour Repairs:**

|   |                                      |  |    | <b>Estimate</b> |
|---|--------------------------------------|--|----|-----------------|
| 3 | TO SUPPLY REAR NUMBER PLATE (S.NETT) |  | \$ | 40.00 bt ✓      |
|   |                                      |  | \$ | 40.00           |
|   |                                      |  | \$ | 4,719.12        |

|                    |                    |
|--------------------|--------------------|
| Less Excess        |                    |
| Total              | \$ 4,719.12        |
| Add GST 7%         | \$ 330.34          |
| <b>Grand Total</b> | <b>\$ 5,049.46</b> |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please let us know if there is any discrepancy or error in the Finalized Bill in the next Three ( 3 ) working days.

Kindly contact Mr. Asyraf at 90700157 if there is any error. If we do not hear from your good office we

Date:

Tanpin 9749549  
 WP  
 20/9/18 @ 1655  
 Resurvey before print.  
 03 days  
 sure@lkkauto.com

25/9/18



**KOMOCO MOTORS PTE LTD**  
 251 Alexandra Road #01-01 Singapore 119955  
 Tel: 686 6471 Fax: 686 4470 Email: info@komocomotors.com.sg  
 REPAIR INQUIRY

(GST REGISTRATION NO: MR-8500364-4)

Date : 18/09/2018

**MS FIRST CAPITAL INSURANCE PTE LTD**  
 Attn: Claim Dept.

Vehicle number : **SLR3666Y**  
 Make and model : Hyundai Ioni6 1.6 DCT S/R Hybrid  
 Registration Date : 14/8/2017  
 Chassis number : KMHC851CVHU041373  
 Engine number : G4LEHU425482

Job No. : 2018035160  
 Owner name : Komoco Car Rental  
 Date of Acc. : 15/9/2018  
 Policy number : VFX/P1305555  
 Claim Type : OD -Excess TBC

|                     |                                   | <b>Finalise</b>         |                |
|---------------------|-----------------------------------|-------------------------|----------------|
| <b>Rear Items :</b> |                                   | <b>Estimate</b>         | <b>Revised</b> |
| 1                   | MOULDING ASSY-RR BUMPER,CTR       | 86610-G2010 \$ 270.10   | \$ 270.10      |
| 2                   | REFLECTOR/REFLEX ASSY-RR LH       | 92405-G2000 \$ 31.90    | Refit          |
| 3                   | REFLECTOR/REFLEX ASSY-RR RH       | 92406-G2000 \$ 31.90    | Refit          |
| 4                   | CAP-RR HOOK                       | 86688-G2000 \$ 9.10     | Refit          |
| 5                   | LAMP ASSY-LICENSE PLATE           | 92501-G2000 \$ 60.40    | \$ 60.40       |
| 6                   | WIRING HARNESS-BWS EXT            | 91890-G2130 \$ 210.10   | Refit          |
| 7                   | COVER-RR BUMPER SIDE UNDER,LH     | 86695-G2000 \$ 27.50    | Refit          |
| 8                   | COVER-RR BUMPER SIDE UNDER,RH     | 86696-G2000 \$ 27.50    | Refit          |
| 9                   | COVER-RR BPR UNDER CTR            | 86691-G2000 \$ 28.70    | \$ 28.70       |
| 10                  | MOULDING-REAR BUMPER LWR,CTR      | 86689-G2000 \$ 47.50    | \$ 47.50       |
| 11                  | COVER-RR BUMPER                   | 86611-G2000 \$ 459.40   | \$ 459.40      |
| 12                  | LAMP ASSY-REAR FOG                | 92405-G2100 \$ 201.50   | Refit          |
| 13                  | BEAM-RR BUMPER                    | 86631-G2010 \$ 294.80   | \$ 294.80      |
| 14                  | BRACKET-RR BEAM LWR,CTR           | 86637-G2010 \$ 6.20     | \$ 6.20        |
| 15                  | BRACKET-RR BEAM LWR MTG,LH        | 86636-G2000 \$ 2.60     | \$ 2.60        |
| 16                  | BRACKET-RR BEAM LWR MTG,RH        | 86639-G2000 \$ 2.60     | \$ 2.60        |
| 17                  | STAY-RR BUMPER LH                 | 86641-G2010 \$ 138.10   | Refit          |
| 18                  | STAY-RR BUMPER RH                 | 86642-G2010 \$ 138.10   | \$ 138.10      |
| 19                  | ANTENNA ASSY-SMARTKEY             | 95420-G2300 \$ 40.50    | Refit          |
| 20                  | SENSOR ASSY-PARKING ASSIST SYSTEM | 95720-D3000EB \$ 140.20 | Refit          |
| 21                  | ULTRASONIC SENSOR ASSY-FBWS       | 95720-F2000EB \$ 132.00 | Refit          |
| 22                  | BRACKET ASSY-RR BUMPER SIDE,RH    | 86614-G2000 \$ 33.10    | \$ 33.10       |
| 23                  | BRACKET ASSY-RR BUMPER SIDE,LH    | 86613-G2000 \$ 33.10    | Refit          |
| 24                  | PANEL ASSY-BACK                   | 69100-G2500 532         | Refit          |
| 25                  | SUNDRIES                          | \$ 100.00               | None           |
|                     |                                   | \$ 2,998.90             | \$ 1,343.50    |
| Less 20% Discount   |                                   | \$ 599.78               | \$ 268.70      |
| Total               |                                   | \$ 2,399.12             | \$ 1,074.80    |

**Body & Paint Repairs:**

|                                              | <b>Estimate</b> | <b>Revised</b> |
|----------------------------------------------|-----------------|----------------|
| 1 TO CARRY OUT BODY REPAIR                   | \$ 1,280.00     | \$ 320.00      |
| 2 TO COMPLETE PUTTY AND SPRAY AFFECTED AREAS | \$ 1,000.00     | \$ 375.00      |
|                                              | \$ 2,280.00     | \$ 695.00      |

**Labour Repairs:**

|                                        | <b>Estimate</b> | <b>Revised</b> |
|----------------------------------------|-----------------|----------------|
| 3 TO SUPPLY REAR NUMBER PLATE (S.NETT) | \$ 40.00        | \$ 40.00       |
|                                        | \$ 40.00        | \$ 40.00       |
|                                        | \$ 4,719.12     | \$ 1,809.80    |

Less Excess

|                    |                    |                    |
|--------------------|--------------------|--------------------|
| Total              | \$ 4,719.12        | \$ 1,809.80        |
| Add GST 7%         | \$ 330.34          | \$ 126.69          |
| <b>Grand Total</b> | <b>\$ 5,049.46</b> | <b>\$ 1,936.49</b> |

Please let us know if there is any discrepancy or error in the Finalized Bill in the next Three ( 3 ) working days.  
 Kindly contact Mr. Asyraf at 90700157 if there is any error. If we do not hear from your good office we



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                |                 |                              |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|-----------------|------------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                |                 | Ref : CS/FCI18017071/T1qd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                |                 | Date : 31-10-2018            |  |
|                                                                                                                                                                                        |                                                                                |                 | Code : FCI2                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                |                 |                              |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 3897Z                                                                      | Veh. Inspected  | SLR 3666Y                    |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088936MFSH                                                                 | Coverage (\$)   | 0.00                         |                                                                                     |
| Claim No.                                                                                                                                                                              | D18006858MFSH                                                                  | Excess (\$)     | 0.00                         |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                                                                    | Assign Date     | 19/09/2018                   |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                |                 |                              |                                                                                     |
| Make & Model                                                                                                                                                                           | HYUNDAI AE IONIQ                                                               | c.c             | 1580                         |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                         | Year of Reg.    | 2017                         |                                                                                     |
| Chassis No.                                                                                                                                                                            | KMHC851CVHU041373                                                              | Colour          | GREY                         |                                                                                     |
| Odometer                                                                                                                                                                               | 27085                                                                          | Steering        | IN ORDER                     |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                       | Modification    | SPORTS RIM                   |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                           |                 |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                |                 |                              |                                                                                     |
|                                                                                                                                                                                        | Size                                                                           | Make            | Balance                      |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 225/45 R17                                                                     | MICHELIN        | 6 mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 225/45 R17                                                                     | MICHELIN        | 6 mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 225/45 R17                                                                     | MICHELIN        | 6 mm                         |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 225/45 R17                                                                     | MICHELIN        | 6 mm                         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                |                 |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                                |                 |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                |                 |                              |                                                                                     |
| Accident Date                                                                                                                                                                          | 15/09/2018                                                                     | Inspection Date | 20/09/2018                   |                                                                                     |
| Survey held at                                                                                                                                                                         | KOMOCO MOTORCYCLES PTE LTD<br>253 ALEXANDRA ROAD<br>#01-04<br>SINGAPORE 159936 |                 |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                |                 |                              |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                |                 |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                |                 |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                | 3 Working Days  |                              |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3666Y

| Qty                         | Description of Parts              | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                   |               |                           |                   |
| 1                           | MOULDING ASSY-RR BUMPER,CTR       | CRACKED       | 270.10                    | 270.10            |
| 1                           | REFLECTOR/REFLEX ASSY-RR LH       | NOT NECESSARY | 31.90                     | -                 |
| 1                           | REFLECTOR/REFLEX ASSY-RR RH       | NOT NECESSARY | 31.90                     | -                 |
| 1                           | CAP-RR HOOK                       | NOT NECESSARY | 9.10                      | -                 |
| 1                           | LAMP ASSY-LICENSE PLATE           | DEFORMED      | 60.40                     | 60.40             |
| 1                           | WIRING HARNESS-BWS EXT            | NOT NECESSARY | 210.10                    | -                 |
| 1                           | COVER-RR BUMPER SIDE UNDER,LH     | NOT NECESSARY | 27.50                     | -                 |
| 1                           | COVER-RR BUMPER SIDE UNDER,RH     | NOT NECESSARY | 27.50                     | -                 |
| 1                           | COVER-RR BPR UNDER CTR            | DEFORMED      | 28.70                     | 28.70             |
| 1                           | MOULDING-REAR BUMPER LWR,CTR      | DEFORMED      | 47.50                     | 47.50             |
| 1                           | COVER-RR BUMPER                   | DEFORMED      | 459.40                    | 459.40            |
| 1                           | LAMP ASSY-REAR FOG                | NOT NECESSARY | 201.50                    | -                 |
| 1                           | BEAM-RR BUMPER                    | CRACKED       | 294.80                    | 294.80            |
| 1                           | BRACKET-RR BEAM LWR,CTR           | NECESSARY     | 6.20                      | 6.20              |
| 1                           | BRACKET-RR BEAM LWR MTG,LH        | NECESSARY     | 2.60                      | 2.60              |
| 1                           | BRACKET-RR BEAM LWR MTG,RH        | NECESSARY     | 2.60                      | 2.60              |
| 1                           | STAY-RR BUMPER LH                 | NOT NECESSARY | 138.10                    | -                 |
| 1                           | STAY-RR BUMPER RH                 | BENT          | 138.10                    | 138.10            |
| 1                           | ANTENNA ASSY-SMARTKEY             | NOT NECESSARY | 40.50                     | -                 |
| 1                           | SENSOR ASSY-PARKING ASSIST SYSTEM | NOT NECESSARY | 140.20                    | -                 |
| 1                           | ULTRASONIC SENSOR ASSY-FBWS       | NOT NECESSARY | 132.00                    | -                 |
| 1                           | BRACKET ASSY-RR BUMPER SIDE,RH    | NECESSARY     | 33.10                     | 33.10             |
| 1                           | BRACKET ASSY-RR BUMPER SIDE,LH    | NOT NECESSARY | 33.10                     | -                 |
| 1                           | PANEL ASSY-BACK                   | NOT NECESSARY | 532.00                    | -                 |
| 1                           | SUNDRIES                          | NOT NECESSARY | 100.00                    | -                 |
|                             | LESS 20% DISCOUNT                 |               | -599.78                   | -268.70           |
|                             |                                   |               | 2,399.12                  | 1,074.80          |
| <b>SPECIAL NETT ITEMS</b>   |                                   |               |                           |                   |
| 1                           | REAR NUMBER PLATE (SN)            | BENT          | 40.00                     | 40.00             |
|                             |                                   |               | 40.00                     | 40.00             |

Report Ref No. CS/FCI18017071/T1qd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                        | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------|-----------|---------------------------|-------------------|
|                                    | <b>LABOUR</b>                               |           |                           |                   |
|                                    | TO CARRY OUT BODY REPAIR.                   |           | 1,280.00                  | 320.00            |
|                                    | TO COMPLETE PUTTY AND SPRAY AFFECTED AREAS. |           | 1,000.00                  | 375.00            |
|                                    |                                             |           | 2,280.00                  | 695.00            |
|                                    | <b>GRAND TOTAL</b>                          |           | <b>4,719.12</b>           | <b>1,809.80</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                             |           |                           | <b>1,809.80</b>   |

Report Ref No. CS/FCI18017071/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.